

ASS. REC. BY:

REF: CS/MSA/7022446/TIV69

Special Instruction:

Surveyor:

Tamilah

ASSIGNMENT (Office)

From (Person):

Lionel Tan

of

MSSG

Date/Time:

23/11/17 @ 511P

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

ED 338C

Insured:

GBC 7571H

at Workshop m/s

Kah Motor

Tel:

82886302

of

Leng Keng

Policy No:

29004183MKF

Claim No:

537105

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

16/11/17

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Vehicle IN/OUT

Date/Time	Action/Instruction () Estimate
	ED 338C x
	GBC 7571H x
27/11/17	Send preli revised by merimen
27/12/17	@ 308pm Patrick will email us finalise when ready
23/1/18	@ 457pm Patrick will email us finalise when ready

Tanpoh

MS19

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD (TP) WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at/Nonance/ma: **Kan Motor**

of: **Long Kee**

Insured: **EQ338C**

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of van: _____

(Policy Condition)

Remark: The van had commenced its repair at the time of inspection.

Sal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

SLA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Pass: Yes or No

Lump Sum: _____ % 3 Val: Yes or No

CA / REV / REP / 24 HRS **WP**

Date: _____ Person Contacted: **Patrick Mok** Vehicle IN / OUT

Date / Time: _____ Action / Instruction: _____

Van No: **EQ338C** In Reg: **2016 Dec.**

Type: ☒ Cycle / Bus / Van / Lorry / Taxi / Prime Mover

Truck / Trailer: _____

Make: **Monoln Accord** **1997**

Colour: **Sl/ner** A/C: **Insured / Std / Nil / NA**

So Reading: **19477** T-Ratio: **Insured / Std / Nil / NA**

Eng No: _____

C No: **MRHCR16306P000061**

Gen. Cond: **B** Good / Fair / Poor / Burnt

Steering: **B** Indented / Jammed / Leaked / Burnt or

Brake: **B** Indented / Jammed / Leaked / Burnt or

Mod: **Nil / S/R** STD A/Rim or

Tyre Size: **P: 225/50R17**
R: ~

BS / DUN / EXNOVA / GY / FS / LIZA / **MC** OHTSU / PIR / SUMI / TOYO / YOKO or

Front	Rear
R.Bel: 6 mm	R.Bel: 6 mm
L.Bel: 6 mm	L.Bel: 6 mm
O.O.A: _____	D.O.I: 24/11/17 @ 1130

Survey held at: **Kan Motor Long Kee**

Des. of Damages: **Fr / Rear: O/S / N/S / UIC / Rooftop or**
Rear o/s

The UIC / Chassis frame / Body Structure affected due to collision

1/2/18 final fig \$935.93 confirmed by email (Ref 306874, 24/1)

RECEIVED 02 FEB 2018

Can Time File Pass to: ☐ : Prel. Report
☐ : Final Report

Days Of Repair: **9**
Resurvey No. of Trio: **1**

1/2 - typist

Add Fee: ☐ Site Visit \$
☐ Night \$
☐ Technical \$
☐ High Risk \$

Report Format: **menimen**
Lump Sum: **9335.93**

Survey Fee: **300**

Survey Department Check List (Case Handler)

Reference No.: CS/MSG17022446/TIVB

Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all information created by the assignment team are **ACCURATE**.

(1) Office Assignment Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No	✓			
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded	✓			
---	-------------------------	---	--	--	--

Check By: VERON 12/12
Case Handler Date

*C: Critical *N: Non-Critical

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG17022446/T1vb

16 RAFFLES QUAY

#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 24-11-2017



Code : MSG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBC 7571H	Veh. Inspected	EQ 338C
Policy No.	290041863MKF	Coverage (\$)	0.00
Claim No.	537105	Excess (\$)	0.00
Assign From	LIONEL TAN (MERIMEN)	Assign Date	23/11/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	16/11/2017	Inspection Date	24/11/2017
Survey held at	KAH MOTOR CO SDN BERHAD NO. 255 ALEXANDRA ROAD SINGAPORE 159937		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Est Approved	Status
Main	16 Nov 2017		23 Nov 2017 17:11 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

[Created by insurer]

CLAIM SUBFOLDER DETAILS

Insured:	GOLDBELL LEASING PTE LTD, Co. Reg. No.: 199001196N		
Main Claimant:	CALVIN YIP CHEE KIN, ID: S72163721		
Vehicle Reg. No.:	EQ338C	Date of Loss:	16/11/2017 08:00 - :59
Claim Type:	TP / 537105	Policy/Cover Note No.:	29004183MKF (Third Party Only) Coverage: 20/08/2017 - 31/08/2018
Vehicle Reg. No. (Insured):	GBC7571H	Policy No. (Claimant):	
		Excess:	S\$5,000.00
Repairer:	- Not Applicable - (-)		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Lionel Tan Tian Pei - 6643 1307]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 24/11/2017]		
Driver/Custodian (Insured):	TAN KAI CHIN (), NRIC: G6643485R, Tel: +6584901690		
Adj Asg. Remarks:	PLS CONTACT Patrick Mok Motor Claims Advisor Kah Motor Co. Sdn. Bhd. Mobile : 82886302 APPT AT 11.30AM ON 24.11.17.OWNER BE AWAITING		

[View All](#) [Compose Case Mail](#)

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Tas..](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

IN

Tanfiken

LKK Auto Consultants Pte Ltd (Co. Reg. No. 199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Lionel Tan Tian Pei

Date: 27 Nov 2017

Preliminary Advice

Insured Vehicle No : GBC7571H

TP Vehicle No : EQ338C

Accident Date : 16/11/2017

Make : HONDA ACCORD

Assignment Date : 23/11/2017

Date of Inspection : 24/11/2017

Est. Duration of Repair : 9.00

Inspection At :

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	12,318.05
Revised Amount	:S\$	8,982.12
Check Items (Estimated)	:S\$	1,210.03
Total	:S\$	10,192.15

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	16/11/2017 14:42
Date Of Accident	16/11/2017 08:50
Exact Location Of Accident	JUNCTION OF JALAN SULTAN & BEACH ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	EQ338C
Insured/Policyholder	
Name Of Registered Owner	CALVIN YIP CHEE KIN
NRIC No	S7216372I
Email Address	CALVIN@YIPNCO.COM.SG
Mobile Phone No	(LOCAL) +65-97330338
Alternative Phone No	OFFICE-97330338

Vehicle Particulars

Manufacturer	HONDA
Model	ACCORD-2.0 I-VTEC (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	LIBERTY INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	SD16V16741/PC2/R00
Cover Note Number	

Driver

Name of Driver	CALVIN YIP CHEE KIN
NRIC No	S7216372I
Date Of Birth	11/05/1972
Occupation	INDOOR
Date Of Driving Pass	25/11/1994
Driving Experience	22 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97330338
Fax Number	
Contact Number	OFFICE-97330338
EMail Address	CALVIN@YIPNCO.COM.SG

Address

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OWNER

Vehicle Registration Number of Driver's Own Vehicle

-

-

-

Insurance Company of Driver's Own Vehicle

-

-

-

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Was any body injured in the Accident? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 3

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

REFER TO ATTACHMENT

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? YES

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GBC7571H

Vehicle Make/Model/Colour MITSUBISHI CANTER FUSO

Details Of Properties FRONTAL

Name of Driver TAN KAI CHIN

NRIC/Passport Number G6643485R

Contact Number 84901690

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

Vehicle No EQ 338 C

SKETCH PLAN

Annex D

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

B. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers") the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and


(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



Vehicle No E0 336 C

Appendix E

Describe Circumstances of the Accident

On 16 November 2017 at around 8.50 am, I was driving along Jalan Sultan turning into Beach Road.

The weather was clear and bright, traffic conditions ~~was~~ moderate.

As I was turning into Beach Road, I slowed down and came to a complete stop because there was a pedestrian crossing on the traffic light junction.

Suddenly a lorry slammed into the rear of my vehicle. The lorry, a Mitsubishi Fuso Canter GRC 75TH was driven by a Mr. Tan Kai Chin (G6643485R).

I inspected my vehicle and found the right side of the rear to be badly damaged, signal/brake lights were smashed and even the bumper had a large crack.

We exchanged details and the driver of the lorry, Mr. Tan asked me to claim insurance.

I have a video recording of the entire accident.

You had been advised by the workshop that in the event that you wish to claim against your own policy (OD claim), there is a Fourteen (14) days clause whereby the claim must be made within the stipulated timeframe from the day of occurrence.

Declaration

We declare the foregoing particulars are true in every respect.

 16/11/17

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time


Witnessed by Reporting Centre Personnel



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : MSIG INSURANCE (SINGAPORE) PTE
 16 RAFFLES QUAY
 HONG LEONG BUILDING
 SINGAPORE 048581

Registration No : EQ338C

Chassis No : MRHCR1630GP000061

Model : ACCORD 2.0 AT 2016

Owner's Name : CALVIN YIP CHEE KIN

Ins Policy No. :

Date of Accident :

Document No. : SQT17004704 Page 1

Date : 16. Nov 2017

Customer No. : WZM003

Svc Advisor : PATRICK MOK LIP KAY

Engine No : R20Z21600079

Date | Time : 16. Nov 2017 2:43:45 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	GST Amt	Amount Incl GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: CALVIN YIP CHEE KIN OWNER INSURER: LIBERTY INSURANCE ACC DATE: 16/11/2017 SURVEYED BY: DATE: REF NO: TP INSURER: MSIG INSURANCE TP VEH: GBC7571H						
BOSUN	SUNDRIES <i>NK</i>	1	100.00		100.00	7.00	107.00
BOJSE	SEALANT FOR BOOT COVER	1	100.00		100.00	7.00	107.00
BOJSE	SEALANT FOR REAR END PANEL	1	100.00		100.00	7.00	107.00
BKRP02M	CUT OFF & RENEW RR PANEL. STRAIGHTEN <i>40</i>	1	3360.00		3360.00	235.20	3595.20
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	180.00		180.00	12.60	192.60
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	180.00		180.00	12.60	192.60
BKBU02R	REMOVE/REINSTALL BOOT COVER REVERSE CAMERA FOR REP	1	380.00		380.00	26.60	406.60
BMI01D	REMOVE/REFIT BOOT TRIMS TO ASSIST REPAIR	1	380.00		380.00	26.60	406.60
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS	1	3200.00		3200.00	224.00	3424.00
	Sum Labor				7980.00	558.60	8,538.60
RS-TMP3040L	VPC 4PCS REAR SENSORS <i>amt</i>	1	320.00		320.00	22.40	342.40
66100-T2M-U00ZZ	PANEL COMPRR. ?	1	383.10	25	287.32	20.11	307.43
68500-T2M-Z10ZZ	LID COMPTRUNK <i>bt</i>	1	831.60	25	623.70	43.66	667.36
68610-T2A-000ZZ	HINGE COMPR.TRUNK ?	1	81.30	25	60.97	4.27	65.24
68660-T2A-000ZZ	HINGE COMPL.TRUNK ?	1	81.30	25	60.97	4.27	65.24
74851-T2A-003	LOCK ASSYTRUNK ?	1	87.90	25	65.92	4.61	70.53
74865-T2A-003	WEATHERSTRIPTRUNK LID <i>amt</i>	1	67.70	25	50.77	3.55	54.32
74896-T2A-000	GARNISH ASSYR.TRUNK HINGE ?	1	15.60	25	11.70	0.82	12.52
74897-T2A-000	GARNISH ASSYL.TRUNK HINGE ?	1	15.60	25	11.70	0.82	12.52

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : MSIG INSURANCE (SINGAPORE) PTE
16 RAFFLES QUAY
HONG LEONG BUILDING
SINGAPORE 048581

Registration No : EQ338C

Chassis No : MRHCR1630GP000061

Model : ACCORD 2.0 AT 2016

Owner's Name : CALVIN YIP CHEE KIN

Ins Policy No. :

Date of Accident :

Document No. : SQT17004704 Page 2

Date : 16. Nov 2017

Customer No. : WZM003

Svc Advisor : PATRICK MOK LIP KAY

Engine No : R20Z21600079

Date | Time : 16. Nov 2017 2:43:45 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	GST Amt	Amount incld GST
74890-T3W-J31	GARNISH ASSYRR.LICENSE ?	1	173.70	25	130.27 ✓	9.12	139.39
84630-T2M-Z01ZA	LININGTRUNK LID ?	1	30.90	25	23.17 ✓	1.62	24.79
84640-T2M-Z01ZA	LINING ASSYRR.PANEL ?	1	90.10	25	67.57 ✓	4.73	72.30
75701-T2A-A02	EMBLEMH ✓	1	25.30	25	18.97 ✓	1.33	20.30
75722-T2A-A01	EMBLEMRR.ACCORD ✓	1	18.30	25	13.72 ✓	0.96	14.68
75725-TG2-K00	EMBLEMRR.I-VTEC ✓	1	32.30	25	24.22 ✓	1.70	25.92
84526-T2F-Y00	SPACER ASSYR.TRUNK ✓	1	54.20	25	40.65 ✓	2.85	43.50
33505-T2A-A11	REFLECTOR ASSYR.RR. ✓	1	25.10	25	18.82 ✓	1.32	20.14
71500-T2M-T80ZZ	FACE ASSYRR.BUMPER ✓	1	630.50	25	472.87 ✓	33.10	505.97
71502-T2M-T50	GARNISHRR.BUMPER LOWER ?	1	78.60	25	58.95 ✓	4.13	63.08
71503-T2M-T50	MOULDINGRR.BUMPER ✓	1	206.80	25	155.10 ✓	10.86	165.96
71504-T2F-A50	COVER,R.FINISHER ?	1	92.80	25	69.60 ✓	4.87	74.47
71508-T3V-A00	PROTECTORRR.BUMPER SIDE ?	1	24.10	25	18.07 ✓	1.26	19.33
71530-T2J-H50ZZ	BEAM COMP,RR BPR ?	1	314.60	25	235.95 ✓	16.52	252.47
71593-T2A-A01	SPACERR.RR.BUMPER SIDE ✓	1	11.60	25	8.70 ✓	0.61	9.31
71598-T2A-A01	SPACERL.RR.BUMPER SIDE ✓	1	11.60	25	8.70 ✓	0.61	9.31
33500-T2A-G21	TAILLIGHT ASSYR. ✓	1	591.40	25	443.55 ✓	31.05	474.60
33550-T2A-G21	TAILLIGHT ASSYL. X	1	591.40	25	443.55 ✓	31.05	474.60
34106-SNB-T01	LENSCOMP. ?	1	10.50	25	7.87 ✓	0.55	8.42
34150-T2A-G01	LIGHT ASSYR.LID ✓	1	389.80	25	292.35 ✓	20.46	312.81
34155-T2A-E01	LIGHT ASSYL.LID X	1	389.80	25	292.35 ✓	20.46	312.81
Sum Item					4338.05	303.67	4,641.72

Survey By : Tan Jia 97495749

Date & Time : 24/11/17 @ 1130

Excess : WP

Status : Resurvey before paint

Signature : [Signature]

7-9 days

surv@thekids.com

12,404.67

Total Amount 12,318.05 862.27 13,180.32

Total (Inclusive of GST) 13,180.32

Read the following notes:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Printed on 23/11/2017 11:16:55 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)

Acknowledged by Repairer

Signature:

Date:



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer: WZM003 / MSIG INSURANCE
Chassis No: MRHCR1630GP000061
License No: EQ338C
Mileage: 20268
Engine No: R20Z21600079

Document No: SVO17074602
Printed By: PATRICKMOK
Order Date: 28. November 2017
Order Time: 10:43:29 AM
Service Advisor: PATRICK MOK LIP KAY

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount	Incid GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: CALVIN YIP CHEE KIN OWNER INSURER: LIBERTY INSURANCE ACC DATE: 16/11/2017 SURVEYED BY: L.K.K. (TAUFIKH) DATE: 24/11/2017 REF NO: TP INSURER: MSIG INSURANCE TP VEH: GBC7571H						
66100-T2M-U00ZZ	PANEL COMPR.	1	383.10	25	287.32	20.11	307.43
68500-T2M-Z10ZZ	LID COMPTUNK	1	831.60	25	623.70	43.66	667.36
74865-T2A-003	WEATHERSTRIPTRUNK LID	1	67.70	25	50.77	3.55	54.32
74890-T3W-J31	GARNISH ASSYRR.LICENSE	1	173.70	25	130.27	9.12	139.39
75701-T2A-A02	EMBLEMH	1	25.30	25	18.97	1.33	20.30
75722-T2A-A01	EMBLEMRR.ACCORD	1	18.30	25	13.72	0.96	14.68
75725-TG2-K00	EMBLEMRR.I-VTEC	1	32.30	25	24.22	1.70	25.92
84526-T2F-Y00	SPACER ASSYR.TRUNK	1	54.20	25	40.65	2.85	43.50
33505-T2A-A11	REFLECTOR ASSYR.RR.	1	25.10	25	18.82	1.32	20.14
71500-T2M-T80ZZ	FACE ASSYR.BUMPER	1	630.50	25	472.87	33.10	505.97
71503-T2M-T50	MOULDINGRR.BUMPER	1	208.80	25	155.10	10.86	165.96
71504-T2F-A50	COVER,R.FINISHER	1	92.80	25	69.60	4.87	74.47
71593-T2A-A01	SPACERR.RR.BUMPER SIDE	1	11.60	25	8.70	0.61	9.31
71598-T2A-A01	SPACERL.RR.BUMPER SIDE	1	11.60	25	8.70	0.61	9.31
33500-T2A-G21	TAILLIGHT ASSYR.	1	591.40	25	443.55	31.05	474.60
34150-T2A-G01	LIGHT ASSYR.LID	1	389.80	25	292.35	20.46	312.81
91505-TM8-003	CLIPBUMPER	4	2.00	25	6.00	0.42	6.42
63320-T2F-A00ZZ	GUTTER COMPR.RR.	1	104.90	25	78.67	5.51	84.18
90650-T2A-003	CLIPRR.COMBINATION LIGHT	1	2.60	25	1.95	0.14	2.09
	SUM PARTS:				2,745.93	192.23	2,938.16
BOSUN	0701 SUNDRIES	1	50.00		50.00	3.50	53.50
BOJSE	1374 SEALANT FOR BOOT COVER	1	100.00		100.00	7.00	107.00
BOJSE	1374 SEALANT FOR REAR END PANEL	1	100.00		100.00	7.00	107.00
BKRP02M	1374 CUT OFF & RENEW RR PANEL. STRAIGHTEN ALIGN RR FLOOR PAN & RENEW DAMAGE PARTS.	1	2,520.00		2,520.00	176.40	2,696.40
BML02I	1374 INSPECT RR LIGHTING MECHANISMS. PERFORM WATER TEST.(N)	1	180.00		180.00	12.60	192.60
BA02R	1374 REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	180.00		180.00	12.60	192.60
BKBU02R	1374 REMOVE/REINSTALL BOOT COVER REVERSE CAMERA FOR REP	1	380.00		380.00	26.60	406.60

9 REPAIR DAYS

(A) all ✓
(A) all ✓
(A) all ✓

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651, Tel: +65 6841 3883 Fax +65 6741 5022

255 Alexandra Road Singapore 159937, Tel: +65 6471 5458 Fax +65 6471 5460

SERVICE PRE-INVOICE

GST Reg No.: M200050223

Company Ref. No.: S60FC1360G

Customer: WZM003 / MSIG INSURANCE
Chassis No: MRHCR1630GP000061
License No: EQ338C
Mileage: 20268
Engine No: R20Z21600079

Document No: SVO17074602
Printed By: PATRICKMOK
Order Date: 28. November 2017
Order Time: 10:43:29 AM
Service Advisor: PATRICK MOK LIP KAY

BMI01D	1374	1	380.00	380.00	26.60	406.60
	REMOVE/REFIT BOOT TRIMS TO ASSIST					
	REPAIR					
BP06R	1610	1	2,700.00	2,700.00	189.00	2,889.00
	SPRAY PAINTING ON REPAIRED OR					
	REPLACED AREAS					
			SUM LABOUR:	6,590.00	461.30	7,051.30
			TOTAL SGD	9,335.93	653.53	9,989.46
Total Payable (SGD)						9,989.46

GST Amount is calculated from individual line(s)

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Thursday, 1 February 2018 1:23 PM
To: 'Patrick Mok'; SUR
Subject: RE: REQUEST TO CONFIRM FINAL BILL FOR EQ338C

Dear Patrick,

Confirmed finalize amount \$9335.93 before GST

No of days: 9 days

Final invoice and all supporting documents sent to MSIG

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Patrick Mok [mailto:patrickmok@honda.com.sg]
Sent: Wednesday, 31 January 2018 5:32 PM
To: SUR <sur@lkkauto.com>
Subject: REQUEST TO CONFIRM FINAL BILL FOR EQ338C

Hi Taufikh and Team,

Kindly refer to the attached documents and photos and request to confirm final cost of repair and the number of repair days recommended.

Looking forward to your finalization soonest.

Thank you for your time.

Warm regards,

Patrick Mok

Bodyshop Service Advisor

Kah Motor Co. Sdn. Bhd.

Mobile : 82886302



...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	16 Nov 2017		23 Nov 2017 17:11 Edit Adj Rpt	S\$9,335.93 Edit Estimates	S\$9,335.93 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	GOLDBELL LEASING PTE LTD, Co. Reg. No.: 199001196N								
Main Claimant:	CALVIN YIP CHEE KIN, ID: S7216372I								
Vehicle Reg. No.:	EQ338C	Date of Loss:	16/11/2017 08:00 - :59						
Claim Type:	TP / 537105	Policy/Cover Note No.:	29004183MKF (Third Party Only) Coverage: 20/08/2017 - 31/08/2018						
Vehicle Reg. No. (Insured):	GBC7571H	Policy No. (Claimant):							
		Excess:	S\$5,000.00						
Repairer:	- Not Applicable - (-)								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Lionel Tan Tian Pei - 6643 1307]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 23/12/2017]								
Driver/Custodian (Insured):	TAN KAI CHIN (), NRIC: G6643485R, Tel: +6584901690								
Adj Asp. Remarks:	PLS CONTACT Patrick Mok Motor Claims Advisor Kah Motor Co. Sdn. Bhd. Mobile : 82886302 APPT AT 11.30AM ON 24.11.17.OWNER BE AWAITING								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*EQ338C (537105)
[GBC7571H]
TP
CALVIN YIP CHEE KIN
Nov 16 2017 8:00AM
[GOLDBELL LEASING PTE LTD]

Upload Documents		Upload Photos	Compose New Letter	View View in Browser	
Assessment Reports				1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print	
1	23/11/17 16:30	Accident Statement From: SC - Reg. No: GBC7571H, Claimant: GOLDBELL LEASING PTE LTD	 Load HTM		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	27/11/17 14:31	Adjuster Immediate Advice	 Load HTM		
Photos/Images				3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	27/11/17 11:30	General View	 Load JPG	☒	
2	27/11/17 11:30	General View	 Load JPG	☒	
3	27/11/17 11:30	General View	 Load JPG	☒	
4	27/11/17 11:30	General View	 Load JPG	☒	
5	27/11/17 11:30	General View	 Load JPG	☒	
6	27/11/17 11:30	General View	 Load JPG	☒	
7	27/11/17 11:30	General View	 Load JPG	☒	
8	27/11/17 11:30	General View	 Load JPG	☒	
9	27/11/17 11:30	General View	 Load JPG	☒	
10	27/11/17 11:30	General View	 Load JPG	☒	
11	27/11/17 11:30	General View	 Load JPG	☒	
12	27/11/17 11:30	General View	 Load JPG	☒	
13	27/11/17 11:30	General View	 Load JPG	☒	
14	27/11/17 11:30	General View	 Load JPG	☒	
15	27/11/17 11:30	General View	 Load JPG	☒	
16	27/11/17 11:30	General View	 Load JPG	☒	
17	27/11/17 11:30	General View	 Load JPG	☒	
18	27/11/17 11:30	General View	 Load JPG	☒	
19	27/11/17 11:30	General View	 Load JPG	☒	
20	27/11/17 11:30	General View	 Load JPG	☒	
21	27/11/17 11:30	General View	 Load JPG	☒	
22	27/11/17 11:30	General View	 Load JPG	☒	
23	27/11/17 11:30	General View	 Load JPG	☒	
24	27/11/17 11:30	General View	 Load JPG	☒	
25	27/11/17 11:30	General View	 Load JPG	☒	
26	27/11/17 11:30	General View	 Load JPG	☒	
27	27/11/17 11:30	General View	 Load JPG	☒	
28	27/11/17 11:30	General View	 Load JPG	☒	
29	27/11/17 11:30	General View	 Load JPG	☒	
30	27/11/17 11:30	General View	 Load JPG	☒	

31	27/11/17 11:30	General View	1	Load JPG	✓
32	27/11/17 11:30	General View	1	Load JPG	✓
33	01/02/18 12:59	Reinspection Photo	1	Load JPG	✓
34	01/02/18 12:59	Reinspection Photo	1	Load JPG	✓
35	01/02/18 12:59	Reinspection Photo	1	Load JPG	✓
36	01/02/18 12:59	Reinspection Photo	1	Load JPG	✓
37	01/02/18 12:59	Reinspection Photo	1	Load JPG	✓
38	01/02/18 12:59	Reinspection Photo	1	Load JPG	✓
39	01/02/18 12:59	Reinspection Photo	1	Load JPG	✓
40	01/02/18 12:59	Reinspection Photo	1	Load JPG	✓
41	01/02/18 12:59	Reinspection Photo	1	Load JPG	✓
42	01/02/18 12:59	Reinspection Photo	1	Load JPG	✓
43	01/02/18 12:59	Reinspection Photo	1	Load JPG	✓
44	01/02/18 12:59	Reinspection Photo	1	Load JPG	✓
Documentation					
			1 per page		✓
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	23/11/17 16:28	TPD EQ338C GIA REPORT.	1	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) 				
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.				

LKK Auto Consultants Pte Ltd (Co.Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG17022446/T1VBQ2

Date: 08/02/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 29004183MKF

Claimant Vehicle No : EQ338C

Insured Vehicle No : GBC7571H

Date of Loss: 16/11/2017

Nature of Claim: TP

Claim No: 537105

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: EQ338C

Make & Model: HONDA ACCORD, 2.0 VTIS 5AT (A)

Engine No: R20Z21600079

Reg. Date: 12/12/2016 (Man. Year: 2016)

Chassis No: MRHCR1630GP000061

Colour: Silver

Odometer: 19973 km

Engine Capacity: 1997 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/50 R17

Rear Tyre Size: 225/50 R17

Front Left Side: Michelin 6 mm

Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,624.67	2,895.93	1,728.74	37.38
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,780.00	6,440.00	1,340.00	17.22
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	12,404.67	9,335.93	3,068.74	24.74
+ GST 7.00/7.00% (S\$)	868.33	653.52	214.81	24.74
Nett Amount (S\$)	13,273.00	9,989.45	3,283.55	24.74

INSPECTION

Date of Assignment: 23/11/2017

Date Inspected: 24/11/2017

Inspected At:

Estimated Period of Repair: 9.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 08 Feb 2018)
Parts: 143	HONDA ACCORD 2.0 VTIS 5AT (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for EQ338C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	100.00 FS	*50.00 FS
2	1		*SEALANT FOR BOOT COVER	Necessary	100.00 FS	*100.00 FS
3	4		*REAR SENSORS	Not Necessary	320.00 FS	*- FS
4	1		*PANEL COPRP	Bent	287.32 FS	*287.32 FS
5	1		*LID COMPTRUNK	Bent	623.70 FS	*623.70 FS
6	1		*HINGE COMPR.TRUNK	Not Necessary	60.97 FS	*- FS
7	1		*HINGE COMPL .TRUNK	Not Necessary	60.97 FS	*- FS
8	1		*LOCK ASSYTRUNK	Not Necessary	65.92 FS	*- FS
9	1		*WEATHERSTRIP TRUNK LID	Necessary	50.77 FS	*50.77 FS
10	1		*GARNISH ASSYR,TRUNK HINGE	Not Necessary	11.70 FS	*- FS
11	1		*GARNISH ASSYLTRUNK HINGE	Not Necessary	11.70 FS	*- FS
12	1		*GARNISH ASSYRR.LICENSE	Deformed	130.27 FS	*130.27 FS
13	1		*LINING TRUNK LID	Not Necessary	23.17 FS	*- FS
14	1		*LINING ASSYRR.PANEL	Not Necessary	67.57 FS	*- FS
15	1		*EMBLEMH	Necessary	18.97 FS	*18.97 FS
16	1		*EMBLEMRR.ACCORD	Necessary	13.72 FS	*13.72 FS
17	1		*EMBLEMRR.I-VTEC	Necessary	24.22 FS	*24.22 FS
18	1		*SPACER ASSYR.TRUNK	Necessary	40.65 FS	*40.65 FS
19	1		*REFLECTOR ASSYR.RR	Cracked	18.82 FS	*18.82 FS
20	1		*FACE ASSYRR.BUMPER	Deformed	472.87 FS	*472.87 FS
21	1		*GARNISHRR.BUMPER LOWER	Not Necessary	58.95 FS	*- FS
22	1		*MOULDINGRR.BUMPER	Cut	155.10 FS	*155.10 FS
23	1		*COVER,R.FINISHER	Deformed	69.60 FS	*69.60 FS
24	1		*PROTECTORRR.BUMPER SIDE	Not Necessary	18.07 FS	*- FS
25	1		*BEAM COMP.RR BPR	Not Necessary	235.95 FS	*- FS
26	1		*SPACERR.RR.BUMPER SIDE	Necessary	8.70 FS	*8.70 FS
27	1		*SPACERL.RR.BUMPER SIDE	Necessary	8.70 FS	*8.70 FS
28	1		*TAILLIGHT ASSYR	Cracked	443.55 FS	*443.55 FS
29	1		*TAILLIGHT ASSYL	Not Necessary	443.55 FS	*- FS
30	1		*LENSCOMP	Not Necessary	7.87 FS	*- FS
31	1		*LIGHT ASSYR,LID	Cracked	292.35 FS	*292.35 FS
32	1		*LIGHT ASSYL.LID	Not Necessary	292.35 FS	*- FS
33	4		*CLIPBUMPER	Necessary	6.00 FS	*6.00 FS
34	1		*GUTTER COMPR.RR	Necessary	78.67 FS	*78.67 FS
35	1		*CLIPRR.COMBINATION LIGHT	Necessary	1.95 FS	*1.95 FS

F=Franchise part. S=SpcNert.

Total Parts (\$\$)	4,624.67	2,895.93
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	SEALANT FOR REAR END PANEL	New	100.00	100.00
2	CUT OFF & RENEW RR PANEL.STRAIGHTEN	New	3,360.00	2,520.00
3	INSPECT RR LIGHTING MECHANISMS .PERFORM WATER	New	180.00	180.00
4	REMOVE & RENEW REVERSE SENSORS	New	180.00	180.00
5	REMOVE/REINSTALL BOOT COVER REVERSE CAMERA FOR REP	New	380.00	380.00
6	REMOVE/REFIT BOOT TRIMS TO ASSIST REPAIR	New	380.00	380.00
7	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS	New	3,200.00	2,700.00
Gross Labour Cost (\$\$)			7,780.00	6,440.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >