

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/1125/2017/JT
Date	:	13-Nov-17

Vehicle not workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Ms. Chin Pek Kwan
Address	:	5500D Marine Parade Road #14-15 Singapore 449287
Telephone	:	HP +65 9322 6255 (Mr. Lim)
Type of Claim	:	Own Damage Claims
Policy No.	:	2100304713-05000
Vehicle No	:	SKG 368 Y
Model Code	:	Audi A5 SB 2.0 TFSI qu
Model / Year	:	Jun-12
Engine No	:	CDN 276438
Chassis No	:	WAUZZZ8T7CA059039
Mileage	:	-
Date In	:	-
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	11-Nov-17
Place of Accident	:	Old Airport Road Carpark

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKG 368 Y.

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor and headlight washer assv.	S/N \$ 360.00	✓
2	To dismantle and renew front bumper and RHS front fender. Re-organize front crash management components. Reinstall all parts removed.	\$ 1,800.00	1000
3	To respray front bumper and RHS front fender.	\$ 1,500.00	1100
4	To renew RHS front rim and carry out wheel alignment.	S/N \$ 280.00	X
5	To carry out diagnostic checks.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 4,132.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKG 368 Y.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER AIR GUIDE GRILLE <i>new</i>	\$ 189.00	+
2	FRONT FENDER - RHS <i>Painted</i>	\$ 900.00	✓
3	FRONT FENDER BRACKET - RHS ?	\$ 49.00	?
4	FRONT <i>FRONT</i> FENDER BRACKET - RHS ?	\$ 49.00	?
5	FRONT BUMPER BRACE - RHS <i>new ?</i>	\$ 102.00	?
6	FRONT WHEEL HOUSING LINER - RHS <i>new</i>	\$ 157.00	+
7	WHEEL HOUSING LINER ATTACHMENT PARTS <i>new</i>	\$ 38.00	+
8	FRONT ALUMINIUM RIM - RHS <i>new</i>	\$ 892.00	+
9	FRONT BUMPER <i>Repair</i>	\$ 2,199.00	+
10	FRONT BUMPER GUIDE PIECE <i>new</i>	\$ 36.00	+
11	SUNDRIES ?	\$ 300.00	?
TOTAL SPARE PARTS :		\$ 4,911.00	
TOTAL LABOUR CHARGES :		\$ 4,132.00	
GRAND TOTAL :		\$ 9,043.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Lij
Surveyed Date : 24/11/17
Authorised Date :
Excess Cost :
Liability :
Remarks : Authorised Repairs, 04 Days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant