

LIAN HER MOTORS

BLK 5038 ANG MO KIO IND. PARK 2 #01-405
SINGAPORE 569541
Tel : 82990599 Fax : 64816131
Email : lhcar@hotmail.sg

*Not Notified
Repairing B4 panel
4 days*

H.L. CAR RENTAL PTE LTD

BLK 5038 ANG MO KIO IND. PARK 2 #01-405
SINGAPORE 569541

VEHICLE NO. SLT2349J
CHASSIS NO. ZYX102074705
MAKE. : TOYOTA C-HR
YEAR. : 2017

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

QTY	Description	Unit Price	Amount
-----	-------------	------------	--------

ESTIMATE COST OF REPAIR

1	Front Bonnet assy			
8	Front Bonnet insulation Clip		\$ 1,260.40	✓
3	Front Bonnet o/s garnish clip	nn	\$ 12.90	
2	Front Bonnet rubber tubing clip	nn	\$ 12.90	\$ 38.70 X
1	Front Fender o/s	nn	\$ 12.90	\$ 25.80 X
1	Front Fender Lower Shield o/s	nn	\$ 819.30	✓
6	Front Fender Lower Shield Clip o/s	nn	\$ 272.60	X
3	Front Fender protector clip o/s	nn	\$ 12.90	\$ 77.40 X
1	Front Fender Emblem (Hybrid)	nn	\$ 12.90	\$ 38.70
1	Front Wheelarch garnish o/s	nn	\$ 138.00	✓
8	Front Wheelarch garnish clip	nn	\$ 173.00	✓
1	Front Wheelarch garnish lower retainer	nn	\$ 12.90	\$ 103.20
3	Front wheelarch garnish lower retainer clip	nn	\$ 113.80	X
			\$ 38.70	X

TOTAL : \$ 3,202.80
-25% \$ 800.70
\$ 2,402.10

LABOUR

To renew & align abovementioned damaged parts
To putty and spray paint
To check wirings and focus headlamps
To apply underseal on the affected areas

400d
\$ 1,000.00
\$ 1,000.00 *440d*
\$ 120.00 *15L*
\$ 150.00 *30d*

GRAND TOTAL : \$ 4,672.10