

M/S INDIA INT'L INS PTE LTD
64 CECIL STREET
#05-01 IOB BUILDING
SINGAPORE 049711

ESTIMATE

DATE : 24/11/2017
ACCT DATE : 24/11/2017
REF NO. : VFIX-TP20170374
POLICY NO. :

Attention: Motor Claim Department

RE : VEHICLE NO.SKN3266B TOYOTA ALPHARD

DESCRIPTION

		AMOUNT S\$
1	1 REAR BUMPER	1,339.50
2	1 REAR BUMPER SIDE RETAINER	72.60
3	1 REAR FENDER COWLING <i>buy under cover</i>	102.00
4	1 REAR BUMPER REFLECTOR	70.50
		1,584.60
	LESS 25%	396.15
		\$ 1,188.45

DESCRIPTION (SPECIAL NETT)

		AMOUNT S\$
1	1 REVERSE SENSOR <i>371.46 25%</i>	390.00 SN
2	5 REAR BUMPER CLIP	30.00 SN
		\$ 420.00

LABOUR & MISCELLANEOUS:

		AMOUNT S\$
1	To remove/replace damaged parts with all necessary components/ attachments apply hot-works where necessary repair/resharpe dented panel in accordance to factory spectification, replace new parts align into position refit all necessary components / attachments	800.00
2	To spray paint replaced/repaired body panels inclusive of preparatory works and painting materials	1,000.00
3	To install all reverse sensor and check function	100.00
		\$ 1,900.00

GRAND TOTAL : \$ 3,508.45

SINGAPORE DOLLARS: **THREE THOUSAND FIVE HUNDRED EIGHT & CENTS FORTY FIVE**

Vfix Auto Service Pte Ltd



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company
- Parts prices are subject to confirmation
- To display damaged part(s) during resurvey
- To resurvey before/after spray painting

Acknowledged by Repairer

Signature: _____

Date: _____

LKK Auto Consultants hence notify the Repairer of the following:

Handwritten calculations:
P-1885-58
252
1414.17
- 30
1414.17 - 730
= 684.17