

# Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761  
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg  
GST:201001158E RCB NO:201001158E

M/S : AXA INSURANCE (S) PTE LTD

8 SHENTON WAY  
#27-02 AXA TOWER  
SINGAPORE 068811

TEL: 63387288

FAX: 68804739

ATTN: Motor Claim Department

WS Ref: TP/AXA/AMK

Claim Type: Third Party

Accident Date: 23/11/2017

TP Veh Reg No: SLF2888T

Estimate No: ES1791340/AMK

Date: 24 Nov 2017

Policy No: 5074972692-02

Veh Reg No: SGA8885Y

Make/Model: NISSAN TEANA 2.5CVT

Chassis No: JN1BBUJ32Z0000623

Engine No: VQ25383918A

Reg. Date: 25/09/2008

## Estimate Repair Cost to Vehicle No :SGA8885Y

PAGE:1/2

| Description                              | U/Price  | Quantity | List Price | Amount   |
|------------------------------------------|----------|----------|------------|----------|
|                                          |          |          | SS         | SS       |
| <b>List Price</b>                        |          |          |            |          |
| 1 REAR BUMPER                            | 804.60   | 1 PC     | 804.60     | ✓        |
| 2 REAR BUMPER SPONGE                     | 133.80   | 1 PC     | 133.80     | ✓        |
| 3 REAR BUMPER REINFORCEMENT              | 360.30   | 1 PC     | 360.30     | ✓        |
| 4 REAR BUMPER REINFORCEMENT BRACKET      | 91.70    | 2 PC     | 183.40     | ✓        |
| 5 REAR BUMPER CHROME MOULDING            | 116.70   | 2 PC     | 233.40     | ✓        |
| 6 REAR BOOT                              | 971.60   | 1 PC     | 971.60     | ✓        |
| 7 REAR BOOT UPPER CHROME                 | 351.00   | 1 PC     | 351.00     | ✓        |
| 8 REAR BOOT INSULATOR                    | 179.00   | 1 PC     | 179.00     | ✓        |
| 9 TAILLAMP PANEL                         | 141.20   | 2 PC     | 282.40     | ✓        |
| 10 REAR FENDER                           | 1,282.40 | 2 PC     | 2,564.80   | ✓        |
| 11 REAR FENDER INNER TRIM                | 233.60   | 2 PC     | 467.20     | ✓        |
| 12 REAR FENDER QUARTER GLASS with Moly   | 971.10   | 2 PC     | 1,942.20   | ✓        |
| 13 REAR END PANEL                        | 560.60   | 1 PC     | 560.60     | ✓        |
| 14 REAR END PANEL INNER TOP GARNISH      | 90.60    | 1 PC     | 90.60      | ✓        |
| 15 REAR SPARE TYRE PANEL                 | 998.10   | 1 PC     | 998.10     | X        |
| 16 REAR SPARE TYRE PANEL INNER TRIM      | 617.90   | 1 PC     | 617.90     | ✓        |
| 17 REAR SPARE TYRE CENTRE SPONGE         | 439.40   | 1 PC     | 439.40     | ✓        |
| 18 REAR SPARE TYRE SIDE SPONGE           | 109.90   | 2 PC     | 219.80     | X        |
|                                          |          |          | 11,400.10  |          |
|                                          |          | Less 30% | 3,420.03   | 7,980.07 |
| <b>Net Price</b>                         |          |          |            |          |
| 19 REAR BUMPER SIDE RETAINER             | 33.20    | 2 PC     | 66.40      | ✓        |
| 20 REAR BUMPER CLIP                      | 4.40     | 5 PC     | 22.00      | ✓        |
| 21 REAR BOOT INNER LOCK                  | 112.50   | 1 PC     | 112.50     | ✓        |
| 22 REAR BOOT INNER RUBBER                | 122.20   | 1 PC     | 122.20     | 50% ✓    |
| 23 REAR BOOT HINGE                       | 171.20   | 2 PC     | 342.40     | ✓        |
| 24 REAR BOOT STRUT                       | 183.20   | 2 PC     | 366.40     | ✓        |
| 25 REAR BOOT LOGO                        | 40.50    | 1 PC     | 40.50      | ✓        |
| 26 REAR BOOT EMBLEM 'TEANA'              | 84.00    | 1 PC     | 84.00      | ✓        |
| 27 REAR BOOT EMBLEM '250XV' & 'V6'       | 64.60    | 1 PC     | 64.60      | ✓        |
| 28 REAR BOOT LOWER CHROME                | 220.00   | 1 PC     | 220.00     | ✓        |
| 29 TAILLAMP                              | 518.20   | 2 PC     | 1,036.40   | ✓        |
| 30 TAILLAMP CLIP                         | 7.40     | 2 PC     | 14.80      | ✓        |
| 31 TAILLAMP GARNISH                      | 36.00    | 2 PC     | 72.00      | ✓        |
| 32 REAR END PANEL INNER TOP GARNISH CLIP | 6.40     | 2 PC     | 12.80      | ✓        |
| 33 REAR END PANEL BUZZER SENSOR          | 74.10    | 1 PC     | 74.10      | ✓        |
| 34 REAR LH EXHAUST MUFFLER               | 591.10   | 1 PC     | 591.10     | ✓        |
|                                          |          |          | 3,242.20   |          |
|                                          |          | Less 10% | 324.22     | 2,917.98 |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

# Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761  
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg  
 GST:201001158E RCB NO:201001158E

M/S : AXA INSURANCE (S) PTE LTD  
 8 SHENTON WAY  
 #27-02 AXA TOWER  
 SINGAPORE 068811

TEL: 63387288 FAX: 68804739  
 ATTN: Motor Claim Department  
 WS Ref: TP/AXA/AMK  
 Claim Type: Third Party  
 Accident Date: 23/11/2017  
 TP Veh Reg No: SLF2888T

Estimate No: ES1791340/AMK  
 Date: 24 Nov 2017  
 Policy No: 5074972692-02  
 Veh Reg No: SGA8885Y  
 Make/Model: NISSAN TEANA 2.5CVT  
 Chassis No: JN1BBUJ32Z0000623  
 Engine No: VQ25383918A  
 Reg. Date: 25/09/2008

## Estimate Repair Cost to Vehicle No :SGA8885Y

PAGE:2/2

| Description                                                                                                                                                                                              | U/Price  | Quantity | List Price<br>S\$    | Amount<br>S\$ |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------|----------|----------------------|---------------|
| <b>Special Net</b>                                                                                                                                                                                       |          |          |                      |               |
| 35 REAR NUMBER PLATE                                                                                                                                                                                     | 35.00    | 1 PC     | 35.00                | ✓             |
| 36 REVERSE SENSOR                                                                                                                                                                                        | 200.00   | 1 SET    | 200.00               | ✓             |
| 37 REAR FENDER QUARTER GLASS SEALANT                                                                                                                                                                     | 40.00    | 1 PC     | 40.00                | ✓             |
| 38 REAR WINDSCREEN GLASS SEALANT                                                                                                                                                                         | 40.00    | 1 PC     | 40.00                | ✓             |
| 39 REAR SPARE TYRE PANEL TOP COAT                                                                                                                                                                        | 100.00   | 1 PC     | 100.00               | X             |
| 40 REVERSE CAMERA                                                                                                                                                                                        | 280.00   | 1 PC     | 280.00               | X             |
|                                                                                                                                                                                                          |          |          | 695.00               | 695.00        |
| <b>Labour</b>                                                                                                                                                                                            |          |          |                      |               |
| 41 TOWING                                                                                                                                                                                                | 60.00    | 1 LA     | 60.00                | ✓             |
| 42 REMOVE AND REFIX REAR WINDSCREEN GLASS                                                                                                                                                                | 120.00   | 1 LA     | 120.00               | ✓             |
| 43 REMOVE & REFIX REAR BOTH FENDER QUARTER GLASSES                                                                                                                                                       | 120.00   | 1 LA     | 120.00               | 80            |
| 44 REMOVE & REFIX REAR BUMPER,REAR BOOT & ATTACHMENTS,TAILLAMPS;TO CUT,WELD & RENEW REAR BOTH FENDERS,REAR END PANEL;KNOCKING & REPAIR REAR SPARE TYRE PANEL,REAR CHASSIS FRAMES;JACK & REALIGN THE SAME | 1,700.00 | 1 LA     | 1,700.00             | 1600          |
| 45 PUTTY & RESPRAY REAR BUMPER,REAR BOOT,BOTH FENDERS,REAR END PANEL,REAR SPARE TYRE PANEL,CHASSIS FRAMES & ALL AFFECTED AREAS                                                                           | 1,400.00 | 1 LA     | 1,400.00             | 1300          |
| 46 REMOVE & REFIX REAR SEAT,CARPET TO FACILITATE REPAIR                                                                                                                                                  | 120.00   | 1 LA     | 120.00               | ✓             |
| 47 REMOVE & REFIX REVERSE CAMERA,RESET & REPOSITION                                                                                                                                                      | 80.00    | 1 PC     | 80.00                | ✓             |
| 48 REMOVE & REFIX REAR EXHAUST MUFFLERS & REALIGN THE SAME                                                                                                                                               | 100.00   | 1 LA     | 100.00               | 60            |
| 49 TO MOUNT ON CAR-O-LINER,JACK & STRAIGHTEN                                                                                                                                                             | 250.00   | 1 LA     | 250.00               | ✓             |
| 50 RUSTPROOFING                                                                                                                                                                                          | 180.00   | 1 LA     | 180.00               | 120           |
|                                                                                                                                                                                                          |          |          | 4,130.00             | 4,130.00      |
|                                                                                                                                                                                                          |          |          | Total                | S\$ 15,723.05 |
|                                                                                                                                                                                                          |          |          | Add GST @ 7%         | 1,100.61      |
|                                                                                                                                                                                                          |          |          | Total Amount Payable | S\$ 16,823.66 |

VEHICLE LYING AT :  
 NO.10 ANG MO KIO INDUSTRIAL PARK 2A  
 #01-04 AMK AUTOPOINT  
 SINGAPORE 568047  
 TEL : 64812001

For Cheng Hoe Motor Pte Ltd

*Dorlyn Li*

AUTHORISED SIGNATURE