



TRANS EUROKARS PTE LTD
NO:5 UBI CLOSE, SINGAPORE 408605
ESTIMATE OF REPAIRS



QBE INSURANCE (SINGAPORE) PTE LTD 1 RAFFLES QUAY #29-10 SOUTH TOWER SINGAPORE 048583 ATTN. : MOTOR CLAIMS FAX :		NAME : Mr Ng Ching Fah ADDRESS : 542 SERANGOON NORTH AVE 4 #07-03 Singapore 550542 TEL : 97396094		WIP : 44215 EXCESS : DATE: 11-Nov-17	
VEH NO :	SGA6166C	DATE IN :		CONTACT PERSON :	JESS 6395 7874
CHASSIS NO :	JM6KE1032G0345043	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM
MODEL :	MAZDA CX5 2.5L	DATE REG.:	17-Nov-15	POLICY NO. :	
NATURE OF WORKS					
Parts Description					
NO	QTY	REVISED	PRICES		
1	REAR BUMPER <i>re</i>	1	MKDY3-50-22XFBB		\$ 1,218.00
2	SENSOR,ULTRASONIC (CENTER) ?	2	MGMK6-67-UC1 E4		\$ 344.40
3	SENSOR,ULTRASONIC (SIDE) <i>X NN</i>	2	MKD49-67-UC1		\$ 385.80
4	RETAINER CENTER, SENSOR ?	2	MKD45-67-UC5AE4		\$ 34.60
5	RETAINER SIDE, SENSOR <i>X NN</i>	2	MKD49-67-UC5A		\$ 19.40
6	TAPE PROTECTOR, SENSOR <i>re</i>	5	MG001-67-061		\$ 37.00
7	CORD,SHORT (SENSOR) ?	1	MKA3B-67-290		\$ 127.80
8	RETAINER(LHS), REAR BUMPER <i>X NN</i>	1	MKD53-50-2J1A		\$ 32.40
9	RETAINER(RHS), REAR BUMPER <i>X NN</i>	1	MKD53-50-2H1A		\$ 32.40
10	BRACKET CENTER, REAR BUMPER <i>re</i>	1	MKD53-50-251		\$ 5.10
11	REFLECTOR LHS <i>X NN</i>	1	MKD31-51-5M0		\$ 101.20
12	REFLECTOR RHS <i>X NN</i>	1	MKD31-51-5L0		\$ 101.20
13	COVER(LHS), TOWING <i>re</i>	1	MKD53-50-EL1A		\$ 2.50
14	COVER(RHS), TOWING <i>re</i>	1	MKD53-50-EK1A		\$ 2.50
15	REAR REINFORCEMENT ?	1	MKD53-50-260D		\$ 495.20
16	STAY, REAR REINFORCEMENT <i>re</i>	2	MKD53-52-B22A		\$ 32.80
17	TAPE PROTECTOR, REAR BUMPER <i>re</i>	2	MG043-62-864A		\$ 6.60
18	FASTENER, REAR BUMPER <i>re</i>	2	MB45A-56-146A		\$ 5.60
19	CLIP, REAR BUMPER <i>re</i>	2	MC274-50-133		\$ 7.00
20	RIVET, REAR BUMPER <i>re</i>	4	ML33X-13-209		\$ 11.20
21	GROMMET, REAR BUMPER <i>re</i>	6	MBHN1-50-0Z1A		\$ 15.00
22	PANEL,REAR END ?	1	MK0Y0-70-75Z		\$ 473.90
23	TAILGATE <i>BUC</i>	1	MKDZ1-62-02XD		\$ 1,321.40
24	TRIM LOWER, TAILGATE ?	1	MKA0G-68-960		\$ 267.10
25	WEATHERSTRIP, TAILGATE ?	1	MKD53-62-761A		\$ 174.50
26	VALVE ONEWAY, TAILGATE <i>X NN</i>	2	MGHP9-58-867		\$ 22.80
27	LOCK, TAILGATE ?	1	MG33M-62-310B		\$ 256.40
28	TAPE PROTECTOR, TAILGATE <i>re</i>	2	MBR5S-56-994		\$ 14.40
29	TAPE PROTECTOR, TAILGATE <i>re</i>	2	MG043-62-864A		\$ 6.60
30	SWITCH,OPEN ?	1	MKD53-62-4B0A		\$ 94.80

31	GARNISH, TAILGATE / <i>es</i>	1	MKD46-50-810AE4		\$ 363.20
32	MAZDA, EMBLEM /	1	MKD53-51-721		\$ 45.30
33	SKYACTIV, EMBLEM /	1	MKD53-51-771		\$ 71.60
34	FASTENER, REAR WINDSCREEN / <i>MCC</i>	2	MC513-50-896		\$ 15.60
35	FASTENER, REAR WINDSCREEN /	2	MD204-50-896A		\$ 5.20
36	SPACER, REAR WINDSCREEN /	3	MGJ6A-50-897		\$ 36.30
37	PIN STUD, REAR WINDSCREEN /	1	MGR4B-63-938		\$ 11.40
38	PROTECTOR, REAR SPOILER /	2	MKD53-51-954		\$ 6.00
39	PROTECTOR, REAR SPOILER /	2	MKD54-51-954		\$ 5.00
40	PROTECTOR, REAR SPOILER /	3	MD01G-51-979		\$ 37.80
41	PROTECTOR, REAR SPOILER /	2	MKD53-51-979A		\$ 5.00
42	PROTECTOR, REAR SPOILER /	2	MKD45-51-979		\$ 5.00
43	PROTECTOR, REAR SPOILER /	4	MBBN9-51-972		\$ 9.20
44	CLIP, REAR SPOILER /	1	MKD53-51-0B6B		\$ 2.50
45	CLIP, REAR SPOILER /	2	MKDY3-51-0A6B		\$ 21.60
46	FASTENER, REAR SPOILER /	3	MEG21-51-146		\$ 17.70
47	CLIP, REAR SPOILER /	2	MEG21-51-SJ3		\$ 10.80
48	ANTENNA, KEYLESS ?	1	MKD47-67-6NXA		\$ 105.80
49	CLIP, ANTENNA ?	1	MKD45-67-6NYA		\$ 2.50
50	GASKET(LHS), TAILLAMP /	1	MKD54-51-163A		\$ 35.20
51	GASKET(RHS), TAILLAMP /	1	MKD54-51-153A		\$ 35.20
52	FASTENER, TAILLAMP / <i>MCC</i>	2	MKD53-51-146B		\$ 7.80
53	GROMMET, TAILLAMP /	2	MGJ6A-51-14Y		\$ 29.80
54	GASKET(LHS), TAILGATE LAMP /	1	MKD53-51-3J8A		\$ 43.70
55	GASKET(RHS), TAILGATE LAMP /	1	MKD53-51-3H8A		\$ 43.70
56	LAMP, LICENSE X	2	MGJ6A-51-270C		\$ 90.60
57	CAMERA-BACK MONITOR X <i>NN</i>	1	MK015-67-RC0A		\$ 790.50
<i>lamp Boot lid - CCA</i>					
TOTAL PARTS					\$ 7,503.60
LESS 10%					\$ 750.36
TOTAL PARTS COST					\$ 6,753.24

Labour Description				
1	MZ-BR-REAR06	TO REPLACE REAR BUMPER, REAR REINFORCEMENT, REAR END PANEL AND TAILGATE.REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.	<i>1890</i>	\$ 3,780.00
2	MZ-SP-SREAR6	TO RESPRAY REAR BUMPER, REAR REINFORCEMENT, REAR END PANEL AND TAILGATE.	<i>1500</i>	\$ 3,000.00
3	MZ-BR-SEALER	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING	<i>?</i>	\$ 350.00
4	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.	<i>150</i>	\$ 250.00
5	MZ-BR-TRIMS2	TO REMOVE & REFIT CARPET & TRIMS ON THE REAR SECTION TO GIVE WAY TO THE REPAIR ON THE REAR SECTION.	<i>315</i>	\$ 630.00

6	MZ-BR-GLASS1	TO REMOVE & REFIT THE WINDSCREEN GLASS. /	NETT	\$ 560.00
7	MZ-BR-GLASS2	TO SUPPLY SEALER ON THE WINDSCREEN GLASS. /	NETT	\$ 120.00
8	MZ-BR-CAMERA	TO TRANSFER REVERSE CAMERA.	315	\$ 630.00
9	MZ-BR-REVSER	TO TRANSFER REVERSE SENSORS.	315	\$ 630.00
10	MZ-BR-PLATE1	TO SUPPLY NUMBER PLATE. X NN ,	NETT	\$ 70.00
11	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	150	\$ 250.00
12	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	180	\$ 350.00
13	MZ-BR-SUNDRI	SUNDRIES. 30	NETT	\$ 100.00

TOTAL LABOUR	\$ -	\$ 10,720.00
TOTAL PARTS	\$ -	\$ 6,753.24
TOTAL	\$ -	\$ 17,473.24
LESS EXCESS	\$ -	\$ -
TOTAL AFTER EXCESS	\$ -	
GST 7%	\$ -	\$ -
GRAND TOTAL	\$ -	\$ -

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A **QUOTATION FEE OF \$400** WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

TRANS EUROKARS PTE LTD

Authorised Signature

7- 8 Days.

before print photos.

Can Qiaf - 8288 0282

24/11/17

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: