

INS. CASE OWNER: NATALIE

CC 4 / 1117022464 1T1 ea3

ASSIGNMENT

Surveyor:

TAUFIKH

DOI:

23/11/17

Date / Time:

24/11/17

Registered in Merimen:

24/11/17

Pre-assign / CCU / FTE



Insured Vehicle No.:

SHC 2894M

Name of Insured:

CTPL

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A.:

22/11/17

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age: LEE TAI BOON

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

HYUNDAI I40

Place of Accident:

AYE TWOS CHANGI AIRPORTOI GIA REPORT YES / NO ; TP GIA REPORT YES / NO

Insured Liability: % Final ? Yes / No

CLN 1304B

INSRS:

WSP: Prime Auto

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time	STAGE	DATE / PIC
<u>28/11/17 (Asker)</u>	Non-Reporting ltr (1st):	
	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call OI:	
	After call ltr to OI:	
	Documentation Check List:	Handler Typist
	Notification ltr (if non-pickup)	☐ ☐
	After call ltr to OI:	☐ ☐
	Authorisation To Act:	☒ ☐
	Release Voucher:	☒ ☐
	Final Repair Bill:	☒ ☐
	Car Rental Invoice:	☒ ☐
	Towing Invoice:	☐ ☐
	LTA / GIA:	☐ ☐
	Medical Bill:	☐ ☐
	PIR:	☐ ☐
	Mandate/Reject Instruction:	☒ ☐
	LOD:	☒ ☐
	Payment Breakdown Form:	☐ ☐
	Post-Repair Photos:	☐ ☐
	Others:	☐ ☐

PRELIMINARY ADVICE Date/Time:

Sent By:

Confirm by: TAUFIKH

FINALIZATION

Date/Time: 30/11/17Confirm with: ALICEEmail ☐ Call ☐

Repair Cost:

P/P \$53,440.16(5 days) Reduction: 16 %

FINAL SETTLEMENT

Date/Time: 11/12/17Confirm with: ALICEEmail ☐ Call ☐

Final Liability:

% 100(Agreed / Assessed) BOLA S/N No.: 21

Repair Cost:

\$53,683.11OLD REAR BUMP B.

Loss of Rental (LOR):

\$56.00(6 days) x 476

Loss of Use (LOU):

\$5 -

(\$ x days)

Loss of Income (LOI):

\$5 -

(\$ x days)

LOR only ☒LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

\$5 -

Medical:

\$5 -

(e.g. Tow/ Independent)

Disbursement:

\$5 -

Legal Cost

\$5 -

Total:

\$54,139.11

Global Sum SS:

Email ☐ Call ☐

FINAL PAYMENT

Date/Time: 11/12/17Confirm with: ALICE

Payee 1:

\$54,139.11

Name 1:

PRIME AUTO CLAIMS SERVICE PTE LTD

Payee 2 (Strike if N.A.):

\$5

Payee 3 (Strike if N.A.):

\$5

1) Claim status: Normal/Reject/Private Settle

2) Report Format: TP3) Survey fee: 380COPY SENT
15/12/17

Tanpin

REF: III

ASSIGNMENT

From: _____ Date: 23.11.2017

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SLN 1304B

at Workshop mis:

Prime Auto

at:

6 Benoi Place

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The Veh had commenced its repair at the time of inspection.



Ball or Market Value:

IDAC Accident Report: _____ Consistent?: Yes or No

GIA / PR Seed: _____ Consistent?: Yes or No

Est. Repairs: 2 days Res: Yes or No

Lum. Surg: - % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted:

Vehicle: IN / OUT

Veh No: SLN 1304B Vc Page: 2017 Apr 1

Type: ☒ Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Fit.

001496

Colour:

Blue

A/S

Insured / Std / NI / NA

Sp Reading:

T Radio

Insured / Std / NI / NA

Eng No:

G No:

GPS 3322138

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt or

Brake: ☒ In order / Jammed / Leaked / Burnt or

Mod: ☒ Nil / S/Rim / STD A/Rim or

Tyre Size:

R:

185/6.0R15

R:

BS / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Wax lake

Front

R. Bal:

6

mm

Rear

R. Bal:

6

mm

L. Bal:

6

mm

L. Bal:

6

D.O.A.

D.O.I.

23/11/17/1740

Survey held at:

Prime Auto

Des. of Damages: ☒ Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date Time Action Instruction

take photo to every car

Plp: + 3,442.16

Red: + 664 16%

Date Time File Pass of

☐

Preli. Report

☐

Final Report

Date Time File Return to

Days Of Repair:

Resurvey No. of Trip:

Survey Fee

Transporter

to

Add Fee:

☐

Site Fee: \$

☐

Inter Fee: \$

☐

Feet Fee: \$

☐

140 and \$

Report Format:

Lump Sum: 1.8 In 3



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
INDIA INTERNATIONAL INSURANCE PL		Ref : CC4/III17022464/T1ea3		
64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711		Date : 24-11-2017		
		Code : III2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 2894M	Veh. Inspected	SLN 1304B	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	24/11/2017	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	22/11/2017	Inspection Date	23/11/2017	
Survey held at	PRIME AUTO CLAIMS SERVICE PTE LTD 6 BENOI PLACE SINGAPORE 629927			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Prime Auto Claims Service Pte Ltd

GST Reg. No : 201606560M

5 Benoi Place Singapore 629926

Tel: 6861 0908 Fax: 6515 2948

Tanjin 97493749
-WP'

Insurance

Resurvey after repair

5 days

Sur @ Udicato.com

23/11/17

Date: 22.11.2017

India International Insurance Pte Ltd

64 Cecil Street #04/#05

IOB Building

Singapore 049711

Attn: Motor Claims Dept

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

RE: ESTIMATE COST OF REPAIR TO VEHICLE SLN1304B HONDA FIT HYBRID

To Supply

1) 1pc	rear bumper	de ✓	\$	774.90 ✓
2) 1set	rear bumper clip	ner ✓	\$	30.00 ✓
3) 1pc	rear boot lid	bl ✓	\$	1,150.00 ✓
4) 1pc	rear boot lid weatherstrip	ner ✓	\$	92.30 ✓
5) 1pc	rear boot lid "Fit" emblem	ner ✓	\$	35.00 ✓
6) 1pc	rear boot lid "Hybrid" emblem	ner ✓	\$	75.50 ✓
7) 1pc	end panel	Rp ✓	\$	485.00 ✓
8) 1pc	end panel top garnish	Rp ✓	\$	115.00 ✓
9) 2pcs	rear glass moulding	ner ✓	@\$35.00	\$ 70.00 ✓

Sub Total Parts \$ 2,827.70

Less: 20% discount \$ (551.54)

Sub total Parts \$ 2,276.16

To Supply S.Nett Parts

1) 1set	reverse sensor	ner ✓	\$	180.00 ✓
2) 1tube	rear boot lid glass sealant	ner ✓	\$	40.00 ✓

Sub total S.Nett Parts \$ 220.00

L/charge

1) To tuff kote	\$ 40	80.00
------------------	-------	-------

- 2) To transfer rear boot lid trim board, wiper & mechanism parts \$ 50 100.00
- 3) To replace reverse sensor, check wiring \$ 30 40.00
- 4) To remove & refit rear glass \$ ✓ 120.00
- 5) To remove rear bumper, rear boot lid. Cut/welding end panel, replace above parts \$ 600 700.00
- 5) To putty, respray painting rear boot lid inner & outer, rear bumper & rear end panel \$ 600 700.00

Sub total L/charges	\$	<u>1,610.00</u>
Estimated Grand Total	\$	<u><u>4,106.16</u></u>



Prime Auto Claims Service Pte Ltd

GST Reg. No : 201605560M
5 Bend Place Singapore 629926
Tel: 6861 0908 Fax: 6515 2948

Date: 22.11.2017

India International Insurance Pte Ltd
64 Cecil Street #04/#05
IOB Building
Singapore 049711

Attn: Motor Claims Dept

Tan Jiah 97493749
-WP
Lumpsum
Repay after repair
5 days
Sur @ Uleasta.com
23/11/17

RE: ESTIMATE COST OF REPAIR TO VEHICLE SLN1304B HONDA FIT HYBRID

To Supply

1) 1pc rear bumper <i>de</i>	\$	774.90
2) 1set rear bumper clip <i>ne</i>	\$	30.00
3) 1pc rear boot lid <i>hl</i>	\$	1,150.00
4) 1pc rear boot lid weatherstrip <i>tri</i>	\$	92.30
5) 1pc rear boot lid "Fit" emblem <i>ne</i>	\$	35.00
6) 1pc rear boot lid "Hybrid" emblem <i>ne</i>	\$	75.50
7) 1pc end panel <i>Ry</i>	\$	485.00 X
8) 1pc end panel top garnish <i>?</i>	\$	115.00 X
9) 2pcs rear glass moulding <i>ne</i>	\$	70.00
@ \$35.00		

Sub Total Parts	\$	2,827.70	2227.70
Less: 20% discount	\$	(551.54)	-445.54
Sub total Parts	\$	2,276.16	1782.16

To Supply S.Net Parts

1) 1set reverse sensor <i>mr</i>	\$	180.00
2) 1tube rear boot lid glass sealant <i>ne</i>	\$	40.00

Sub total S.Net Parts \$ 220.00 ✓

L/charge

1) To tuff kote

\$ 40 80.00

Catherine Chong (LKK Auto)

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Thursday, 23 November, 2017 9:14 AM
To: Chrissy; 'sur@lkkauto.com'; Catherine Chong (LKK Auto)
Cc: aliceleong@primeautoclaims.com; peiyee@primeautoclaims.com; Natalie Lee
Subject: RE: PRI REQUEST TO ACCIDENT ON 22.11.2017 INVOLVING SLN1304B & SHC2894M
Attachments: img-171122190229.pdf

Dear Sir / Mdm,

Please conduct a survey on TP vehicle SLN1304B and let us have your report urgently.

This claim will be handled by Ms Natalie.

*Kindly upload this survey request email to merimen.

Thank You.

Best Regards,
Gabriel Wee

Motor Claims Dept.
India International Insurance Pte Ltd
64 Cecil Street | #05 IOB Building | Singapore 049711
Tel: 6347 6100, Ext - 248

23.11.2017 @ 9:24am
Pei Yee veh in

Taufik

From: Chrissy [mailto:chrissy@primeautoclaims.com]
Sent: 22 November, 2017 5:09 PM
To: Motor Claim - III <motorclaim@iii.com.sg>
Cc: aliceleong@primeautoclaims.com; peiyee@primeautoclaims.com
Subject: PRI REQUEST TO ACCIDENT ON 22.11.2017 INVOLVING SLN1304B & SHC2894M
Importance: High

Hi,

The above referred.

Our client's GIA report enclosed for your retention. Please arrange PRI on urgent basis.

****Please inform surveyor to avoid 11.45am -12.45pm lunch hour.**

We select: LKK Auto Consultants Pte. Ltd.

Thank you.

Important Note: Our company will be migrating to Prime Auto Claims Services Pte. Ltd. with effective on 01.07.2017. Section Automotive Services will officially terminate on 31.12.2017.



Prime Auto Claims Service Pte Ltd

GST Reg. No : 201606560M
5 Benoi Place Singapore 629926
Tel: 6861 0908 Fax: 6515 2948

Date: 02.12.2017

Our Ref: SLN1304B
Your Ref: Please advised

India International Insurance Pte Ltd
64 Cecil Street #04/#05
IOB Building
Singapore 049711

Without prejudice

Attn: Ms. Natalie
Motor Claims Dept

Dear Madam,

ACCIDENT ON 22.11.2017 INVOLVING VEHICLE NO. SLN1304B & SHC2894M

The above refers.

We are on behalf of M/s Best Motor Leasing & Limousine Services Pte Ltd owner of vehicle SLN1304B in their third party claim against your insured / driver of SHC2894M

Appended below our client's claim:-

1. Cost of repair	\$ 3,683.11
2. Loss of rental @\$76.00 x 6 days	\$ 456.00

Estimated total	\$ 4,139.11

We enclosed herewith our invoice no. 1019, letter of authorization and Letter of Certification for your retention. Please acknowledge receipt.

For amicable settlement, please let us have your offer.

Regards

Yours faithfully,


.....
Alice Leong

Encl.


LETTER OF AUTHORITY

To: PRIME AUTO CLAIMS SERVICE PTE. LTD.

Re: ACCIDENT ON 22.11.2017 INVOLVING SLN1304B & SHC2894M
ALONG AYE

I/ We, M/S Best Motor Leasing & Limousine Services Pte. Ltd. hereby authorized you to carry out repairs of the damage caused to my / our vehicle no. SLN1304B in the above accident.

I/ We further also confirm and agree that all sums of money to be recovered by you on my/ our behalf shall be paid to you. I/ We hereby also authorise the third party insurer to release to you such sums of money recovered on my / our behalf.



.....
Signature (Company's stamp if applicable)
Name: **BEST MOTOR LEASING & LIMOUSINE SERVICES P/L**
NRIC: **201512366 W**

EXPRESS SETTLEMENT

DISCHARGE VOUCHER III-Direct Settlement (PODS)

India Ref: MCT17110777
Claimant Ref: SLN 1304B

We/I, PRIME AUTO CLAIMS SERVICE PTE LTD ("the workshop") hereby confirm that we/I have reached an agreement with the appointed Surveyor of India International Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of Surveyor) with respect to the amount claimed for S\$ 3,683.11 (repair cost), S\$ 456.00 (loss of ~~rental~~ rental), S\$ (search fee), vehicle no. SLN 1304B that was damaged pursuant to the accident which occurred on 22/11/2017 (date) at AYE (location) involving vehicle no. SHC 2894M (insured vehicle). This is pursuant to the inspection conducted on 23/11/2017 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner BEST MOTOR LEASING & LIMOUSINE SERVICES PTE LTD ("the third party claimant") of vehicle no. SLN 1304B to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify India International Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to cost of repairs and/or rental and/or loss of use pursuant to the damage to SLN 1304B (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of all claims of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

We/I authorize you to pay the total amount of S\$ 4,139.11 to PRIME AUTO CLAIMS SERVICE PTE LTD.

Dated this 14th day of December 2017

CLAIMANT:

Signature: [Signature]

Name: Angie Suk Ching

NRIC: S261221469

Address: c/o No. 5 Boro Place
S' 628926

Nationality: PR

Occupation: claims manager



WITNESS:

Signature: [Signature]

Name: LKK AUTO CONSULTANTS PTE LTD

NRIC: 199607198R

Address: 51 UBI AVE 1, PAYA UBI INDUSTRIAL PARK
#02-25 SINGAPORE 408933

Nationality: -

Occupation: -



TAX INVOICE

No: 1019

**Prime Auto Claims Service Pte Ltd**

5 Benoi Place Singapore 629926

Tel: 6861 0908 Fax: 6515 2948

GST Reg. No: 201606560M

Reg No. 201606560M

MESSRS

India International Insurance Pte Ltd

30/11/2017

64 Cecil Street

#04/05 10B Building

Singapore 049711

Date:

1001

Works Order No:

SLN1304B

Vehicle No:

ITEM	DESCRIPTION	UNIT PRICE	AMOUNT
	Make/Model : Honda Fit Repair Date : 30/11/2017 Terms of Payment: COD		
	Third Party Claims		
	To Supply		
1.	1 pc rear bumper.		\$ 774.90
2.	1 set rear bumper clip.		\$ 30.00
3.	1 pc rear boot lid.		\$ 1,150.00
4.	1 pc rear boot lid weatherstrip.		\$ 92.30
5.	1 pc rear boot lid "Fit" emblem.		\$ 35.00
6.	1 pc rear boot lid "Hybrid" emblem.		\$ 75.50
7.	2 pcs rear glass moulding.		\$ 70.00
	Sub Total Parts:		\$ 2,227.20
	Less: 20% discount		<u>(\$ 445.54)</u>
			\$ 1,782.16
	To Supply S.Nett Parts		
1.	1 set reverse sensor.		\$ 180.00
2.	1 tube rear boot lid glass sealant.		\$ 40.00
	Sub Total S.Nett Parts:		\$ 220.00
	Labour Charges		
1.	To tuff kote.		\$ 40.00
2.	To transfer rear boot lid trim board, wiper & mechanism parts.		\$ 50.00
3.	To replace reverse sensor, check wiring.		\$ 30.00
4.	To remove & refit rear glass.		\$ 120.00
5.	To remove rear bumper, rear boot lid. Cut/welding end panel, replace Above parts.		\$ 600.00
6.	To putty, respray painting rear boot lid inner & outer, rear bumper & Rear end panel.		\$ 600.00
	Sub Total Labour Charges:		<u>\$ 1,440.00</u>

* Compound interests at the rate of 1% per month will be charged on late payment.

SUB TOTAL	\$ 3,442.16
GST 7%	\$ 240.95
TOTAL	\$ 3,683.11

Prepared by

 Prime Auto Claims Service Pte Ltd
 Manager



COMFORT LIMOUSINE SERVICES PTE LTD
PRIME TRANSPORT & LIMOUSINE SERVICES PTE LTD
BEST MOTOR LEASING & LIMOUSINE SERVICES PTE LTD

Member of Prime Group of Companies
6 Benoi Place Singapore 629926
Tel: 6862 8878 Fax: 6863 6566
Co. Registration No: 201508380W
201544118N 201512366W

Your Ref : Please advise

Date : 22-November-2017

To : Whom it May Concern

From : Best Motor Leasing & Limousine Services Pte Ltd.

RE : LETTER OF CERTIFICATION FOR MR. ONG CHIN SYE.

This letter serves to confirm that Mr. Ong Chin Sye of NRIC number S0121091B is a Chauffeur-driven hirer for Best Motor Leasing & Limousine Services Pte Ltd hiring Vehicle Registration Number SLN1304B at a daily rate of Singapore Dollars Seventy-Six (S\$76.00) only.

Should clarification require I can be contacted at 8121 6313.

Thank you with Best Regards.

Yours Sincerely

Ms Veronica Lim
Deputy Manager



...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	27 Nov 2017 Edit Reg		23 Nov 2017 00:00 Edit Adj Rpt	S\$3,442.16 Edit Estimates	S\$3,442.16 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

Insured:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R		[Created by adjuster]
Main Claimant:	BEST MOTOR LEASING & LIMOUSINE SERVICES PTE LTD, Co. Reg. No.: 201512366W		
Vehicle Reg. No.:	SLN1304B	Date of Loss:	22/11/2017 11:00 - :59
Claim Type:	TP / MCT17110777	Policy/Cover Note No.:	MCOM0016
Vehicle Reg. No. (Insured):	SHC2894M	Policy No. (Claimant):	17-MG000658-R02
		Excess:	
Repairer:	Prime Auto Claims Service Pte Ltd (HQ) 6 Benoi Place, 629927 Pioneer - Tel: 68610908		
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by NATALIE LEE - 63476100 ext 243]		
Claimant's Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH] ... [Final Rpt due 05/12/2017]		

ASSOCIATED MAIL RECEIVED

- [View All](#)
[Compose Case Mail](#)
- III_SG (06/12/2017): Alert - Adj Mandate Approved (S\$4139.11) - SLN1304B - Claim Handler: NATALIE LEE
 - III_SG (29/11/2017): Alert - Adj Mandate Approved (S\$0.00) - SLN1304B - Claim Handler: NATALIE LEE

ALL ASSOCIATED TASKS

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.

Claim Documents

*SLN1304B (MCT17110777)
[SHC2894M]

TP

BEST MOTOR LEASING & LIMOUSINE SERVICES PTE LTD

Nov 22 2017 11:00AM

[COMFORT TRANSPORTATION PTE LTD]

Prime Auto Claims Service Pte Ltd

Upload Documents

Upload Photos

Compose New Letter

View

Use Viewer

Photos/Images

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	3 per page	Thumbnail	Print
1	30/11/17 12:02	Odometer Reading		Load JPG	☒
2	30/11/17 12:02	Chassis Number		Load JPG	☒
3	30/11/17 12:02	General View		Load JPG	☒
4	30/11/17 12:02	General View		Load JPG	☒
5	30/11/17 12:02	General View		Load JPG	☒
6	30/11/17 12:02	General View		Load JPG	☒
7	30/11/17 12:02	General View		Load JPG	☒
8	30/11/17 12:02	General View		Load JPG	☒
9	30/11/17 12:02	General View		Load JPG	☒
10	30/11/17 12:02	General View		Load JPG	☒
11	30/11/17 12:02	General View		Load JPG	☒
12	30/11/17 12:02	General View		Load JPG	☒
13	30/11/17 12:02	General View		Load JPG	☒
14	30/11/17 12:02	General View		Load JPG	☒
15	30/11/17 12:02	General View		Load JPG	☒
16	30/11/17 12:02	General View		Load JPG	☒
17	30/11/17 12:02	General View		Load JPG	☒
18	30/11/17 12:02	General View		Load JPG	☒
19	30/11/17 12:02	General View		Load JPG	☒
20	30/11/17 12:02	General View		Load JPG	☒
21	30/11/17 12:02	General View		Load JPG	☒
22	30/11/17 12:02	Reinspection Photo		Load JPG	☒
23	30/11/17 12:02	Reinspection Photo		Load JPG	☒
24	30/11/17 12:02	Reinspection Photo		Load JPG	☒
25	30/11/17 12:02	Reinspection Photo		Load JPG	☒
26	30/11/17 12:02	Reinspection Photo		Load JPG	☒
27	30/11/17 12:02	Reinspection Photo		Load JPG	☒

Documentation

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	1 per page	Thumbnail	Print
1	24/11/17 18:28	ACKNOWLEDGEMENT EMAIL TO III 23.11.2017		Load PDF	
2	24/11/17 18:28	TP GIA REPORT		Load PDF	
3	28/11/17 09:08	TP ESTIMATE- MARKED		Load PDF	
4	04/12/17 17:16	WORKSHOP INVOICE		Load PDF	
5	04/12/17 17:16	RENTAL RECEIPT		Load PDF	
6	04/12/17 17:16	LOD		Load PDF	
7	22/12/17 12:26	DISCHARGE VOUCHER		Load PDF	
8	22/12/17 12:26	AUTHORISATION TO ACT FORM		Load PDF	
No	Finalized On	India International Insurance Pte Ltd (HQ)		Thumbnail	Print
1	27/11/17 08:41	Singapore Accident Statement		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III17022464/T1EA3Q2
Date: 22/12/2017

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: MCOM0016
Claimant Vehicle No: SLN1304B Insured Vehicle No: SHC2894M
Date of Loss: 22/11/2017 Nature of Claim: TP Claim No: MCT17110777

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLN1304B
Make & Model: HONDA FIT, 1.5 HYBRID (A)
Reg. Date: 24/04/2017 (Man. Year: 2016) Engine No: LEB4730378
Colour: Blue Chassis No: GP53322138
Engine Capacity: 1496 cc Odometer: 0 km
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 185/60 R15 Rear Tyre Size: 185/60 R15
Front Left Side: West Lake 6 mm Rear Left Side: West Lake 6 mm
Front Right Side: West Lake 6 mm Rear Right Side: West Lake 6 mm
The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	2,482.16	2,002.16	480.00	19.34
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,740.00	1,440.00	300.00	17.24
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,222.16	3,442.16	780.00	18.47
+ GST 7.00/7.00% (S\$)	295.55	240.95	54.60	18.47
Nett Amount (S\$)	4,517.71	3,683.11	834.60	18.47
+ Car Rental (6.0 x S\$76.00/day) (S\$)		456.00		
Nett Liability (S\$)		4,139.11		

INSPECTION

Date of Assignment: 23/11/2017
Date Inspected: 23/11/2017 Inspected At: Prime Auto Claims Service Pte Ltd (HQ)
6 Benoi Place
Singapore 629927
Estimated Period of Repair: 5.0 days

Adjuster: MOHD TAUFIKH

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 04 Dec 2017)
Parts: 144	HONDA FIT 1.5 HYBRID (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLN1304B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	774.90 FL	*774.90 FL
2	1		*SET REAR BUMPER CLIP	Necessary	30.00 FL	*30.00 FL
3	1		*REAR BOOT LID	Bent	1,150.00 FL	*1,150.00 FL
4	1		*REAR BOOT LID WEATHERSTRIP	Twisted	92.30 FL	*92.30 FL
5	1		*REAR BOOT LID FIT EMBLEM	Necessary	35.00 FL	*35.00 FL
6	1		*REAR BOOT LID HYBRID EMBLEM	Necessary	75.50 FL	*75.50 FL
7	1		*END PANEL	Repair	485.00 FL	*- FL
8	1		*END PANEL TOP GARNISH	Not Necessary	115.00 FL	*- FL
9	2		*REAR GLASS MOULDING	Necessary	70.00 FL	*70.00 FL
10	1		*SET REVERSE SENSOR	Not Working	180.00 FS	*180.00 FS
11	1		*TUBE REAR BOOT LID GLASS SEALANT	Necessary	40.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3,047.70	2,447.70
- List Item Discount on L Items 20.00/20.00% (\$\$)	565.54	445.54
Total Parts (\$\$)	2,482.16	2,002.16

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO TUFF KOTE	New	80.00	40.00
2	TO TRANSFER REAR BOOT LID TRIM BOARD ,WIPER & MECHANISM PARTS	New	100.00	50.00
3	TO REPLACE REVERSE SENSOR ,CHECK WIRING	New	40.00	30.00
4	TO REMOVE & REFIT REAR GLASS	New	120.00	120.00
5	TO REMOVE REAR BUMPER ,REAR BOOT LID ,CUT/WELDING END PANEL,REPLACE ABOVE PARTS	New	700.00	600.00
6	TO PUTTY ,RESPRAY PAINTING REAR BOOT LID INNER & OUTER ,REAR BUMPER & REAR END PANEL	New	700.00	600.00
Gross Labour Cost (S\$)			1,740.00	1,440.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >