

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/1162/2017/JT
Date : 14-Nov-17

Vehicle not in workshop. Kindly arrange for survey.

Your insured vehicle number : S GBD 1791 Z

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Edmund Woon Khim Wah
Address : 281 Joo Chiat Place
#04-04
Singapore 427962
Telephone : HP +65 9387 5396
Type of Claim : Third Party Claims
Policy No. :
Vehicle No : **SKS 9180 Z**
Model Code : Audi A3 Sedan 1.4 TFSI 8V
Model / Year : May-15
Engine No : CZC 248525
Chassis No : WAUZZZ8V2F1123364
Mileage : -
Date In :
Liability : -
Excess Cost : -
Estimated By : Allan Wu
Accident Date : 22-Nov-17
Place of Accident : Stil Road > ECP before Joo Chiat Place junction

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKS 9180 Z.

S/n	Nature of Jobs	Estimated Charges	Remark
1	To remove & transfer rear parking aid. Check function. Renew according to damages	S/N \$ 280.00 ✓	
2	To remove & transfer rear lid's convenience lock & wire harness for tail lights.	S/N \$ 280.00 ✓	
3	To dislodge and reinstall rear wire harness for tail lights, battery manager, fuse and relay trays, electrical and audio equipments.	\$ 480.00 ✓	
4	To dismantle rear bumper and rear lid. Cut out and weld rear outer, inner rear cross panels and connecting plates. Re-organize rear crash management components. Renew rear bumper and boot lid, align to position. Reinstall all parts removed.	\$ 3,600.00 2250	
5	To respray rear bumper, rear lid and end panelling. To carry out joint sealer works and stone chip treatments.	S/N \$ 2,200.00 1650 .	
6	To carry out diagnostic check	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: \$ 7,032.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKS 9180 Z.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	REAR BUMPER <i>Delid</i>	\$ 1,567.00	✓
2	RAER BUMPER GUIDE - LHS/RHS <i>3 new</i>	\$ 26.00	+
3	REAR BUMPER LOCKING PIN	\$ 49.00	+
4	REAR BUMPER REFLECTOR - LHS/RHS <i>new</i>	\$ 48.00	+
5	REAR BUMPER SPOILER <i>Delid</i>	\$ 193.00	✓
6	REAR BUMPER LOWER GUIDE - LHS/RHS <i>new</i>	\$ 108.00	+
7	REAR REINFORCEMENT BEAM ?	\$ 481.00	?
8	REAR BUMPER BRACKET ?	\$ 20.00	?
9	REAR PARKING AID ?	\$ 415.00	?
10	REAR LID <i>Dented</i>	\$ 2,225.00	✓
11	REAR LID HINGE - LHS/RHS <i>new</i>	\$ 434.00	+
12	REAR WEATHERSTRIP <i>new</i>	\$ 167.00	+
13	REAR LID LOCK <i>new</i>	\$ 165.00	+
14	REAR LID STRIKER <i>new</i>	\$ 42.00	+
15	PACKING ADHESIVE <i>new</i>	\$ 14.00	✓
16	AUDI EMBLEM <i>3</i>	\$ 105.00	-
17	"A3" EMBLEM <i>1 new</i>	\$ 81.00	-
18	"TFSI" EMBLEM	\$ 81.00	✓
19	REAR CROSS PANEL <i>Dented</i>	\$ 307.00	✓
SUB-TOTAL SPARE PARTS		\$ 6,528.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKS 9180 Z.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
21	CROSS PANEL REINFORCEMENT ?	\$ 622.00	?
22	CROSS PANEL CONNECTING PLATE - LHS/RHS ?	\$ 244.00	?
23	CROSS PANEL TRIM <i>del d</i>	\$ 131.00	?
24	ACRYLIC SEALER <i>2</i>	S/N \$ 180.00	✓
25	CAVITY WAX <i>1/2</i>	S/N \$ 140.00	✓
26	STONE CHIP	S/N \$ 180.00	✓
27	SUNDRIES ?	\$ 500.00	?
TOTAL SPARE PARTS CHARGES		: \$ 8,525.00	
TOTAL LABOUR CHARGES		: \$ 7,032.00	
GRAND TOTAL		: \$ 15,557.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian S
Surveyed Date : 28/11/17.
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 07 Days.

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant