



# AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047  
TEL: 6483 1244 ( 4 lines ) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg  
GST:M9-0009639-E RCB NO:06470300B

**SURVEYOR COPY**

M/S : AXA INSURANCE SINGAPORE PTE LTD  
8 SHENTON WAY  
#27-01 AXA TOWER  
SINGAPORE 068811

TEL: 63387288

FAX: 63382522

ATTN: Motor Claim Department

LKIC Auto.

Estimate No: MC0912620

Date: 25 Nov 2017

Policy No: GA151662/1

Veh Reg No: SKZ5889C

Make/Model: TOYOTA HARRIER  
ELEGANCE 2.0

Your Ref No: SKZ5889C

Claim Type: Own Damage

Accident Date: 24/11/2017

## Estimate Repair Cost to Vehicle No :SKZ5889C

| Description                                                              | U/Price | Quantity | Cost       | Amount     |
|--------------------------------------------------------------------------|---------|----------|------------|------------|
|                                                                          |         |          | <u>S\$</u> | <u>S\$</u> |
| <b>SPARE PARTS</b>                                                       |         |          |            |            |
| 1 FRONT BONNET <del>X Repair</del> - buc                                 |         | 1 PC     | 530.00     |            |
| 2 FRONT BONNET HINGE LH & RH X                                           |         | 2 PC     | 60.00      |            |
| 3 FRONT BONNET ABSORBER LH & RH X SNN                                    |         | 2 PC     | 180.00     |            |
| 4 FRONT BONNET LOCK / BT                                                 |         | 1 PC     | 50.00      |            |
| 5 FRONT BONNET LOCK CABLE X SNN                                          |         | 1 PC     | 22.00      |            |
| 6 FRONT BONNET INSULATOR CLIPS X SNN                                     |         | 9 PC     | 9.00       |            |
| 7 FRONT BONNET CHROME MOULDING OUTER - Cut                               |         | 1 PC     | 90.00      |            |
| 8 FRONT GRILLE / PR                                                      |         | 1 PC     | 200.00     |            |
| 9 FRONT GRILLE CLIPS / MC                                                |         | 8 PC     | 8.00       |            |
| 10 HEADLAMP WITH HID LH & RH - CRA                                       |         | 2 PC     | 1,800.00   |            |
| 11 HEADLAMP LOWER BEAM LH & RH - CHECK PRICE < LH? RH - BT               |         | 2 PC     | 0.0000     |            |
| 12 HEADLAMP CLIPS X NN                                                   |         | 4 PC     | 4.00       |            |
| 13 HEADLAMP TOP SIDE PANEL LH & RH X Repair.                             |         | 2 PC     | 130.00     |            |
| 14 FRONT BUMPER / DS                                                     |         | 1 PC     | 530.00     |            |
| 15 FRONT BUMPER SIDE RETAINER LH & RH - MC                               |         | 2 PC     | 76.00      |            |
| 16 FRONT BUMPER CLIPS / MC                                               |         | 12 PC    | 12.00      |            |
| 17 FRONT BUMPER INNER TOP BEAM CTR - BT                                  |         | 1 PC     | 100.00     |            |
| 18 FRONT BUMPER INNER TOP SIDE BRACKET LH & RH ?                         |         | 2 PC     | 90.00      |            |
| 19 FRONT BUMPER REINFORCEMENT - BT                                       |         | 1 PC     | 145.00     |            |
| 20 FRONT BUMPER REINFORCEMENT BRACKET LH & RH X NN                       |         | 2 PC     | 160.00     |            |
| 21 FRONT BUMPER SPONGE CTR BIG / CRA                                     |         | 1 PC     | 40.00      |            |
| 22 FRONT BUMPER SIDE SPONGE SMALL LH & RH                                |         | 2 PC     | 36.00      |            |
| 23 FRONT BUMPER TOW COVER LH & RH < LH? RH - DS                          |         | 2 PC     | 24.00      |            |
| 24 FRONT BUMPER LOWER GRILLE CTR - Cut RH - mis                          |         | 1 PC     | 85.00      |            |
| 25 FRONT BUMPER LOWER COVER ?                                            |         | 1 PC     | 45.00      |            |
| 26 FRONT BUMPER LOWER SPOILER BLACK B - CRA                              |         | 1 PC     | 100.00     |            |
| 27 ENGINE UNDER COVER CTR ?                                              |         | 1 PC     | 60.00      |            |
| 28 FOGLAMP < LH? RH - CRA                                                |         | 2 PC     | 230.00     |            |
| 29 FOGLAMP COVER OUTER LH & RH < LH? RH - MC                             |         | 2 PC     | 80.00      |            |
| 30 RADIATOR SUPPORT PANEL X Repair. < LH? RH - NN                        |         | 1 PC     | 320.00     |            |
| 31 RADIATOR SUPPORT PANEL INNER SIDE AIR GUIDE BIG LH & RH < LH? RH - MC |         | 2 PC     | 90.00      |            |
| 32 RADIATOR SUPPORT PANEL INNER SIDE AIR GUIDE SMALL LH & RH ?           |         | 2 PC     | 90.00      |            |
| 33 RADIATOR SUPPORT PANEL TOP GARNISH / MC                               |         | 1 PC     | 135.00     |            |
| 34 RADIATOR SUPPORT PANEL TOP GARNISH CLIPS / MC                         |         | 12 PC    | 18.00      |            |
| 35 BRACE PANEL / BT                                                      |         | 1 PC     | 75.00      |            |
| 36 HORN X NN                                                             |         | 2 PC     | 100.00     |            |
| 37 AIR CON CONDENSER ASSY ORI ?                                          |         | 1 PC     | 530.00     |            |
| 38 AIR CON CONDENSER PIPE (COND-VALVE) ?                                 |         | 1 PC     | 200.00     |            |
| 39 AIR CON CONDENSER PIPE (COND-COMP) ?                                  |         | 1 PC     | 135.00     |            |





# AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047  
TEL: 6483 1244 ( 4 lines ) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg  
GST:M9-0009639-E RCB NO:06470300B

**SURVEYOR COPY**

M/S: AXA INSURANCE SINGAPORE PTE LTD  
8 SHENTON WAY  
#27-01 AXA TOWER  
SINGAPORE 068811  
TEL: 63387288 FAX: 63382522  
ATTN: Motor Claim Department

Estimate No: MC0912620  
Date: 25 Nov 2017  
Policy No: GA151662/1  
Veh Reg No: SKZ5889C  
Make/Model: TOYOTA HARRIER  
ELEGANCE 2.0

Your Ref No: SKZ5889C  
Claim Type: Own Damage  
Accident Date: 24/11/2017

## Estimate Repair Cost to Vehicle No :SKZ5889C

| Description                                 | U/Price | Quantity | Cost       | Amount     |
|---------------------------------------------|---------|----------|------------|------------|
|                                             |         |          | <u>S\$</u> | <u>S\$</u> |
| 40 AIR CON CONDENSER FAN MOTOR ?            |         | 1 PC     | 160.00     |            |
| 41 AIR CON CONDENSER FAN BLADE ?            |         | 1 PC     | 65.00      |            |
| 42 RADIATOR ASSY ORI ?                      |         | 1 PC     | 480.00     |            |
| 43 RADIATOR FAN BLADE ?                     |         | 1 PC     | 60.00      |            |
| 44 RADIATOR FAN MOTOR ?                     |         | 1 PC     | 160.00     |            |
| 45 RADIATOR FAN COWLING ?                   |         | 1 PC     | 125.00     |            |
| 46 RADIATOR SPARE TANK X                    |         | 1 PC     | 130.00     |            |
| 47 WIPER WASHER TANK RH ?                   |         | 1 PC     | 65.00      |            |
| 48 FRONT FENDER LH & RH - <i>huc LH ?</i>   |         | 2 PC     | 580.00     |            |
| 49 FRONT FENDER COWLING <i>&lt; RH - TV</i> |         | 2 PC     | 310.00     |            |
| 50 FRONT FENDER COWLING CLIPS <i>- MCC.</i> |         | 20 PC    | 30.00      |            |

8,754.00

### Special Nett

|                             |      |       |
|-----------------------------|------|-------|
| 51 RADIATOR COOLANT ?       | 1 PC | 35.00 |
| 52 NUMBER PLATE X <i>NN</i> | 1 PC | 35.00 |

70.00

### LABOUR

|                                                                                                                                                                                                                                                        |      |          |            |
|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|----------|------------|
| 53 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.                                                                                         | 1 PC | 40.00    | <i>20</i>  |
| 54 TO REMOVE AND REPLACE A/C CONDENSER AND PIPES, RADIATOR AND HOSES, VACUUM A/C SYSTEM AS WELL AS REFILL A/C GAS.                                                                                                                                     | 1 PC | 120.00   | <i>100</i> |
| 55 TO REMOVE & REINSTALL FRONT ENGINE MOUNTING, GEARBOX MOUNTING                                                                                                                                                                                       | 1 PC | 150.00   | <i>?</i>   |
| 56 LABOUR TO RESET ENGINE MANAGEMENT SYSTEM WITH DIAGNOSTIC FAULT - AIR BAG LIGHT & ENGINE LIGHT.                                                                                                                                                      | 1 PC | 180.00   | <i>?</i>   |
| 57 TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD RADIATOR SUPPORT PANEL, BRACE PANEL, FRONT BUMPER REINFORCEMENT, FRT BUMPER TOP BEAM CTR, SIDE BRACKET, HEADLAMP TOP PANEL. TO KNOCK & REPAIR FRT DOOR, FRT WHEELHOUSE SIDE PANEL, FRT CHASSIS FRAME. | 1 PC | 1,200.00 | <i>600</i> |
| 58 TO SPRAY FRT BONNET, FRT BUMPER, FRT BUMPER REINFORCEMENT, FRT BUMPER TOP BEAM CTR, FRT BUMPER SIDE BRACKET, BRACE PANEL, RADIATOR SUPPORT PANEL, HEADLAMP TOP PANEL, FRT FENDER, FRT DOOR, FRT CHASSIS FRAME, FRT WHEELHOUSE PANEL.                | 1 PC | 1,400.00 | <i>600</i> |





# AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047  
TEL: 6483 1244 ( 4 lines ) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg  
GST:M9-0009639-E RCB NO:06470300B

**SURVEYOR COPY**

M/S : AXA INSURANCE SINGAPORE PTE LTD  
8 SHENTON WAY  
#27-01 AXA TOWER  
SINGAPORE 068811  
TEL: 63387288 FAX: 63382522  
ATTN: Motor Claim Department

Estimate No: MC0912620  
Date: 25 Nov 2017  
Policy No: GA151662/1  
Veh Reg No: SKZ5889C  
Make/Model: TOYOTA HARRIER  
ELEGANCE 2.0

Your Ref No: SKZ5889C  
Claim Type: Own Damage  
Accident Date: 24/11/2017

## Estimate Repair Cost to Vehicle No :SKZ5889C

| Description | U/Price | Quantity | Cost       | Amount     |
|-------------|---------|----------|------------|------------|
|             |         |          | <u>S\$</u> | <u>S\$</u> |
|             |         |          |            | 3,090.00   |

|                      |               |
|----------------------|---------------|
| Amount Before Excess | S\$ 11,914.00 |
| Add GST @ 7%         | 833.98        |
| Total Amount payable | S\$ 12,747.98 |

TOTAL: SINGAPORE DOLLAR TWELVE THOUSAND SEVEN HUNDRED FORTY SEVEN AND CENTS NINETY EIGHT ONLY

Please arrange this vehicle to be surveyed soonest possible.  
Thank You

Excess : \$500  
Authorized.  
part by part.  
before paint photos.  
5 Days.

27/11/17

Guo Qiang - 82880282

For AH LIM MOTOR COMPANY



AUTHORISED SIGNATURE

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: