



# AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047  
TEL: 6483 1244 ( 4 lines ) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg  
GST:M9-0009639-E RCB NO:06470300B

M/S : AXA INSURANCE PTE LTD  
8 SHENTON WAY  
#27-01 AXA TOWER  
SINGAPORE 068811

TEL: 63387288

FAX: 63382522

ATTN: Motor Claim Department

Claim No: MC0912620

Final No: AL0927204

Date: 07 Feb 2018

Policy No: GA151662/1

Veh Reg No: SKZ5889C

Make/Model: TOYOTA HARRIER  
ELEGANCE 2.0

Your Ref No: S7M004R9

Claim Type: Own Damage

Accident Date: 24/11/2017

## Tax Invoice-Final Repair Cost to Vehicle No :SKZ5889C

| Description                                           | U/Price | Quantity | Cost<br>S\$ | Amount<br>S\$ |
|-------------------------------------------------------|---------|----------|-------------|---------------|
| <b>SPARE PARTS</b>                                    |         |          |             |               |
| 1 FRONT BONNET                                        |         | 1 PC     | 530.00      |               |
| 2 FRONT BONNET LOCK                                   |         | 1 PC     | 50.00       |               |
| 3 FRONT BONNET CHROME MOULDING OUTER                  |         | 1 PC     | 90.00       |               |
| 4 FRONT GRILLE                                        |         | 1 PC     | 200.00      |               |
| 5 FRONT GRILLE CLIPS                                  |         | 8 PC     | 8.00        |               |
| 6 HEADLAMP WITH HID LH & RH                           |         | 2 PC     | 1,800.00    |               |
| 7 HEADLAMP TOP SIDE PANEL LH & RH                     |         | 2 PC     | 130.00      |               |
| 8 FRONT BUMPER                                        |         | 1 PC     | 530.00      |               |
| 9 FRONT BUMPER SIDE RETAINER LH & RH                  |         | 2 PC     | 76.00       |               |
| 10 FRONT BUMPER CLIPS                                 |         | 10 PC    | 18.00       |               |
| 11 FRONT BUMPER INNER TOP BEAM CTR                    |         | 1 PC     | 100.00      |               |
| 12 FRONT BUMPER REINFORCEMENT                         |         | 1 PC     | 145.00      |               |
| 13 FRONT BUMPER SPONGE CTR BIG                        |         | 1 PC     | 40.00       |               |
| 14 FRONT BUMPER SIDE SPONGE SMALL LH & RH             |         | 2 PC     | 36.00       |               |
| 15 FRONT BUMPER TOW COVER RH                          |         | 1 PC     | 12.00       |               |
| 16 FRONT BUMPER LOWER GRILLE CTR                      |         | 1 PC     | 85.00       |               |
| 17 FRONT BUMPER LOWER SPOILER BLACK                   |         | 1 PC     | 100.00      |               |
| 18 ENGINE UNDER COVER CTR                             |         | 1 PC     | 65.00       |               |
| 19 FOGLAMP RH                                         |         | 1 PC     | 115.00      |               |
| 20 FOGLAMP COVER OUTER RH                             |         | 1 PC     | 40.00       |               |
| 21 RADIATOR SUPPORT PANEL                             |         | 1 PC     | 320.00      |               |
| 22 RADIATOR SUPPORT PANEL INNER SIDE AIR GUIDE BIG RH |         | 1 PC     | 45.00       |               |
| 23 RADIATOR SUPPORT PANEL TOP GARNISH                 |         | 1 PC     | 135.00      |               |
| 24 RADIATOR SUPPORT PANEL TOP GARNISH CLIPS           |         | 12 PC    | 18.00       |               |
| 25 BRACE PANEL                                        |         | 1 PC     | 75.00       |               |
| 26 AIR CON CONDENSER PIPE (COND-VALVE)                |         | 1 PC     | 200.00      |               |
| 27 FRONT FENDER LH & RH                               |         | 2 PC     | 580.00      |               |
| 28 FRONT FENDER COWLING RH                            |         | 1 PC     | 155.00      |               |
| 29 FRONT FENDER COWLING CLIPS                         |         | 20 PC    | 30.00       |               |
| 30 RADIATOR SUPPORT SIDE GARNISH RH                   |         | 1 PC     | 20.00       |               |
| 31 WIPER GRILLE SIDE GARNISH RH                       |         | 1 PC     | 20.00       |               |

5,768.00

Special Nett

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Industrial Park 2A  
#01-09 AMK Autopoint Singapore 568047



# AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047  
TEL: 6483 1244 ( 4 lines ) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg  
GST:M9-0009639-E RCB NO:06470300B

M/S : AXA INSURANCE PTE LTD  
8 SHENTON WAY  
#27-01 AXA TOWER  
SINGAPORE 068811

TEL: 63387288

FAX: 63382522

ATTN: Motor Claim Department

Claim No: MC0912620

Final No: AL0927204

Date: 07 Feb 2018

Policy No: GA151662/1

Veh Reg No: SKZ5889C

Make/Model: TOYOTA HARRIER  
ELEGANCE 2.0

Your Ref No: S7M004R9

Claim Type: Own Damage

Accident Date: 24/11/2017

## Tax Invoice-Final Repair Cost to Vehicle No :SKZ5889C

| Description | U/Price | Quantity | Cost<br>S\$ | Amount<br>S\$ |
|-------------|---------|----------|-------------|---------------|
|-------------|---------|----------|-------------|---------------|

35.00

### LABOUR

- |    |                                                                                                                                                                                                                                            |      |        |
|----|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|--------|
| 33 | TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.                                                                                | 1 PC | 20.00  |
| 34 | TO REMOVE AND REPLACE A/C CONDENSER AND PIPES, RADIATOR AND HOSES, VACUUM A/C SYSTEM AS WELL AS REFILL A/C GAS.                                                                                                                            | 1 PC | 100.00 |
| 35 | TO DISMANTLE ALL DAMAGED PARTS.T0 CUT & WELD RADIATOR SUPPORT PANEL,BRACE PANEL,FRONT BUMPER REINFORCEMENT,FRT BUMPER TOP BEAM CTR,SIDE BRACKET,HEADLAMP TOP PANEL.TO KNOCK & REPAIR FRT DOOR,FRT WHEELHOUSE SIDE PANEL, FRT CHASSIS FRAME | 1 PC | 800.00 |
| 36 | TO SPRAY FRT BONNET,FRT BUMPER,FRT BUMPER REINFORCEMENT,FRT BUMPER TOP BEAM CTR,FRT BUMPER SIDE BRACKET,BRACE PANEL,RADIATOR SUPPORT PANEL,HEADLAMP TOP PANEL,FRT FENDER, FRT DOOR,FRT CHASSIS FRAME,FRT WHEELHOUSE PANEL.                 | 1 PC | 700.00 |

1,620.00

|                      |              |
|----------------------|--------------|
| Amount Before Excess | S\$ 7,423.00 |
| Less Excess          | S\$ 500.00   |
| Amount Before GST    | S\$ 6,923.00 |
| Add GST @ 7%         | 484.61       |
| Total Amount payable | S\$ 7,407.61 |

TOTAL: SINGAPORE DOLLAR SEVEN THOUSAND FOUR HUNDRED AND SEVEN AND CENTS SIXTY ONE ONLY

The above vehicle was surveyed by GUO XIANG - LKK on 27/11/2017

For AH LIM MOTOR COMPANY  
AH LIM MOTOR COMPANY  
No. 10 Ang Mo Kio Industrial Park 2A  
#01-09 AMK Autopoint Singapore 568047  
Tel: 6483 1244 Fax: 6483 6170  
AUTHORISED SIGNATURE

E. & O. E.