



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

AXA Insured's Veh No : GR2925R

Date of Accident : 22 November 2017

Mr Fam Kim Meng

Date : 23 November 2017

LKK

Estimate To Repair SJG8741L - Subaru Legacy Sedan 2.5GT
Chassis No : JF1BL9KV58G037277

S/No	Quantity	Description	Amount
<u>LIST ITEMS</u>			
01	1 pc	n/s front fender <i>rolled</i>	\$ 564.40
02	1 pc	n/s front fender inner cowling <i>17</i>	\$ 238.00
03	6 ps	n/s front fender inner cowling clips @ \$3.80 <i>17</i>	\$ 22.80
04	1 pc	front bumper <i>Def/Deep cut</i>	\$ 660.00
05	1 pc	n/s front bumper side retainer <i>500</i>	\$ 35.80
06	10 ps	front bumper clips @ \$3.80 <i>new</i>	\$ 38.00
07	1 pc	n/s headlamp <i>one 2150</i>	\$ 2,280.00
			\$ 3,839.00
Less 10% <i>20%</i>			\$ 383.90
			\$ 3,455.10
<u>LABOUR & MISC. CHARGES</u>			
01		To check electrical lighting concerned.	\$ 60.00
02		To rust-proofing of the affected areas.	\$ 50.00
03		To check steering geometry and computer wheel alignment.	\$ 120.00
04		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 500.00
05		Putty and spray painting of the affected portion.	\$ 700.00
			\$ 1,430.00
Total			\$ 4,885.10

not Acknowledged
h/k
h/s #2750
3 day
like ph. After up
27/11/17

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: