

ASS. REC. BY:

REF:

CS/ALH17022508/Kfbnz

Special Instruction:

Surveyor:

Kenneth

ASSIGNMENT (Office)

From (Person):

Ashley Chan

of

All

Date/Time: 24.11.2017 4:28pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBG 50700

Insured:

SJZ 30H

at Workshop m/s

T & B Motor

Tel:

6458 0296

of

160 Sin Ming Dme #08-13

Policy No:

Claim No:

841007059136003

Sum Insured:

Excess:

Make of Veh:

D.O.A.

23.11.2017

(Client's Record)

27.11.2017

CA / REV / REP. / REV 24 HRS Wp

H.O.D. Endorsement:

Date/Time:

24.11.2017 4:30pm

Person Contacted:

Judy

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	GBG 50700 - X
	SJZ 30H - CS/TEL11013112/Ryn
	DOA: 05092011
1/3	11/24 @ 39000 Confirm (Red: 6522.47: 62%)

REF: ALH

ASSIGNMENT

From: Date: 27.11.2017

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: GBG 5070D
at Workshop m/s T & B Motor
of 160 Sim Ming Drive #08-03

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Report: Consistent?: Yes or No

GIA / PR Seen: Consistent?: Yes or No

Est. Repairs: 04 days Res.: Yes or No

Lum Sum: 76 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: GBG 5070D Regn: 08 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Ty Dyno c.c. 2982

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 10252 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JTFA7354-70K208562

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195R-75R15

R: 155R12x8(10)

ES / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 3 mm

L/Bal. 3 mm

D.O.A. 23/11/17

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S 17

The U/C / Chassis frame / Body Structure affected due to collision.

Rear

R/Bal. 8 8 mm

L/Bal. 8 8 mm

D.O.I. 27/11/17

Date / Time Action / Instruction

28/11 15h pass to Customer

RECEIVED 01 MAR 2018

Date/Time, File Pass to?

1) 1/3 Typist

Date/Time, File Return to?

2)

☐ : Preli. Report
☒ : Final Report

Days Of Repair: 4

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

\$ + RS \$

Photos

Others

TOTAL

Add Fee:

☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Report Format: TP

Lump Sum / I.B.I. (\$) 3900

250

20

270



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CS/AIG17022508/Ktb

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 27-11-2017



Code : AIG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJZ 30H	Veh. Inspected	GBG 5070D
Policy No.		Coverage (\$)	0.00
Claim No.	8410020591SG003	Excess (\$)	0.00
Assign From	ASHLEY CHAN	Assign Date	24/11/2017

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	23/11/2017	Inspection Date	27/11/2017
Survey held at	160 SIN MING DRIVE #08-03		
Repairer	T & B MOTOR REPAIRS SERVICES PTE LTD		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

- Pre repair inspection request - GBG5070D VS SJZ30H (OI) DOA 23/11/2017

From: Chan, Yoke Shi
To: assignments@kkauto.com, admin-a@kkauto.com
Cc: Tan, Lily (AIG), Fong, Andy-SY, Kaur, Baljit, Chin, Lee-Ying, Abu Kassim, Noor Mariesa, Md Ishak, Mohd Imran, Lim, Sheng Yang, Loo, Kar Yong, Fan, Winnie-LW
Sent: Friday, 24 November, 2017 4:28:35 PM
Attachments: 0036 - HQA PDF QIA report - GBG5070D ITP Claim 24Nov17.pdf

Hi,

Please refer to the enclosed request from **Cheonghoh Law**.

Claim no : 8410020591SG003
Case Owner : BENNIE TAN WEI ZHONG

If you have any queries/concerns, please let us know.
Kindly assist to assign Kenneth Kong as Single Joint Expert as requested.

Thank you.

Regards,

Yoke Shi @ Ashley
AIG
Claim Adjuster II, Singapore FNOL, Claims Operations – Auto
Shared Services – Malaysia | Global Business Services

AIG Shared Services (M) Sdn Bhd (887191-D)
Menara Worldwide, Level 12, 198 Jalan Bukit Bintang, 55100 Kuala Lumpur, Malaysia
Tel +6 03 2719 6000 | Ext 1012102

yokeshi.chan@aig.com www.aig.com

From: Cheonghoh Law [mailto:mail@cheonghoh.sg]
Sent: Friday, November 24, 2017 4:23 PM
To: Chan, Yoke Shi
Cc: Tan, Lily (AIG); Fong, Andy-SY; Kaur, Baljit; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Md Ishak, Mohd Imran; Lim, Sheng Yang; Loo, Kar Yong; Fan, Winnie-LW
Subject: Re: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SJZ30H AND GBG5070D ON 23/11/2017

Dear Mdm,

We refer to the above matter and to your email of even date.

Our client hereby nominate Kenneth Kong from LKK Auto Consultants Pte Ltd of your said letter to conduct the pre-repair survey of the damages to our client's vehicle arising out of the above mentioned accident.

Please be informed that our client's vehicle is currently laying at our client's workshop, T & B Motor Repairs Services Pte Ltd, Blk 160 Sin Ming Drive #08-03 Sin Ming Auto City Singapore 575722. Kindly proceed to do the needful and you may contact the person in charge Mr Tay at 6458 0296 before your surveyor attend at the said workshop.

Thanks & regards,
Rayline
CHEONGHOH LAW CORPORATION
Blk 53 Chin Swee Road #03-05 Singapore 160053
T: 6337 8700 | F: 6337 3700 | E: mail@cheonghoh.sg

On 24 Nov 2017, at 2:45 PM, Chan, Yoke Shi <yokeshi.chan@aig.com> wrote:

Without Prejudice

Your Reference : GBG5070D
Our Reference : 8410020591SG003

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We i n t e n d t o c o n d u c t a p r e - repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached repair survey as a single joint expert.

Name of Surveyor	Company Name
Lim Kok Chong	AIG Asia Pacific Insurance Pte Ltd
Kumar Uthaya	AIG Asia Pacific Insurance Pte Ltd
Ken Wong	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd

Ricky Teng	RT Appraisal Pte Ltd
Elson Teng	RT Appraisal Pte Ltd
Michael Cheong	RT Appraisal Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Henry Ng	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Steven Foong	LKK Auto Consultants Pte Ltd
Wei Jie	LKK Auto Consultants Pte Ltd
Ma Chin Fook	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thank you.

Regards,

Yoke Shi @ Ashley

AIG

Claim Adjuster II, Singapore FNOL, Claims Operations – Auto
Shared Services – Malaysia | Global Business Services

AIG Shared Services (M) Sdn Bhd (887191-D)

Menara Worldwide, Level 12, 198 Jalan Bukit Bintang, 55100 Kuala Lumpur, Malaysia
Tel +6 03 2719 6000 | Ext 1012102

yokeshi.chan@aig.com | www.aig.com

<70936 - NOA.PDF><GIA report - GBG5070D (TP Claim)24Nov17.pdf>

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	23/11/2017 17:52
Date Of Accident	23/11/2017 08:30
Exact Location Of Accident	ANCHORVALE ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBG5070D
Insured/Policyholder	
Name Of Registered Owner	SIONG HONG SEAFOOD ENTERPRISE
Co Reg No	201222170D
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-67531788
Vehicle Particulars	
Manufacturer	TOYOTA
Model	DYNA
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE
Insurance Company	
Name of Insurance Company	GREAT AMERICAN INSURANCE COMPANY
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	MOMVC000005913-00-000
Cover Note Number	
Driver	
Name of Driver	ONG YONG SOON
NRIC No	S0191876A
Date Of Birth	02/01/1953
Occupation	INDOOR
Date Of Driving Pass	17/12/1977
Driving Experience	39 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address	BLK 526 WOODLANDS DRIVE 14 #04-467
Postcode	730526
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJZ30H
Vehicle Make/Model/Colour	MERCEDES BENZ
Details Of Properties	
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Details of Witness

Name	
Phone Number	
Email Address	

Sketch Plan Pg. 1

SKETCH PLAN


IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) in law complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:


Driver's Signature
(if driver is not the policyholder)
Date & Time:

73/11/70
3-45p

Reporting Centre Personnel's Signature
Name:
NRE/RII No:

Sketch Plan Pg. 2


SKETCH PLAN

A: GBC9 5070 D

B: SJZ 30 H

TIME: 8 30AM

DATE: 23/11/17



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

ON 23/11/17 AT ABOUT 8.30AM I WAS DRIVING ALONG ANCHORVALE ROAD ON THE MOST RIGHT LANE TURNING INTO SENGKANG E WAY ON MY RIGHT. WHEN I WAS TURNING A VEHICLE SJZ 30 H CAME FROM MY LEFT AND HIT ON TO MY VEHICLE FRONT LEFT PORTION. NOBODY WAS INJURED.

* Repair at other workshop *



Police Officer's Signature
Date & Time

Driver's Signature
(If driver is not the policyholder)
Date & Time

23/11/17
5:45pm

Reporting Centre Personnel's Signature
Name
NCC 2474

T & B MOTOR REPAIRS SERVICES PTE LTD

Page 1 / 2

160 SIN MING DRIVE #08-03 SIN MING AUTOCITY SINGAPORE 575722

Tel No. : 6458 0296 / 6454 8007 Fax No. : 6554 2640

E-Mail : tbmotor@hotmail.sg

Buss. Reg. No. : 199001597D

WITHOUT PREJUDICE

SIONG HONG SEAFOOD ENTERPRISE PTE LTD

15 WOODLANDS LOOP #03-54 /56
738322

Attention : Motor Claim Department

Estimate : ES003278

Date : 23/11/2017

Vehicle Num. : GBG5070D

Make/Model : TOYOTA DYNA 150

Chassis/Eng# :

Accident Date : 23/11/2017

Claim No. :

Reference :

Policy No. : MOMVC00000-5913-00-000

*Not Authorize
U/Ly & 390d
Resurvey After Paint
4 days*

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.		FRONT DOOR LH	1,873.30	✓
2.		FRONT DOOR INNER LOCK LH	333.63	X
3.		FRONT DOOR GLASS OUTER MOULDING LH	119.35	X
4.		FRONT DOOR WEATHERSTRIP LH	197.60	X
5.	(FRONT)	FRONT DOOR INNER RUBBER LH	170.20	X
6.	(LOWER)	FRONT DOOR INNER RUBBER LH	191.62	X
7.		FRONT DOOR LOWER HINGE LH	99.66	X
8.		FRONT DOOR TOP HINGE LH	99.66	X
9.		FRONT SIDE GARNISH LH	237.22	✓
10.		FRONT SIDE GARNISH BRACKET L/H	115.67	X
11.		FRONT HEAD LAMP L/H	1,210.75	✓
12.		FRONT BUMPER	792.88	✓
13.		FRONT BUMPER BRACKET LH	250.90	X
14.		FRONT STEP GARNISH LH	319.22	✓
15.		FRONT ARCH PANEL CONNER RUBBER L/H	121.77	X
16.		AIRCON CONDENSER	860.42	X
17.		AIRCON CONDENSER FAN MOTOR (ASSY)	1,094.50	X
18.		AIRCON CONDENSER BRACKET L/H	357.94	✓
19.		FRONT DOOR SPEAKER	369.23	X
20.		AIRCON CONDENSER HIGH PRESSURE PIPE	670.78	X
21.		FRONT BUMPER SPORT LIGHT GARNISH L/H	66.33	X
List Total S\$:			9,552.63	
25.00% Discount S\$:			2,388.16	
			7,164.47	
LABOUR :				
1. FRONT DOOR STICKER			28.00	✓

CONTINUE / ...

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

T & B MOTOR REPAIRS SERVICES PTE LTD

Page 2 / 2

160 SIN MING DRIVE #08-03 SIN MING AUTOCITY SINGAPORE 575722

Tel No. : 6458 0296 / 6454 8007 Fax No. : 6554 2640

E-Mail : tbmotor@hotmail.sg

Buss. Reg. No. : 199001597D

WITHOUT PREJUDICE

SIONG HONG SEAFOOD ENTERPRISE PTE LTD

15 WOODLANDS LOOP #03-54 /56

738322

Attention : Motor Claim Department

Estimate : ES003278

Date : 23/11/2017

Vehicle Num. : GBG5070D

Make/Model : TOYOTA DYNA 150

Chassis/Eng# :

Accident Date : 23/11/2017

Claim No. :

Reference :

Policy No. : MOMVC00000-5913-00-000


S/N	Quantity	Particular	Unit Price	Amount S\$
		2. CHECK & REPAIR WIRING		200
		3. SPRAY ANTI-RUST COATING	300	100.00
		4. REMOVE & REFIX FRONT DOOR GLASS	600	150.00
		5. COMPUTER WHEEL ALIGNMENT AND COMPUTER HIGH SPEED TYRE BALANCING	22	130.00 *
		6. SPRAY PAINTING ON AFFECTED PORTIONS	550	1,200.00
		7. LABOUR CHARGE FOR REPAIRING, REPLACING, ADJUSTING, KNOCKING AND WELDING THE DAMAGED PARTS, STRAIGHTEN THE ABOVE	600	1,500.00
		Labour Total S\$:		3,258.00

SingDollars : Ten Thousand Four Hundred Twenty-Two & Cents Forty-Seven Only

E. & O.E.

Total S\$: 10,422.47

=====


for T & B MOTOR REPAIRS SERVICES PTE LTD

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG17022508/KTBN2

Date: 02/03/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant Vehicle No: GBG5070D Insured Vehicle No: SJZ30H

Date of Loss: 23/11/2017 Nature of Claim: TP Claim No: 8410020591SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GBG5070D Engine No: 1KD2733320

Make & Model: TOYOTA DYNA 150, 3.0 D (M) Chassis No: JTFAT35Y70K208562

Reg. Date: 21/08/2017 (Man. Year: 2017) Odometer: 10252 km

Colour: Blue

Engine Capacity: 2982 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 195R75R15 Rear Tyre Size: 155 R12X8 (D)

Front Left Side: Bridgestone 9 mm Rear Left Side: Bridgestone 8/8 mm

Front Right Side: Bridgestone 9 mm Rear Right Side: Bridgestone 8/8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	7,192.47	3,613.48	3,578.99	49.76
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,230.00	1,260.00	1,970.00	60.99
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	10,422.47	4,873.48	5,548.99	53.24
Approved Total (Overridden) (\$\$)		3,900.00		
Nett Amount (\$\$)	10,422.47	3,900.00	6,522.47	62.58

INSPECTION

Date of Assignment: 24/11/2017

Date Inspected: 27/11/2017 Inspected At: T & B Motor Repairs Services Pte Ltd (HQ)
Blk 20, #01-28, Sin Ming Road
Singapore 575678

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR LH	Bent	1,873.30 FL	*1,873.30 FL
2	1		*FRONT DOOR INNER LOCK LH	Repair	333.63 FL	*- FL
3	1		*FRONT DOOR GLASS OUTER MOULDING LH	Serviceable	119.35 FL	*- FL
4	1		*FRONT DOOR WEATHERSTRIP LH	Serviceable	197.60 FL	*- FL
5	1		*FRONT DOOR INNER RUBBER LH	Serviceable	170.20 FL	*- FL
			(FRONT)			
6	1		*FRONT DOOR INNER RUBBER LH LOWER	Serviceable	191.62 FL	*- FL
7	1		*FRONT DOOR LOWER HINGE LH	Repair	99.66 FL	*- FL
8	1		*FRONT DOOR TOP HINGE LH	Repair	99.66 FL	*- FL
9	1		*FRONT SIDE GARNISH LH	Cut	237.22 FL	*237.22 FL
10	1		*FRONT SIDE GARNISH BRACKET LH	Repair	115.67 FL	*- FL
11	1		*FRONT HEAD LAMP LH	Cut	1,210.75 FL	*1,210.75 FL
12	1		*FRONT BUMPER	Bent	792.88 FL	*792.88 FL
13	1		*FRONT BUMPER BRACKET LH	Repair	250.90 FL	*- FL
14	1		*FRONT ARCH PANEL CONNER RUBBER L/H	Serviceable	121.77 FL	*- FL
15	1		*FRONT STEP GARNISH LH	Dented/Cut	319.22 FL	*319.22 FL
16	1		*AIRCON CONDENSER	Serviceable	860.42 FL	*- FL
17	1		*AIRCON CONDENSER FAN MOTOR (ASSY)	Serviceable	1,094.50 FL	*- FL
18	1		*AIRCON CONDENSER BRACKET L/H	Distorted	357.94 FL	*357.94 FL
19	1		*FRONT DOOR SPEAKER	Serviceable	369.23 FL	*- FL
20	1		*AIRCON CONDENSER HIGH PRESSURE PIPE	Serviceable	670.78 FL	*- FL
21	1		*FRONT BUMPER SPORT LIGHT GARNISH L/H	Serviceable	66.33 FL	*- FL
22	1		*FRONT DOOR STICKER	Necessary	28.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	9,580.63	4,811.31
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,388.16	1,197.83
Total Parts (\$\$)	7,192.47	3,613.48

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CHECK & REPAIR WIRING	New	100.00	20.00
2	SPRAY ANTI-RUST COATING	New	150.00	30.00
3	REMOVE & REFIX FRONT DOOR GLASS	New	150.00	60.00
4	COMPUTER WHEEL ALIGNMENT AND COMPUTER HIGH SPEED TYRE BALANCING	New	130.00	-
5	SPRAY PAINTING ON AFFECTED PORTIONS	New	1,200.00	550.00
6	LABOUR CHARGE FOR REPAIRING, REPLACING, ADJUSTING, KNOCKING AND WELDING THE DAMAGED PARTS, STRAIGHTEN THE ABOVE	New	1,500.00	600.00
Gross Labour Cost (S\$)			3,230.00	1,260.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >