

22/03/2002

ASS. REC. BY:

REF: CS/CY17022509/Kgber

Special Instruction:

Supervisor: Kenneth

## ASSIGNMENT (Office)

From (Person):

Irene Tay

of

CTI

Date/Time: 27/11/17 @ 9:55am

Estimated Cost:

Bill to:

OD ~~TP~~ / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SIN 5642Y

Insured:

GBG 2581R

at Workshop m/s

City Auto

Tel:

6463 1235

of

Blk 160 Sin Ming Ind. Est # 01-60/62

Policy No:

PMCVSN174701700

Claim No:

SNM17D0677502

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

22/11/2017

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

10:17am @ 27/11/17

Person Contacted:

Vronica

Vehicle: IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SIN 5642Y - X
	GBG 2581R - X
7/12	11 Lm & 7500 enrol
	8/1001
8/12	11 Lm & 8/1001 Calmmed Vronica (Red & 9186, 53%)

ASS. REC. BY:

REF: C72/

Kenneth

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

08 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: NII / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or

Front

Rear

R/Bal.

R/Bal.

L/Bal.

L/Bal.

D.O.A.

D.O.I.

Survey held at

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

28/11

File pass to Customer

Date/Time, File Pass to?

1) 08/12 Trans

Date/Time, File Return to?

2)

: Prell. Report

: Final Report

Days Of Repair: 8

Resurvey No. of Trip: 1

Add Fee:

: Site Insp (\$

: Interview (\$

: Tech. Invs (\$

: Weekend (\$

Survey Fee:

Transportation:

S + RS SI

Photos

Others

TOTAL

Report Format:

Lump Sum / I.B.I. (\$

MER-TP

8100

200

200




# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CS/CTI17022509/Kqb		
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 27-11-2017		
		Code : CTI		
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	GBG 2581R	Veh. Inspected	SJN 5642Y	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From	IRENE TAY	Assign Date	27/11/2017	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
<b>4. Description of Damages</b>				
<b>5. General Information</b>				
Accident Date	22/11/2017	Inspection Date	27/11/2017	
Survey held at	BLK 160, # 07-10, 575722			
Repairer	CITY AUTO PTE LTD			
<b>5a. Remarks</b>				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Reference No.: C9/CT117022509/K96  
Policy Type: OD / (TP) TP RES / TL / EVA

SJN 56424

**Typist**

**Admin (Cathy):** Case handler to make sure all information created by the assignment team are **ACCURATE**.

[illegible]

- |   |                                       |
|---|---------------------------------------|
| C | Reference No.                         |
| C | Customer Code                         |
| N | Assign From                           |
| C | Assign Date                           |
| C | Veh No (Inspected)                    |
| C | Veh No (Insured)                      |
| C | D.O.A                                 |
| C | Policy No                             |
| C | Claim No                              |
| C | Insurance Authorisation (CA /REV/REP) |
| C | Report Type                           |
| C | Weekend Charges                       |
| N | Survey held at/Repairer               |
| C | Excess                                |

**(1) Assignment Form**



- |   |                        |
|---|------------------------|
| C | Vehicle No             |
| C | Regn Month/Year        |
| N | Vehicle Type           |
| N | Make & Model           |
| C | Engine Capacity. (C.C) |
| N | Colour                 |
| C | Odometer. (Sp.Reading) |
| C | Chassis No             |
| N | General Condition      |
| N | Steering               |
| N | Brake                  |
| N | Modification (Modi)    |
| C | Tyre Size              |
| N | Tyre Make              |
| C | Tyre Balance           |
| C | Date of Inspection     |
| N | Survey held            |
| N | Des.of Damages         |

[illegible]

C Damaged Vehicle Photographs Uploaded

--	--	--	--

- N ALL Parts condition
- C Market Value for OD cases
- C Estimate Repair Cost for PRI (RSI, TMI, MSIG)
- C Days of repair
- C Finalised Amount
- C Re-inspection Cases to Finalize within 5 Days


C Resurvey photo Uploaded

[illegible]

men  
o Uploaded

*Ch* 08/27/18

--	--

Case Handler Date

Date \_\_\_\_\_

21/05/2014

**Nivitha (LKK Auto)**

---

**From:** Irene Tay <irene.tay@sg.cntaiping.com>  
**Sent:** Monday, 27 November, 2017 9:55 AM  
**To:** City Auto; assignments@lkkauto.com  
**Cc:** assignments@lkkauto.com  
**Subject:** CTP REF NO. GBG2581R CITYAUTO REF NO. SJN5642Y - ACCIDENT INVOLVING GBG2581R AND SJN5642Y ON 22 NOVEMBER 2017

**WITHOUT PREJUDICE**

Dear Sir/Mdm,

We refer to the above matter and the email below.

Please assist to get your surveyor, Kenneth to liaise with City Auto.

Regards

**Irene Tay**

Claims Department  
China Taiping Insurance (Singapore) Pte. Ltd.  
3, Anson Road, #16-00  
Springleaf Tower,  
Singapore 079909  
Co. Reg. No. 200208384E  
DID: 6389-6192  
Fax: 6224 7175  
Email: [claimsdept@sg.cntaiping.com](mailto:claimsdept@sg.cntaiping.com)  
Email: [irene.tay@sg.cntaiping.com](mailto:irene.tay@sg.cntaiping.com)  
Website: [www.sg.cntaiping.com](http://www.sg.cntaiping.com)

**From:** City Auto [mailto:cityauto@singnet.com.sg]  
**Sent:** Monday, 27 November, 2017 9:15 AM  
**To:** Irene Tay <irene.tay@sg.cntaiping.com>  
**Subject:** RE: CTP REF NO. GBG2581R CITYAUTO REF NO. SJN5642Y - ACCIDENT INVOLVING GBG2581R AND SJN5642Y ON 22 NOVEMBER 2017

Dear Irene,

Kindly arrange Surveyor Kenneth to survey.

Thank you.

***Best Regards,***

***Vronica Law***

*City Auto Pte Ltd  
Blk 8 Sin Ming Industrial Estate,  
#01-60/62 Sin Ming Road,  
Singapore 575643  
Tel : 6453 1235  
Fax : 6453 7944*

**From:** Irene Tay [<mailto:irene.tay@sg.cntaiping.com>]

**Sent:** Monday, 27 November, 2017 9:11 AM

**To:** City Auto

**Cc:** City Auto

**Subject:** CTP REF NO. GBG2581R CITYAUTO REF NO. SJN5642Y - ACCIDENT INVOLVING GBG2581R AND SJN5642Y ON 22 NOVEMBER 2017

**Without Prejudice**

**Save As To Costs**

Dear Sir/Mdm,

We refer to your pre-repair survey request / email.

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop.

Here are the list of surveyors ;

**Tay Beng Hee**

**See Chew Seng**

**Dereck Oh Siong Wee**

**Mohd Fadhilah Bin Osman**

**Kalvin Ang**

**Bryan Ang**

**Steven Foong**

**Adrian Ling**

**Marcus Chua**

**Kenneth Kong**

**Henry Ng**

We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Thank you.

Regards,

**Irene Tay**

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3, Anson Road, #16-00

Springleaf Tower,

Singapore 079909

Co. Reg. No. 200208384E

DID: 6389-6192

Fax: 6224 7175

Email: [claimsdept@sg.cntaiping.com](mailto:claimsdept@sg.cntaiping.com)

Email: [irene.tay@sg.cntaiping.com](mailto:irene.tay@sg.cntaiping.com)

Website: [www.sg.cntaiping.com](http://www.sg.cntaiping.com)

**From:** Tee Sunny [<mailto:sunny@wahhong.sg>]

**Sent:** Friday, 17 November, 2017 2:10 PM

**To:** Claims Dept of CTI <[claimsdept@sg.cntaiping.com](mailto:claimsdept@sg.cntaiping.com)>; Irene Tay <[irene.tay@sg.cntaiping.com](mailto:irene.tay@sg.cntaiping.com)>

**Cc:** Wah Hong Motors (Nicholas Tee) <[nicholas@wahhong.sg](mailto:nicholas@wahhong.sg)>; Wah Hong Motors (Michael Tee) <[michael@wahhong.sg](mailto:michael@wahhong.sg)>

**Subject:** Re: Pre-Repairs Assessment Request for SJM9058M - Accident with SCR6656M (China Taiping) on 2017-11-12 - our case no. 171111

Hi Irene

Here are the files.

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---

Here are the files.

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---



## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type	Singapore NRIC
Owner ID	8562B

### Vehicle Details

Vehicle No.	SJN5642Y
Vehicle to be Exported	Yes
Intended De-registration Date	29 Nov 2017
Vehicle Make	HONDA
Vehicle Model	CROSSROAD 1.8L A
Primary Colour	Black
Manufacturing Year	2008
Engine No.	R18A3011471
Chassis No.	RT11008440
Maximum Power Output	103.0 kW (138 bhp)
Open Market Value	\$23,861.00
Original Registration Date	19 Feb 2009
First Registration Date	19 Feb 2009
Transfer Count	0
Actual ARF Paid	\$23,861.00

### Intended PARF Rebate Details

PARF Eligibility	Yes
PARF Eligibility Expiry Date	18 Feb 2019
PARF Rebate Amount	\$13,123.00

### Intended COE Rebate Details

COE Expiry Date	18 Feb 2019
COE Category	B - Car (1601cc & above)
COE Period(Years)	10
QP Paid	\$689.00
COE Rebate Amount	\$84.00
<b>Total Rebate Amount</b>	<b>\$13,207.00</b>

The information contained herein is correct as at 29 Nov 2017

OK



Please read through the [Privacy Statement](#), [Terms of Use](#), and [Disclaimer](#).

Please do not use the Back or Forward buttons on your browser as this may alter the results of the transactions.

Best viewed with IE 10 and above, Chrome, Firefox, and Safari.

Copyright 2017 LTA [Privacy Statement](#) [Terms of Use](#) [Disclaimer](#) [Rate the Website](#) [Rate this e-Service](#)

Last updated on 19 Nov 2017 at 12:12 AM

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	23/11/2017 17:13
Date Of Accident	22/11/2017 18:20
Exact Location Of Accident	ALONG SLE TOWARDS CTE(CITY)
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJN5642Y
<b>Insured/Policyholder</b>	
Name Of Registered Owner	TAN SEW LAN
NRIC No	S1828562B
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-93662009
Alternative Phone No	OTHERS-93662009

### Vehicle Particulars

Manufacturer	HONDA
Model	CROSSROAD-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	ALLIED WORLD ASSURANCE COMPANY, LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	AVPCSB0315861701
Cover Note Number	

### Driver

Name of Driver	CHEOW SIEW MEI (ZOU XIUMEI)
NRIC No	S7337489H
Date Of Birth	25/09/1973
Occupation	OUTDOOR
Date Of Driving Pass	13/07/1995
Driving Experience	22 YEARS AND 4 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-93662009
Fax Number	
Contact Number	
Email Address	CERLIACHEOW@POLAR.COM.SG

Vehicle Make/Model/Colour

Details Of Properties

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

**Details of Witness**

Name

Phone Number

Email Address

**DETAILS OF OTHER VEHICLE PROPERTY 3**

Vehicle Registration Number SLT996D

Vehicle Make/Model/Colour

Details Of Properties

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

**Details of Witness**

Name

Phone Number

Email Address

**DETAILS OF OTHER VEHICLE PROPERTY 4**

Vehicle Registration Number GZ337J

Vehicle Make/Model/Colour

Details Of Properties

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

**Details of Witness**

Name

Phone Number

Email Address

## Sketch Plan #2 Pg. 1

### SKETCH PLAN

C B E D E  
 1 1 1 1 1  
 →  
 8 2 8  
 B 1000000  
 D 1000000  
 A 1000000

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

There was 5 vehicles chain accident

## DECLARATION

We declare the foregoing rules are true in every respect

Salmon Creek, California  
July 1, 1900

Order's Signature \_\_\_\_\_  
 Product Name and Manufacturer Code \_\_\_\_\_  
 Date & Time \_\_\_\_\_

Department of Psychology, University of Illinois at Chicago  
3121 S. Maryland Ave., Chicago, IL 60607-7131  
Tel: 312/996-3000  
Fax: 312/996-3000  
E-mail: jk@uic.edu



# CITY AUTO PTE LTD

BLK 8, SIN MING IND. ESTATE, #01-60/62, SIN MING ROAD, SINGAPORE 575643.

TEL: 6453 1235, 6452 0850 FAX: 6453 7944

24hrs Towing Services Tel: 9823 9898

Co. Reg. No.: 199503435C GST Reg. No.: M2-8920979-4

China TaiPing Insurance (Singapore) Pte Ltd

3 Anson Road

#16-00 Springleaf Tower Singapore 069534

Attention : Motor Claim Department

Contact : 62222366 Fax No. : 62247175

Estimate : ES004845

Date : 24/11/2017

Vehicle Num. : SJN 5642Y

Make/Model : Honda Crossroad

Chassis/Eng# : RT1-1008440

Accident Date : 22/11/2017

Claim No. : TP CHINA TAIPING

Reference : -

Policy No. : AVPCSB0315861701

*Not for repair  
11 Day @ 81000  
Repair After Rain  
8 days*

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

## LIST ITEMS :

- |     |   |                             |
|-----|---|-----------------------------|
| 1.  | 1 | Tailgate                    |
| 2.  | 1 | Tailgate logo               |
| 3.  | 1 | Tailgate emblem - Crossroad |
| 4.  | 1 | Tailgate outer garnish      |
| 5.  | 1 | Tailgate weatherstrip       |
| 6.  | 1 | Tailgate lock               |
| 7.  | 1 | Tailgate damper             |
| 8.  | 1 | Tailgate outer handle       |
| 9.  | 1 | Tailgate glass sealant      |
| 10. | 1 | Tailgate glass moulding     |
| 11. | 2 | Rear number plate light     |
| 12. | 1 | Rear wiper motor            |
| 13. | 1 | Rear wiper arm              |
| 14. | 1 | Rear bumper                 |
| 15. | 1 | Rear bumper towing cover    |
| 16. | 1 | Rear bumper pad cover -LH   |
| 17. | 1 | Rear bumper pad cover -RH   |
| 18. | 2 | Rear bumper bracket         |
| 19. | 2 | Rear bumper retainer        |
| 20. | 1 | Rear bumper reflector - LH  |
| 21. | 8 | Rear bumper clip            |
| 22. | 2 | Rear bumper lower bracket   |
| 23. | 1 | Rear bumper lower beam      |
| 24. | 1 | Taillamp -LH                |

R1	1,247.00	✓
mc	35.50	✓
mc	58.00	✓
cm	535.30	✓
sm	185.00	X
DA	109.40	✓
sm	195.00	X
sm	53.40	X
mc	25.00	✓
mc	85.00	✓
32.80	sm	65.60 X
	sm	550.00 ✓
	sm	85.00 X
R1	1,050.40	✓
mc	20.50	✓
Bu	180.00	✓
sm	180.00	X
R	28.00	✓
NIPIS	27.50	✓
cm	50.00	✓
3.80	mc	30.40 ✓
28.00	mc	56.00 ✓
	mc	70.00 ✓
sm	435.00	X

CONTINUE / ...

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:



# CITY AUTO PTE LTD

BLK 8, SIN MING IND. ESTATE, #01-60/62, SIN MING ROAD, SINGAPORE 575643.  
 TEL: 6453 1235, 6452 0850 FAX: 6453 7944  
 24hrs Towing Services Tel: 9823 9898  
 Co. Reg. No.: 199503435C GST Reg. No.: M2-8920979-4

China TaiPing Insurance (Singapore) Pte Ltd  
 3 Anson Road  
 #16-00 Springleaf Tower Singapore 069534

Attention : Motor Claim Department  
 Contact : 62222366 Fax No. : 62247175

## Estimate : ES004845

Date : 24/11/2017  
 Vehicle Num. : SJN 5642Y  
 Make/Model : Honda Crossroad  
 Chassis/Eng# : RT1-1008440  
 Accident Date : 22/11/2017  
 Claim No. : TP CHINA TAIPING  
 Reference : -  
 Policy No. : AVPCSB0315861701

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

25.	1	Rear exhaust muffler	B <sub>1</sub> 980.00	X
26.	1	Rear exhaust heatshield	B <sub>1</sub> 85.00	X
27.	1	Rear end panel	R 510.70	X
28.	1	Rear end panel top garnish	R 240.70	X
29.	1	Bonnet	B <sub>1</sub> 785.60	X
30.	1	Bonnet lock	R 75.00	X
31.	1	Front bumper - upper	B <sub>1</sub> 1,308.60	X
32.	2	Front bumper bracket	57.00 R 114.00	X
33.	2	Front bumper retainer	MSD 30.50 61.00	X
34.	1	Front bumper pad cover - LH	R 235.00	X
35.	1	Front bumper pad cover - RH	S 235.00	X
36.	1	Front bumper reinforcement	B <sub>1</sub> 330.60	X
37.	1	Front bumper centre	S 533.20	X
38.	1	Front bumper mesh - LH	S 115.00	X
39.	1	Front bumper mesh - RH	S 115.00	X
40.	10	Front bumper clip	3.80 R 38.00	X
41.	1	Front grille base	S 280.00	X
42.	1	Front grille garnish	S 225.00	X
43.	6	Front grille clip	3.80 R 22.80	X
44.	1	Front grille logo	R 24.00	X
45.	2	Headlamp	S 875.00 1,750.00	X
46.	2	Headlamp lower bracket	57.00 R 114.00	X
47.	1	A/C Condenser	R 866.80	X
List TotalS\$ :			14,457.50	
20.00% Discount S\$ :			2,891.50	
			11,566.00	

CONTINUE / ...



# CITY AUTO PTE LTD

BLK 8, SIN MING IND. ESTATE, #01-60/62, SIN MING ROAD, SINGAPORE 575643.  
 TEL: 6453 1235, 6452 0850 FAX: 6453 7944  
 24hrs Towing Services Tel: 9823 9898  
 Co. Reg. No.: 199503435C GST Reg. No.: M2-8920979-4

China TaiPing Insurance (Singapore) Pte Ltd  
 3 Anson Road  
 #16-00 Springleaf Tower Singapore 069534

Attention : Motor Claim Department  
 Contact : 62222366 Fax No. : 62247175

## Estimate : ES004845

Date : 24/11/2017  
 Vehicle Num. : SJN 5642Y  
 Make/Model : Honda Crossroad  
 Chassis/Eng# : RT1-1008440  
 Accident Date : 22/11/2017  
 Claim No. : TP CHINA TAIPING  
 Reference : -  
 Policy No. : AVPCSB0315861701

S/N	Quantity	Particular	Unit Price	Amount SS
-----	----------	------------	------------	-----------

- SPECIAL NETT ITEMS :
1. 1 Rear number plate
  2. 1 Rear number plate casing
  3. 4 Reverse sensor
  4. 1 Rear view camera
  5. 1 Front number plate
  6. 1 Front number plate casing
  7. 1 Company advertisement - Sticker

	25.00	} 4500
	35.00	
350.00	1,400.00	} 4000
	350.00	
	25.00	} 4500
	35.00	
	400.00	3000
<b>Special Nett Total SS :</b>		<b>2,270.00</b>

### LABOUR :

- \*To towing
- \*To check wiring and lighting
- \*To remove and refit rear windscreen glass
- \*To supply sealant and reseal all weld spot seam & gaps
- \*To knock jackout damaged parts, panel beating, welding, align, refix and to renew accident parts
- \*Spray painting on affected & replace parts
- \*To pull & realign rear chassis member
- \*To remove and install a/c parts and recharge a/c gas

	50.00	✓
	80.00	400
	150.00	1200
	90.00	X
	1,300.00	7000
	1,450.00	1200
	180.00	X
	150.00	X
<b>Labour Total SS :</b>		<b>3,450.00</b>

E. & O.E.

Total SS : 17,286.00

=====

for CITY AUTO PTE LTD

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	24 Nov 2017		27 Nov 2017 12:51 <a href="#">Edit Adj Rpt</a>	<b>S\$8,100.00</b> <a href="#">Edit Estimates</a>	<b>S\$8,100.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

<b>Main</b>	<b>Reference</b>	<b>Claim Details</b>	<b>Documents</b>	<b>Show All</b>
-------------	------------------	----------------------	------------------	-----------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]			
Insured:	-, Co. Reg. No.: -				
Main Claimant:	<b>TAN SEW LAN</b> , ID: S1828562B				
Vehicle Reg. No.:	<b>SJN5642Y</b>	Date of Loss:	22/11/2017 18:00 - :59		
Claim Type:	<b>TP / SNM17D06775C02</b>	Policy/Cover Note No.:	DMCVSN1747011700		
Vehicle Reg. No. (Insured):	<b>GBG2581R</b>	Policy No. (Claimant):	AVPCSB0315861701		
		Excess:	S\$0.00		
Repairer:	<b>City Auto Pte Ltd ( )</b> Blk 13, Sin Ming Industrial Estate Sector B, #01-47/49, 575657 Sin Ming - Tel:				
Handling Insurer:	<b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Irene Tay Hui Ping</b> - 638986192]				
Claimant's Insurer:	<b>Allied World Assurance Company, Ltd (HQ)</b> - Tel: 62201188				
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>KENNETH KONG</b> ] ... <b>[Final Rpt due 06/12/2017]</b>				
Adj Asg. Remarks:	PLEASE ASSIST TO CONDUCT PRS AND REVERT WITH YOUR RECOMMENDATION				

ASSOCIATED MAIL RECEIVED	<a href="#">View All</a>	<a href="#">Compose Case Mail</a>
There are no mail for this case.		

ALL ASSOCIATED TASKS		<a href="#">View All</a>	<a href="#">Search Tasks</a>	<a href="#">Create New Task</a>	<a href="#">Complete</a>				
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



## Claim Documents

\*SJN5642Y (SNM17D06775C02)

[GBG2581R]

TP

TAN SEW LAN

Nov 22 2017 6:00PM

[-]
















City Auto Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			View <div>View in Browser</div>		
Assessment Reports									1 per page		<input checked="" type="checkbox"/>
No	Finalized On	STA INSPECTION PTE LTD (Sin Ming)							Thumbnail	Print	
1	24/11/17 10:00	Accident Statement						1	Load HTM		
Photos/Images									3 per page		<input checked="" type="checkbox"/>
No	Finalized On	STA INSPECTION PTE LTD (Sin Ming)							Thumbnail	Print	
1	24/11/17 09:57	Accident Photo [Linked Accident Report Documents]						1	Load JPG	<input checked="" type="checkbox"/>	
2	24/11/17 09:57	Accident Photo [Linked Accident Report Documents]						1	Load JPG	<input checked="" type="checkbox"/>	
3	24/11/17 09:57	Accident Photo [Linked Accident Report Documents]						1	Load JPG	<input checked="" type="checkbox"/>	
4	24/11/17 09:57	Accident Photo [Linked Accident Report Documents]						1	Load JPG	<input checked="" type="checkbox"/>	
5	24/11/17 09:57	Accident Photo [Linked Accident Report Documents]						1	Load JPG	<input checked="" type="checkbox"/>	
6	24/11/17 09:57	Accident Photo [Linked Accident Report Documents]						1	Load JPG	<input checked="" type="checkbox"/>	
7	24/11/17 09:57	Accident Photo [Linked Accident Report Documents]						1	Load JPG	<input checked="" type="checkbox"/>	
8	24/11/17 09:57	Accident Photo [Linked Accident Report Documents]						1	Load JPG	<input checked="" type="checkbox"/>	
9	24/11/17 09:57	Accident Photo [Linked Accident Report Documents]						1	Load JPG	<input checked="" type="checkbox"/>	
10	24/11/17 09:57	Accident Photo [Linked Accident Report Documents]						1	Load JPG	<input checked="" type="checkbox"/>	
11	24/11/17 09:57	Accident Photo [Linked Accident Report Documents]						1	Load JPG	<input checked="" type="checkbox"/>	
12	24/11/17 09:57	Accident Photo [Linked Accident Report Documents]						1	Load JPG	<input checked="" type="checkbox"/>	
13	24/11/17 09:57	Accident Photo [Linked Accident Report Documents]						1	Load JPG	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print	
1	08/02/18 11:38	General View						1	Load JPG	<input checked="" type="checkbox"/>	
2	08/02/18 11:38	General View						1	Load JPG	<input checked="" type="checkbox"/>	
3	08/02/18 11:38	General View						1	Load JPG	<input checked="" type="checkbox"/>	
4	08/02/18 11:38	General View						1	Load JPG	<input checked="" type="checkbox"/>	
5	08/02/18 11:38	General View						1	Load JPG	<input checked="" type="checkbox"/>	
6	08/02/18 11:38	General View						1	Load JPG	<input checked="" type="checkbox"/>	
7	08/02/18 11:38	General View						1	Load JPG	<input checked="" type="checkbox"/>	
8	08/02/18 11:38	General View						1	Load JPG	<input checked="" type="checkbox"/>	
9	08/02/18 11:38	General View						1	Load JPG	<input checked="" type="checkbox"/>	
10	08/02/18 11:38	General View						1	Load JPG	<input checked="" type="checkbox"/>	
11	08/02/18 11:38	General View						1	Load JPG	<input checked="" type="checkbox"/>	
12	08/02/18 11:38	General View						1	Load JPG	<input checked="" type="checkbox"/>	
13	08/02/18 11:38	General View						1	Load JPG	<input checked="" type="checkbox"/>	

14	08/02/18 11:38	General View	1	Load JPG	<input checked="" type="checkbox"/>
15	08/02/18 11:38	General View	1	Load JPG	<input checked="" type="checkbox"/>
16	08/02/18 11:38	General View	1	Load JPG	<input checked="" type="checkbox"/>
17	08/02/18 11:38	General View	1	Load JPG	<input checked="" type="checkbox"/>
18	08/02/18 11:38	General View	1	Load JPG	<input checked="" type="checkbox"/>
19	08/02/18 11:38	General View	1	Load JPG	<input checked="" type="checkbox"/>
20	08/02/18 11:38	General View	1	Load JPG	<input checked="" type="checkbox"/>
21	08/02/18 11:38	General View	1	Load JPG	<input checked="" type="checkbox"/>
22	08/02/18 11:38	General View	1	Load JPG	<input checked="" type="checkbox"/>
23	08/02/18 11:38	General View	1	Load JPG	<input checked="" type="checkbox"/>
24	08/02/18 11:38	General View	1	Load JPG	<input checked="" type="checkbox"/>
25	08/02/18 11:38	General View	1	Load JPG	<input checked="" type="checkbox"/>
26	08/02/18 11:38	General View	1	Load JPG	<input checked="" type="checkbox"/>
27	08/02/18 11:38	General View	1	Load JPG	<input checked="" type="checkbox"/>
28	08/02/18 11:47	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
29	08/02/18 11:47	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
30	08/02/18 11:47	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
31	08/02/18 11:47	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
32	08/02/18 11:47	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
33	08/02/18 11:47	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
34	08/02/18 11:47	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
35	08/02/18 11:47	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
36	08/02/18 11:47	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
37	08/02/18 11:47	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
38	08/02/18 11:47	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
39	08/02/18 11:47	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
40	08/02/18 11:47	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
41	08/02/18 11:47	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
42	08/02/18 11:47	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
43	08/02/18 11:47	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
44	08/02/18 11:47	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
45	08/02/18 11:47	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
46	08/02/18 11:47	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
47	08/02/18 11:47	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
<b>Documentation</b>					
				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	27/11/17 12:52	EMAIL FROM CA(1)	1	Load PDF	
2	27/11/17 12:52	EMAIL FROM CA(2)	1	Load PDF	
3	27/11/17 12:52	EMAIL FROM CA(3)	1	Load PDF	
No	Finalized On	STA INSPECTION PTE LTD (Sin Ming)		Thumbnail	Print
1	24/11/17 09:59	Sketch Plan [Linked Accident Report Documents]	1	Load TIF	
2	24/11/17 09:59	Sketch Plan #2 [Linked Accident Report Documents]	1	Load TIF	

## Linked Accident Report Documents

				View	View in Browser
				1 per page	<input checked="" type="checkbox"/>
<b>Assessment Reports</b>					
No	Finalized On	STA INSPECTION PTE LTD (Sin Ming)		Thumbnail	Print
1	24/11/17 10:00	Accident Statement	1	Load HTM	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	STA INSPECTION PTE LTD (Sin Ming)	Thumbnail	Print
1	24/11/17 09:57	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	24/11/17 09:57	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	24/11/17 09:57	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	24/11/17 09:57	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	24/11/17 09:57	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	24/11/17 09:57	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	24/11/17 09:57	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
8	24/11/17 09:57	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
9	24/11/17 09:57	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
10	24/11/17 09:57	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
11	24/11/17 09:57	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
12	24/11/17 09:57	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
13	24/11/17 09:57	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	STA INSPECTION PTE LTD (Sin Ming)	Thumbnail	Print
1	24/11/17 09:59	Sketch Plan	 Load TIF	
2	24/11/17 09:59	Sketch Plan #2	 Load TIF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div> <div style="text-align: right; margin-top: 5px;"> <span>^</span>  <span>v</span> </div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI17022509/KQBE2**Date:** 12/02/2018REFERENCE**Handling Insurer:** China Taiping Insurance  
(Singapore) Pte. Ltd.**Policy No:** DMCVSN1747011700**Claimant Vehicle  
No :** SJN5642Y**Insured Vehicle  
No :** GBG2581R**Date of Loss:** 22/11/2017**Nature of Claim:** TP**Claim  
No:** SNM17D06775C02DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No:** SJN5642Y**Make & Model:** HONDA CROSSROAD, 1.8 (A)**Engine No:** R18A3011471**Reg. Date:** 19/02/2009 (Man. Year: 2008)**Chassis No:** RT11008440**Colour:** Metallic Black**Odometer:** 223956 km**Engine Capacity:** 1799 cc**Market Value/New Car Price:** N/A**Sum Insured (\$\$):** Market Value/New Car PriceCONDITION OF VEHICLE AT THE TIME OF SURVEY

<b>General Condition:</b>	<b>Steering (Serviceable):</b>	<b>Yes</b>	<b>Footbrake (Serviceable):</b>	<b>Yes</b>
<b>Handbrake (Serviceable):</b>	<b>Yes</b>	<b>Engine Modification:</b>	<b>No</b>	<b>Pre-accident Condition:</b>

CONDITION OF TYRES**Front Tyre Size:** 215/65 R16**Rear Tyre Size:** 215/65 R16**Front Left Side:** Kumho 7 mm**Rear Left Side:** Kumho 2 mm**Front Right Side:** Kumho 7 mm**Rear Right Side:** Kumho 2 mm*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	13,836.00	7,822.08	6,013.92	43.47
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,450.00	2,310.00	1,140.00	33.04
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>17,286.00</b>	<b>10,132.08</b>	<b>7,153.92</b>	<b>41.39</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>8,100.00</b>		
<b>(\$\$)</b>	17,286.00	8,100.00	9,186.00	53.14
<b>+ GST 7.00/7.00% (\$\$)</b>	1,210.02	567.00	643.02	53.14
<b>Nett Amount (\$\$)</b>	<b>18,496.02</b>	<b>8,667.00</b>	<b>9,829.02</b>	<b>53.14</b>

INSPECTION**Date of Assignment:** 27/11/2017**Date Inspected:** 27/11/2017 **Inspected At:**

Blk 160 Sin Ming Ind. Est #01-60/62

Repairer : City Auto Pte Ltd

**Estimated Period of Repair:** 8.0 days

---

**Adjuster:** KENNETH KONG**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG      **Version:** 1.0 (Last Synchronised: 12 Feb 2018)

**Parts:** M1-SUV      **HONDA CROSSROAD 1.8 (A)** (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's      (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SJN5642Y)

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Bent	1,247.00 FL	*1,247.00 FL
2	1		*TAILGATE LOGO	Necessary	35.50 FL	*35.50 FL
3	1		*TAILGATE EMBLEM - CROSSROAD	Necessary	58.00 FL	*58.00 FL
4	1		*TAILGATE OUTER GARNISH	Cracked	535.30 FL	*535.30 FL
5	1		*TAILGATE WEATHERSTRIP	Serviceable	185.00 FL	*- FL
6	1		*TAILGATE LOCK	Dented	109.40 FL	*109.40 FL
7	1		*TAILGATE DAMPER	Serviceable	195.00 FL	*- FL
8	1		*TAILGATE OUTER HANDLE	Serviceable	53.40 FL	*- FL
9	1		*TAILGATE GLASS SEALANT	Necessary	25.00 FL	*25.00 FL
10	1		*TAILGATE GLASS MOULDING	Necessary	85.00 FL	*85.00 FL
11	2		*REAR NUMBER PLATE LIGHT	Serviceable	65.60 FL	*- FL
12	1		*REAR WIPER MOTOR	Jammed	550.00 FL	*550.00 FL
13	1		*REAR WIPER ARM	Serviceable	85.00 FL	*- FL
14	1		*REAR BUMPER	Bent	1,050.40 FL	*1,050.40 FL
15	1		*REAR BUMPER TOWING COVER	Missing	20.50 FL	*20.50 FL
16	1		*REAR BUMPER PAD COVER - LH	Buckled	180.00 FL	*180.00 FL
17	1		*REAR BUMPER PAD COVER - RH	Serviceable	180.00 FL	*- FL
18	2		*REAR BUMPER BRACKET	Repair	56.00 FL	*- FL
19	1		*REAR BUMPER RETAINER	N/S Distorted	55.00 FL	*27.50 FL
20	1		*REAR BUMPER REFLECTOR - LH	Cracked	50.00 FL	*50.00 FL
21	8		*REAR BUMPER CLIP	Necessary	30.40 FL	*30.40 FL
22	2		*REAR BUMPER LOWER BRACKET	Distorted	56.00 FL	*56.00 FL
23	1		*REAR BUMPER LOWER BEAM	Bent	70.00 FL	*70.00 FL
24	1		*TAILLAMP - LH	Serviceable	435.00 FL	*- FL
25	1		*REAR EXHAUST MUFFLER	Bent	980.00 FL	*980.00 FL
26	1		*REAR EXHAUST HEATSHIELD	Bent	85.00 FL	*85.00 FL
27	1		*REAR END PANEL	Repair	510.70 FL	*- FL
28	1		*REAR END PANEL TOP GARNISH	Serviceable	240.70 FL	*- FL
29	1		*BONNET	Bent	785.60 FL	*785.60 FL
30	1		*BONNET LOCK	Repair	75.00 FL	*- FL
31	1		*FRONT BUMPER - UPPER	Buckled	1,308.60 FL	*1,308.60 FL
32	2		*FRONT BUMPER BRACKET	Repair	114.00 FL	*- FL
33	1		*FRONT BUMPER RETAINER	N/S Distorted	61.00 FL	*30.50 FL
34	1		*FRONT BUMPER PAD COVER - LH	Dented	235.00 FL	*235.00 FL
35	1		*FRONT BUMPER PAD COVER - RH	Serviceable	235.00 FL	*- FL
36	1		*FRONT BUMPER REINFORCEMENT	Bent	330.60 FL	*330.60 FL
37	1		*FRONT BUMPER CENTRE	Serviceable	533.20 FL	*- FL
38	1		*FRONT BUMPER MESH - LH	Serviceable	115.00 FL	*- FL
39	1		*FRONT BUMPER MESH - RH	Serviceable	115.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	10		*FRONT BUMPER CLIP	Necessary	38.00 FL	*38.00 FL
41	1		*FRONT GRILLE BASE	Serviceable	280.00 FL	*- FL
42	1		*FRONT GRILLE GARNISH	Serviceable	225.00 FL	*- FL
43	6		*FRONT GRILLE CLIP	Not Necessary	22.80 FL	*- FL
44	1		*FRONT GRILLE LOGO	Not Necessary	24.00 FL	*- FL
45	2		*HEADLAMP	Serviceable	1,750.00 FL	*- FL
46	2		*HEADLAMP LOWER BRACKET	Repair	114.00 FL	*- FL
47	1		*A/C CONDENSER	Punctured	866.80 FL	*866.80 FL
48	1		*REAR NUMBER PLATE }	Dented	25.00 FS	*45.00 FS
49	1		*REAR NUMBER PLATE CASING }		35.00 FS	*- FS
50	4		*REVERSE SENSOR	Dented	1,400.00 FS	*400.00 FS
51	1		*REAR VIEW CAMERA	Serviceable	350.00 FS	*- FS
52	1		*FRONT NUMBER PLATE }	Cracked	25.00 FS	*45.00 FS
53	1		*FRONT NUMBER PLATE CASING }		35.00 FS	*- FS
54	1		*COMPANY ADVERTISEMENT - STICKER	Necessary	400.00 FS	*300.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	16,727.50	9,580.10
- List Item Discount on L Items 20.00/20.00% (\$\$)	2,891.50	1,758.02
Total Parts (\$\$)	13,836.00	7,822.08

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO TOWING	New	50.00	50.00
2	TO CHECK WIRING AND LIGHTING	New	80.00	40.00
3	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	New	150.00	120.00
4	TO SUPPLY SEALANT AND RESEAL ALL WELD SPOT SEAM & GAPS	New	90.00	0.00
5	TO KNOCK JACKOUT DAMAGED PARTS , PANEL BEATING, WELDING, ALIGN, REFIX AND TO RENEW ACCIDENT PARTS	New	1,300.00	900.00
6	SPRAY PAINTING ON AFFECTED & REPLACE PARTS	New	1,450.00	1,200.00
7	TO PULL & REALIGN REAR CHASSIS MEMBER	New	180.00	0.00
8	TO REMOVE AND INSTALL A/C PARTS AND RECHARGE A/C GAS	New	150.00	0.00
Gross Labour Cost (\$\$)			3,450.00	2,310.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >