


S/N	LABOUR DESCRIPTION	Man-Hour Rate (\$)	Man-Hour Qty	Total Man-Hour Cost (\$)
1	Scope Of Repairs			
1.1	TO REPLACE AND RESPRAY BONNET INCLUDING REFLECTIVE STICKER	53.80	8	430.40
1.2	TO REPLACE AND RESPRAY RH FENDER INCLUDING REFLECTIVE STICKER	53.80	6	322.80
1.3	TO REPLACE AND RESPRAY FRT BUMPER INCLUDING REFLECTIVE STICKER	53.80	8	430.40
1.4	TO REPLACE AND RESPRAY SUPPORT PANEL	53.80	2	107.60
1.5	TO REPLACE RADIATOR, CONDENSER, INTER COOLER AND TOP UP AC GAS	53.80	2	107.60
1.6	TO CHECK WIRING, RESET AND PROGRAM ELECTRONIC SYSTEM	53.80	5	269.00
1.7	TO REPAIR AND RESPRAY RH SPORT RIM	53.80	4	215.20
2	Additional Services			
2.1	TO REPLACE ADDITIONAL ITEM	53.80	2	107.60
		22.00		0.00
			Labour Total:	\$ 1,990.60
			GRAND TOTAL :	\$ 21,496.59
Contractor shall complete the entire repair within <u>12</u> working days upon quotation approved date.				

Verification of Scope of Work					
Contractor QC		Vetted By:		Approved By:	
Name:	Gan Hup Tiong	Name:		Name:	
Date:	23/11/17	Date:		Date:	
Sign:	 	Sign:		Sign:	
Verification of Completed Repairs					
Contractor QC		Home Team QC / Fleet Manager / Appointed Surveyor		Home Team Contract / Fleet Manager	
Name:		Name:		Name:	
Date:		Date:		Date:	
Sign:		Sign:		Sign:	
All completed repairs must be verified by Home Team Contract Manager / Fleet Manager before payment can be made					

Excess : TBA

Not Authorised.

After repair photos / before paint photos.

Eno Qiang - 82880282

27/11/17

7 Days.

 12/12/17

ANSON  
8511 4276

**UKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: