

ASS. REC. BY:

REF: CS/C7717022516/A602

Special Instruction:

Surveyor: Adnan

ASSIGNMENT (Office)

From (Person): Irene Tay

of

CTI

Date/Time: 27/11/2017 @ 9:56 am

Estimated Cost:

Bill to:

OD / TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SFD 41P

Insured:

WC 5984P

at Workshop m/s

JOO Huk Kee

Tel:

67431913

of

3007 Ubi Rd 1 # 01-406, 408 701

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

D.O.A 23/11/2017

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 10:21 am @ 27/11/17

Person Contacted:

Nabilah

Vehicle: IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SFD 41P - CCG/AIG10005908/Un1p2 - D.O.A : 25/03/2010
	WC 5984P - x
	Lump Sum \$2200/- (Red: 4969.71; 69%)

ASSIGNMENT

From: _____ Date: **27/11/17**

Estimated Cost: _____

OD: (TP) / WS / TP RES / OD RES / EVA / INV / MV

To inspect vehicle No: **SFD 41P**
at Workshop No: **Joo Hak Kee Auto**
of: **3007 Ubi Rd 1 # 01-106, 108701**

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____

Excess: _____

Client's Record: _____

Make of Van: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

NS	OS

Ball or Market Value: _____

DAC Accident Report: _____ Consistent? : Yes or No

GIA / PP Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res: Yes or No

Lum. Surp: _____ % 3 Val: Yes or No

OA / REV / REP. / 24 HRS

'up'

Date: _____ Person Contacted: _____

Vehicle IN / OUT

From: **SFD41P** At Page: **2010 Jan.**

Type: (M/Cycle) Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: **Toyota Camry** Yr: **1998**

Colour: **Silver** A.C. Insured / Std / Nil / NA

Se. Reading: **359961** Radio Insured / Std / Nil / NA

Eng No: _____

C No: **MROS3BK4107053878**

Gen. Cond: (Good) Fair / Poor / Burnt

Steering: (In order) / Jammed / Leaked / Burnt or

Brake: (In order) / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / (STD A/Rim) or

Tyre Size F: **215/60R16**

R: **215/60R16**

BS / DUN / EXNOVA / GY / FS / LIZA / (MIC) / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R. Bal. **06** mm R. Bal. **06** mm

L. Bal. **06** mm L. Bal. **06** mm

D.O.A. D.O.I. **27/11/17**

Survey held at: **JHK**

Des. of Damages: (Fr) Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date Time Action Instruction

TP Chirn

RECEIVED 15 JAN 2018

Date Time File Passed

151 Typist

Date Time File Returned



Preli. Report



Final Report

Days Of Repair: **4**

Resurvey No. of Trip: **—**

Survey Fee

Transportation

Add Fee:



Site Insp \$



Interfer \$



Techn \$



Adm \$

Report Format:

Sum. Sum. (B) \$

TP 22001-

150

150




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CS/CTI17022516/Atb	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 27-11-2017	
		Code : CTI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	WC 5984P	Veh. Inspected	SFD 41P
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	IRENE TAY	Assign Date	27/11/2017
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	23/11/2017	Inspection Date	27/11/2017
Survey held at	JOO HAK KEE AUTO PTE LTD 3007 UBI ROAD 1 #01-406 KAMPONG UBI INDUSTRIAL ESTATE SINGAPORE 408701		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

Nivitha (LKK Auto)

From: Irene Tay <irene.tay@sg.cntaiping.com>
Sent: Monday, 27 November, 2017 9:56 AM
To: Nabilah Nabilah; assignments@lkkauto.com
Cc: assignments@lkkauto.com
Subject: CTP REF NO. WC5984P JHK REF NO. SFD41P - ACCIDENT INVOLVING WC5984P AND SFD41P ON 23 NOVEMBER 2017

WITHOUT PREJUDICE

Dear Sir/Mdm,

We refer to the above matter and the email below.

Please assist to get your surveyor, Adrian Ling to liaise with JHK.

Regards

Irene Tay

Claims Department
China Taiping Insurance (Singapore) Pte. Ltd.
3, Anson Road, #16-00
Springleaf Tower,
Singapore 079909
Co. Reg. No. 200208384E
DID: 6389-6192
Fax: 6224 7175
Email: claimsdept@sg.cntaiping.com
Email: irene.tay@sg.cntaiping.com
Website: www.sg.cntaiping.com

From: Nabilah Nabilah [mailto:nabilah@jhk.com.sg]
Sent: Monday, 27 November, 2017 9:47 AM
To: Irene Tay <irene.tay@sg.cntaiping.com>
Subject: Re: CTP REF NO. WC5984P JHK REF NO. SFD41P - ACCIDENT INVOLVING WC5984P AND SFD41P ON 23 NOVEMBER 2017

Dear Irene,

Kindly arrange Adrian Ling for the survey. Thank you.

Best regards,

Nabilah Senin | Admin Clerk
Joo Hak Kee Auto Pte Ltd
3007 Ubi Road 1
#01-406 Singapore 408701
O: 6743 1913 | F: 6743 5234
E: nabilah@jhk.com.sg

On Mon, Nov 27, 2017 at 9:05 AM, Irene Tay <irene.tay@sg.cntaiping.com> wrote:

Without Prejudice

Save As To Costs

Dear Sir/Mdm,

We refer to your pre-repair survey request / email.

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop.

Here are the list of surveyors ;

Tay Beng Hee

See Chew Seng

Dereck Oh Siong Wee

Mohd Fadhilah Bin Osman

Kalvin Ang

Bryan Ang

Steven Foong

Adrian Ling

Marcus Chua

Kenneth Kong

Henry Ng

We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Thank you.

Regards,

Irene Tay

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3, Anson Road, #16-00

Springleaf Tower,

Singapore 079909

Co. Reg. No. 200208384E

DID: 6389-6192

Fax: 6224 7175

Email: claimsdept@sg.cntaiping.com

Email: irene.tay@sg.cntaiping.com

Website: www.sg.cntaiping.com

From: Tee Sunny [<mailto:sunny@wahhong.sg>]

Sent: Friday, 17 November, 2017 2:10 PM

To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>; Irene Tay <irene.tay@sg.cntaiping.com>

Cc: Wah Hong Motors (Nicholas Tee) <nicholas@wahhong.sg>; Wah Hong Motors (Michael Tee) <michael@wahhong.sg>

Subject: Re: Pre-Repairs Assessment Request for SJM9058M - Accident with SCR6656M (China Taiping) on 2017-11-12 - our case no. 171111

Hi Irene

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	24/11/2017 00:39
Date Of Accident	23/11/2017 14:00
Exact Location Of Accident	PUNGGOL DR BEF PUNGGOL RD JUNCTION LANE 1
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SFD41P
Insured/Policyholder	
Name Of Registered Owner	CHUA HOI TEK
NRIC No	S2559997G
Email Address	CHUAHOITEK@GMAIL.COM
Mobile Phone No	(LOCAL) +65-91770752
Alternative Phone No	OFFICE-NOPHONE

Vehicle Particulars

Manufacturer	TOYOTA
Model	CAMRY-2.0 (A)

Exact Purpose for which vehicle was being used at time of accident	LEISURE
--	---------

Are you claiming under your own insurance policy for repair to your vehicle?	NO
--	----

If No, Please state action to be taken	THIRD PARTY
--	-------------

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5057750432-04
Cover Note Number	

Driver

Name of Driver	CHUA HOI TEK
NRIC No	S2559997G
Date Of Birth	20/04/1961
Occupation	INDOOR
Date Of Driving Pass	18/09/1993
Driving Experience	24 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91770752
Fax Number	
Contact Number	OFFICE-NOPHONE
EEmail Address	CHUAHOITEK@GMAIL.COM

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**
3. Information provided must be as **truthful and accurate as possible**. Any willful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

23/1/17
1500hrs

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: Arianan
NRIC/IN No.: S823471717

Enquire Transfer Fee

Vehicle Details

Vehicle No.	SFD41P
Vehicle Type	P10 - Passenger Motor Car
Vehicle Attachment 1	No Attachment
Vehicle Scheme	Normal
Vehicle Make	TOYOTA
Vehicle Model	CAMRY 2.0 AUTO ABS AIRBAG
Chassis No.	MR053BK4107053878
Propellant	Petrol
Engine No.	1AZE159833
Engine Capacity	1998 cc
Maximum Power Output	108.0 kW (144 bhp)
Maximum Laden Weight	1970 kg
Unladen Weight	1530 kg
Year Of Manufacture	2009
Original Registration Date	28 Jan 2010
Lifespan Expiry Date	-
COE Category	B - Car (1601cc & above)
Quota Premium	\$22,400.00
COE Expiry Date	27 Jan 2020
Road Tax Expiry Date	27 Jan 2018
PARF Eligibility Expiry Date	27 Jan 2020
Inspection Due Date	27 Jan 2019
Intended Transfer Date	24 Nov 2017
CO2 Emission	-

The current road tax expiry is 27 Jan 2018. You may renew the road tax from 28 Oct 2017 with all pre-requisite (s) fulfilled. If the road tax is renewed after 27 Jan 2018, late renewal fee(s) will be imposed. Please use [Enquire Road Tax Payable](#) to check on the late fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

Amount Payable (From 28 Jan 2018 to 27 Jul 2018)

Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
----------------------------	---------------------	---------------------------



JOO HAK KEE AUTO PTE LTD

裕合记汽车私人有限公司

SINCE 1986

ATTN: MOTOR CLAIMS DEPARTMENT

OWNER : CHUA HOI TEK

INSURER : NTUC INCOME INSURANCE CO-OPERATIVE LTD

POLICY NO.: 5057750432-04

REFERENCE: CHINA TAIPING DIRECT SETTLE

DATE OF ACCIDENT: 23/11/2017

Denial

REPAIR ESTIMATE

Est. No. : E17110005

Date : 24/11/2017

Vehicle Num. : SFD41P

Make/Model : TOYOTA, CAMRY 2.0
AUTO ABS AIRBAG

Chassis/Eng# : MR053BK4107053878

Yr. of Manu : 2009

No	Description	Qty	U/P	Amt
Section: LIST ITEMS				
1	FRONT BUMPER <i>Distorted</i>	1.00	596.88	596.88 ✓
2	FRONT BUMPER CLIPS <i>an</i>	10.00	4.20	42.00 ✓
3	FRONT BUMPER REINFORCEMENT <i>Bent</i>	1.00	435.60	435.60 ✓ <i>391.80</i>
4	FRONT BUMPER SIDE RETAINER LH <i>an</i>	1.00	68.25	68.25 ✓
5	FRONT BUMPER SIDE RETAINER RH <i>an</i>	1.00	68.25	68.25 ✓
6	FRONT BUMPER LOWER GRILLE <i>new</i>	1.00	95.31	95.31 +
7	FRONT BUMPER FOG LAMP COVER LH <i>green</i>	1.00	98.60	98.60 +
8	FRONT BUMPER FOG LAMP COVER RH	1.00	98.60	98.60 +
9	FRONT BUMPER FOG LAMP LH <i>green</i>	1.00	275.14	275.14 +
10	FRONT BUMPER FOG LAMP RH	1.00	275.14	275.14 +
11	FRONT GRILLE <i>Cancelled</i>	1.00	275.81	275.81 ✓ <i>50.00</i>
12	FRONT GRILLE EMBLEM <i>an</i>	1.00	124.16	124.16 ✓
13	FRONT GRILLE CHROME GARNISH <i>new</i>	1.00	237.30	237.30 +
14	FRONT SUPPORT PANEL <i>Right</i>	1.00	957.90	957.90 +
15	HEAD LAMP LH <i>new</i>	1.00	487.97	487.97 +
16	HEAD LAMP RH <i>new</i>	1.00	487.97	487.97 +
17	HEAD LAMP BRACKET LH <i>green</i>	1.00	262.90	262.90 +
18	HEAD LAMP BRACKET RH	1.00	262.90	262.90 +
19	BONNET <i>Destroyed</i>	1.00	687.90	687.90 ✓
20	BONNET LOCK <i>2nd</i>	1.00	185.40	185.40 ✓
21	BONNET CATCH <i>new</i>	1.00	78.90	78.90 +
22	AIR CON CONDENSER <i>new</i>	1.00	798.96	798.96 +

Continue on next page...



BLK 3007 UBI ROAD 1 #01-406, SINGAPORE 408701
BLK 3014 UBI ROAD 1 #01-324, SINGAPORE 408702

TEL: 6743 1913 FAX: 6743 5234
EMAIL: admin@jhk.com.sg

CO/GST REG NO: 201300082W
WEBSITE: www.jhk.com.sg

bizSAFE₃

REPAIR ESTIMATE

ATTN: MOTOR CLAIMS DEPARTMENT
 OWNER : CHUA HOI TEK
 INSURER : NTUC INCOME INSURANCE CO-OPERATIVE LTD
 POLICY NO.: 5057750432-04
 REFERENCE: CHINA TAIPING DIRECT SETTLE
 DATE OF ACCIDENT: 23/11/2017

Est. No. : E17110005
 Date : 24/11/2017
 Vehicle Num. : SFD41P
 Make/Model : TOYOTA,CAMRY 2.0
 AUTO ABS AIRBAG
 Chassis/Eng# : MR053BK4107053878
 Yr. of Manu : 2009

No	Description	Qty	U/P	Amt
23	AIR CON SUCTION PIPE	1.00	168.80	168.80 +
24	AIR CON DISCHARGE PIPE	1.00	153.90	153.90 +
25	AIR CON FAN BLADE	1.00	179.50	179.50 +
26	AIR CON FAN COWLING	1.00	278.60	278.60 +
27	RADIATOR	1.00	1,230.30	1,230.30 +
28	RADIATOR FAN BLADE	1.00	121.30	121.30 +
29	RADIATOR FAN COWLING	1.00	278.60	278.60 +
30	RADIATOR TOP HOSE	1.00	86.90	86.90 +
31	RADIATOR BOTTOM HOSE	1.00	78.60	78.60 +
32	FRONT BUMPER SPONGE	1.00	81.40	81.40 ✓

Amt S\$ 9,559.74
 Discount (25.00%) S\$ 999.99
 Subtotal S\$ 7,169.81

Section: SPECIAL NETT ITEMS

33	FRONT NUMBER PLATE W/COVER	1.00	50.00	50.00 ✓
				Amt S\$ 50.00
				Discount (0.00%) S\$ 0.00
				Subtotal S\$ 50.00

Section: LABOUR

34	TO PANEL BEAT AND RENEWAL OF ALL DAMAGED PARTS	1.00	750.00	750.00 400
35	TO PUTTY & SPRAY PAINTING ON ACCIDENT DAMAGED PORTION	1.00	780.00	780.00 440
36	TO CHECK WIRING FUNCTION AND REFIT WIRING	1.00	60.00	60.00 30
37	TO ANTI-RUST	1.00	30.00	30.00 +

LKK Auto Consultants Ltd. certify
 the Repair of the following:
 • To resurvey before after spray painting
 • To display damaged parts during survey
 • Part prices are subject to confirmation
 • Third party survey is on a Without Prejudice basis
 • No legal mediation(s) is allowed
 • Any item(s) must be resurveyed and
 final approval from Insurance Company

Adrian Lim
 27/11/17
 04 PAYS.

Continue on next page...
 total 276591
 c/s: 22K.

ATTN: MOTOR CLAIMS DEPARTMENT
 OWNER : CHUA HOI TEK
 INSURER : NTUC INCOME INSURANCE CO-OPERATIVE LTD
 POLICY NO.: 5057750432-04
 REFERENCE: CHINA TAIPING DIRECT SETTLE
 DATE OF ACCIDENT: 23/11/2017

REPAIR ESTIMATE

Est. No. : E17110005
Date : 24/11/2017
Vehicle Num. : SFD41P
Make/Model : TOYOTA,CAMRY 2.0
 AUTO ABS AIRBAG
Chassis/Eng# : MR053BK4107053878
Yr. of Manu : 2009


No	Description	Qty	U/P	Amt
				Amt S\$ 1,620.00
				Discount (0.00%) S\$ 0.00
				Subtotal S\$ 1,620.00

Surveyed by/Company : _____
 Contact Number : _____
 Date/Time : _____
 Licensed Automotive Surveyor's Sign : _____

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices will subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer
 Signature: _____
 Date: _____



Joo Hak Kee Auto Pte. Ltd.

LIST ITEMS Subtotal S\$ 7,169.81
SPECIAL NETT ITEMS Subtotal S\$ 50.00
LABOUR Subtotal S\$ 1,620.00
Total S\$ 8,839.81

BLK 3007 UBI ROAD 1 #01-406, SINGAPORE 408701
 BLK 3014 UBI ROAD 1 #01-324, SINGAPORE 408702

TEL: 6743 1913 FAX: 6743 5234
 EMAIL: admin@jhk.com.sg

CO/GST REG NO: 201300082W
 WEBSITE: www.jhk.com.sg

bizSAFE₃

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	24 Nov 2017		27 Nov 2017 11:04 Edit Adj Rpt	S\$2,200.00 Edit Estimates	S\$2,200.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	-, Co. Reg. No.: -		
Main Claimant:	CHUA HOI TEK		
Vehicle Reg. No.:	SFD41P	Date of Loss:	23/11/2017 14:00 - :59
Claim Type:	TP / SNM17D06781C02	Policy/Cover Note No.:	DMCVSN164477101
Vehicle Reg. No. (Insured):	WC5984P	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Joo Hak Kee Auto Pte Ltd (HQ) Blk 3007 Ubi Road 1, #01-406, 408701 Ubi - Tel: 67431913		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 06/12/2017]		
Adj Asg. Remarks:	PLEASE ASSIST TO CONDUCT PRS AND REVERT WITH YOUR RECOMMENDATION		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)



























There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SFD41P (SNM17D06781C02)
[WC5984P]
TP
CHUA HOI TEK
Nov 23 2017 2:00PM
[-]
Joo Hak Kee Auto Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			View View in Browser		
Photos/Images									3 per page	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print	
1	08/01/18 18:34	General View							 Load JPG	<input checked="" type="checkbox"/>	
2	08/01/18 18:34	Chassis Number							 Load JPG	<input checked="" type="checkbox"/>	
3	08/01/18 18:34	General View							 Load JPG	<input checked="" type="checkbox"/>	
4	08/01/18 18:34	General View							 Load JPG	<input checked="" type="checkbox"/>	
5	08/01/18 18:34	General View							 Load JPG	<input checked="" type="checkbox"/>	
6	08/01/18 18:34	General View							 Load JPG	<input checked="" type="checkbox"/>	
7	08/01/18 18:34	General View							 Load JPG	<input checked="" type="checkbox"/>	
8	08/01/18 18:34	General View							 Load JPG	<input checked="" type="checkbox"/>	
9	08/01/18 18:34	General View							 Load JPG	<input checked="" type="checkbox"/>	
10	08/01/18 18:34	General View							 Load JPG	<input checked="" type="checkbox"/>	
11	08/01/18 18:34	General View							 Load JPG	<input checked="" type="checkbox"/>	
12	08/01/18 18:34	General View							 Load JPG	<input checked="" type="checkbox"/>	
13	08/01/18 18:34	General View							 Load JPG	<input checked="" type="checkbox"/>	
14	08/01/18 18:34	General View							 Load JPG	<input checked="" type="checkbox"/>	
15	08/01/18 18:34	General View							 Load JPG	<input checked="" type="checkbox"/>	
16	08/01/18 18:34	General View							 Load JPG	<input checked="" type="checkbox"/>	
17	08/01/18 18:34	General View							 Load JPG	<input checked="" type="checkbox"/>	
18	08/01/18 18:34	General View							 Load JPG	<input checked="" type="checkbox"/>	
19	08/01/18 18:34	General View							 Load JPG	<input checked="" type="checkbox"/>	
20	08/01/18 18:34	General View							 Load JPG	<input checked="" type="checkbox"/>	
21	08/01/18 18:34	General View							 Load JPG	<input checked="" type="checkbox"/>	
22	08/01/18 18:34	General View							 Load JPG	<input checked="" type="checkbox"/>	
23	08/01/18 18:34	General View							 Load JPG	<input checked="" type="checkbox"/>	
24	08/01/18 18:34	General View							 Load JPG	<input checked="" type="checkbox"/>	
Documentation									1 per page	<input checked="" type="checkbox"/>	
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)							Thumbnail	Print	
1	27/11/17 11:07	EMAIL FROM JHK(1)							 Load PDF		
2	27/11/17 11:07	EMAIL FROM JHK(2)							 Load PDF		

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

^
v

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT117022516/ATBE2

Date: 17/01/2018

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSN164477101

Claimant Vehicle No: SFD41P Insured Vehicle No: WC5984P

Date of Loss: 23/11/2017 Nature of Claim: TP Claim No: SNM17D06781C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SFD41P**

Make & Model: TOYOTA CAMRY, 2.0 (A) Engine No: 1AZE159833

Reg. Date: 28/01/2010 (Man. Year: 2009) Chassis No: MR053BK4107053878

Colour: Silver Odometer: 359961 km

Engine Capacity: 1998 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16

Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,219.80	1,885.92	5,333.88	73.88
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,620.00	880.00	740.00	45.68
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	8,839.80	2,765.92	6,073.88	68.71
Approved Total (Overridden) (\$\$)		2,200.00		
(S\$)	8,839.80	2,200.00	6,639.80	75.11
+ GST 7.00/7.00% (\$\$)	618.79	154.00	464.79	75.11
Nett Amount (\$\$)	9,458.59	2,354.00	7,104.59	75.11

INSPECTION

Date of Assignment: 27/11/2017

Date Inspected: 27/11/2017 Inspected At: Joo Hak Kee Auto Pte Ltd (HQ)
Blk 3007 Ubi Road 1, #01-406
Singapore 408701

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG **Version:** 1.0 (Last Synchronised: 17 Jan 2018)
Parts: 143 **TOYOTA CAMRY 2.0 (A) (Catalogue:Merimen Singapore 1.0)**
Labour: Repairer's (Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SFD41P)
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	596.88 FL	*596.88 FL
2	10		*FRONT BUMPER CLIPS	Necessary	42.00 FL	*42.00 FL
3	1		*FRONT BUMPER REINFORCEMENT	Bent	435.60 FL	*391.80 FL
4	1		*FRONT BUMPER SIDE RETAINER LH	Necessary	68.25 FL	*68.25 FL
5	1		*FRONT BUMPER SIDE RETAINER RH	Necessary	68.25 FL	*68.25 FL
6	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	95.31 FL	*- FL
7	1		*FRONT BUMPER FOG LAMP COVER LH	Not Necessary	98.60 FL	*- FL
8	1		*FRONT BUMPER FOG LAMP COVER RH	Not Necessary	98.60 FL	*- FL
9	1		*FRONT BUMPER FOG LAMP LH	Not Necessary	275.14 FL	*- FL
10	1		*FRONT BUMPER FOG LAMP RH	Not Necessary	275.14 FL	*- FL
11	1		*FRONT GRILLE	Cracked	275.81 FL	*275.81 FL
12	1		*FRONT GRILLE EMBLEM	Necessary	124.16 FL	*50.20 FL
13	1		*FRONT GRILLE CHROME GARNISH	Not Necessary	237.30 FL	*- FL
14	1		*FRONT SUPPORT PANEL	Repair	957.90 FL	*- FL
15	1		*HEAD LAMP LH	Not Necessary	487.97 FL	*- FL
16	1		*HEAD LAMP RH	Not Necessary	487.97 FL	*- FL
17	1		*HEAD LAMP BRACKET LH	Not Necessary	262.90 FL	*- FL
18	1		*HEAD LAMP BRACKET RH	Not Necessary	262.90 FL	*- FL
19	1		*BONNET	Dented	687.90 FL	*687.90 FL
20	1		*BONNET LOCK	Damaged	185.40 FL	*185.40 FL
21	1		*BONNET CATCH	Not Necessary	78.90 FL	*- FL
22	1		*AIR CON CONDENSER	Not Necessary	798.96 FL	*- FL
23	1		*AIR CON SUCTION PIPE	Not Necessary	168.80 FL	*- FL
24	1		*AIR CON DISCHARGE PIPE	Not Necessary	153.90 FL	*- FL
25	1		*AIR CON FAN BLADE	Not Necessary	179.50 FL	*- FL
26	1		*AIR CON FAN COWLING	Not Necessary	278.60 FL	*- FL
27	1		*RADIATOR	Not Necessary	1,230.30 FL	*- FL
28	1		*RADIATOR FAN BLADE	Not Necessary	121.30 FL	*- FL
29	1		*RADIATOR FAN COWLING	Not Necessary	278.60 FL	*- FL
30	1		*RADIATOR TOP HOSE	Not Necessary	86.90 FL	*- FL
31	1		*RADIATOR BOTTOM HOSE	Not Necessary	78.60 FL	*- FL
32	1		*FRONT BUMPER SPONGE	Cracked	81.40 FL	*81.40 FL
33	1		*FRONT NUMBER PLATE W/COVER	Deformed	50.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	9,609.74	2,497.89
- List Item Discount on L Items 25.00/25.00% (S\$)	2,389.94	611.97
Total Parts (S\$)	7,219.80	1,885.92

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PANEL BEAT AND RENEWAL OF ALL DAMAGED PARTS	New	750.00	400.00
2	TO PUTTY & SPRAY PAINTING ON ACCIDENT DAMAGED PORTION	New	780.00	450.00
3	TO CHECK WIRING FUNCTION AND REFIT WIRING	New	60.00	30.00
4	TO ANTI-RUST	New	30.00	0.00
Gross Labour Cost (S\$)			1,620.00	880.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >