

HITACHI
 Inspire the Next

 INSURER: **MSIG Insurance (Singapore) Pte. Ltd. (HQ)**
PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	SLF6325A
Policy No:	MSD/VPCP/17-001233-00-181	Date of Loss:	22/11/2017
Vehicle Reg. No.:	SLF6325A	Driveable?	
Driver Age/Info:	53 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	HITACHI CAPITAL ASIA PACIFIC PTE LTD		
Driver:	LIM KOK TIONG		
Make/Model:	TOYOTA COROLLA ALTIS, 1.6 CLASSIC CVT (A)	Vehicle Reg. Date:	01/09/2016
Vehicle Colour:	BLACK	Chassis No:	MR053REH104557369
Engine No:	1ZRY330793		
Odometer:	70265 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	20		
Description of Accident/Loss	REFER TO ATTACHMENT		
Present Location:	HITACHI CAPITAL ASIA PACIFIC PTE. LTD (HQ)		

27/11/17.
 Tauphu 92495749
 Ex \$1500 @ 12pm.
 Repairing before paint.
 Sur @ 11km auto. with
 10 days
 # Report not authorised

COST OF CLAIMS

	Amount
Parts	6,946.40
Miscellaneous Items	0.00
Labour	6,090.00
Paintwork Labour	0.00
Towing	0.00
Calculated Gross Total (S\$)	13,036.40
- Excess (S\$)	1,500.00
(S\$)	11,536.40
+ GST 7.00% (S\$)	807.55
Nett Amount (S\$)	12,343.95

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

 This claim is handled by: **SUN ZHU MEI**

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 24 Nov 2017)**Parts:** 143 TOYOTA COROLLA ALTIS 1.6 CLASSIC CVT (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** Hitachi Capital Asia Pacific Pte. Ltd/SLF6325A/24/11/2017 15:27**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Rear Bumper <i>in</i>	0.00	0.00	*180.00 F
2	2		*Rear Bumper Inner Retainer <i>RH/LH^x</i>	0.00	0.00	*80.00 F
3	2		*Rear Bumper Outer Retainer <i>RH/LH^x</i>	0.00	0.00	*56.00 F
4	1		*Rear RH Reflector Light <i>x</i>	0.00	0.00	*25.00 F
5	1		*Rear RH Fender <i>bu</i>	0.00	0.00	*380.00 F
6	1		*Rear RH Fender Shield <i>de</i>	0.00	0.00	*25.00 F
7	10		*Rear RH Fender Shield Clips <i>ne</i>	0.00	0.00	*15.00 F
8	1		*Rear Windscreen Moulding <i>ne</i>	0.00	0.00	-
9	1		*Sealant <i>ne</i>	0	0.00	*50.00 FS
10	1	REPAIR	*Rear RH Inner Wheel House <i>RY</i>	0.00	0.00	-
11	1		*Rear RH Door <i>bt</i>	0.00	0.00	*450.00 F
12	1		*Rear RH Door Sticker Set <i>ne</i>	0.00	0.00	*25.00 F
13	1		*Rear RH Door Hander <i>nt</i>	0.00	0.00	*95.00 F
14	1		*Rear RH Door Hander Retainer <i>ne</i>	0.00	0.00	*30.00 F
15	1		*Rear RH Door Chrome Moulding <i>?</i>	0.00	0.00	*55.00 F
16	1		*Rear RH Door Weatherstrip <i>?</i>	0.00	0.00	*55.00 F
17	2		*Rear RH Door Hinge Top / Bottom <i>?</i>	0.00	0.00	*60.00 F
18	1		*Rear RH Door Checker <i>?</i>	0.00	0.00	*60.00 F
19	1		*Rear RH Lower Pillar <i>RY</i>	0.00	0.00	-
20	1		*Rear RH Door Inner Board <i>?</i>	0.00	0.00	*600.00 F
21	1		*Rear RH Door Lock <i>?</i>	0.00	0.00	*185.00 F
22	1		*Rear RH Door Power Window Regulator 1set <i>?</i>	0.00	0.00	*210.00 F
23	1		*Rear RH Lower Pillar and Mulffer Cutter <i>?</i>	0.00	0.00	-
24	1		*Driver Door <i>bt</i>	0.00	0.00	*450.00 F
25	1		*Driver Door Hander <i>nt</i>	0.00	0.00	*130.00 F
26	1		*Driver Door Hander Retainer <i>ne</i>	0.00	0.00	*25.00 F
27	2		*Driver Door Hinge Top / Bottom <i>RY</i>	0.00	0.00	*70.00 F
28	1		*Driver Door Checker <i>x</i>	0.00	0.00	*55.00 F
29	1		*Driver Door Inner Board <i>x</i>	0.00	0.00	*770.00 F
30	1		*Driver Door Weatherstrip <i>?</i>	0.00	0.00	*70.00 F
31	1		*Driver Door Power Window Regulator 1set <i>?</i>	0.00	0.00	*120.00 F
32	1		*RH Wing Mirror Cover <i>bu</i>	0.00	0.00	*35.00 F
33	1		*Front RH Fender <i>RY</i>	0.00	0.00	*190.00 F
34	1		*Front RH Fender Logo <i>ne</i>	0.00	0.00	*18.00 F
35	1		*Front RH Fender Quarter Garnish <i>nt</i>	0.00	0.00	*25.00 F
36	2		*Rim (R16) <i>Rear RH cut, Frt RH x NC</i>	0.00	0.00	*900.00 F
37	2		*Tyre Hankook 205/55/R16 <i>?</i>	0	0.00	*600.00 FS
38	1	REPAIR	*Bonnet <i>x</i>	0.00	0.00	-
39	1	REPAIR	*Driver Door Center Pillar <i>RY</i>	0.00	0.00	-
40	1		*RH Wing Mirror 1set <i>bu</i>	0.00	0.00	*280.00 F

F=Franchise part. S=SpcNett.

Sub Total (\$\$) **6,374.00**
+ Margin on L,N Items 10.00% (\$\$) **572.40**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
Total Parts (S\$)						6,946.40

Hitachi Capital Asia Pacific Pte. Ltd/SLF6325A/24/11/2017 15:27. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	Panel beat, cut, weld, re-align & replace damaged parts of affected area	New 1200	3,000.00
2	Putty, blend and paint affected area	New 1200	2,000.00
3	Check Wiring, re-align headlamps and ensure proper function	New 80	80.00
4	Remove & reinstall bumper sensors	New 30	120.00
5	Conduct four wheel alignment / side slip test	New 80	180.00
6	Remove, replace & balance rim / tire	New 4 30	80.00
7	Remove & re-install Rear Fender Windscreen	New 120	180.00
8	Transfer door lock & mechanism to new door	New 120	300.00
9	Remove & re-install rear trim compartment to facilitate cutting and repairing work	New 80	150.00
Gross Labour Cost (S\$)			6,090.00

Hitachi Capital Asia Pacific Pte. Ltd./SLF6325A/24/11/2017 15:27. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Hitachi Capital Asia Pacific Pte. Ltd. (Main Office) Co. Reg. No. 199400399N

111 Somerset Road #11-05 Singapore 238164 Tel: (65) 6734 1222 Fax : 6734 8835

www.hitachi-capital.com.sg

Jun Taiyo Service Centre (Automobile Leasing & Workshop)

8 Fourth Lok Yang Road Singapore 629705 Tel: (65) 6466 3022 Fax: (65) 6896 6591