

22/03/2012

ASS. REC. BY:

REF: CS/CTI7022520 / Agbe2

Special Instruction:

Survivor:
Mentor: AdrianASSIGNMENT (Office)

From (Person): Joel Goh

of CTI

Date/Time: 27/11/2017 @ 10.20am

Estimated Cost:

Bill to:

OD - TP - WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJF 5432D

Insured:

GT 5778T

at Workshop m/s

Sk Automobile

Tel:

67895155

of 23 Kelki Bukit Ave 4 # 03-01, 415933

Policy No: DMCVSN3059541700

Claim No:

SNM17D06745C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A 22/11/2017

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 11:02am @ 27/11/17

Person Contacted:

Siew

Vehicle IN / OUT

Date/Time	Action/Instruction () Estimate
	SJF 5432D - X
	GT 5778T - CC4 / AIG 12014180 / M1b1 + 292 - D.O.A 13/07/2012
	US \$5000, 7 days (Red \$12034.51, 71%)

ADDITIONAL

02/06/08

From: Date 27/11/2017

SJF5432D. Page 2008 June

Estimated Cost:

Type: ☒ M/Car / ☐ M/Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime MoverOD / ☒ TP / ☐ RES / ☐ CD RES / ☐ EVA / ☐ INV / ☐ MV

Truck / Trailer or

To inspect Vehicle No SJF5432D

Make Nissan Latio 1498

at Workshop/s SK Automobile

Colour Silver A.D. Insured / Std / Nil / NA

at 23 Kaki Bukit Ave 4, #03-01, 415933

So Peeding 185958. T-Radio Insured / Std / Nil / NA

Insured

Eng No

Policy No

C No JN1BAAC1120005971

Claims No

Gen. Cond. ☒ Good / ☐ Fair / ☐ Poor / ☐ Burnt

Sum Insured

Excess:

Steering ☒ In Order / ☐ Jammed / ☐ Leaked / ☐ Burnt or

(Client's Record)


Brakes ☒ In Order / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Make of Veh

Mod. Nil / ☒ S/Rim / ☐ STD A/Rim or

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Ball or Market Value:

Front

Rear

DAD Accident Report Consistent? : Yes or No

R.Bal. 06 mm

R.Bal. 06 mm

GIA / PP Seen Consistent? : Yes or No

L.Bal. 06 mm

L.Bal. 06 mm

Est. Repairs: 7 days Res: Yes or No

D.O.A

D.O.A 27/11/17.

Lum Sum: % 3 Val: Yes or No

Survey held at

S.K.

CA / REV / REP. / 24 HRS

Des. of Damages: Frt ☒ Rear / ☐ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or

Date: Person Contacted

Vehicle IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision

Date Time Action Instruction

TP Chin.

MV: 12.5K
PV: 7.5K
Nett: 5K.

RECEIVED 1 JAN 2018

Date Time File Passed

☐

Preli. Report

Days Of Repair: 7

3/1/2018

☐

Final Report

Resurvey No. of Trip.

Survey Fee

Date Time File Returned

Transport

1

Add Fee:

☐

Site Insp

☐

Test

☐

Tech

☐

At

Report Format

Lump Sum (S.K.)

MER-TP
5000

200

200

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CS/CTI17022520/Aqb

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 27-11-2017



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GT 5778T	Veh. Inspected	SJF 5432D
Policy No.	DMCVSN3059541700	Coverage (\$)	0.00
Claim No.	SNM17D06745C02	Excess (\$)	0.00
Assign From	MERIMEN (JOEL GOH)	Assign Date	27/11/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	22/11/2017	Inspection Date	27/11/2017
Survey held at	SK AUTOMOBILE PTE LTD 23 KAKI BUKIT AVE 4 # 03-01 SINGAPORE 415933		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

SJF 5432D

Admin (Catherine): Case handler to make sure all Information created by the assignment team are **ACCURATE**.

(1) Office Assign Form

C	Reference No.
C	Customer Code
N	Assign From
C	Assign Date
C	Veh No (Inspected)
C	Veh No (Insured)
C	D.O.A
C	Policy No
C	Claim No
C	Insurance Authorisation (CA /REV/REP)
C	Report Type
C	Weekend Charges
N	Survey held at/Repairer
C	Excess

[illegible]

Surveyor (Adrian): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C	Vehicle No
C	Regn Month/Year
N	Vehicle Type
N	Make & Model
C	Engine Capacity. (C.C)
N	Colour
C	Odometer. (Sp.Reading)
C	Chassis No
N	General Condition
N	Steering
N	Brake
N	Modification (Modi)
C	Tyre Size
N	Tyre Make
C	Tyre Balance
C	Date of Inspection
N	Survey held
N	Des.of Damages

[illegible]

(2) System - (Views/Merimen)

C Damaged Vehicle Photographs Uploaded

☒	☐	☐	☐
-------------------------------------	--------------------------	--------------------------	--------------------------

(3) Workshop Estimate/Assignment Form

- N ALL Parts condition
- C Market Value for OD cases
- C Estimate Repair Cost for PRI (RSI, TMI, MSIG)
- C Days of repair
- C Finalised Amount
- C Re-inspection Cases to Finalize within 5 Days

✓	
✓	

(4) System - (Views/Merimen)

C Resurvey photo Uploaded

--	--	--	--

Check By:

Case Handler

Date _____

*C: Critical *N: Non-Critical

21/05/2014

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	26 Nov 2017		27 Nov 2017 10:20 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured: COLOURTREND PAINTS PTE LTD, Co. Reg. No.: 200616131Z		[Created by insurer]	
Main Claimant: MOHD SHUKRI, ID: S1615486E			
Vehicle Reg. No.: SJF5432D	Date of Loss: 22/11/2017 08:00 - :59		
Claim Type: TP / SNM17D06745C02/8	Policy/Cover Note No.: DMCVSN3059541700 (TP, Fire & Theft)		
Vehicle Reg. No. (Insured): GT5778T	Policy No. (Claimant):		
	Excess: S\$0.00		
Repairer: SK Automobile Pte Ltd (HQ) 23 Kaki Bukit Avenue 4, #03-01 Vicom Inspection Centre, 415933 Kaki Bukit - Tel: 67895155			
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Joel Goh]			
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 06/12/2017]			
Adj Asg. Remarks: NO ESTIMATES. GUO QIANG SELECTED AS SJE FOR WP PRS			

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS ☐

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type	Company
Owner ID	4355Z

Vehicle Details

Vehicle No.	SJF5432D
Vehicle to be Exported	Yes
Intended De-registration Date	23 Nov 2017
Vehicle Make	NISSAN
Vehicle Model	LATIO 1.5L A
Primary Colour	Silver
Manufacturing Year	2007
Engine No.	HR15179061A
Chassis No.	JN1BAAC11Z0005971
Maximum Power Output	80.0 kW (107 bhp)
Open Market Value	\$13,199.00
Original Registration Date	02 Jun 2008
First Registration Date	02 Jun 2008
Transfer Count	2
Actual ARF Paid	\$13,199.00

Intended PARF Rebate Details


PARF Eligibility	Yes
PARF Eligibility Expiry Date	01 Jun 2018
PARF Rebate Amount	\$6,599.00

Intended COE Rebate Details

COE Expiry Date	01 Jun 2018
COE Category	A - Car (1600cc & below)
COE Period(Years)	10
QP Paid	\$15,701.00
COE Rebate Amount	\$823.00
Total Rebate Amount	\$7,422.00

The information contained herein is correct as at 23 Nov 2017

OK



Username / Email Add

password

Connect Sign Up New Account
Forgot Password

Latio

Price Range

Depreciation

2008

Vehicle Type



Advanced Search

Used Car Comparison


--- Comparing 4 Vehicles ---

Nissan Latio 1.5A Premium

Nissan Latio 1.5A

Nissan Latio 1.5A

Nissan Latio 1.5A



Clear All

Add all to Shortlist

Back to search result

Add to Shortlist

Add to Shortlist

Add to Shortlist

Add to Shortlist

CAR DETAILS

Price	\$12,800	\$13,800	\$12,600	\$12,838
Instalment	\$1,516	\$1,634	\$2,227	\$3,018
Registration Date	30-May-2008	17-Jun-2008	23-Apr-2008	06-Mar-2008
Manufactured	2007	2007	2007	2007
Mileage	-	140,300 km	125,000 km	138,000 km
Transmission	Auto	Auto	Auto	Auto
Engine Cap	1,498 cc	1,498 cc	1,498 cc	1,498 cc
Road Tax	\$684 /yr	\$684 /yr	\$684 /yr	\$684 /yr
Power	80.0 kW (107 bhp)	80.0 kW (107 bhp)	80.0 kW (107 bhp)	80.0 kW (107 bhp)
Curb Weight	1,130 kg	1,110 kg	1,110 kg	1,110 kg
Features	Powerful And Responsive 1.5L DOHC Engine,CVT Auto Transmission, ABS, Dual Airbag, Keyless Start/Entry, Immobilizer, Climatic Digital Aircon Control.	1.5L DOHC Engine, 4 Speed Auto Transmission, ABS, SRS Airbags, Keyless Entry, Immobilizer, Climatic Digital Aircon.	Well Maintained. Powerful Engine. All Owners Within Same Family.	Powerful And Fuel Efficient Engine, Digital Climate Control, Immobilizer, Keyless Entry, Airbags, Etc.
Accessories	Sport Rims, Leather Seats, Bodykit With Rear Lip, Factory Fitted Audio System, Reverse Sensors, Solar Film, Retractable Side Mirrors, Center Arm Rest.	Sports Rims, Leather Seats, Reverse Sensors, Audio Player, Solar Films, Fog Lamps, Side Mirror With Indicators.	Original Accessories. Black Interior. Leather Condition Still Good.	Sports Rims, Keyless Entry, Reverse Sensors, Factory Fitted Audio System, Solar Film.
Description	Only 1 Owner, Original Bodykit And Rear Lip, Certified Pre-Owned Car, No Repair Require, Extended Warranty Available, Buy With A Peace Of Mind From A Company Accredited With Outstanding Awards, Excellent After Sales Service, Ready For Viewing.	Low Mileage For A 9 Year Old Car. Excellent Condition. 1 Careful Owner. Loan Can Be Arranged, Trade In Welcome. See To Believe.	High Scrap Value. Safe Buy. Odourless Smoker Free Cabin.	Nice Condition, Don't Miss It. And View This Unit, Direct Owner Sale. In House Loan Available. Payment.
COE	\$15,701	\$15,701	\$16,930	\$7,491
OMV	\$15,372	\$14,393	\$14,213	\$14,212
ARF	\$15,372	\$14,393	\$14,213	\$14,172
Depreciation	\$10,260 /yr	\$12,050 /yr	-	-
No. of Owners	1	1	3	3
Type of Vehicle	Sedan	Sedan	Sedan	Sedan
Category	PARF Car	PARF Car	PARF Car, Direct Owner Sale	PARF Car
Availability	Available	Available	Available	Available

SELLER INFORMATION

Seller	Dickson Automobile	SK Automobile Trade	Direct Owner	Hoe Beng Auto Trading
--------	--------------------	---------------------	--------------	-----------------------

MVA317154948 / VAC - Kaki Bukit
ENTRY DATE & TIME: 23/11/2017 12:27

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow Insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the Insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 23/11/2017 12:27
Date Of Accident 22/11/2017 08:35
Exact Location Of Accident TAMPINES AVENUE 07
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SJF5432D
Insured/Policyholder
Name Of Registered Owner STARK EXPRESS PTE. LTD.
Co Reg No 201434355Z
Email Address NOEMAIL

Mobile Phone No
Alternative Phone No OFFICE-90000000

Vehicle Particulars
Manufacturer NISSAN
Model LATIO 1.5LA

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own Insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE HIRE

Insurance Company
Name of Insurance Company NTUC INCOME INSURANCE CO-OPERATIVE LTD

Type Of Coverage THIRD PARTY

Fleet Policy YES

Policy Number 5091306656-01

Cover Note Number

Driver
Name of Driver MOHD SHUKRI BIN ABDUL RAHIM

NRIC No S1615486E

Date Of Birth 17/10/1962

Occupation OUTDOOR

Date Of Driving Pass 16/05/1987

Driving Experience 30 YEARS AND 6 MONTHS

Gender MALE

Mobile Number (LOCAL) +65-93807479

Fax Number

Contact Number

Email Address NOEMAIL

Address 1 BUKIT BATOK CRESCENT #06-19 WCEGA PLAZA
Postcode 658064
Was driver an employee of the Insured's Company NO
If No, Relationship of the Driver with the Insured OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle -
Vehicle -
Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Was any body injured in the Accident? NO
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 2

Details of Police Action

Was the accident reported to the police? YES
If Yes, Please state which Police Station
Police Station Name HOUGANG NEIGHBOURHOOD POLICE CENTRE
Police Station Address ROAD: 60 HOUGANG AVE 9, POSTCODE: 538775, COUNTRY: SINGAPORE
Police Station Contact TEL NO: 1800-4890999 - FAX NO: 63128989
Was notice of Intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

AS PER POLICE REPORT No. T/20171122/2046, ATTENDED BY SIT1

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? NO
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GT5778T
Vehicle Make/Model/Colour
Details Of Properties
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

Details of Witness

Name
Phone Number

Email Address

Accident Sketch Plan Pg. 1

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow Insurance companies to repudiate policy liability.
4. The Issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the Insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the judgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the Information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

23 NOV 2017

IDAC KAKI BUKIT (VAC)
23 KAKI BUKIT AVE 4
Singapore 413933

Reporting Centre Officer's Signature
Name: Fax: 67492 105
NRIC/Photo: vackb@singnet.com.sg

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100 101 102 103 104 105 106 107 108 109 110 111 112 113 114 115 116 117 118 119 120 121 122 123 124 125 126 127 128 129 130 131 132 133 134 135 136 137 138 139 140 141 142 143 144 145 146 147 148 149 150 151 152 153 154 155 156 157 158 159 160 161 162 163 164 165 166 167 168 169 170 171 172 173 174 175 176 177 178 179 180 181 182 183 184 185 186 187 188 189 190 191 192 193 194 195 196 197 198 199 200 201 202 203 204 205 206 207 208 209 210 211 212 213 214 215 216 217 218 219 220 221 222 223 224 225 226 227 228 229 230 231 232 233 234 235 236 237 238 239 240 241 242 243 244 245 246 247 248 249 250 251 252 253 254 255 256 257 258 259 260 261 262 263 264 265 266 267 268 269 270 271 272 273 274 275 276 277 278 279 280 281 282 283 284 285 286 287 288 289 290 291 292 293 294 295 296 297 298 299 300 301 302 303 304 305 306 307 308 309 310 311 312 313 314 315 316 317 318 319 320 321 322 323 324 325 326 327 328 329 330 331 332 333 334 335 336 337 338 339 340 341 342 343 344 345 346 347 348 349 350 351 352 353 354 355 356 357 358 359 360 361 362 363 364 365 366 367 368 369 370 371 372 373 374 375 376 377 378 379 380 381 382 383 384 385 386 387 388 389 390 391 392 393 394 395 396 397 398 399 400 401 402 403 404 405 406 407 408 409 410 411 412 413 414 415 416 417 418 419 420 421 422 423 424 425 426 427 428 429 430 431 432 433 434 435 436 437 438 439 440 441 442 443 444 445 446 447 448 449 450 451 452 453 454 455 456 457 458 459 460 461 462 463 464 465 466 467 468 469 470 471 472 473 474 475 476 477 478 479 480 481 482 483 484 485 486 487 488 489 490 491 492 493 494 495 496 497 498 499 500 501 502 503 504 505 506 507 508 509 510 511 512 513 514 515 516 517 518 519 520 521 522 523 524 525 526 527 528 529 530 531 532 533 534 535 536 537 538 539 540 541 542 543 544 545 546 547 548 549 550 551 552 553 554 555 556 557 558 559 560 561 562 563 564 565 566 567 568 569 570 571 572 573 574 575 576 577 578 579 580 581 582 583 584 585 586 587 588 589 590 591 592 593 594 595 596 597 598 599 600 601 602 603 604 605 606 607 608 609 610 611 612 613 614 615 616 617 618 619 620 621 622 623 624 625 626 627 628 629 630 631 632 633 634 635 636 637 638 639 640 641 642 643 644 645 646 647 648 649 650 651 652 653 654 655 656 657 658 659 660 661 662 663 664 665 666 667 668 669 670 671 672 673 674 675 676 677 678 679 680 681 682 683 684 685 686 687 688 689 690 691 692 693 694 695 696 697 698 699 700 701 702 703 704 705 706 707 708 709 710 711 712 713 714 715 716 717 718 719 720 721 722 723 724 725 726 727 728 729 730 731 732 733 734 735 736 737 738 739 740 741 742 743 744 745 746 747 748 749 750 751 752 753 754 755 756 757 758 759 760 761 762 763 764 765 766 767 768 769 770 771 772 773 774 775 776 777 778 779 780 781 782 783 784 785 786 787 788 789 790 791 792 793 794 795 796 797 798 799 800 801 802 803 804 805 806 807 808 809 810 811 812 813 814 815 816 817 818 819 820 821 822 823 824 825 826 827 828 829 830 831 832 833 834 835 836 837 838 839 840 841 842 843 844 845 846 847 848 849 850 851 852 853 854 855 856 857 858 859 860 861 862 863 864 865 866 867 868 869 870 871 872 873 874 875 876 877 878 879 880 881 882 883 884 885 886 887 888 889 890 891 892 893 894 895 896 897 898 899 900 901 902 903 904 905 906 907 908 909 910 911 912 913 914 915 916 917 918 919 920 921 922 923 924 925 926 927 928 929 930 931 932 933 934 935 936 937 938 939 940 941 942 943 944 945 946 947 948 949 950 951 952 953 954 955 956 957 958 959 960 961 962 963 964 965 966 967 968 969 970 971 972 973 974 975 976 977 978 979 980 981 982 983 984 985 986 987 988 989 990 991 992 993 994 995 996 997 998 999 1000 1001 1002 1003 1004 1005 1006 1007 1008 1009 1010 1011 1012 1013 1014 1015 1016 1017 1018 1019 1020 1021 1022 1023 1024 1025 1026 1027 1028 1029 1030 1031 1032 1033 1034 1035 1036 1037 1038 1039 1040 1

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

23 NOV 2017

Name: Email: vackb@slingshot.net.sg

Page 5 of 16

Accident Sketch Plan Pg. 1



**SINGAPORE
POLICE FORCE**



T/20171122/2046

Police Station Of Origin:
Hougang N.P.C
60 Hougang Avenue 9 SINGAPORE 538776
Tel No: 1800-4890999

1 of 3

Report No. T/20171122/2046

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 22/11/2017 12:21		Vide Report No.:		Station Diary No.: 34
Informant's Particulars				
Name of Informant: MOHD SHUKRI BIN ABDUL RAHIM		Address: APT BLK 245 TAMPINES STREET 21 #02-309 SINGAPORE 521246		
ID Type / ID No.: NRIC NO / S1615488E		Contact No.: Home/Office: Mobile: 93807479		
Nationality: SINGAPORE CITIZEN		Email:		
Sex: Male	Age: 54	Date of Birth: 17/10/1963	Type of Informant: Driver	
Race: Malay		Language:	Institution / School Name:	
Occupation: GRAB DRIVER		Driving Licence Information: Class: 2B,2A,3 Date of Expiry:		

General Information of the Accident				
Type of Accident:	Non-Injury Others	Drink Drive: No	Date/Time of Accident: 22/11/2017 08:35	Type of Location: Straight Road
Location: Along Road 1 TAMPINES AVENUE 7 AFTER TAMPINES AVENUE 7				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control:	Traffic Volume: Light	
Type of Collision: Between Moving Vehicles - Head To Rear			Anyone conveyed by ambulance: No	

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No. of Passenger
GT5778T	Van				Slightly Damaged	0
SJF5432D	Car				Slightly Damaged	1

Accident Sketch Plan Pg. 1

**SINGAPORE
POLICE FORCE**

T/20171122/2048

Police Station Of Origin:

Hougang N.P.C

60 Hougang Avenue 9 SINGAPORE 538776

Tel No: 1800-4890999

2 of 3

Report No. T/20171122/2048

CONTINUATION OF REPORT

Brief Details.

On 22/11/2017 at about 0835hrs. I was driving (SJF5432D) along Tampines avenue 7 after avenue 4, I stop my vehicle at the zebra crossing due to the traffic light show red light. Subsequently, the bus on my right move on as the traffic light only show green light for bus. Suddenly a van (GT5778T) from behind hit on to my rear bumper and I went down to make a check, no one was injured and not police attended. I only have a CCTV installed at my front of the car and I have also went to see a doctor and was given 1 day MC.

I am lodging this report for my own record purposed and for my insurance claim.

Accident Sketch Plan Pg. 1

**SINGAPORE
POLICE FORCE**

T/20171122/2046

Police Station Of Origin:
Hougang N.P.C
60 Hougang Avenue 9 SINGAPORE 538775
Tel No: 1800-4890999

3 of 3

Report No. T/20171122/2046

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: F / Sgt 2 LIM JIA HE	
Signature Of Interpreter: Not applicable	
Officer In Charge Of Case: TP / GIA / Staff Sgt TANG SIEW PING Contact No.: 65478430	

Authentication Stamp
NP168

Signature Of Informant:	
Date/Time: 22/11/2017 12:21	
Classification Of Case:	



SK Automobile Pte Ltd
(Co Reg. No. 201500047H)
23 Kaki Bukit Ave 4 #03-01
Vicom Inspection Centre
Singapore 415933
Tel: 6789 5155 Fax : 6783 5155

\$5000

7 days
S.S.D

TO	: CHINA TAIPING INSURANCE	DATE	: 22-Nov-17
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	: Xico Chen		
<u>OWNER'S PARTICULAR</u>		<u>VEHICLE DETAILS</u>	
NAME	:	VEHICLE NO	: SJF5432D
ADDRESS	:	MODEL	: NISSAN LATIO
TEL. NO.	:	CHASSIS NO	: JN1BAACH120008971
OWNER'S INSURANCE	:		
POLICY NO.	:		
<u>ACCIDENT DETAILS</u>		DATE	:
		TIME	:
THIRD PARTY REQUESTOR / CONTACT : WEI HONG / 91920930			

QUOTATION SUMMARY

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	BOOT LID Distorted	1	\$ 995.20	\$ 995.20
2	BOOT LID HINGE	2	\$ 91.10	\$ 182.20
3	REAR FLOOR PANEL Buckled	1	\$ 1,098.00	\$ 1,098.00
4	REAR END PANEL Dented	1	\$ 585.00	\$ 585.00

1578.7
1385.09

TOTAL PRICE \$ 2,860.40
LESS 30% \$ 858.12
SUB TOTAL PRICE \$ 2,002.28

764.60
771.50
1126.0

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	BOOT LID INNER LOCK Dgd	1	\$ 357.60	\$ 357.60
2	BOOT LID STRIKER	1	\$ 38.20	\$ 38.20
3	BOOT LID OPENER SWITCH	1	\$ 289.20	\$ 289.20
4	BOOT LID HINGE	2	\$ 57.60	\$ 115.20

97.50
X
X
X

List
List
List
List

5	BOOT LID WEATHERSTRIP <i>lt</i>	1	\$ 174.90	\$ 174.90
6	BOOT LID CHROME MOULDING <i>2h</i>	1	\$ 329.50	\$ 329.50
7	REAR BUMPER <i>Dishd</i>	1	\$ 694.50	\$ 694.50
8	REAR BUMPER SIDE RETAINER <i>m</i>	2	\$ 79.20	\$ 158.40
9	REAR BUMPER BRACKET <i>LH Dented</i>	2	\$ 99.80	\$ 199.60
10	REAR BUMPER BEAM <i>MM</i>	2	\$ 259.00	\$ 519.00
11	SMART ENTRY ANTENNA <i>Cabled</i>	1	\$ 457.20	\$ 457.20
12	TAILLAMP <i>lt</i>	2	\$ 429.00	\$ 858.00
13	TAILLAMP PANEL <i>Pyr</i>	2	\$ 350.40	\$ 700.80
14	REAR FENDER SIDE INNER TRIM <i>MM</i>	2	\$ 576.30	\$ 1,152.60
15	BOOT LID INNER TRIM <i>MM</i>	1	\$ 246.10	\$ 246.10
16	REAR END PANEL TOP GARNISH <i>Deland</i>	1	\$ 298.00	\$ 298.00
17	REAR FLOOR PANEL BOARD <i>Deland</i>	1	\$ 495.00	\$ 495.00
18	REAR SPARE TYRE BOLT <i>MM</i>	1	\$ 28.50	\$ 28.50
19	REAR EXHAUST PIPE <i>3HP</i>	1	\$ 754.60	\$ 754.60
20	REAR EXHAUST MOUNTING <i>2MM</i>	2	\$ 28.00	\$ 56.00

List

List - 1377.6
Less 30% 264.32

Net 790.00
4.10% 711.09

TOTAL PRICE \$ 7,984.70
LESS 10% \$ 798.47
SUB TOTAL PRICE \$ 7,186.23

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR NUMBER PLATE WITH CASING <i>HPM</i>	1	\$ 50.00	\$ 50.00
2	REAR BUMPER UNDER SPOILER <i>Deland</i>	1	\$ 850.00	\$ 850.00
3	REAR BUMPER CLIP SET <i>m</i>	1	\$ 65.00	\$ 65.00
4	BOOT LID SEALANT <i>MM</i>	1	\$ 80.00	\$ 80.00
5	BOOT LID INNER TRIM CLIP SET <i>MM</i>	1	\$ 55.00	\$ 55.00
6	BOOT LID CHROME MOULDING CLIP SET <i>m</i>	1	\$ 13.00	\$ 13.00
7	BOOT LID SPOILER <i>MM</i>	1	\$ 900.00	\$ 900.00
8	TAILLAMP CLIP SET <i>m</i>	1	\$ 30.00	\$ 30.00
9	TAILLAMP PANEL SEALANT <i>MM</i>	1	\$ 160.00	\$ 160.00
10	REAR FENDER COWLING CLIP SET <i>3mm</i>	1	\$ 90.00	\$ 90.00
11	REAR FENDER INNER TRIM CLIP SET	1	\$ 85.00	\$ 85.00
12	REAR END PANEL TOP GARNISH CLIP SET <i>m</i>	1	\$ 28.00	\$ 28.00
13	REAR END PANEL SEALANT <i>MM</i>	1	\$ 90.00	\$ 90.00
14	REAR FLOOR PANEL SEALANT <i>MM</i>	1	\$ 90.00	\$ 90.00
15	REAR FLOOR PANEL INSULATOR <i>sh</i>	1	\$ 250.00	\$ 250.00
16	REVERSE SENSOR <i>Danged</i>	1	\$ 300.00	\$ 300.00

1093

TOTAL

\$ 3,136.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

1	PANEL BEATING, REMOVAL AND REPLACING PARTS.	\$ 4,800.00	1200	
2	TO SPRAY PAINT ON AFFECTED AREA.	\$ 1,600.00	1200	
3	TO APPLY TUFF COAT.	\$ 220.00	40	
4	PERFORM REAR LIGHTING WIRING CHECK.	\$ 120.00	30	
5	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTERY AND ROOF LINNING TO FACILITATE REPAIR.	\$ 180.00	60	
6	REMOVE AND INSTALL REVERSE SENSOR AND DISTANCE SETTING.	\$ 80.00	40	
7	PERFORM REAR CHASSIS ALIGNMENT.	\$ 250.00	X	
8	REMOVE AND REPLACE SMART KEYLESS ANTENNA AND BUZZER. RESET SMART ENTRY SYSTEM.	\$ 180.00	X	
9	TRANSFER BOOTLID MECHANISM. ADJUST NEW BOOT LID TO PROPER POSITION.	\$ 80.00	X	
10	CONDUCT WATER LEAKAGE TEST.	\$ 80.00	X	
11	REMOVE AND REFIX REAR EXHAUST PIPE.	\$ 120.00	X	

TOTAL

\$ 4,710.00

ESTIMATE REPORT

LKK Auto Repair Ltd. is not responsible for the Repair.

• To resurvey the repair after spray painting

• To display damaged part(s) during resurvey

• Parts prices are subject to confirmation

• Third party survey is on a non-binding basis

• No illegal trade-in price is allowed

• Surveys are subject to insurance company

RE-SURVEY

Acknowledged by Repairer

Signature:

Date:

TOTAL PARTS COST : \$ 12,324.51

TOTAL LABOUR COST : \$ 4,710.00

TOTAL REPAIR COST : \$ 17,034.51

APPROVED DETAILS

EXCESS

NO. OF WORKING DAYS

RE-SURVEY

4/s Adrian G

27/11/17.

07 days.

4/s: SK

4/s: 622350

4/s: SK

PART BY PART OR LUMP SUM :

DATE & TIME OF SURVEY :

SURVEYED BY :

CONTACT NUMBER :

FAX NUMBER :

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	26 Nov 2017		27 Nov 2017 10:20 Edit Adj Rpt	\$5,000.00 Edit Estimates	\$5,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	-----------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	COLOURTREND PAINTS PTE LTD, Co. Reg. No.: 200616131Z		
Main Claimant:	MOHD SHUKRI, ID: S1615486E		
Vehicle Reg. No.:	SJF5432D	Date of Loss:	22/11/2017 08:00 - :59
Claim Type:	TP / SNM17D06745C02/8	Policy/Cover Note No.:	DMCVSN3059541700 (TP, Fire & Theft)
Vehicle Reg. No. (Insured):	GT5778T	Policy No. (Claimant):	
		Excess:	\$0.00
Repairer:	SK Automobile Pte Ltd (HQ) 23 Kaki Bukit Avenue 4, #03-01 Vicom Inspection Centre, 415933 Kaki Bukit - Tel: 67895155		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Joel Goh]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 06/12/2017]		
Adj Asg. Remarks:	NO ESTIMATES. GUO QIANG SELECTED AS SJE FOR WP PRS		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SJF5432D (SNM17D06745C02/8)**
[GT5778T]

TP

MOHD SHUKRI

Nov 22 2017 8:00AM

[COLOURTREND PAINTS PTE LTD]

SK Automobile Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			View View in Browser		
Assessment Reports									1 per page		☒
No	Finalized On	K Kim Hin Auto Pte Ltd (HQ)							Thumbnail	Print	
1	22/11/17 18:21	Accident Statement								Load HTM	
Photos/Images									3 per page		☒
No	Finalized On	K Kim Hin Auto Pte Ltd (HQ)							Thumbnail	Print	
1	22/11/17 18:19	Accident Photo [Linked Accident Report Documents]								Load JPG	☒
2	22/11/17 18:19	Accident Photo [Linked Accident Report Documents]								Load JPG	☒
3	22/11/17 18:19	Accident Photo [Linked Accident Report Documents]								Load JPG	☒
4	22/11/17 18:19	Accident Photo [Linked Accident Report Documents]								Load JPG	☒
5	22/11/17 18:19	Accident Photo [Linked Accident Report Documents]								Load JPG	☒
6	22/11/17 18:19	Accident Photo [Linked Accident Report Documents]								Load JPG	☒
7	22/11/17 18:19	Accident Photo [Linked Accident Report Documents]								Load JPG	☒
8	22/11/17 18:19	Accident Photo [Linked Accident Report Documents]								Load JPG	☒
9	22/11/17 18:19	Accident Photo [Linked Accident Report Documents]								Load JPG	☒
10	22/11/17 18:19	Accident Photo [Linked Accident Report Documents]								Load JPG	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print	
1	29/01/18 18:51	General View								Load JPG	☒
2	29/01/18 18:51	Chassis Number								Load JPG	☒
3	29/01/18 18:51	General View								Load JPG	☒
4	29/01/18 18:51	General View								Load JPG	☒
5	29/01/18 18:51	General View								Load JPG	☒
6	29/01/18 18:51	General View								Load JPG	☒
7	29/01/18 18:51	General View								Load JPG	☒
8	29/01/18 18:51	General View								Load JPG	☒
9	29/01/18 18:51	General View								Load JPG	☒
10	29/01/18 18:51	General View								Load JPG	☒
11	29/01/18 18:51	General View								Load JPG	☒
12	29/01/18 18:51	General View								Load JPG	☒
13	29/01/18 18:51	General View								Load JPG	☒
14	29/01/18 18:51	General View								Load JPG	☒
15	29/01/18 18:51	General View								Load JPG	☒
16	29/01/18 18:51	General View								Load JPG	☒
17	29/01/18 18:51	General View								Load JPG	☒
18	29/01/18 18:51	General View								Load JPG	

			1		☒
19	29/01/18 18:51	General View	1	Load JPG	☒
20	29/01/18 18:51	General View	1	Load JPG	☒
21	29/01/18 18:51	General View	1	Load JPG	☒
22	29/01/18 18:51	General View	1	Load JPG	☒
23	29/01/18 18:51	General View	1	Load JPG	☒
24	29/01/18 18:51	General View	1	Load JPG	☒
25	29/01/18 18:51	General View	1	Load JPG	☒
26	29/01/18 18:51	General View	1	Load JPG	☒
27	29/01/18 18:51	General View	1	Load JPG	☒
28	29/01/18 18:51	General View	1	Load JPG	☒
29	29/01/18 18:51	General View	1	Load JPG	☒
30	29/01/18 18:51	General View	1	Load JPG	☒
31	29/01/18 18:51	General View	1	Load JPG	☒
32	29/01/18 18:51	General View	1	Load JPG	☒
33	29/01/18 18:51	General View	1	Load JPG	☒
34	29/01/18 18:51	General View	1	Load JPG	☒
35	29/01/18 18:51	General View	1	Load JPG	☒
36	29/01/18 18:51	General View	1	Load JPG	☒
37	29/01/18 18:51	General View	1	Load JPG	☒
38	29/01/18 18:51	General View	1	Load JPG	☒
39	29/01/18 18:51	General View	1	Load JPG	☒
40	29/01/18 18:51	General View	1	Load JPG	☒
41	29/01/18 18:51	General View	1	Load JPG	☒
42	29/01/18 18:51	General View	1	Load JPG	☒
43	29/01/18 18:51	General View	1	Load JPG	☒
44	29/01/18 18:51	General View	1	Load JPG	☒
45	29/01/18 18:51	General View	1	Load JPG	☒
46	29/01/18 18:51	General View	1	Load JPG	☒
47	29/01/18 18:51	General View	1	Load JPG	☒
48	29/01/18 18:51	General View	1	Load JPG	☒
Documentation					1 per page ☒
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	27/11/17 10:21	OI GIA REPORT	1	Load PDF	
No	Finalized On	K Kim Hin Auto Pte Ltd (HQ)		Thumbnail	Print
1	22/11/17 18:18	Sketch Plan [Linked Accident Report Documents]	1	Load TIF	

Linked Accident Report Documents

View

Assessment Reports			1 per page	☒	
No	Finalized On	K Kim Hin Auto Pte Ltd (HQ)		Thumbnail	Print
1	22/11/17 18:21	Accident Statement	1	Load HTM	
Photos/Images			3 per page	☒	
No	Finalized On	K Kim Hin Auto Pte Ltd (HQ)		Thumbnail	Print
1	22/11/17 18:19	Accident Photo	1	Load JPG	☒
2	22/11/17 18:19	Accident Photo	1	Load JPG	☒
3	22/11/17 18:19	Accident Photo	1	Load JPG	☒
4	22/11/17 18:19	Accident Photo	1	Load JPG	☒

5	22/11/17 18:19	Accident Photo		Load JPG	☒
6	22/11/17 18:19	Accident Photo		Load JPG	☒
7	22/11/17 18:19	Accident Photo		Load JPG	☒
8	22/11/17 18:19	Accident Photo		Load JPG	☒
9	22/11/17 18:19	Accident Photo		Load JPG	☒
10	22/11/17 18:19	Accident Photo		Load JPG	☒
Documentation					
				1 per page	☒
No	Finalized On	K Kim Hin Auto Pte Ltd (HQ)		Thumbnail	Print
1	22/11/17 18:18	Sketch Plan		Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT17022520/AQBE2

Date: 05/02/2018

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSN3059541700

Claimant Vehicle
No : SJF5432DInsured Vehicle
No : GT5778T

Date of Loss: 22/11/2017

Nature of Claim: TP

Claim
No: SNM17D06745C02/8

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJF5432D**

Make & Model: NISSAN LATIO, 1.5 L (A)

Engine No: HR15179061A

Reg. Date: 02/06/2008 (Man. Year: 2007)

Chassis No: JN1BAAC11Z0005971

Colour: Silver

Odometer: 185958 km

Engine Capacity: 1498 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size: 195/65 R15

Front Left Side: Falken 6 mm

Rear Left Side: Falken 6 mm

Front Right Side: Falken 6 mm

Rear Right Side: Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,324.51	4,153.50	8,171.01	66.30
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,710.00	2,570.00	2,140.00	45.44
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,034.51	6,723.50	10,311.01	60.53
Approved Total (Overridden) (S\$)		5,000.00		
(S\$)	17,034.51	5,000.00	12,034.51	70.65
+ GST 7.00/7.00% (S\$)	1,192.42	350.00	842.42	70.65
Nett Amount (S\$)	18,226.93	5,350.00	12,876.93	70.65

INSPECTION

Date of Assignment: 27/11/2017

Date Inspected: 27/11/2017 Inspected At:

 SK Automobile Pte Ltd (HQ)
 23 Kaki Bukit Avenue 4, #03-01 Vicom
 Inspection Centre
 Singapore 415933

Estimated Period of Repair: 7.0 days

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 05 Feb 2018)
Parts: 143 NISSAN LATIO 1.5 L (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SJF5432D)
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID	Distorted	995.20 FL	*764.60 FL
2	2		*BOOT LID HINGE	Not Necessary	182.20 FL	*- FL
3	1		*REAR FLOOR PANEL	Buckled	1,098.00 FL	*771.50 FL
4	1		*REAR END PANEL	Dented	585.00 FL	*442.60 FL
5	1		*BOOT LID INNER LOCK	Damaged	357.60 FN	*97.90 FN
6	1		*BOOT LID STRIKER	Not Necessary	38.20 FN	*- FN
7	1		*BOOT LID OPENER SWITCH	Not Necessary	289.20 FN	*- FN
8	2		*BOOT LID HINGE	Not Necessary	115.20 FN	*- FN
9	1		*BOOT LID WEATHERSTRIP	Cut	174.90 FN	*57.00 FN
10	1		*BOOT LID CHROME MOULDING	Deformed	296.55 FS	*180.18 FS
11	1		*REAR BUMPER	Distorted	625.05 FS	*356.30 FS
12	2		*REAR BUMPER SIDE RETAINER	Necessary	142.56 FS	*49.28 FS
13	1		*REAR BUMPER BRACKET	N/S Dented	179.64 FS	*32.06 FS
14	2		*REAR BUMPER BEAM	Not Necessary	519.00 FN	*- FN
15	1		*SMART ENTRY ANTENNA	Cracked	519.00 FN	*57.50 FN
16	2		*TAILLAMP	Cut	858.00 FN	*504.60 FN
17	2		*TAILLAMP PANEL	Repair	700.80 FN	*- FN
18	2		*REAR FENDER SIDE INNER TRIM	Not Necessary	1,152.60 FN	*- FN
19	1		*BOOT LID INNER TRIM	Not Necessary	246.10 FN	*- FN
20	1		*REAR END PANEL TOP GARNISH	Deformed	298.00 FN	*73.10 FN
21	1		*REAR FLOOR PANEL BOARD	Deformed	445.50 FS	*346.50 FS
22	1		*REAR SPARE TYRE BOLT	Not Necessary	28.50 FN	*- FN
23	1		*REAR EXHAUST PIPE	Not Necessary	754.60 FN	*- FN
24	2		*REAR EXHAUST MOUNTING	Not Necessary	56.00 FN	*- FN
25	1		*REAR NUMBER PLATE WITH CASING	Not Necessary	50.00 FS	*- FS
26	1		*REAR BUMPER UNDER SPOILER	Deformed	850.00 FS	*550.00 FS
27	1		*SET REAR BUMPER CLIP	Necessary	65.00 FS	*30.00 FS
28	1		*BOOT LID SEALANT	Not Necessary	80.00 FS	*- FS
29	1		*SET BOOTLID INNER TRIM CLIP	Not Necessary	55.00 FS	*- FS
30	1		*SET BOOTLID CHROME MOULDING CLIP	Necessary	13.00 FS	*13.00 FS
31	1		*BOOT LID SPOILER	Not Necessary	900.00 FS	*- FS
32	1		*SET TAILLAMP CLIP	Necessary	30.00 FS	*30.00 FS
33	1		*TAILLAMP PANEL SEALANT	Not Necessary	160.00 FS	*- FS
34	1		*SET REAR FENDER COWLING CLIP	Not Necessary	90.00 FS	*- FS
35	1		*SET REAR FENDER INNER TRIM CLIP	Not Necessary	85.00 FS	*- FS
36	1		*SET REAR END PANEL TOP GARNISH CLIP	Necessary	28.00 FS	*10.00 FS
37	1		*REAR END PANEL SEALANT	Necessary	90.00 FS	*60.00 FS
38	1		*REAR FLOOR PANEL SEALANT	Not Necessary	90.00 FS	*- FS
39	1		*REAR FLOOR PANEL INSULATOR	Necessary	250.00 FS	*200.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1		*REVERSE SENSOR	Damaged	300.00 FS	*200.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.						
Sub Total (S\$)					13,793.40	4,826.12
- List Item Discount on L Items 30.00/30.00% (S\$)					858.12	593.61
- Nett Item Discount on N Items 10.00/10.00% (S\$)					610.77	79.01
Total Parts (S\$)					12,324.51	4,153.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	New	1,800.00	1,200.00
2	TO SPRAY PAINT ON AFFECTED AREA	New	1,600.00	1,200.00
3	TO APPLY TUFF COAT	New	220.00	40.00
4	PERFORM REAR LIGHTING WIRING CHECK	New	120.00	30.00
5	REMOVE AND REFIX CUSHION SEAT / UPHOLSTRY AND ROOF LINING TO FACILITATE REPAIR	New	180.00	60.00
6	REMOVE AND INSTALL REVERSE SENSOR AND DISTANCE SETTING	New	80.00	40.00
7	PERFORM REAR CHASSIS ALIGNMENT	New	250.00	0.00
8	REMOVE AND REPLACE SMART KEYLESS ANTENNA AND BUZZER. RESET SMART ENTRY SYSTEM	New	180.00	0.00
9	TRANSFERS BOOTLID MECHANISM. ADJUST NEW BOOT LID TO PROPER POSITION	New	80.00	0.00
10	CONDUCT WATER LEAKAGE TEST	New	80.00	0.00
11	REMOVE AND REFIX REAR EXHAUST PIPE	New	120.00	0.00
Gross Labour Cost (\$\$)			4,710.00	2,570.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >