

ASS. REC. BY:

REF: CS/CTI17022523/A9bⁿ²

Special Instruction:

Surveyor: Adrian

ASSIGNMENT (Office)

Menimen

From (Person): Joel Goh

of

CTI

Date/Time: 27/11/17 @ 10:26am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLP 6196C

Insured:

SJR 9865Z

at Workshop m/s

SK Automobile

Tel:

67895155

of 23 Kekki Bukit Ave 4, # 03-01, 415933

Policy No:

DMHCSN1687081600

Claim No:

SNM17D06770C02/5

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

22/11/2017

CA / REV / REP. / REV 24 HRS

lwp

H.O.D. Endorsement:

Date/Time:

11:01am @ 27/11/17

Person Contacted:

Siew

Vehicle ☒ IN ☐ OUT

Date/Time

Action/Instruction (☒ Estimate

SLP 6196C-X

SJR 9865Z-X

vs 4820, 6 days, (had to 19543.47, 70%)

ASSIGNMENT

From: Date: 27/11/17

Estimated Cost:

QD ☒ WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SLP 6196C

at Workshop this: SK Automobile

of 23 Kelki Bukit Ave 4, #03-01, 415993

Insured:

Policy No:

Claims No:

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 6 days Res.: Yes or No

Lump Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS 1wp

Date: Person Contacted:

Vehicle: IN / OUT

Date / Time: Action / Instruction

TP China.

RECEIVED 01 MAR 2019

Veh No: SLP 6196C In Page: 2017 June

Type: ☒ M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover

Truck / Trailer or

Make: Lexus IS200 - 1998

Colour: White - A.O. Insured / Std / NI / NA

Sp. Reading: 8054 - T. Paid: Insured / Std / NI / NA

Eng No:

O No: JTHBAID2205054103.

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orMod: Nil / ☒ R/Rim / STD A/Rim or

Tyre Size: F: 225/45 R17

R: 225/45 R17.

☒ BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front:

R. Bal. 06 mm

L. Bal. 06 mm

D.O.A.:

Survey held at: SK.

Des. of Damages: Frt: ☒ Rear: ☐ O/S: ☐ N/S: ☐ U/C: ☐ Rooftop: ☐

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time: File Pass to:



Prel. Report



Final Report

01/3 thair

Date/Time: File Return to:

Days Of Repair: 6

Resurvey No. of Trip: 1

Survey Fee

Transportation

STAFF

Other

Total

TOTAL

Add Fee:



Site Insp: \$



Interview: \$



Tech Insp: \$



Web and: \$

Report Format:

Lump Sum: ☒

MER - TP

8200



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CS/CTI17022523/Aqb		
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 27-11-2017		
		Code : CTI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJR 9865Z	Veh. Inspected	SLP 6196C	
Policy No.	DMHCSN1687081600	Coverage (\$)	0.00	
Claim No.	SNM17D06770C02/5	Excess (\$)	0.00	
Assign From	MERIMEN (JOEL GOH)	Assign Date	27/11/2017	
2. Vehicle Particulars & Condition				
Make & Model	c.c		0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.	Colour			
Odometer	-	Steering		
Brakes	Modification			
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	22/11/2017	Inspection Date	27/11/2017	
Survey held at	SK AUTOMOBILE PTE LTD 23 KAKI BUKIT AVE 4 # 03-01 SINGAPORE 415933			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	26 Nov 2017		27 Nov 2017 10:26 Assign				New Assignment Cancel Case

[Main](#)[Reference](#)[Claim Details](#)[Documents](#)[Show All](#)

CLAIM SUBFOLDER DETAILS

[\[Created by insurer\]](#)

Insured:			
Main Claimant:	PHUAH LEE CHING		
Vehicle Reg. No.:	SLP6196C	Date of Loss:	22/11/2017 00:00 - :59
Claim Type:	TP / SNM17D06770C02/5	Policy/Cover Note No.:	DMHCSN1687081600
Vehicle Reg. No. (Insured):	SJR9865Z	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	SK Automobile Pte Ltd (HQ) 23 Kaki Bukit Avenue 4, #03-01 Vicom Inspection Centre, 415933 Kaki Bukit - Tel: 67895155		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Joel Goh]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 06/12/2017]		
Adj Asg. Remarks:	NO ESTIMATES. GUO QIANG SELECTED AS SJE FOR WP PRS		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.

Joel Goh

From: SK Admin <admin@skauto.com.sg>
Sent: Friday, 24 November, 2017 2:53 PM
To: Joel Goh
Cc: JING XIONG KHOO; Yeam Wei Hong
Subject: Re: Arrange surveyor for SLP6196C Your Ref:SJR9865Z (SNM17D06770C02/5)

Dear Joel,

Thanks for your reply.
We choose surveyor: Xing Guo Qiang

Regards,
Huey Lee
SK Automobile Pte Ltd

On Fri, Nov 24, 2017 at 2:47 PM, Joel Goh <joel.goh@sg.cntaiping.com> wrote:

Without Prejudice

Dear Huey Lee

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

TAY BENG HEE
DERECK OH SIONG WEE
SEE CHEW SENG
MOHD FADHILAH BIN OSMAN
XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA
HENRY NG

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Best Regards

Joel Goh

Claims Executive (Motor Division)

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-02

Springleaf Tower Singapore 079909

Co. Reg. No. 200208384E

DID: 6389 6184

Fax: 6224 7175 / 6224 7478

Email: claimsdept@sg.cntaiping.com

joel.goh@sg.cntaiping.com

Website: www.sg.cntaiping.com

Disclaimer : This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: SK Admin [<mailto:admin@skauto.com.sg>]

Sent: Wednesday, 22 November, 2017 5:51 PM

To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>

Cc: JING XIONG KHOO <xiongskauto@gmail.com>; Yeam Wei Hong <yeamweihong@skauto.com.sg>

Subject: Arrange surveyor for SLP6196C Your Ref:SJR9865Z

Dear Sir / Mdm,

We the repairers of motor vehicle no. SLP6196C

Please provide a list of surveyor for further inspection.

Location : 8 Kaki Bukit Ave 4#08-46

Premier @ Kaki Bukit

Singapore 415875

Contact No : 8121 0478 Xiong

We appreciate your early reply.

Thanks.

--

*Regards,
Huey Lee*

SK Automobile Pte Ltd

Tel: 6789 5155 Fax: 6783 5155

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

facebook

www.facebook.com/sgcarmart



our official
Facebook page now!

Username / Email Add

password



Connect

Sign Up New Account

Forgot Password

Post an Advertisement

Sell it yourself! Advertise it at just

\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

June 2009 Nissan Teana 2.5A At \$31K Top Condition.



Well Maintained And
Immaculate Interior. Careful
Owner. Low Mileage. High Part
Direct Owner. Start Ad



Sort by Date Posted

20 results/page

9 vehicles

Lexus IS200

Basic Search



Price Any price

Depre Any depre

Reg Date Any date

Eng Cap

Any

Veh Type All types

Fuel

Any fuel

Mileage Any

OMV Any

Gear

Any Gear

Past Owners Any

Category All categories

Scheme All schemes

Dealer Any Dealer

Location Any

Status Any status

Make & Model

Price

Depreciation

Reg Date

Eng Cap

Mileage

Veh Type

Status



**Lexus IS Turbo IS200t
Executive**

\$158,000

\$14,940 /yr

23-Dec-2016

1,998 cc

11,800 km

Luxury

Available

Downpayment \$15,800 Only! 1 Owner, Fully Serviced By Agent, Genuine Mileage. Valid Borneo Warranty Until 2019/100,000km. 3 Servicing Packages For New Owner. Immaculately Maintained, Spanking New! Come...

Cars 88 Pte Ltd

Posted: 18-Nov-2017 Tags: 2016 Lexus IS, 2016 Lexus IS, Lexus IS, Lexus IS, Lexus IS, IS, Used Lexus

Details



**Lexus IS Turbo IS200t
Executive**

\$146,800

\$14,580 /yr

06-Jun-2016

1,998 cc

28,000 km

Luxury

Available

100% Cheapest In The Market! 5 Year Warranty, 3 Year Free Servicing. Full Serviced By Borneo Motors. Car Is Accident Free! Call Now To Make Your Appointment! \$10-13k Drive Away.

Mayfair Motoring

Posted: 16-Nov-2017 Tags: 2016 Lexus IS, 2016 Lexus IS, Lexus IS, Lexus IS, Lexus IS, IS, Used Lexus

Details



**Lexus IS200 (COE till
03/2019)**

\$19,800

\$14,690 /yr

30-Mar-1999

1,988 cc

271,881 km

Luxury

Available

Classy 4 Doors Sports Car In Stylish Silver And Large Sports Rims. Purring 2.0L Engine, Reliable Gearbox, Reverse Radar And Seat Heating. No Repairs Needed.

Posted: 09-Nov-2017 Tags: 1999 Lexus IS200, 1999 Lexus IS200, Lexus IS200, Lexus IS200, Lexus IS200, IS200, Used Lexus

Details



**Lexus IS Turbo IS200t
Executive**

-

N.A

23-Dec-2016

1,998 cc

-

Luxury

SOLD

Best Buy In The Almost New Car Category! Lowest Mileage In The Market And Still Has New Car Scent. Bidded Number 2088 Included In The Price. 8 Speed Auto Transmission For Extremely Smooth Ride. Comes ...

Posted: 22-Oct-2017 Tags: 2016 Lexus IS, 2016 Lexus IS, Lexus IS, Lexus IS, Lexus IS, IS, Used Lexus

Details

Car Buying

Car Selling

Car Aftermarket

Car Ownership

On The Move

Lifestyle



**Lexus IS Turbo IS200t
Executive**

-

N.A

10-Aug-2016

1,998 cc

-

Luxury

SOLD

Fully Serviced By Agent With Valid Warranty. Down Payment Of 20% With Monthly Installment From \$1900. Highly Desirable And Stylish Luxury Compact Sedan.

VinCar Pte Ltd

Posted: 18-Oct-2017 Tags: 2016 Lexus IS, 2016 Lexus IS, Lexus IS, Lexus IS, Lexus IS, IS, Used Lexus

Details



**Lexus IS Turbo IS200t
Executive**

-

N.A

26-Feb-2016

1,998 cc

-

Luxury

SOLD

Agent Unit W/ Producing 241 Warranty! Low Mileage! Road Tax Till Feb 2018! 1 Owner Only! As Good As Brand New, Performance Inspired Luxury Sedan ; Well Maintained In Tip Top Condi...

Details

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type	Singapore NRIC
Owner ID	1557Z
Vehicle Details	
Vehicle No.	SLP6196C
Vehicle to be Exported	Yes
Intended De-registration Date	22 Nov 2017
Vehicle Make	TOYOTA
Vehicle Model	LEXUS IS200T EXECUTIVE
Primary Colour	White
Manufacturing Year	2017
Engine No.	8ARZ079126
Chassis No.	JTHBA1D2205054103
Maximum Power Output	180.0 kW (241 bhp)
Open Market Value	\$38,430.00
Original Registration Date	13 Jun 2017
First Registration Date	13 Jun 2017
Transfer Count	0
Actual ARF Paid	\$45,802.00
Intended PARF Rebate Details	
PARF Eligibility	Yes
PARF Eligibility Expiry Date	12 Jun 2027
PARF Rebate Amount	\$34,351.00
Intended COE Rebate Details	
COE Expiry Date	12 Jun 2027
COE Category	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years)	10
QP Paid	\$50,110.00
COE Rebate Amount	\$40,088.00
Total Rebate Amount	\$74,439.00

The information contained herein is correct as at 22 Nov 2017

OK

MALP17154687 / Alpine Motors Pte Ltd - HQ
ENTRY DATE & TIME: 22/11/2017 16:30

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 22/11/2017 16:30
Date Of Accident 22/11/2017 10:50
Exact Location Of Accident PIE TWDS CHANGI (OUTSIDE THE EXIT LOR 6 TOA PAYOH)
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLP6198C
Insured/Policyholder
Name Of Registered Owner PHUAH LEE CHING
NRIC No S1641557Z
Email Address NOEMAIL
Mobile Phone No (LOCAL) +65-96623410
Alternative Phone No OFFICE-60000000
Vehicle Particulars
Manufacturer LEXUS
Model IS-200 (A)
Exact Purpose for which vehicle was being used at time of accident PRIVATE USE
Are you claiming under your own Insurance policy for repair to your vehicle? NO
If No, Please state action to be taken THIRD PARTY
Vehicle Category PRIVATE CAR
Insurance Company
Name of Insurance Company AXA INSURANCE PTE LTD
Type Of Coverage COMPREHENSIVE
Fleet Policy NO
Policy Number CN632957
Cover Note Number
Driver
Name of Driver PHUAH LEE CHING
NRIC No S1641557Z
Date Of Birth 17/01/1964
Occupation INDOOR
Date Of Driving Pass 20/09/2010
Driving Experience 7 YEARS AND 2 MONTHS
Gender FEMALE
Mobile Number (LOCAL) +65-96623410
Fax Number
Contact Number OFFICE-60000000
Email Address NOEMAIL

Address

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OWNER

Vehicle Registration Number of Driver's Own Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

COLLISION - HEAD TO REAR

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Was any body injured in the Accident? YES

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

Report please refer to Sketch plan

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SJR9865Z

Vehicle Make/Model/Colour

Details Of Properties

Name of Driver WESLEY

NRIC/Passport Number

Contact Number 97799908

Address

Postcode

Insurance Company Name

CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

DETAILS OF INJURED PERSON 1

Name PHUAH LEE CHING

Approximate Age 53

Injuries Sustain	UNKNOWN
Injured person in which vehicle?	SLP6196C
Were seat belts worn?	YES
Was Injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

Sketch Plan

~~CONFIDENTIAL~~**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be submitted by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wrong misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police, for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims, (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in qualifying, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time

Driver's Signature
(if driver is not the policyholder)
Date & Time

Reporting Centre Person's Signature
Name: P. S. S. S.
NIC/FIN No.: 57112090

Sketch Plan #2



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 22/11/17 at about 1050 hrs, I was travelling along PIE towards Changi (just outside Lor 6 Toa Payoh exit).

Traffic flow was moderate. Vehicle in front slowed and I followed suit. I braked and stopped my car momentarily as vehicle in front applied brake and stopped.

Suddenly I felt an impact in the rear of my car. I realised SJR 9865Z travelling behind me hit the back of my car and caused the accident.

My car was damaged as a result.

DECLARATION

I/we declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)

Reporting Centre Personnel's Signature
Name: A. J. J. J.



SK Automobile Pte Ltd
(Co Reg. No. 201500047H)
23 Kaki Bukit Ave 4 #03-01
Vicom Inspection Centre
Singapore 415933
Tel: 6789 5155 Fax : 6783 5155

TO	: CHINA TAIPING INSURANCE	DATE	: 22-Nov-17
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
<u>OWNER'S PARTICULAR</u>		<u>VEHICLE DETAILS</u>	
NAME	: Xiao Chen	VEHICLE NO	: SLP6196C
ADDRESS	:	MODEL	: LEXUS IS200
TEL. NO.	:	CHASSIS NO	: JTHBAID2205054103
OWNER'S INSURANCE	:		
POLICY NO.	:		
<u>ACCIDENT DETAILS</u>	DATE :		
	TIME :		
THIRD PARTY REQUESTOR / CONTACT : WEI HONG / 91920930			

QUOTATION SUMMARY

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR PARKING SENSOR UNIT <i>3 pieces</i>	4	\$ 258.30	\$ 1,033.20
2	REAR PARKING SENSOR RETAINER <i>3 pieces</i>	4	\$ 29.00	\$ 116.00
3	REAR PARKING SENSOR WIRE HARNESS <i>NP</i>	1	\$ 185.40	\$ 185.40
4	REAR BUMPER <i>Detached</i>	1	\$ 1,328.60	\$ 1,328.60
5	REAR BUMPER LOWER LIP <i>Detached</i>	1	\$ 788.30	\$ 788.30
6	REAR BUMPER TOWING COVER <i>Detached</i>	1	\$ 42.30	\$ 42.30
7	REAR BUMPER REFLECTOR <i>Cracked</i>	2	\$ 207.40	\$ 414.80
8	REAR BUMPER REINFORCEMENT <i>Bent</i>	1	\$ 453.60	\$ 453.60
9	REAR BUMPER REINFORCEMENT SPONGE <i>Cracked</i>	1	\$ 288.20	\$ 288.20
10	REAR BUMPER UPPER BRACKET <i>Scratched</i>	2	\$ 112.10	\$ 224.20
11	REAR BUMPER SIDE RETAINER <i>Scratched</i>	2	\$ 98.20	\$ 196.40
12	SMART ENTRY ANTENNA <i>Cracked</i>	1	\$ 375.70	\$ 375.70

774.50

87

486 x

1080

220

13	SMART ENTRY ANTENNA BRACKET <i>new</i>	1	\$ 97.60	\$ 97.60	+
14	BOOT LID <i>Buckled</i>	1	\$ 1,781.30	\$ 1,781.30	→ 1K50
15	BOOT LID CHROME MOULDING <i>new</i>	1	\$ 556.30	\$ 556.30	+
16	BOOT LID HINGES <i>new</i>	2	\$ 115.30	\$ 230.60	+
17	BOOT LID WEATHERSTRIP <i>new</i>	1	\$ 270.50	\$ 270.50	-
18	BOOT LID STOPPER <i>new</i>	2	\$ 45.00	\$ 90.00	+
19	BOOT LID INNER LOCK <i>new</i>	1	\$ 656.30	\$ 656.30	385
20	BOOT LID STRIKER <i>new</i>	1	\$ 105.90	\$ 105.90	+
21	BOOT LID EMBLEM <i>2</i>	1	\$ 118.00	\$ 118.00	-
22	BOOT LID EMBLEM "IS" <i>new</i>	1	\$ 95.00	\$ 95.00	-
23	BOOT LID EMBLEM "200"	1	\$ 94.30	\$ 94.30	-
24	BOOT LID EMBLEM "LEXUS"	1	\$ 108.40	\$ 108.40	-
25	REAR END PANEL <i>new</i>	1	\$ 903.50	\$ 903.50	-
26	REAR END PANEL TOP GARNISH <i>new</i>	1	\$ 728.60	\$ 728.60	295
27	REAR FLOOR PANEL TOP BOARD <i>new</i>	1	\$ 824.40	\$ 824.40	455
28	REAR FLOOR PANEL SIDE TOOL BOX <i>new</i>	2	\$ 323.80	\$ 647.60	+
29	BOOT LID INNER TRIM <i>new</i>	1	\$ 646.30	\$ 646.30	+
30	REAR FENDER SIDE INNER TRIM <i>new</i>	2	\$ 956.10	\$ 1,912.20	+
31	BOOT LID LAMP <i>new</i>	2	\$ 846.80	\$ 1,693.60	+
32	TAILLAMP <i>2H ut</i>	2	\$ 1,347.20	\$ 2,694.40	1347.20 688.
33	EXHAUST PIPE SILENCER (DUAL PIPE) <i>new</i>	1	\$ 2,129.60	\$ 2,129.60	+
34	EXHAUST PIPE HEAT SHIELD <i>3 new</i>	1	\$ 146.60	\$ 146.60	+
35	EXHAUST PIPE MOUNTING	2	\$ 35.30	\$ 70.60	+

9169.10
8252.19

TOTAL PRICE	\$ 22,048.30
LESS 10%	\$ 2,204.83
SUB TOTAL PRICE	\$ 19,843.47

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR NUMBER PLATE WITH CASING <i>new</i>	1	\$ 50.00	\$ 50.00
2	REAR-VIEW REVERSE CAMERA SET <i>new</i>	1	\$ 1,300.00	\$ 1,300.00
3	REAR BUMPER CLIP SET <i>new</i>	1	\$ 70.00	\$ 70.00
4	REAR FENDER INNER SHIELD CLIP SET <i>new</i>	1	\$ 45.00	\$ 45.00
5	BOOT LID JOINT SEALANT <i>new</i>	1	\$ 90.00	\$ 90.00
6	BOOT LID INNER TRIM CLIP SET <i>new</i>	1	\$ 70.00	\$ 70.00
7	REAR END PANEL TOP GARNISH CLIP SET <i>new</i>	1	\$ 45.00	\$ 45.00
8	REAR END PANEL SEALANT <i>new</i>	1	\$ 90.00	\$ 90.00
9	REAR FLOOR PANEL SEALANT <i>new</i>	1	\$ 90.00	\$ 90.00

10	REAR FLOOR PANEL INSULATOR	2	1	\$ 300.00	\$ 300.00	*
11	REAR FENDER SIDE INNER TRIM CLIP SET	1	2	\$ 65.00	\$ 130.00	*
12	REAR END PANEL JOINT SEALANT	1	1	\$ 90.00	\$ 90.00	*

100 SUB TOTAL PRICE \$ 2,370.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

1	CUT OFF, REPLACE REAR END PANEL AND FLOOR PANEL. STRAIGHTEN, REALIGN REAR CHASSIS FRAME AND RENEW OTHER DAMAGE PARTS.	\$ 1,800.00	800	
2	SPRAY PAINTING ON DAMAGE AND AFFECTED AREA.	\$ 1,600.00	800	
3	DISMENTLE AND INSTALL EXHAUST PIPE SYSTEM TO ENABLE REPAIRS.	\$ 200.00	*	
4	REMOVE AND INSTALL REAR PARKING SENSOR AND WIRING HARNESS. PERFORM DISTANCE SENSORY TESTING.	\$ 200.00	50	
5	RENEW REAR FLOOR INSULATOR.	\$ 100.00	*	
6	REMOVE AND REPLACE SMART KEYLESS ANTENNA AND BUZZER. RESET SMART ENTRY SYSTEM.	\$ 200.00	50	
7	DISMENTLE AND INSTALL REAR SEATS, SPEAKER BOARD AND SEATS TRIMMING.	\$ 150.00	*	
8	PERFORM REAR LIGHTING WIRING CHECK AND TEST FUCTION.	\$ 200.00	30	
9	REMOVE AND INSTALL REAR MULTI-VIEW CAMERA ASSY. PERFORM AIMING AND ADJUST TO POSITION.	\$ 200.00	60	
10	CONDUCT WATER LEAKAGE ON WELDING JOINT AREA.	\$ 100.00	*	
11	REMOVE AND INSTALL FUEL TANK AND FUEL PIPING TO ENABLE REPAIRS.	\$ 200.00	*	
12	TRANSFER BOOT LID ATTACHMENT AND MECHANISM INTO NEW BOOT LID ASSY. RE-ALIGN TO POSITION.	\$ 180.00	60	
13	DISMENTLE AND RE-INSTALL REAR INTERIOR COMPARTMENT TRIMMING.	\$ 200.00	60	

14	APPLY TUFF COATING TREATMENT.	\$	200.00	50	
----	-------------------------------	----	--------	----	--

SUB TOTAL

\$ 5,530.00

1960

ESTIMATE REPORT

TOTAL PARTS COST : \$ 22,213.47
TOTAL LABOUR COST : \$ 5,530.00
TOTAL REPAIR COST : \$ 27,743.47

APPROVED DETAILS

EXCESS :
NO. OF WORKING DAYS :
RE-SURVEY :

PART BY PART OR LUMP SUM :

DATE & TIME OF SURVEY :
SURVEYED BY :
CONTACT NUMBER :
FAX NUMBER :

Adrian Lj

L/s 27/11/17.

06 days

total: 10312.19

L/s: 8.2K.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary dem(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:
Signature:
Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI17022523/AQBN2

Date: 04/03/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMHCSN1687081600	
Claimant Vehicle No :	SLP6196C	Insured Vehicle No :	SJR9865Z	
Date of Loss:	22/11/2017	Nature of Claim:	TP	Claim No: SNM17D06770C02/5

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLP6196C	Engine No:	8ARZ079126
Make & Model:	LEXUS IS, 200 (A)	Chassis No:	JTHBA1D2205054103
Reg. Date:	13/06/2017 (Man. Year: 2017)	Odometer:	8054 km
Colour:	White		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45R17	Rear Tyre Size:	225/45R17
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	22,213.47	8,352.19	13,861.28	62.40
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,530.00	1,960.00	3,570.00	64.56
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	27,743.47	10,312.19	17,431.28	62.83
Approved Total (Overridden) (\$\$)		8,200.00		
(\$\$)	27,743.47	8,200.00	19,543.47	70.44
+ GST 7.00/7.00% (\$\$)	1,942.04	574.00	1,368.04	70.44
Nett Amount (\$\$)	29,685.51	8,774.00	20,911.51	70.44

INSPECTION

Date of Assignment:	27/11/2017	
Date Inspected:	27/11/2017 Inspected At:	SK Automobile Pte Ltd (HQ) 23 Kaki Bukit Avenue 4, #03-01 Vicom Inspection Centre Singapore 415933
Estimated Period of Repair:	6.0 days	

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 04 Mar 2019)
Parts:	143	LEXUS IS 200 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLP6196C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR PARKING SENSOR UNIT (4 Pcs)	Damaged (3 Pcs only)	1,033.20 FL	*774.90 FL
2	1	*REAR PARKING SENSOR RETAINER (4 Pcs)	Damaged (3 Pcs only)	116.00 FL	*87.00 FL
3	1	*REAR PARKING SENSOR WIRE HARNESS	Not Necessary	185.40 FL	*- FL
4	1	*REAR BUMPER	Deformed	1,328.60 FL	*1,080.00 FL
5	1	*REAR BUMPER LOWER LIP	Deformed	788.30 FL	*788.30 FL
6	1	*REAR BUMPER TOWING COVER	Deformed	42.30 FL	*42.30 FL
7	2	*REAR BUMPER REFLECTOR	Cracked	414.80 FL	*220.00 FL
8	1	*REAR BUMPER REINFORCEMENT	Bent	453.60 FL	*453.60 FL
9	1	*REAR BUMPER REINFORCEMENT SPONGE	Cracked	288.20 FL	*288.20 FL
10	2	*REAR BUMPER UPPER BRACKET	Not Necessary	224.20 FL	*- FL
11	2	*REAR BUMPER SIDE RETAINER	Necessary	196.40 FL	*196.40 FL
12	1	*SMART ENTRY ANTENNA	Cracked	375.70 FL	*375.70 FL
13	1	*SMART ENTRY ANTENNA BRACKET	Not Necessary	97.60 FL	*- FL
14	1	*BOOT LID	Buckled	1,781.30 FL	*1,450.00 FL
15	1	*BOOT LID CHROME MOULDING	Not Necessary	556.30 FL	*- FL
16	2	*BOOT LID HINGES	Not Necessary	230.60 FL	*- FL
17	1	*BOOT LID WEATHERSTRIP	Necessary	270.50 FL	*270.50 FL
18	2	*BOOT LID STOPPER	Not Necessary	90.00 FL	*- FL
19	1	*BOOT LID INNER LOCK	Damaged	656.30 FL	*385.00 FL
20	1	*BOOT LID STRIKER	Not Necessary	105.90 FL	*- FL
21	1	*BOOT LID EMBLEM	Necessary	118.00 FL	*118.00 FL
22	1	*BOOT LID EMBLEM IS	Necessary	95.00 FL	*95.00 FL
23	1	*BOOT LID EMBLEM 200	Necessary	94.30 FL	*94.30 FL
24	1	*BOOT LID EMBLEM LEXUS	Necessary	108.40 FL	*108.40 FL
25	1	*REAR END PANEL	Dented	903.50 FL	*903.50 FL
26	1	*REAR END PANEL TOP GARNISH	Deformed	728.60 FL	*295.00 FL
27	1	*REAR FLOOR PANEL TOP BOARD	Deformed	824.40 FL	*455.00 FL
28	2	*REAR FLOOR PANEL SIDE TOOL BOX	Not Necessary	647.60 FL	*- FL
29	1	*BOOT LID INNER TRIM	Not Necessary	646.30 FL	*- FL
30	2	*REAR FENDER SIDE INNER TRIM	Not Necessary	1,912.20 FL	*- FL
31	2	*BOOT LID LAMP	Not Necessary	1,693.60 FL	*- FL
32	1	*TAILLAMP	O/s Cut	2,694.40 FL	*688.00 FL
33	1	*EXHAUST PIPE SILENCER (DUAL PIPE)	Not Necessary	2,129.60 FL	*- FL
34	1	*EXHAUST PIPE HEAT SHIELD	Not Necessary	146.60 FL	*- FL
35	2	*EXHAUST PIPE MOUNTING	Not Necessary	70.60 FL	*- FL
36	1	*REAR NUMBER PLATE WITH CASING	Not Necessary	50.00 FS	*- FS
37	1	*SET REAR VIEW REVERSE CAMERA	Not Necessary	1,300.00 FS	*- FS
38	1	*SET REAR BUMPER CLIP	Necessary	70.00 FS	*30.00 FS
39	1	*SET REAR FENDER INNER SHIELD CLIP	Not Necessary	45.00 FS	*- FS
40	1	*BOOT LID JOINT SEALANT	Not Necessary	90.00 FS	*- FS
41	1	*SET BOOT LID INNER TRIM CLIP	Not Necessary	70.00 FS	*- FS
42	1	*SET REAR END PANEL TOP GARNISH CLIP	Necessary	45.00 FS	*10.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
43	1	*REAR END PANEL SEALANT	Necessary	90.00 FS	*60.00 FS
44	1	*REAR FLOOR PANEL SEALANT	Not Necessary	90.00 FS	*- FS
45	1	*REAR FLOOR PANEL INSULATOR	Not Necessary	300.00 FS	*- FS
46	2	*SET REAR FENDER SIDE INNER TRIM CLIP	Not Necessary	130.00 FS	*- FS
47	1	*REAR END PANEL JOINT SEALANT	Not Necessary	90.00 FS	*- FS

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (S\$)	24,418.30	9,269.10
- List Item Discount on L Items 10.00/10.00% (S\$)	2,204.83	916.91
Total Parts (S\$)	22,213.47	8,352.19

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CUT OFF,REPLACE REAR END PANEL AND FLOOR PANEL STRAIGHTEN,REALIGN REAR CHASSIS FRAME AND RENEW OTHER DAMAGE PARTS	New	1,800.00	800.00
2	SPRAY PAINTING ON DAMAGE AND AFFECTED AREA	New	1,600.00	800.00
3	DISMENTLE AND INSTALL EXHAUST PIPE SYSTEM TO ENABLE REPAIRS	New	200.00	0.00
4	REMOVE AND INSTALL REAR PARKING SENSOR AND WIRING HARNESS,PERFORM DISTANCE SENSORY TESTING	New	200.00	50.00
5	RENEW REAR FLOOR INSULATOR	New	100.00	0.00
6	REMOVE AND REPLACE SMART KEYLESS ANTENNA AND BUZZER.RESET SMART ENTRY SYSTEM	New	200.00	50.00
7	DISMENTLE AND INSTALL REAR SEATS,SPEAKER BOARD AND SEATS TRIMMING	New	150.00	0.00
8	PERFORM REAR LIGHTING WIRING CHECK AND TEST FUNCTION	New	200.00	30.00
9	REMOVE AND INSTALL REAR MULTI-VIEW CAMERA ASSY.PERFORM AIMING AND ADJUST TO POSITION	New	200.00	60.00
10	CONDUCT WATER LEAKAGE ON WELDING JOINT AREA	New	100.00	0.00
11	REMOVE AND INSTALL FUEL TANK AND FUEL PIPING TO ENABLE REPAIRS	New	200.00	0.00
12	TRANSFER BOOT LID ATTACHMENT AND MECHANISM INTO NEW BOOT LID ASSY,RE-ALIGN TO POSITION	New	180.00	60.00
13	DISMENTLE AND RE-INSTALL REAR INTERIOR COMPARTMENT TRIMMING	New	200.00	60.00
14	APPLY TUFF COATING TREATMENT	New	200.00	50.00
Gross Labour Cost (\$\$)			5,530.00	1,960.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >