

ASS. REC. BY:

REF: CS/FCI/17022526/Ktb⁷²

Special Instruction:

Supervisor:

Kenneth

ASSIGNMENT (Office)

CWS

From (Person):

May Chua

of

FCI

Date/Time: 8:44am @ 27/11/17

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SFH 5251X

Insured:

SHD 6750M

at Workshop m/s

Ah Him Motor

Tel:

64831244

of 176 Sin Ming Drive #05-12

Policy No:

Claim No:

D17010917 MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A. 21/11/2017

(Client's Record)

29/11/2017 @ 10:30am owner waiting

CA / REV / REP. / REV 24 HRS

'wp'

H.O.D. Endorsement:

Date/Time: 10:25am @ 27/11/17

Person Contacted:

Zr/a

Vehicle IN (OUT)

Date/Time	Action/Instruction (✓) Estimate
	SFH 5251X - X
	SHD 6750M - X
	Part by Part 1309.04 (Red: 2380.20 : 64%)

REF: FCI

ASSIGNMENT

Form: Date: 29/11/17

Estimated Cost:

OD: ☒ WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SFH 5251X

at Workshop: Ah Lim Motor

of: 176 Sin Ming Drive # 05-12

Insured: BIK 10 AMK Ind Park 2A #011A

Policy No:

Claims No:

Sum Insured: Excess:

(Client's Record)

Make of Veh:

10:30am @ owner waiting

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAO Accident Report: Consistent? : Yes or No

GIA / PR Sent: Consistent? : Yes or No

Est. Repairs: 02 days Res: Yes or No

Lump Sum: 1. B. 1 % 3 Val: Yes or No

QA / REV / REP. / 24 HRS 'up

Vehicle IN / OUT

Date: Person Contacted:

Veh No: SFH 5251X (Page: 08 18)

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover

Truck / Trailer or

Make: Peugeot A 5008 cc 1560

Colour: Grey A/E Insured / Std / NI / NA

Sp Reading: 85687 T Radio: Insured / Std / NI / NA

Eng No:

C No:

Gen Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: R:

R:

SS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front:

R/Bal: 1 mm

L/Bal: 1 mm

D.O.A: 21/11/17

Survey held at:

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

C/S Rec

The U/C / Chassis frame / Body Structure affected due to collision:

Date Time Action / Instruction

30/11 File pass to Cathryn

RECEIVED 06 FEB 2018

Date Time File Passed:

06 Typist



: Preli. Report

Final Report

Date Time File Returned:

Days Of Repair: 2

Resurvey No. of Trip: 1

Survey Fee

Transportation

Lump Sum

Road

Open

Total

Add Fee:



Site Insp

Inter. Insp

Tech Insp

Witness Insp

Report Format:

Lump Sum / Fee

TP 1309.04

130
50
50
13

243




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI17022526/Ktb	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 27-11-2017	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHD 6750M	Veh. Inspected	SFH 5251X
Policy No.		Coverage (\$)	0.00
Claim No.	D17010917MFSH	Excess (\$)	0.00
Assign From	CWS (MAY CHUA)	Assign Date	27/11/2017
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	21/11/2017	Inspection Date	27/11/2017
Survey held at	AH LIM MOTOR COMPANY 176 SIN MING DRIVE #05-12 SIN MING AUTOCARE SINGAPORE 575721		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

First Capital Insurance Limited

A FAIRFAX Company

Company Reg. No. 195000106C
GST Reg. No. M2-0001676-9

MOTOR SURVEY ASSIGNMENT

Date	23-11-2017	Our Ref No. D17010917MFSH
Accident Date	21-11-2017	Claim Type. Third Party
Insured Vehicle	SHD6750M	Third Party Vehicle. SFH5251X
Survey Location	176 SIN MING DRIVE #05-12 SIN MING AUTOCARE	
Contact Person.	ZILA	
Contact No.	64831244/ 64831244	Fax No. 64836170
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	AH LIM MOTOR COMPANY	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	MAY CHUA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/230595)



PRI Documents



Close X

PRI Header Details

Claim No	D17010917MFSH	Policy No	D-15072701MFSH	Claimant S.No & Name	1 & AH LIM M
Workshop Name	AH LIM MOTOR COMPANY (Contact Person : ZILA)	Survey Location & Contact Details	176 SIN MING DRIVE #05-12 SIN MING AUTOCARE Mobile: 64831244 , Phone: 64831244 , Fax: 64836171 EmailId: ZILA@AHLIMMOTOR.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM 1		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHD6750M	TP Vehicle No	SFH5251X
PRI Recieved Date	24-11-2017 08:00:32 PM	Surveyor Appointed Date	27-11-2017 08:43:00 AM	Surveyor Accept Date	27-11-2017 0

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	27-11-2017	Upload Survey Report *:	<input type="button" value="Choose File"/>
-----------------------------	--	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select Year ▼
Chasis No	<input type="text"/>	Engine No	<input type="text"/>	Mileage	<input type="text"/>
Color	<input type="text"/>	Cubic Capacity	<input type="text"/>		

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks	<input type="text"/>	<input type="button" value="Save"/>
---------	----------------------	-------------------------------------

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type	Singapore NRIC
Owner ID	7486G

Vehicle Details

Vehicle No.	SFH5251X
Vehicle to be Exported	Yes
Intended De-registration Date	24 Nov 2017
Vehicle Make	PEUGEOT
Vehicle Model	5008 (A) 1.6 E-HDI ETG ACTIVE MPV
Primary Colour	Grey
Manufacturing Year	2014
Engine No.	10JBFT0059265
Chassis No.	VF30E9HD8E5067193
Maximum Power Output	84.0 kW (112 bhp)
Open Market Value	\$25,490.00
Original Registration Date	15 Aug 2014
First Registration Date	15 Aug 2014
Transfer Count	0
Actual ARF Paid	\$12,686.00

Intended PARF Rebate Details


PARF Eligibility	Yes
PARF Eligibility Expiry Date	14 Aug 2024
PARF Rebate Amount	\$9,514.00

Intended COE Rebate Details

COE Expiry Date	14 Aug 2024
COE Category	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years)	10
QP Paid	\$64,600.00
COE Rebate Amount	\$43,431.00
Total Rebate Amount	\$52,945.00

The information contained herein is correct as at 24 Nov 2017

OK





Car Insurance Policy Schedule

POLICYHOLDER

INSURED:
FAMILY NAME Lim Teck Beng
GIVEN NAME (lin Deming)
BUSINESS/PROFESSION: Lecturer / Teacher / Tutor

COVER

TYPE OF COVER: Comprehensive
TYPE OF PLAN: Dual-Year Plan
OWN DAMAGE POLICY EXCESS \$1,000.00
YOUNG AND/OR INEXPERIENCED DRIVER EXCESS: \$2,500.00
(Aged 24 and below and/or has held a valid driving license for less than 1 year.)
note: in addition to Own Damage Policy Excess if applicable
WINDSCREEN EXCESS: \$100.00
All excess subject to GST if applicable

USE INSURED AGAINST

Use for social, domestic and pleasure purposes and for use in connection with the policyholders own business. The policy does not cover use for (i) Hire and rewards, (ii) Racing, pace making, reliability trial or speed testing, (iii) Driving tuition, (iv) The carriage of goods for hire and reward, (v) Any purpose in connection with the motor trade.

PREMIUM CALCULATION

PREMIUM	S\$ 1315.72
GST @ 7.00%	S\$ 92.10
TOTAL DUE	S\$ 1407.82
DATE ISSUED	20-Sep-2017 at 17:14hours

POLICY NO.: 10604726

PERIOD OF INSURANCE (both dates inclusive)

FROM: 15-Aug-2017 00:00hours
TO: 14-Aug-2019 23:59hours
ENDORSEMENT EFFECTIVE DATE: 15-Aug-2017

AGENT'S DETAILS

CODE: 10000001
NAME: DIRECT (GEN-INS)
COMPANY NAME: DIRECT (GEN-INS)

CAR INSURED

MAKE & TYPE OF BODY: PEUGEOT 5008 1.6 e-HDi 1560cc
REGISTRATION NO.: SFH5251X
SUM INSURED: Market Value inclusive of COE
YEAR OF REGISTRATION: 2014
OFF-PEAK CAR: No
PERIOD OF OWNERSHIP OF CAR TO BE INSURED: 2 to <3 years
MODIFICATIONS TO YOUR CAR: No
WHICH DO NOT COMPLY WITH AND/OR ARE NOT APPROVED BY LTA:

ADDITIONAL COVERS

WHO MAY DRIVE YOUR CAR

Any driver aged 30 or over

NO CLAIMS DISCOUNT

(This NCD amount is specific to your Aviva policy only)
NCD%: 50

BREAKDOWN ASSISTANCE

If your car breakdown and you need assistance, please call our hotline at 6333 2222

POLICY OWNERS' PROTECTION SCHEME (PPF)

This policy is protected under the Policy Owners' Protection Scheme which is administered by the Singapore Deposit Insurance Corporation (SDIC). Coverage for your policy is automatic and no further action is required from you. For more information on the types of benefits that are covered under the scheme as well as the limits of coverage, where applicable, please contact us or visit the GIA or SDIC web-sites (www.gia.org.sg or www.sdic.org.sg).

ORIGINAL

Aviva Ltd 4 Shenton Way #01-01 SGX Centre 2 Singapore 068807 • Tel: (65) 6827 9966 • Website: www.aviva.com.sg
Company Reg. No.: 196900499K GST Reg. No.: MR-8500166-8



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlmmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : LIM TECK BENG
BLK 863A TAMPINES ST 83
#01-504
SINGAPORE 521863

ATTN:

Your Ref No: SFH5251X
Claim Type: Third Party
Accident Date: 21/11/2017
TP Veh Reg No: SHD6750M

Estimate No: MC0912618
Date: 24 Nov 2017
Policy No: 10604726
Veh Reg No: SFH5251X
Make/Model: PEUGEOT 5008 (A) 1.6 E-HDI

LKK
29/11/17
10:30 AM

Not Authorised
1.B.1
Runny After Paint
2 days

Estimate Repair Cost to Vehicle No :SFH5251X

Description	Quantity	List Price	Amount
		SS	SS
SPARE PARTS			
1 REAR BUMPER	1 PC	958.00 X	
2 REAR BUMPER SIDE RETAINERS RH/LH (1 SET)	1 PC	186.00 X	
3 REAR BUMPER CLIPS	10 PC	55.00 X	
4 TAILAMP RH	1 PC	765.60 ✓	
5 REAR BUMPER SENSOR HOLDER	4 PC	779.00 X	
		2,743.60	
	Less 10%	274.36	2,469.24
LABOUR			
6 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00 2ed	
7 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS. (4 PCS)	1 PC	120.00 λ	
8 TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS.	1 PC	60.00 X	
9 TO DISMANTLE ALL DAMAGED PARTS TO CUT & WELD. TO KNOCK & REPAIR REAR FENDER RH INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	500.00 2ed	
10 TO SPRAY REAR FENDER RH, REAR BUMPER.	1 PC	500.00 4ed	
		1,220.00	1,220.00
Total			SS 3,689.24
Add GST @ 7%			258.25
Total Amount Payable			SS 3,947.49

TOTAL: SINGAPORE DOLLAR THREE THOUSAND NINE HUNDRED FORTY SEVEN AND CENTS FORTY NINE ONLY

Please arrange this vehicle to be surveyed soonest possible.
Thank You

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be surveyed and is subject to final approval from the Insurance Company

Acknowledged by Repairer

Sign

Date

For AH LIM MOTOR COMPANY



AUTHORISED SIGNATURE



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlmmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

DRAFT FINALISATION

M/S : LIM TECK BENG
BLK 863A TAMPINES ST 83
#01-504
SINGAPORE 521863

Claim No: MC0912618
No: MF0910764
Date: 26 Jan 2018
Policy No: 10604726
Veh Reg No: SFH5251X
Make/Model: PEUGEOT 5008 (A) 1.6 E-HDI

ATTN:

Your Ref No: SFH5251X
Claim Type: Third Party
Accident Date: 21/11/2017
TP Veh Reg No: SHD6750M

DRAFT FINALISATION

Repair Cost to Vehicle No (For Finalization):SFH5251X

Description	Quantity	List Price S\$	Amount S\$
SPARE PARTS			
1 TAILAMP RH	1 PC	765.60	
		765.60	
	Less 10%	76.56	689.04
LABOUR			
2 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	20.00	
3 TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD. TO KNOCK & REPAIR REAR FENDER RH INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	200.00	
4 TO SPRAY REAR FENDER RH,REAR BUMPER.	1 PC	400.00	
		620.00	620.00
Total			S\$ 1,309.04
Less Excess			S\$ 0.00
Amount Before GST			S\$ 1,309.04
Add GST @ 7%			91.63
Total Amount Payable			S\$ 1,400.67

TOTAL: SINGAPORE DOLLAR ONE THOUSAND FOUR HUNDRED AND CENTS SIXTY SEVEN ONLY

The above vehicle was surveyed by KENNETH KONG -LKK on 29/11/2017

For AH LIM MOTOR COMPANY
AH LIM MOTOR COMPANY
No. 10 Ang Mo Kio Industrial Park 2A
#01-09 AMK Autopoint Singapore 568047
Tel: 6483 1244 Fax: 6483 6170
AUTHORISED SIGNATURE



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimnc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : LIM TECK BENG
BLK 863A TAMPINES ST 83
#01-504
SINGAPORE 521863

Estimate No: MC0912618
Date: 24 Nov 2017
Policy No: 10604726
Veh Reg No: SFH5251X
Make/Model: PEUGEOT 5008 (A) 1.6 E-HDI

ATTN:

Your Ref No: SFH5251X
Claim Type: Third Party
Accident Date: 21/11/2017
TP Veh Reg No: SHD6750M

LKK

29/11/17

10 3000

Keneth

10-40 AM

P.B.P

Not Notified
1.B.I.
Running After Party

2 days

Estimate Repair Cost to Vehicle No :SFH5251X

Description	Quantity	List Price SS	Amount SS
SPARE PARTS			
1 REAR BUMPER	1 PC	958.00	X
2 REAR BUMPER SIDE RETAINERS RH/LH (1 SET)	1 PC	186.00	X
3 REAR BUMPER CLIPS	10 PC	55.00	X
4 TAILAMP RH	1 PC	765.60	✓
5 REAR BUMPER SENSOR HOLDER	4 PC	779.00	X
		2,743.60	
	Less 10%	274.36	2,469.24
LABOUR			
6 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00	200
7 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS. (4 PCS)	1 PC	120.00	X
8 TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS.	1 PC	60.00	X
9 TO DISMANTLE ALL DAMAGED PARTS TO CUT & WELD. TO KNOCK & REPAIR REAR FENDER RH INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	500.00	200
10 TO SPRAY REAR FENDER RH, REAR BUMPER.	1 PC	500.00	400
		1,220.00	1,220.00
Total			SS 3,689.24
Add GST @ 7%			258.25
Total Amount Payable			SS 3,947.49

TOTAL: SINGAPORE DOLLAR THREE THOUSAND NINE HUNDRED FORTY SEVEN AND CENTS FORTY NINE ONLY

Please arrange this vehicle to be surveyed soonest possible.
Thank You

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplier quotation(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Sign:

Date:

For AH LIM MOTOR COMPANY



AUTHORISED SIGNATURE




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI17022526/Ktbn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 07-02-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 6750M	Veh. Inspected	SFH 5251X	
Policy No.	D-15072701MFSH	Coverage (\$)	0.00	
Claim No.	D17010917MFSH	Excess (\$)	0.00	
Assign From	MAY CHUA	Assign Date	27/11/2017	
2. Vehicle Particulars & Condition				
Make & Model	PEUGEOT 5008 (A)	c.c	1560	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	VF30E9HD8ES067193	Colour	METALLIC GREY	
Odometer	85681	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/55 R16	BRIDGESTONE	1 mm	
L/H Front Tyre	215/55 R16	BRIDGESTONE	1 mm	
R/H Rear Tyre	215/55 R16	BRIDGESTONE	1 mm	
L/H Rear Tyre	215/55 R16	BRIDGESTONE	1 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	21/11/2017	Inspection Date	29/11/2017	
Survey held at	AH LIM MOTOR COMPANY 176 SIN MING DRIVE #05-12 SIN MING AUTOCARE SINGAPORE 575721			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SFH 5251X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	TO REPAIR SEE LABOUR	958.00	-
1	REAR BUMPER SIDE RETAINERS RH/LH (1 SET)	SERVICEABLE	186.00	-
10	REAR BUMPER CLIPS	NOT NECESSARY	55.00	-
1	TAILLAMP RH	CUT	765.60	765.60
4	REAR BUMPER SENSOR HOLDER	SERVICEABLE	779.00	-
	LESS 10% DISCOUNT		-274.36	-76.56
			2,469.24	689.04
	LABOUR			
	TO DISCONNECT AND CHECK ELECTRICAL WIRING,WIRE SOCKETS AND ETC.TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS,TEST AND RECTIFY FOR PROPER FUNCTIONING.		40.00	20.00
	TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS (4 PCS).	NOT NECESSARY	120.00	-
	TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS.	NOT NECESSARY	60.00	-
	TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD.TO KNOCK & REPAIR REAR FENDER RH,INNER PANELS AND AFFECTED AREAS.TO REFIT LISTED PARTS BACK SAME.INCLUSIVE OF THE REPAIR OF REAR BUMPER.		500.00	200.00
	TO SPRAY REAR FENDER RH,REAR BUMPER.		500.00	400.00
			1,220.00	620.00
	GRAND TOTAL		3,689.24	1,309.04
	RECOMMENDED COST OF REPAIRS			1,309.04

Report Ref No. CS/FCI17022526/Ktbn2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.