Surveyor Tautikh	ASSIGNME	WD .	DotasTirna	77/11/17 9.42a)
From (Person): Gara H	of		Date I line	Trinio I
Estimated Cost:		Bill to:		
OD/TP+WS+TP RES / OD RES		3	9 8	
To Inspect Vehicle No:	SLA 2749M		Insured:	10.4
at Workshop m/s	exformance Mo	ors	_ Tel: 9116 5	199
of 303 Alexand	tra Road	1		11.00
Policy No: PNPV2017 - 00	980 000	Claim No:		1+22
	0	Excess:	\$ 800.00	
Sum Insured:		_	D.O.A 11/	1112017
Make of Veh: (Client's Record)			D.O.L	7.1
***************************************	me		H.O.D. End	orsement:
CA / REV / REP. / REV 24 F	IKS	Movine	Vehice TVL	OUT
Date/Time: 1136am@27/11]	Person Contacted:	110101-	Veinte	
Date/Time Action/Instruction	() Estimate	p		
E. company				
SLA 27.411	Y-X			
J8/11/17 Revert b	1 merimen		1	
	y merimen red from clava	by mer	imen	

ASSIC	GNMENT
ASSIC From: Date: Estimated Cost: OD/TP/WS/TP RES/OD RES/EVA/INV/MV To Inspect Vehicle No: at Workshop m/s of Insured: Policy No. Claims No. Sum Insured: Excess: (Client's Record) Make of Veh: (Policy Condition) Remark: The veh had commenced its repair at the time of inspection. Bal. or Market Value: IDAC Accident Rport: Consistent? : Yes or No	SNMENT Veh No: SLA 2749 M Yr Regn: 2016 For Type: MCar / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or Make: MW STO I c.c 1997 Colour A/C: Insured / Std / NI / NA Sp.Reading 1657 T/Radio: Insured / Std / NI / NA Eng/No: C/No: WS 45 V 320 30 D 8 291 8 3 Gen. Cond: Good / Fair / Poor / Burnt Steering: Inprder / Jammed / Leaked / Burnt or Brake: Inorder / Jammed / Leaked / Burnt or Modi: Nil / S/Rim / STD A/Rim or Tyre Size: F: 225 55 R 7 R: BS) DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Front Rear R/Bal. C mm R/Bal. C mm
100	B/Pal G
Date / Time Action / Instruction RECEIVED 2 8 FES 2018	The U/C / Chassis frame / Body Structure affected due to collision.
	Days Of Repair: 5 Resurvey No. of Trip: Survey Fee: 250 Transportation: 50
Report Format: merimen Lump Sum / I.B.I: (\$ 9301.95)	: Site Insp (\$) _S+RS_SI 50 : Interview (\$) Photos : Tech. Invs (\$) Others : Weekend (\$) TOTAL

Survey Department Check List (Case Handler)

cs fwo 17022530 Tivh Reference No.: Policy Type: OD / TP / TP RES / TL / EVA Case Handler Typist): Case handler to make sure all Information created by the assignment team are ACCURATE. Admin (Y-Date N-Date Y-Date N-Date (1) Office Assign Form Reference No. C ~ C Customer Code N Assign From Assign Date C ~ C Veh No (Inspected) C Veh No (Insured) C D.O.A Policy No. C C Claim No C Insurance Authorisation (CA /REV/REP) C ~ Report Type C Weekend Charges N Survey held at/Repairer C Excess): Case handler to make sure the surveryor completed all required information. Surveyor ((1) Assignment Form C Vehicle No C Regn Month/Year N Vehicle Type Make & Model N C Engine Capacity. (C.C) ~ Colour N C Odometer. (Sp.Reading) C Chassis No V General Condition Steering N Brake Modification (Modi) N V C Tyre Size Tyre Make N v C Tyre Balance C Date of Inspection ~ N Survey held N Des.of Damages (2) System - (Views/Merimen) Damaged Vehicle Photographs Uploaded (3) Workshop Estimate/Assignment Form ~ ALL Parts condition Market Value for OD cases C C Estimate Repair Cost for PRI (RSI, TMI, MSIG) C Days of repair V C Finalised Amount Re-inspection Cases to Finalize within 5 Days (4) System - (Views/Merimen) Resurvey photo Uploaded

*C: Critical *N: Nor-Critical

Check By:

VERON Case Handler

Date



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Internat	ionale Des Experts En Autom	obile
FWE	SINGAPORE PTE	ELTD	Ref : CS/FWD17022	530/T1vb
	MASEK BOULEVA	ARD ER 4SINGAPORE 038986	Date: 27-11-2017 Code: FWD	
1.		Policy Particu	lars :- OWN DAMAGE	
	Insured Veh.		Veh. Inspected	SLA 2749M
	Policy No.		Coverage (\$)	0.00
	Claim No.	1201700007722	Excess (\$)	800.00
	Assign From	CLARA LI	Assign Date	27/11/2017
2.		Vehicle Par	ticulars & Condition	
	Make & Model		c.c	0
	Engine No.	HIDDEN	Year of Reg.	
	Chassis No.	***	Colour	
	Odometer	V #5	Steering	
	Brakes		Modification	
	General			
3.		Cond	itions of Tyres	
		Size	Make	Balance
	R/H Front Tyre			mm
	L/H Front Tyre			mm
	R/H Rear Tyre			mm
	L/H Rear Tyre			mm
4.		Descrip	tion of Damages	
5.		Gene	ral Information	
	Accident Date	11/11/2017	Inspection Date	27/11/2017
	Survey held at	PERFORMANCE MOTORS L	TD	
		303 ALEXANDRA ROAD SINGAPORE 159941		
5a.			Remarks	
	A)THE MARKET \ B)IN ACCORDAN	ALUE IS S\$(EST. AV CE TO YOUR INSTRUCTIONS,	ERAGE) . WE HAVE AUTHORISED I	REPAIRS.

Veron Chen (LKKAuto)

From:

Veron Chen (LKKAuto)

Sent:

Tuesday, 28 November, 2017 3:57 PM

To:

Merina Chia San San

Cc:

Keith Leo Chi Yung; PBSP; SUR

Subject:

SLA 2749M-DOA: 11/11/2017 (FWD OD)

Dear Merina,

As instructed by our client FWD, please proceed to repair the insured vehicle SLA 2749M (Excess \$800/-).

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

View Received Message

This mail is associated with:

*SLA2749M (1201700007722)

OD Nov 11 2017 3:00PM [YU YAH LENG] Performance Motors Limited

Reply Reply All Mark as Unread Print Message Delete Message Forward

From FWD Singapore Pte. Ltd. (HQ) (FWD_SG), sent on 28/11/2017 11:25 AM.

To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$10530.10) - SLA2749M - Claim Handler: Clara Li Zi Rong

Approved:10530.10:Policy excess \$800

DOCUMENTS SUMMARY

There are no documents.

Nivitha (LKK Auto)

From:

clara.li@fwd.com

Sent:

Monday, 27 November, 2017 9:42 AM

To:

assignments@lkkauto.com; sur@lkkauto.com; admin-a@lkkauto.com; admin-

d@lkkauto.com

Subject:

FW: Submit Addendum - from TP to OD - SLA2749M // 1. SG Police Report, 2.

Letter of Authorisation and 3. Supplementary Text for Report. Our Ref:

1201700007722

Attachments:

SLA2749M Quotation.pdf

Importance:

High

Hi LKK team,

Please refer to the email below and liaise with the repairer for OD survey.

Attached is the repair estimate. Policy excess \$800.00.

Please create the case in Merimen and revert to us with prelim report.

Thank you.

Kind Regards

Clara Li

Senior Executive, Claims

FWD Singapore Pte. Ltd.

6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

T (65) 6727 5722

E clara.li@fwd.com

W fwd.com.sg











From: Merina Chia San San [mailto:merina.chia.sansan@simedarby.com.sg]

Sent: Friday, 24 November, 2017 6:34 PM

To: Clara Li Zirong - SGUser Cc: formiscmails@gmail.com

Subject: RE: Submit Addendum - from TP to OD - SLA2749M // 1. SG Police Report, 2. Letter of Authorisation and 3.

Supplementary Text for Report. Our Ref: 1201700007722

Importance: High

Dear Clara.

Please refer to the attached quotation for your perusal.

Please kindly assist to arrange survey for the vehicle. Car in workshop.

Thank you

Regards,

Morina Chia

Customer Service Advisor | Body and Paint

Performance Motors Limited

303 Alexandra Road

Sime Darby Performance Centre

Singapore 159941

Hp (+65) 9116 5199 | Fax (+65) 6479 4601

merina.chia.sansan@simedarby.com.sq



https://www.pml-bmw.com.sg/en/ssl/test-drive.html

*4

Please consider the environment before printing this e-mail.

"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."

From: clara.li@fwd.com [mailto:clara.li@fwd.com]

Sent: Thursday, 23 November, 2017 4:43 PM

To: Merina Chia San San
Cc: formiscmails@gmail.com

Subject: RE: Submit Addendum - from TP to OD - SLA2749M // 1. SG Police Report, 2. Letter of Authorisation and 3.

Supplementary Text for Report. Our Ref: 1201700007722

Hi Merina,

We refer to the email below from Mr Chin.

Please submit a copy of repair estimate to us and arrange for OD survey.

Thank you.

Kind Regards

Clara Li

Senior Executive, Claims

FWD Singapore Pte. Ltd.

. 6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

- T (65) 6727 5722
- E clara.li@fwd.com

W fwd.com.sg





Endowment Plan
Get the biggest guaranteed return for a 3
year plan available online
Limited time offer!





From: formiscmails [mailto:formiscmails@gmail.com]

Sent: Thursday, 23 November, 2017 2:09 PM

To: merina.chia.sansan@simedarby.com.sg; Clara Li Zirong - SGUser

Subject: Re: Submit Addendum - from TP to OD - SLA2749M // 1. SG Police Report, 2. Letter of Authorisation and 3.

Supplementary Text for Report. Our Ref: 1201700007722

Hello Clara -

Allow me to introduce Merina from PML.

I have dropped my car with Merina to assess the cost to repair and to repair.

Clara, when you help me to recover from the Third Party, please help with full recovery:

- 1. Cost of repair
- 2. Excess
- 3. Loss of use.

Thank you very much!

Wee Sheng

Sent from my iPhone

From: formisemails < formisemails@gmail.com>

Date: 22 November 2017 at 19:30:36 SGT

To: clara.li@fwd.com

Subject: Re: Submit Addendum - from TP to OD - SLA2749M // 1. SG Police Report, 2. Letter of Authorisation and 3. Supplementary Text for

Report. Our Ref: 1201700007722

Noted with much thanks!

Sent from my iPhone

On 22 Nov 2017, at 16:08, <<u>clara.li@fwd.com</u>> <<u>clara.li@fwd.com</u>> wrote:

Hi Mr Chin,

You may inform your preferred workshop i.e. Performance Motors Ltd to submit repair estimate to us directly for our assessment on your own damage claim.

Thank you.

Kind Regards

Clara Li

Senior Executive, Claims

FWD Singapore Pte. Ltd.

6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

T (65) 6727 5722

E clara.li@fwd.com

W <u>fwd.com.sg</u> <image004.png>

<image005.jpg>

From: charn's customcraft [mailto:toaddphoto@gmail.com]

Sent: Wednesday, 22 November, 2017 3:51 PM

To: formiscmails@gmail.com Cc: Clara Li Zirong - SGUser

Subject: RE: Submit Addendum - from TP to OD - SLA2749M // 1. SG Police Report, 2. Letter of Authorisation and 3. Supplementary Text

for Report. Our Ref: 1201700007722

Hi,

Amended accident report as attached.

THANKS & REGARDS, KELLY LEE CHARN'S CUSTOMCRAFT

TELEPHONE: 6272 5429

GST REG NO: M90367863L

From: clara.li@fwd.com [mailto:clara.li@fwd.com]
Sent: Wednesday, 22 November, 2017 2:10 PM

To: toaddphoto@gmail.com
Cc: formiscmails@gmail.com

Subject: Submit Addendum - from TP to OD - SLA2749M // 1. SG Police Report, 2. Letter of Authorisation and 3. Supplementary Text

for Report.

Importance: High

Hi Kelly,

Please assist our policyholder to amend the accident report from "claiming against TP" to "claiming under own insurance policy".

Attached is the signed addendum and please fill up with the necessaries.

Kindly forward our policyholder a copy of the full accident report afterwhich.

Thank you.

Kind Regards Clara Li Senior Executive, Claims

FWD Singapore Pte. Ltd. 6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

T (65) 6727 5722
E clara.li@fwd.com
W fwd.com.sg
<image006.png>

<image007.jpg>

From: W Chin [mailto:formiscmails@gmail.com]
Sent: Tuesday, 21 November, 2017 12:34 PM

To: charn's customcraft Cc: Clara Li Zirong - SGUser

Subject: Re: SLA2749M // 1. SG Police Report, 2. Letter of Authorisation and 3. Supplementary Text for Report.

Thanks Kelly.

Signed and attached. Please see if all's good? I'm hoping to drop off my car to Performance Motors this Thursday AM to be fixed, as i'm travelling on 24th Nov till 11th December.

Thanks Chin

<image008.jpg>

On 21 Nov 2017, at 9:12 AM, charn's customcraft < toaddphoto@gmail.com > wrote:

Please sign and return the attached addendum form in order for us to amend the report.

Thanks & Regards, Kelly lee Charn's Customcraft Telephone: 6272 5429 GST Reg No: M90367863L

----Original Message-----

From: formisemails [mailto:formisemails@gmail.com]

Sent: Monday, 20 November, 2017 7:29 PM

To: toaddphoto@gmail.com Cc: clara.li@fwd.com

Subject: Re: SLA2749M // 1. SG Police Report, 2. Letter

of Authorisation and

3. Supplementary Text for Report.

Thanks Sharon.

Can you kindly change my report to Own Damage claim?

This way I can have PML fix my damage and thereafter FWD can attempt to help me recover both my repair costs and excess.

Thanks much.

Sent from my iPhone

On 15 Nov 2017, at 14:07, W Chin <formiscmails@gmail.com> wrote:

Hello Sharon.

1 & 2, please see attached.

3 \ Please add this note to my report, on the 6th line please add this

line gI immediately came to a complete stop and honked. h

Any question, you can reach me at 9199 2289.

<SG Police Report.pdf> <FWD_LETTER OF AUTHORIZATION_20171115.pdf>

<ADDENDUM.tif>

ATTENTION:

The email and any attachments transmitted with it are private

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To:	FWD Singar 6 Temasek #18-01 Sun Singapore 0	tec Tower 4	51 Ubi Ave	Consultants Pte Ltd e 1 #01-25 Industrial Park e 408933
Attn:	Clara Li Zi F	Rong	Date: 28 Nov 20	017
		Preli	minary Advice	
Vehicle	e No	: SLA2749M	Accident Da	te : 11/11/2017
Make		: BMW 520I	Policy No.	: PNPV2017- 00000689
Assign	ment Date	: 27/11/2017	Excess	: S\$800.00
00)1411188944	of Inspection	: 27/11/2017	Est. Duration	n of Repair : 5.00
Inspec	ction At	: PERFORMANCE MOTOR 303 ALEXANDRA ROAD, SINGAPORE 159941	S LIMITED (ALEXANDRA) SIME DARBY PERFORMANC	CE CENTRE

ehicle s	ustained impact / damages front n/s portion	and parts claime	ed are consistent to the accident.
	Repairer's Estimate (Gross)	:S\$	11,725.10
	Revised Amount	:S\$	9,148.40
	Check Items (Estimated)	:S\$	1,381.70
	Total	:S\$	10,530.10
	Lump Sum Repair	:S\$	
	Total Loss Consideration		
	New for Old Value	:S\$	
	Pre-Accident Value	:S\$	160,000.00
	COE / PARF Rebate	:S\$	72,651.00
	Salvage Value	:S\$	
	Margin for Repair	:S\$	87,349.00

Rei	ma	ark	<u>s</u>
()	<)	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
()	The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
()	Other comments :

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of
- Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

性。	ACCIDENT STATEMENT	
Date Of Report	13/11/2017 17:14	
Date Of Accident	11/11/2017 15:40	
Exact Location Of Accident	ALONG JALAN TEKUN 1	
Country/State of Loss	SINGAPORE	

DETAILS OF OWN VEHICLE		
Vehicle Registration Number	SLA2749M	
Insured/Policyholder		
Name Of Registered Owner	YU YAH LENG	
NRIC No	S7211153B	

BMW

11110110	
Email Address	FORMISCMAILS@GMAIL.COM
Mobile Phone No	(LOCAL) +65-81216894
Alternative Phone No	OFFICE-NOPHONE

Vehicle Particulars	
Manufacturer	

Model	5201-2.0 (A)

Exact Purpose for which vehicle was being used at	PRIVATE
time of accident	

Are you claiming under your own insurance policy	YES
for repair to your vehicle?	,

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
A STATE OF THE PARTY OF THE PAR	

Insurance Company	
Name of Insurance Company	FWD SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO

Policy Number PNPV2017-00000689

Cover	IAOTE	INUI	HDGI
. Western			

Driver	
Name of Driver	CHIN WEE SHENG
NRIC No	S7033401A
Date Of Birth	05/08/1970
Occupation	INDOOR
Date Of Driving Pass	05/08/1970

Driving Experience 47 YEARS AND 3 MONTHS

Gender MALI

Mobile Number (LOCAL) +65-91992289

Fax Number Contact Number

EMail Address FORMISCMAILS@GMAIL.COM

Address

BLK 103 AH HOOD ROAD #09-08

.Postcode

320103

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

SPOUSE

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

SIDE SWIPE

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

YES

Foreign Vehicle Registration Number

SD283 (PRIVATE CAR)

Was any body injured in the Accident?

NO

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

1

Details of Police Action

Was the accident reported to the police?

YES

If Yes, Please state which Police Station

POLICE STATION NAME [OTHER]

MOULMEIN NPP

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

REFER TO SKETCH

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SD283

Vehicle Make/Model/Colour

Details Of Properties

CHEN SOON SERNG

NRIC/Passport Number

A38712199

Contact Number

Name of Driver

+601124074122

Address

Postcode

Insurance Company Name

Nature Of Damage


No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

va 1140 stantage	1510-01-5 71- 7-4-1 7+ 10
	driving along Jalan Tekun 1 It was
a straight road and I was	going straight. I was travelling ve
slowly and carefully as	TH is a new area to me. I was
ving along around 15 -2	20 Kully. Then suddenly I see this
	my left from a side road onto
y road. I immediate	
71	and didn't stopped till it hit
	2010K 211500 31317 251 111 11 17 17
14 car When I got	
CHEN SOON SERNY (Malaycia	
rath of that his road is	was along & paid his line of
sight mas blocked bu	
he daimed he complete	
	the Malayrian policy police togeth
	7
ne recognized that	he was in the wrong.
)	J
	/
OWN DAMAGE () 3RD PARTY CLAIM (() REPORTING ONLY () OWN WORKSHOP ()

Policyholder's Signature Date & Time:

Driver's Signature (If driver is not the policyholder) Date & Time:

CHARN'S CUSTOMORAN Reporting Centre Personne's Signature Name: NRIC/FIN No.:

SKETCH PLAN

IMPORTANT NOTICE

VEHICLE NO: SLAJ749 M ACCIDENT DATE: 11/11/17.

- 1. Rease report correctly the details of the accident to speed up the claims process,
- 2. his Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withholding of material fiets may allow insurance companies to <u>repudiate policy liability</u>.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance Companies.
- Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by Interested parties.
- by the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

lunderstand, acknowledge, agree and consent that:

- My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or

(ii) for complying with requirements under any regulations, laws or court orders.

NOTE: DO NOTE THAT YOU MAY HAVE A 14-DAYS TIMEFRAME FOR YOU TO SUBMIT AN OWN DAMAGE.

CLAIM UNDER YOUR OWN POLICY. PLEASE REFER TO YOUR POLICY FOR MORE INFORMATION.

Policyholder's Signature Date & Time; Driver's Signature

(If driver is not the policyholder)

Date & Time: \

CHARN'S CUSTOMCKAPT

Reporting Centre Personne's Signature

Name:

NRIC/FIN No.:

Pol.316

Page 1 of 1

POL.316



POLIS DIRAJA MALAYSIA CAWANGAN TRAFIK IBU PEJABAT POLIS DAERAH JOHOR BAHRU SELATAN, JALAN TEBRAU, 80250 JOHOR BAHRU 07-2237977

Resit Akuan Penerimaan Repot	Polic :	
Nama Pengadu	: CHIN WEE SHENG	
No Kad Pengenalan / Paspot	: E6273782B	
No Repot Polis		
Tarikh @ Masa Repot Polis	: TRAFIK JOHOR BAHRU(S)/026171/17 : 11/11/2017 @ 17:27	
	: 11/11/2017 @ 17:27	
Pengesahan Penerimaan Repot	Tandatangan Ketua Pejabat Pertanyaar	,,,,,,
Pegawai Penyiasat :	/	
Nama Pegawai Penyiasat	: (R92851) SJN SAHRIL ANUAR BIN HASHIM	
Tempat Tugas	: JOHOR , J/BAHRU SELATAN	
No Telefon Pejabat	: No Telefon Bimbit	: 019-7686566
Tarikh @ masa Perjumpaan	, , , , , , , , , , , , , , , , , , , ,	tas.
Pengesahan Penerimaan Repot	: (MOHD FAIZ BIN ZAHARI) SJN 171741 Pent Pendwai Penyiasat Asiail Pelis Trafik IPPB Jeher Bahru (S)	
	Tandatangan Pegawai Penyiasat	****
Juru Gambar :		
Nama :	No Badan :	Pangkat :

Tarikh @ Masa Gambar Diambi		***************************************
Pengesahan Gambar Diambil	•	
	Tandatangan Juru Gambar	
Unit Pembekalan Dokumen Sia	satan:	
No Telefon Unit Pembekalan D	okumen :	
Waktu Pejabat :	Jenis Dokumen Dibekal Kepada Pen	madu:/
Isnin - Khamis :	1. Salingn Repor Polis	
08:00 Pagi - 01:00 Tengah Har		
02:00 Petang - 04:30 Petang Jumaat :	2/Gambar Kenderaan	
08:00 Pagi - 12:30 Tengah Har	i 3. Rajah Kasar Kemalangan	
02:45 Petang - 04:30 Petang Cuti Umum / Khas : Tutup	4. Keputusan Siasatan	
cuti omani / knas : rucup	5. Lain-lain Dokumen	
	Tarikh @ Masa Dokumen Diserah :	
	rankii w masa Dokumen Diserani.	***************************************
	Pengesahan Kaunter Pembekalan Dokumen :	
		Tandatangan Pegawai Kaunter Pembekalan Dokumen

11/11/2017



Report No. E/20171114/2071

POLICE REPORT (NP299)

Police Station Of Origin Moulmein NPP

101 Jalan Rajah #01-01 SINGAPORE 321 Tel No: 1800-25089999

Address APT BLK 103 / 320103 Contact No. Home/Office			08 SINGA	PORE .
Contact No.			. 07	
		Mobile 91992289		27
Email Address		9 4 12		却
	1		Race	
Language English		33,33,1313	joini ioso	ă.
Along Jalan Te		aysia	e M	
	Sex Ag Male 47 Language English Location Of Inc	Email Address Sex Age I Male 47 (Language English Location Of Incident Along Jalan Tekun, Mala	Email Address Sex Age Date of Birth Male 47 05/08/1970 Language English Location Of Incident Along Jalan Tekun, Malaysia	Email Address Sex Age Date of Birth Race Male 47 05/08/1970 Chinese Language English Location Of Incident Along Jalan Tekun, Malaysia

Brief details.

On 11/11/2017, I drove my vehicle SLA2749M into Malaysia. At about 1542hrs, when I was driving slowly and carefully along Jalan Tekun, a straight road, at about 15 to 20 km per hour, I saw a Malaysia vehicle registration number SD283 coming on my left from a side road. I Immediately stopped my vehicle and . sounded my horn, but to my surprise that vehicle SD283 did not stop and kept coming till it collided with the left front corner of my car.

Signature Of Officer Recording The Report: E / Staff Sgt NG YING RAN	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 14/11/2017 15:16
Officer In-Charge Of Case: E / Tanglin Police Divisional Investigation Branch / Insp A MUHAMMAD HAFIZ BIN LATIF Contact No.: 63910000	Classification Of Case:

Authentication Stamp







2 of 2

POLICE REPORT (NP299)

CONTINUATION OF REPORT

Report No. E/20171114/2071

After the accident both myself and the driver of vehicle SD283, namely Chen Soon Serng, a Malaysian got off our vehicle. The Chen Soon Serng informed that the reason that the accident had happened was because the side he was at is a slope and also there was another vehicle blocking his blind spot, hence he did not see my vehicle till his vehicle collided into mine.

The both of us had lodge a police report in Malaysia and Chen Soon Serng agreed that I claim the repair fee of the damages from his insurance. When I went to my insurance company on 13/11/2017 and was told to lodge a police report before they could proceed with the claim.

Signature Of Informant: Signature Of Officer Recording The Report: E / Staff Sqt NG YING RAN Date/Time: Signature Of Interpreter: 14/11/2017 15:16 Not applicable Classification Of Case:

Officer In-Charge Of Case: E / Tanglin Police Divisional Investigation Branch / Insp A MUHAMMAD HAFIZ BIN LATIF Contact No.: 63910000

Authentication Stamp



Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type	Singapore NRIC
Owner ID	1153B
Vehicle Details	
Vehicle No.	SLA2749M
Vehicle to be Exported	No
Intended De-registration Date	27 Nov 2017
Vehicle Make	B.M.W.
Vehicle Model	520I AT 2WD 4DR HID NAV
Primary Colour	Grey
Manufacturing Year	2015
Engine No.	A9831317N20B20B
Chassis No.	WBA5A32030D829183
Maximum Power Output	135.0 kW (181 bhp)
Open Market Value	\$37,993.00
Original Registration Date	26 Feb 2016
First Registration Date	26 Feb 2016
Transfer Count	0
Actual ARF Paid	\$45,191.00
Intended PARF Rebate Details	
PARF Eligibility	Yes
PARF Eligibility Expiry Date	25 Feb 2026
PARF Rebate Amount	\$33,893.00
Intended COE Rebate Details	
COE Expiry Date	25 Feb 2026
COE Category	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years)	10
QP Paid	\$46,970.00
COE Rebate Amount	\$38,758.00
Total Rebate Amount	\$72,651.00

The information contained herein is correct as at 27 Nov 2017

Land Transport Authority

Please read through the Privacy Statement, Terms of Use, and Disclaimer.

Please do not use the Back or Forward buttons on your browser as this may alter the results of the transactions.

Best viewed with IE 10 and above, Chrome, Firefox, and Safari.

Copyright 2017 LTAPrivacy StatementTerms of UseDisclaimerRate the WebsiteRate this e-Service

Last updated on 19 Nov 2017 at 12:12 AM

BMW Dealer

Performance Motors Limited

A member of the Sime Darby Group Co. Reg. No. 197401555W GST Reg. No M2-0020081-x

103, Alexandra Road Sime Darby Performance Centre Singapore 159941 Tel 63190100 (Sales & Admin) 63190111 (AfterSales) Fax, 64747770

180, Kampony Arang Road East Coast Centre Singapore 438180

Tel. 63190888 (AfterSales) Fax. 63469773

315. Alexandra Road Sime Darby Business Centre Singapore 159944 Tal. 63190528 (AfterSales) 63190533/530 (Motorrad) Fax. 64796624 (Motorrad)

J # NO N 2017

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Page No. : 1 of 2 44958 Estimate No. : b1 Date Estimated : 24/11/2017

: Merina Chia San San Prepared By 163385 - ACCOUNT -- ESTIMATE REPAIR FOR -FWD Singapore Pte. Ltd. Yu Yah Leng (Yu YaLin) 6 Temasek Boulevard 103 Ah Hood Road #18-01 Suntec Tower 4 #09-08 Singapore 038986 Singapore 320103

MILEAGE MODEL REGN. DATE CHASSIS NO. REGN. NO. 0 26/02/2016 520iA D829183 SLA2749M

SLAZ / 49M			
	DESCRIPTION To replace front bumper, front left fender including attachments etc and to knock out dented area caused accident	17	VALUE 2,550.00
	To paint front bumper and front left fender	× 1730	1,923.00
	To replace left or right headlight including program and conduct tests for proper function.	451	531.00
	To remove old PDC assembly, replace damaged part reconnect to new bumper including conduct checks for	ts and or	177.00
	proper function. To check electrical wiring systems at the front section	150	177.00
	for proper function including adjustments of headlight To carry out body cavity preservation.	/ 100	118.00
	(Per panel).	%° 7	150.00
	Sundries.	hai s	150.00
		Total Labour 1:	5,626.00

			1#
DESCRIPTION.	QTY	PRIC	VALUE
DESCRIPTION PRACTED 7	1	31.35	31.35
FRT LH 2 SIDE PANEL BRACKET	1	31.35	31.35
FRT LH 3 SIDE PANEL BRACKET?	1	31.35	31.35
FRT LH 4 SIDE PANEL BRACKET ?	1	67.45	67.45
FRT LH 1 SIDE PANEL BRACKET	1	842.30	842.30
FRT LH FENDER 61	1	99.25	99.25
	1	668.10	668.10
FRT BUMPER CARRIER ?	1	153.65	153.65
FRT BUMPER BOTTOM MOUNT ',	1	9.20	9.20
FRT BUMPER LH SPACER MA	1	80.65	∑ (80.65
GRILLE AIR INLET MIDDLE 7.	1	74.25	nm 74.25
LH GRILLE AIR INLET PARTLY CLOSED SHOCK ABSORBER FRONT	1	46.80	(46.80

m

VN Xnn × nr

BMW Dealer

Performance Motors Limited

ember of the Sime Darby Group Reg. No. 197401559W OST Reg. No M2-0020081-x

303, Alexandra Road

303, Alexandra Road Sime Darby Performance Centre Singapore 159941 Tel. 63190100 (Sales & Admin) 63150111 (AfterSales) Fax. 64747770

280, Kampong Arang Road Bast Coast Centre

Singapore 438180 Tel 63190888 (AfterSales) Pax 63449773

315, Alexandra Road Sime Darby Business Centre Singapore 18994 Tel 63190528 (AfterSa: 63190533/530 (Motorrac Fax. 64796601 (Motorrac 64796604 (Motorrac (AfterSales)

QTY



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No.

: b1 44958

: 24/11/2017

Prepared By

Date Estimated

: Merina Chia San San

Page No. : 2 of 2

MILEAGE

REGN. NO. SLA2749M CHASSIS NO. D829183

REGN. DATE 26/02/2016 MODEL 520iA

0

DESCRIPTION FRT BUMPER LH PROTECTIVE RUBBER STR FRT BUMPER PANEL PRIMED, (PDC) de -COVERING PRIMEND LH

EMBLEM GROMMET we-BMW EMBLEM

LH BI XENON HEADLIGHT (1/19)

DECOUPLING RING PDC TORQUE CONVERTE WH/

21.75	1
1,246.40	1
39.10	1
0.80	2
67.80	1
2,566.95	1
4.95	4

Total Parts

6,099.10

VALUE

de 21.75

1,246.40

39.10

1.60

67.80

19.80

2.566.95

KNY

KNY

K WY

400 1111) (1640Excess SS OR W/No PML Yes/No full & ahanto work

LKK Auto Consultants hence notify the Repairer of the following:

- . To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- . No illegal modification(s) is allowed
- . Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

11,844-20

5,626.00 11×25.10 6,099.10 Labour 1 Parts Labour 2 0.00 Excess 820.76 Total GST @ 7%

12,545.86 Grand Total

^{**} THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

^{**} PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Veron Chen (LKKAuto)

From:

Veron Chen (LKKAuto)

Sent:

Wednesday, 28 February 2018 2:45 PM

To:

'PBSP'; Taufikh (LKKAuto)

Cc:

SUR

Subject:

RE: FINAL REPORT / SLA2749M

Dear Caroline,

Confirmed finalize \$9,301.95 before excess \$800 and GST

Repair days: 5 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: PBSP [mailto:pml-pbsp@simedarby.com.sg]

Sent: Monday, 29 January 2018 4:07 PM

To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>; Taufikh (LKKAuto) <Taufikh@lkkauto.com>

Subject: Re: FINAL REPORT / SLA2749M

Gentle reminder

From: PBSP

Sent: Wednesday, 17 January 2018 2:06:07 PM

To: Veron Chen; taufikh@lkkauto.com Subject: FINAL REPORT / SLA2749M

Dear Taufikh and Veron

We refer to the above and attached Final Report.

Please confirm COR as follows:

Total Labour : 4,361.00 Total Parts: 4,940.95

Total Labour & Parts: 9,301.95

Repair days: 5

Thank you.

Regards, Caroline C/o Performance Motors Limited - Body and Paint 303 Alexandra Road Singapore 159941 DID: 6319 0174 Fax: 6479 4601

Performance Motors Limited

A member of the Sime Darby Group Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



FINAL REPORT

Estimate No.

b1 44958

Page No. :

Date Estimated :

24/11/2017

Prepared By

Merina Chia San San

REPAIR FOR -

- ACCOUNT -

163385

Yu Yah Leng (Yu YaLin)

FWD Singapore Pte. Ltd.

103 Ah Hood Road

6 Temasek Boulevard

#18-01 Suntec Tower 4

#09-08

Singapore 038986

Singapore 320103

EGN NO	OHASSIS NO	REGN DATE	MODEL.		M LEA	Œ
LA2749M	D829183	26/02/2016	520iA	ORIGINAL PRICE	DISC. %	NETT
and attachmen	it bumper and attachm ts include knocking ou	ents, front LH fender at dents caused by		1700.00		1,700.00
the accident				1730.00		1,730.00
	bi xenon headlight inc			451.00		451.00
To remove old reconnect to r	g tests for proper func I PDC assembly, replace new bumper including	tion. ce damaged parts and		150.00		150.00
proper functio	n. strical wiring systems a ction including adjustn	t the front section		150.00		150.00
To carry out b	oody cavity preservatio			100.00		100.00
(Per panel). Sundries.				80.00		80.08

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT	
FRT LH 1 SIDE PANEL BRACKET FRT LH FENDER FRT BUMPER LH SPACER # SUPPORT * FRT BUMPER LH PROTECTIVE RUBBER STR FRT BUMPER PANEL PRIMED (PDC) # LH GRILLE AIR INLET CLOSED * BMW EMBLEM # RIVET * # HEADLIGHT GASKET SET * LH BI XENON HEADLIGHT	67.45 842.30 9.20 16.20 21.75 1,246.40 70.35 67.80 0.45 30.75 2,566.95	1.00 1.00 1.00 1.00 1.00 1.00 1.00 4.00 1.00		67.45 842.30 9.20 16.20 21.75 1,246.40 70.35 67.80 1.80 30.75 2,566.95	

Performance Motors Limited

A member of the Sime Darby Group Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



FINAL REPORT

SUPPLEMENTARY ITEMS

Total Labour:	4,361.00
Total Parts :	4,940.95
Total Labour & Parts :	9,301.95
Deduction for Excess:	800.00
Total Repair Costs less Excess:	8,501.95
GST @7%:	595.14
Grand Total:	9,097.09
Grand Total	

Performance Motors Limited

A member of the Sime Darby Group Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



SUPPLEMENTARY

Estimate No.

: b1 44958

Date Estimated : 24/11/2017

Prepared By

: Merina Chia San San

REPAIR FOR -

Yu Yah Leng (Yu YaLin)

103 Ah Hood Road

#09-08

- ACCOUNT -

163385

Page No. :

FWD Singapore Pte. Ltd.

6 Temasek Boulevard

#18-01 Suntec Tower 4

Total Parts:

Total Labour & Parts:

Singapore 038986

Singapore 320103

REGN NO

CHASSIS NO

REGN DATE

MODEL

M LEAGE

SLA2749M

D829183

26/02/2016

520iA

NETT

DESCRIPTION

ORIGINAL PRICE

DISC. %

119.10

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# SUPPORT * # LH GRILLE AIR INLET CLOSED * # RIVET * # HEADLIGHT GASKET SET *	16.20 70.35 0.45 30.75	1.00 1.00 4.00 1.00		16.20 NU 70.35 NU 1.80 NU 30.75 NU
	Total Labour:			0.00 119.10

...CLAIM SUBFOLDER...(Pending for Survey Report)

AIM SUB	FOLDER TRACK		The same succession	4 J: Dat	Adi Submitted	Ins Auth'ed	Status
Case	Notified 27 Nov 2017 Edit Reg	Est Submitted	27 Nov 2017 00:00 Edit Adj Rpt	S\$9,301.95 Edit Estimates	\$\$9,301.95 View Rpt		Pending for Survey Report Cancel Case
	Main	Refere		Claim Details	T t	ocuments	Show All
	UBFOLDER DET	ATIS	CONTRACTOR OF THE PERSON NAMED IN			[Created by a	djuster]
	OBFOLDER DET	YU YAH LEN	G. ID: S7211153	3B			
Insured:	- No.	SLA2749N		Date of Los	s:	11/11/2017 15:	
Vehicle Reg. No.: Claim Type:			OD / 1201700007722		Policy/Cover Note No.:		0689)
Claim Type.		AUTO PROCESSOR STORY				S\$800.00	
Repairer:		V V C C C C C C C C C C C C C C C C C C	F-1, C2100177/631	90174			ance Centre, 15994
Handling	Insurer:		Dt - 144 (M	O) - Tol: 6727 5700	[Handled by Cl	ara Li Zi Rong	H BIN HAMID
Adjuster:		LKK Auto C	onsultants Pte Lt due 06/12/201	t d (HQ) - Tel: 6256 17]	-3561 [Handled	DY MOND TAUFT	(H BIN HAMID]
Driver/Cu	istodian:	CHIN WEE S	ENG (), NRIC: S	7033401A			
		FTVED				View All	Compose Case Mai
ASSOCI	ATED MAIL REC	ETAED		**************************************	2749M - Claim H	andler: Clara Li 2	
 FWD_ 	SG (28/11/2017):	Alert - Adj Man	date Approved (S	5\$10530.10) - SL			
ALL AS	SOCIATED TASK	(SE		1000 01 10			New Task Complet
Due Da	ate Priority	Type Task Gr	oup Subject	Handler Ass	igned By Con	npieteu on C	i cured on

Claim Documents

*SLA2749M (1201700007722) OD Nov 11 2017 3:00PM [YU YAH LENG] Performance Motors Limited

1 per page ▼	oad Photos Compose New Letter	load Docume
Thumbnail Print		essment F
1 Load HTM	LKK Auto Consultants Pte Ltd (HQ) Adjuster Immediate Advice	Finalized (
	Adjuster Immediate Advice	28/11/17
3 per page ▼ ✓		otos/Imag
Thumbnail Prin	LKK Auto Consultants Pte Ltd (HQ)	Relabel/
€ Load JPG €	General View	28/11/17
	General View	28/11/17
V	General View	28/11/17
	General View	28/11/17
9	General View	28/11/17
	General View	28/11/17
	General View	28/11/17
	General View	28/11/17
•	General View	28/11/1
● Load JPG	General View	28/11/1
1 Load JPG ☑	General View	28/11/1
1 Load JPG ☑	General View	28/11/1
1 Load JPG €	General View	28/11/1
■ Load JPG	General View	28/11/1
€ Load JPG	General View	
● Load JPG	General View	5 28/11/1
● Load JPG 🗹	General View	
€ Load JPG	General View	
1 Load JPG ✓	General View	
1 Load JPG ✓	General View	
● Load JPG 🗹	General View	
€ Load JPG	General View	1 28/11/2
€ Load JPG		2 28/11/
1 Load JPG ☑	O THE PROPERTY OF THE PROPERTY	3 28/11/
■ Load JPG		4 28/02/
1 Load JPG 2		25 28/02/
● Load JPG 🗹	No. of the Physics	26 28/02/
● Load JPG 🗹		27 28/02/
⑤ Load JPG €		28 28/02/
	Keinspection Floto	29 28/02/
1 per page Thumbnail P		Document

12010			♠ Load PDF
1	28/11/17 11:21	ESTIMATE	
3	28/02/18 14:37	SUPPLEMENTARY	1 Load PDF

Documents Checklist

DOCUMENTS CHECKLIST	Reset Save Print
There are no document checklists configured.	
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	
Show Remarks To: Handling Insurer Note: Remarks are private unless you show it to other parties.	The state of the s

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

FWD Singapore Pte. Ltd.

6 Temasek Boulevard, #18-01 Suntec Tower 4

Singapore 038986

Our File No:

CS/FWD17022530/T1VBS2

Date:

02/03/2018

REFERENCE

Insured/Claimant: Date of Loss:

YU YAH LENG 11/11/2017

Policy No: Nature of Claim: PNPV2017-00000689

OD

Claim No:

1201700007722

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SLA2749M

Make & Model:

BMW 5201, 2.0 (A)

26/02/2016 (Man. Year: 2015)

Engine No: Chassis No: A9831317N20B20B WBA5A32030D829183

Reg. Date: Colour:

Black

Engine Capacity: Market Value/New Car Price: 1997 cc

Sum Insured (S\$):

S\$160,000.00 Market Value/New Car Price Odometer:

17657 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Good

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: Front Left Side:

225/55R17

Bridgestone 6 mm Bridgestone 6 mm Rear Tyre Size:

225/55R17

Rear Left Side: Rear Right Side: Bridgestone 6 mm Bridgestone 6 mm

Front Right Side: The above values represent the remaining tyre treads depth

	Renairer's	Adjuster's	Difference	Diff %
			1,347.25	21.16
		(10.000,000)	0.00	
			1,195.00	21.82
		0.00	0.00	
		0.00	0.00	
THE RESERVE THE PROPERTY OF TH	1782-777-70-1	0.204.05	2 542 25	21.46
Calculated Gross Total (S\$)	11,844.20			0.00
- Excess (S\$)	800.00	800.00	0.00	
(22)	11 044 20	8,501.95	2,542.25	23.02
		595.14	177.95	23.0
	07070(847479	9,097.09	2,720.20	23.0
	Calculated Gross Total (S\$) - Excess (S\$) (S\$) + GST 7.00/7.00% (S\$) Nett Amount (S\$)	- Excess (S\$) 800.00 (S\$) 11,044.20 + GST 7.00/7.00% (S\$) 773.09	6,368.20 5,020.95 0.00 0.00 5,476.00 4,281.00 0.00 0.00 0.00 0.00 Calculated Gross Total (S\$) 11,844.20 9,301.95 - Excess (S\$) 800.00 800.00 (S\$) 11,044.20 8,501.95 + GST 7.00/7.00% (S\$) 773.09 595.14	Calculated Gross Total (S\$) 11,844.20 11,044.20 12,542.25 13,007.00% (S\$) 17,007.00% (S\$) 17,007.00% (S\$) 17,007.00% 17,007.00% (S\$) 17,007.00% (S\$) 17,007.00% (S\$) 177.95 177

INSPECTION

Date of Assignment:

27/11/2017

Date Inspected:

27/11/2017 Inspected At:

Performance Motors Limited (Alexandra)

303 Alexandra Road, Sime Darby Performance Centre

Singapore 159941

Estimated Period of Repair:

5.0 days

MOHD TAUFIKH BIN HAMID Adjuster:

Manager:

VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster&fuseaction=gen_printrpt&caseid=660995&extid=257744&CFID=29512240&C... 1/4

REPAIR DETAILS

Reference

Version: 1.0 (Last Synchronised: 02 Mar 2018) Part Source: MRM-SG

BMW 520I 2.0 (A) (Catalogue:Merimen Singapore 1.0) 143 Parts:

(Price-denominated Standard List) Repairer's Labour:

(Unsubmitted, no print-code for SLA2749M) Print Code:

These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the Validity:

END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

No.	commende Qty Part No.		Condition	Repairer's	Amount
7.732.0	New Marie Committee	*FRT LH 2 SIDE PANEL BRACKET	Not Necessary	31.35 FS	*-FS
1	1		Not Necessary	31.35 FS	*-FS
2	1	*FRT LH 3 SIDE PANEL BRACKET	Not Necessary	31.35 FS	*-FS
3	1	*FRT LH 4 SIDE PANEL BRACKET	Necessary	67.45 FS	*67.45 FS
4	1	*FRT LH 1 SIDE PANEL BRACKET	Necessary	842.30 FS	*842.30 FS
5	1	*FRT LH FENDER	Not Necessary	99.25 FS	*-FS
6	1	*FRT LH BOTTOM DEFORMATION ELEMENT	Not Necessary	668.10 FS	*-FS
7	1	*FRT BUMPER CARRIER	Not Necessary	153.65 FS	*-FS
8	1	*FRT BUMPER BOTTOM MOUNT	Necessary	9.20 FS	*9,20 FS
9	1	*FRT BUMPER LH SPACER	Not Necessary	80.65 FS	*-FS
10	1	*GRILLE AI INLET MIDDLE	Not Necessary	74.25 FS	*-FS
11	1	*LH GRILLE AIR INLET PARTLY CLOSED	Not Necessary	46.80 FS	*-FS
12	1	*SHOCK ABSORBER FRONT	Deformed	21.75 FS	*21.75 FS
13	1	*FRT BUMPER LH PROTECTIVE RUBBER STR		1,246.40 FS	*1,246.40 FS
14	1	*FRT BUMPER PANEL PRIMED (PDC)	Deformed	39.10 FS	*-FS
15	1	*COVERING PRIMED LH	Not Necessary	1.60 FS	*-FS
16	2	*EMBLEM GROMMET	Not Necessary	67.80 FS	*67.80 FS
17	1	*BMW EMBLEM	Necessary		*2,566.95 FS
18	1	*LH BI XENON HEADLIGHT	Cracked	2,566.95 FS	*-FS
19	4	*DECOUPLING RING PDC TORQUE CONVERTE	Not Necessary	19.80 FS	*80.00 FS
20	1	*SUNDRIES	Necessary	150.00 FS	
21	1	*SUPPORT	Necessary	16.20 FS	*16.20 FS *70.35 FS
22	1	*LH GRILLE AIR INLET CLOSED	Deformed	70.35 FS	
23	4	*RIVET	Necessary	1.80 FS	*1.80 FS *30.75 FS
24	1	*SET HEADLIGHT GASKET	Necessary	30.75 FS	30.75 F3
7. 100	ranchise part. S=Spo		Total Parts (S\$)	6,368.20	5,020.95

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Re	commended Labour			1200000000
No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items	New	2.550.00	1,700.00
1	TO REPLACE FRONT BUMPER, FRONT LEFT FENDER INCLUDING ATTACHMENTS ETC AND TO KNOCK OUT DENTED AREA CAUSED BY ACCIDENT.	New	2,000.00	POD 08/00A (/ 98/00A)
2	TO PAINT FRONT BUMPER AND FRONT LEFT FENDER.	New	1,923.00	1,730.00
3	TO REPLACE LEFT OR RIGHT HEADLIGHT INCLUDING PROGRAM AND CONDUCT TESTS FOR PROPER FUNCTION.	New	531.00	451.00
4	TO REMOVE OLD PDC ASSEMBLY, REPLACE DAMAGED PARTS AND RECONNECT TO NEW BUMPER INCLUDING CONDUCT CHECKS FOR PROPER FUNCTION.	New	177.00	150.00
5	TO CHECK ELECTRICAL WIRING SYSTEMS AT THE FRONT SECTION FOR PROPER FUNCTION INCLUDING ADJUSTMENTS OF HEADLIGHTS.	New	177.00	150.00
6	TO CARRY OUT BODY CAVITY PRESERVATION. (PER PANEL)	New	118.00	100.00
	Gross Labor	ur Cost (S\$)	5,476.00	4,281.00
	Report was unsubmitted during this p	rint-out.		

< END OF ESTIMATES >