



FINAL REPORT

Estimate No. : **b1 44958**  
Date Estimated : **24/11/2017**  
Prepared By : **Merina Chia San San**

Page No. :

**REPAIR FOR -**  
**Yu Yah Leng (Yu YaLin)**  
**103 Ah Hood Road**  
**#09-08**

**Singapore 320103**

**- ACCOUNT - 163385**  
**FWD Singapore Pte. Ltd.**  
**6 Temasek Boulevard**  
**#18-01 Suntec Tower 4**  
**Singapore 038986**

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE
SLA2749M	D829183	26/02/2016	520iA	0
DESCRIPTION		ORIGINAL PRICE	DISC. %	NETT
To replace front bumper and attachments, front LH fender and attachments include knocking out dents caused by the accident		1700.00		1,700.00
To paint front bumper and front LH fender		1730.00		1,730.00
To replace LH bi xenon headlight include programming and conducting tests for proper function.		451.00		451.00
To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct checks for proper function.		150.00		150.00
To check electrical wiring systems at the front section for proper function including adjustments of headlights.		150.00		150.00
To carry out body cavity preservation. (Per panel).		100.00		100.00
Sundries.		80.00		80.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
FRT LH 1 SIDE PANEL BRACKET	67.45	1.00		67.45
FRT LH FENDER	842.30	1.00		842.30
FRT BUMPER LH SPACER	9.20	1.00		9.20
# SUPPORT *	16.20	1.00		16.20
FRT BUMPER LH PROTECTIVE RUBBER STR	21.75	1.00		21.75
FRT BUMPER PANEL PRIMED (PDC)	1,246.40	1.00		1,246.40
# LH GRILLE AIR INLET CLOSED *	70.35	1.00		70.35
BMW EMBLEM	67.80	1.00		67.80
# RIVET *	0.45	4.00		1.80
# HEADLIGHT GASKET SET *	30.75	1.00		30.75
LH BI XENON HEADLIGHT	2,566.95	1.00		2,566.95



FINAL REPORT

# SUPPLEMENTARY ITEMS

Total Labour :	4,361.00
Total Parts :	4,940.95
Total Labour & Parts :	9,301.95
Deduction for Excess :	800.00
Total Repair Costs less Excess:	8,501.95
GST @7%:	595.14
Grand Total :	9,097.09