

INS. CASE OWNER:

Syabeda

CC 4/QBE170 22534 / K2A302

LKK:

IDAC:

ASSIGNMENT

Surveyor:

KENNETH

DOI:

27/11/17

Date / Time:

27/11/17

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

XD 9347K

Name of Insured:

HONG HILL PTE LTD

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A.:

22/11/17

Is driver the owner?

(YES ☒ NO ☐

Nature of Accident:

If NO, Driver Name / Age: RE LEILEI

Driver Tel No.: 9653 9423

(V/L ☒ YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SLN 6794L



INSRS:

WSP: Complete VMS

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

18/12/17 (Zayn)

8-FEB-18

9-2-18

FOR MANDATE

RECEIVED 03 FEB 2018

RECEIVED 24 APR 2018

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time: 08/12/17

Sent By:

Shirley Hew

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

(

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with

Email

Call

Final Liability:

%

(Agreed / Assessed)

BOLA S/N No.: 27

If NO or B 28, Ass. Lia:

Repair Cost:

SS

2,675

Loss of Rental (LOR):

SS

days

Loss of Use (LOU):

SS

300

(560 x 5)

days

Loss of Income (LOI):

SS

-

(\$ x days)

LOR only

☐

LOU only

☐

LOR + LOU

☐

LOR + LOI

☐

[Tick only one]

GIA/LTA Search

SS

5.35

Medical:

SS

-

Disbursement:

SS

-

(e.g. Tow/ Independent)

Legal Cost

SS

-

Total:

SS

2,980.35

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

2,980.35

Name 1:

COMPLETE VMS PTE LTD

Payee 2: (Strike if N.A.)

SS

X

Name 2:

Payee 3: (Strike if N.A.)

SS

X

Name 3:

REF:

QBE

ASSIGNMENT

From: _____ Date: **27/11/17**

Estimated Cost: _____

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: **SLN 6794L**

at Workshop/s: **Complete VMS**

of: **Blk 176 Sin Ming Drive #03-14, 575721**

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: **5** Consistent? : Yes or NoEst. Repairs: **4-5** days Res: Yes or NoLump Sum: **20** % 3 Val: Yes or NoCA / REV / REP: / 24 HRS **'ds'**

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: **SLN 6794L** (Reg: **01 05**)

Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or

Make: **Toy A/TIS** CC: **1598**

Colour: **M. Grey** A/C: _____ Insured / Std / NI / NA

Sp Reading: **109637** T. Radio: Insured / Std / NI / NA

Eng No: _____

C.No: **MRO 538EC 107 076063**

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt or

Brake: ☒ In order / Jammed / Leaked / Burnt or

Mod: ☒ Nil / S/Rim / STD A/Rim or

Tyre Size: F: **185/70R14**
R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or **Continental**

Front: _____ Rear: _____

R. Bal: **7** mm R. Bal: **7** mm

L. Bal: **7** mm L. Bal: **7** mm

D.O.A: **22/11/17** D.O.I: **27/11/17**

Survey held at: ☒

Des. of Damages: Frt / ☒ Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

28/11 **File pass to Cathum****4/5 \$2,500/-****RED (\$2,851.09/53%)**

Date/Time: File Pass to?

☐

Preli. Report

☐

Final Report

Date/Time: File Return to?

Days Of Repair:

Resurvey No. of Trip:

Survey Fee

Transportation

S. & P. C. S.

Road

Other

Total

Report Format:

Lump Sum / I.B.I. (S)

Add Fee:

☐

Site Insp. (S)

☐

Interview (S)

☐

Tech. Insp. (S)

☐

Weekend (S)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
QBE INSURANCE (SINGAPORE) PTE LTD		Ref : CC4/QBE17022534/Kza3	
1 RAFFLES QUAY #29-10 SOUTH TOWERSINGAPORE 048583		Date : 27-11-2017	
		Code : QBE	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	XD 9347K	Veh. Inspected	SLN 6794L
Policy No.	8-V0008716-MVA-R003	Coverage (\$)	0.00
Claim No.	VC010932	Excess (\$)	0.00
Assign From		Assign Date	27/11/2017
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	22/11/2017	Inspection Date	27/11/2017
Survey held at	COMPLETE VMS PTE LTD BLK 176 SIN MING DRIVE #03-14 SIN MING AUTOCARE COMPLEX SINGAPORE 575721		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: TBA
Our ref: CC4/QBE17022534/Kza3

Date: 08.12.2017

The Motor Claims Department
M/s QBE INSURANCE (SINGAPORE) PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.


SLN 6794L

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 27/11/2017 at the premises of M/S Complete Vms Pte Ltd (Sin Ming Drive) and have the following to report:-

Workshop Estimate Amount	: S\$	5,351.09
Revised Estimate Amount	: S\$	2,194.25
"Check" Items Amount	: S\$	1,850.78
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:
The vehicle sustained damages at the
Rear Portion



Comments/Present Status:
Damages Consistent
Estimated normal period for repairs: 4.5 days

Yours faithfully,

KENNETH KONG
Licensed Appraiser

We are agreeable to proceed with direct settlement for this matter subject to our surveyor's recommendation on COR, LOU/LOR as per benchmark.

Please choose from the list below:

1. AUTOMOBILE INSPECTION SERVICES
2. KM AUTO ASSESSORS PTE LTD
3. LKK AUTO CONSULTANTS PTE LTD
4. PRIORITY SERVICES
5. QUANTUM RISK MANAGEMENT (S) PTE LTD
6. APPRAISALS ASSOCIATES PTE LTD

Thank you.

Syaheeda Othman

Senior Executive, Claims
QBE Asia Pacific – Singapore

QBE Insurance (Singapore) Pte Ltd
DID: +6477 1130 Fax : +6533 3270
Email: syaheeda.othman@qbe.com
Visit us on the web at www.qbe.com.sg

From: Gan Li Hui [<mailto:lihui@completevms.com.sg>]

Sent: Friday, 24 November, 2017 11:44 AM

To: Jenny Toh <jenny.toh@qbe.com>; Syaheeda Nacah Binte Mohamed Othman <syaheeda.othman@qbe.com>

Subject: Re: NOTICE OF ACCIDENT: SLN6794L Your ref: XD9347K

REMINDER

On 23 November 2017 at 13:50, Gan Li Hui <lihui@completevms.com.sg> wrote:

Without Prejudice

Dear OIC,

ACCIDENT INVOLVING SLN6794L AND XD9347K ON 22/11/2017 ALONG SIMS WAY TOWARDS PIE/TUAS AT ABOUT 14:05 HRS.

We act for TAN AH CHIN owner of vehicle no. SLN6794L with instruction to repair the vehicle.

Please be informed that the said vehicle can be inspected at:-

Venue

:

Complete VMS Pte Ltd

176, Sin Ming Drive,

#03-14,

Singapore 575721

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you. Please note that there will also be a storage charge of \$60 per day on the 2 day notice period commencing from the date of this letter.

Thank you & Best Regards,
Gan Li Hui (Ms)

Complete VMS PTE LTD

Tel: 6455 0012 Fax: 6554 0012

Block 176 Sin Ming Drive, #03-14

Sin Ming Autocare Complex, Singapore 575721

IMPORTANT NOTICE : The information in this email is confidential and may also be privileged. If you are not the intended recipient, any use or dissemination of the information and any disclosure or copying of this email is unauthorised and strictly prohibited. If you have received this email in error, please promptly inform us by reply email or telephone. You should also delete this email and destroy any hard copies produced.

IMPORTANT NOTICE : The information in this email is confidential and may also be privileged. If you are not the intended recipient, any use or dissemination of the information and any disclosure or copying of this email is unauthorised and strictly prohibited. If you have received this email in error, please promptly inform us by reply email or telephone. You should also delete this email and destroy any hard copies produced.



COMPLETE VMS PTE LTD The Premier One-Stop Vehicle Accident Claims Centre
 176 Sin Ming Drive, #03-14, Sin Ming Autocare Complex, Singapore 575721
 (Tel) 6455 0012 (Fax) 6554 0012 (Web) www.completevms.com.sg

Email : darren@completevms.com.sg ()
 lily@completevms.com.sg ()
 lihui@completevms.com.sg ()

TAN AH CHIN @TAN CHIN WAH
 97 MARINE PARADE #05-01
 SINGAPORE 449273

Attention : THE OWNER
 Contact : 96987237

Estimate : ES006216

Date : 22/11/2017
 Vehicle Num. : SLN6794L
 Make/Model : TOYOTA COROLLA 1.6-2004
 Chassis/Eng# : MR053ZEC107076063/3ZZ4410167
 Accident Date : 22/11/2017
 Claim No. :
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LIST ITEMS : <i>610.00</i>				
1.	1	BOOT LID	<i>Bu</i> 845.30	✓
2.	1	BOOT LID LOCK	<i>R</i> 129.30	X
3.	1	BOOT WEATHERSTRIP	<i>Ln</i> 191.00	X
4.	1	REAR END PANEL	<i>Bu</i> 700.80	✓
5.	1	REAR END PANEL TOP GARNISH	<i>ng oil</i> 178.10	✓
6.	1	REAR BUMPER	<i>Bu</i> 587.70	✓
7.	2	REAR BUMPER BRACKET	<i>R</i> 74.40	X
8.	6	REAR BUMPER CLIP	6.50	✓
9.	2	REAR BUMPER SIDE RETAINER	<i>clsd's</i> 68.90	✓
10.	2	TAIL LAMP	<i>Ln</i> 359.45	X
List TotalS\$:			3,676.70	
25.00% Discount S\$:			919.18	
			2,757.52	

SPECIAL NETT ITEMS :				
1.	1	1.6 E EMBLEM	<i>Ln</i> 63.35	✓
2.	1	VVTI EMBLEM	<i>Ln</i> 49.80	✓
3.	1	COROLLA EMBLEM	<i>Ln</i> 55.80	✓
4.	1	ALTIS EMBLEM	<i>Ln</i> 49.62	✓
5.	1	REVERSE SENSOR	<i>shot</i> 280.00	200.00
Special Nett Total S\$:			498.57	

LABOUR :
 RUST PROOFING TREATMENT
 CHANGE TAIL LAMP AND CHECK LIGHTING
 SPRAY PAINT DAMAGED AREA AFFECTED

2cl 100.00 *6cl*
 65.00
 950.00 *60cl*

CONTINUE / ...

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



COMPLETE VMS PTE LTD The Premier One-Stop Vehicle Accident Claims Centre
 176 Sin Ming Drive, #03-14, Sin Ming Autocare Complex, Singapore 575721
 (Tel) 6455 0012 (Fax) 6554 0012 (Web) www.completevms.com.sg

Email : darren@completevms.com.sg ()
 lily@completevms.com.sg ()
 lihui@completevms.com.sg ()

TAN AH CHIN @TAN CHIN WAH
 97 MARINE PARADE #05-01
 SINGAPORE 449273

Attention : THE OWNER
 Contact : 96987237

Estimate : ES006216

Date : 22/11/2017
 Vehicle Num. : SLN6794L
 Make/Model : TOYOTA COROLLA 1.6-2004
 Chassis/Eng# : MR053ZEC107076063/3ZZ4410167
 Accident Date : 22/11/2017
 Claim No. :
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		TO CUT OFF REAR END PANEL, KNOCK AND STRAIGHTEN REAR FLOOR PANEL AND CHASSIS FRAME		980.00
		Labour Total S\$:		2,095.00

SingDollars : Five Thousand Three Hundred Fifty-One & Cents Nine Only

Total S\$: 5,351.09

COMPLETE VMS PTE LTD

This is only an estimate bases on our preliminary inspection and does not cover additional parts and labour time which may be required after the work has begun



Email : darren@completevms.com.sg ()
lily@completevms.com.sg ()
lihui@completevms.com.sg ()

TAN AH CHIN @TAN CHIN WAH
97 MARINE PARADE #05-01
SINGAPORE 449273

Attention : THE OWNER
Contact : 96987237

*Not Authorised
Lily B?
Remy Atk Pains*

Estimate : ES006216

Date : 22/11/2017
Vehicle Num : SLN6794L
Make/Model : TOYOTA COROLLA 1.6-2004
Chassis/Eng# : MR053ZEC107076063/3ZZ4410167
Accident Date : 22/11/2017
Claim No :
Reference :
Policy No :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

1.	1	LIST ITEMS :		
2.	1	BOOT LID	Bu 845.30	✓
3.	1	BOOT LID LOCK	129.30	x
4.	1	BOOT WEATHERSTRIP	191.00	x
5.	1	REAR END PANEL	700.80	7
6.	1	REAR END PANEL TOP GARNISH	178.10	7
7.	2	REAR BUMPER	Bu 587.70	✓
8.	6	REAR BUMPER BRACKET	74.40	7
9.	2	REAR BUMPER CLIP	6.50	na
10.	2	REAR BUMPER SIDE RETAINER	68.90	137.80
		TAIL LAMP	359.45	718.90
		List TotalS\$:		3,676.70
		25.00% Discount S\$:		919.18
				2,757.52
1.	1	SPECIAL NETT ITEMS :		
2.	1	1.6 E EMBLEM	na 63.35	✓
3.	1	VVTI EMBLEM	na 49.80	✓
4.	1	COROLLA EMBLEM	na 55.80	✓
5.	1	ALTIS EMBLEM	na 49.62	✓
		REVERSE SENSOR	shot 280.00	2017
		Special Nett Total S\$:		498.57
		LABOUR :		
		RUST PROOFING TREATMENT	2cl 100.00	7
		CHANGE TAIL LAMP AND CHECK LIGHTING	65.00	
		SPRAY PAINT DAMAGED AREA AFFECTED	950.00	60cl

CONTINUE / ...

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Email : darren@completevms.com.sg ()
lily@completevms.com.sg ()
lihui@completevms.com.sg ()

TAN AH CHIN @TAN CHIN WAH
97 MARINE PARADE #05-01
SINGAPORE 449273

Attention : THE OWNER
Contact : 96987237

Estimate : ES006216

Date : 22/11/2017
Vehicle Num. : SLN6794L
Make/Model : TOYOTA COROLLA 1.6-2004
Chassis/Eng# : MR053ZEC107076063/3ZZ4410167
Accident Date : 22/11/2017
Claim No. :
Reference :
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		TO CUT OFF REAR END PANEL, KNOCK AND STRAIGHTEN REAR FLOOR PANEL AND CHASSIS FRAME		980.00 ?
		Labour Total S\$:		2,095.00

SingDollars : Five Thousand Three Hundred Fifty-One & Cents Nine Only

Total S\$: 5,351.09
=====

COMPLETE VMS PTE LTD

This is only an estimate bases on our preliminary inspection and does not cover additional parts and labour time which may be required after the work has begun

845.30	129.30	63.35	80.00	20.00	100.00
587.70	191.00	49.80		600.00	45.00
39.00	700.80	55.80			350.00
68.90	178.10	49.62			980.00
	148.80	200.00			
	68.90				
	718.90				

418.57

80.00

620.00

2135.80

1475.00

0.00

1540.90

3676.70

1540.90

2135.80

498.57

418.57

80.00

2095.00

620.00

1475.00

1540.90

385.23

1155.68

418.57

620.00

2194.25

700.80

178.10

148.80

}

CHECK ITEM

1027.70

256.93

770.78

100.00

980.00

1850.78

DISCHARGE VOUCHER

Without Prejudice
Save As to Costs

Your Reference : TPDS17184-SLN6794L
Our Reference : VC010932

I/We, claimant **COMPLETE VMS PTE LTD** do hereby acknowledge the sum of Singapore Dollars: **Two Thousand Nine Hundred Eighty and Thirty Five Cents (S\$2,980.35)** being full discharge and satisfaction of all claims against QBE Insurance (Singapore) Pte Ltd and their Insured, **HONG HILL PTE LTD**, over damage to my/our vehicle **SLN 6794L** from an accident involving **XD 9347K** at/along **SIMS AVE/WAY TOWARDS PIE/KPE**, which occurred on **22 NOVEMBER 2017** at about **1350-1405** hours.

Further, I/we hereby acknowledge and accept that the above said sum paid to me is 'strictly on a without admission of liability basis' and I/we hereby discharge and release the said QBE Insurance (Singapore) Pte Ltd and their Insured, **HONG HILL PTE LTD**, from all claims, demands or action of damages as a result of the said accident.

Also, I/we hereby agree to indemnify and keep indemnified the said QBE Insurance (Singapore) Pte Ltd against all and any claims whatsoever made or to be made by any person or persons on my/our behalf in respect of the said accident.

Dated this (day) 19 of (month) April (year) 2018

Signature

Tan Ah Chin

Claimant's Name

S0117723J

FIN/NRIC No.

97 Marine Parade #05-01

Singapore 449273

Address



Company stamp if applicable

Witness's Signature

Gan Li Hui

Witness's Name

S8780056C

FIN/NRIC No.

176 Sin Ming Blvd

03-14

S575721

Address

Please return to:
General Claims Department
QBE Insurance (Singapore) Pte Ltd
1 Raffles Quay
#29-10 South Tower
Singapore 048583
Fax: 6533 3270

This indemnity is signed without prejudice
to my rights to claim for compensation
for my personal injury.

COMPLETE VMS PTE LTD

176 Sin Ming Drive, #03-14 / 07, Sin Ming Autocare Complex, S575721
Tel: 6455 0012 Fax: 6554 0012 Email: main@completevms.com.sg
Business Reg. No. 200416180E GST Reg. No.: 200416180E



2

QBE INSURANCE (SINGAPORE) PTE LTD
1 RAFFLES QUAY #29-10, SOUTH TOWER
SINGAPORE 048583

Attention : MOTOR CLAIMS DEPT

Proforma Invoice : TP006216

Date : 21/12/2017
Vehicle Num. : SLN6794L
Make/Model : TOYOTA COROLLA 1.6-2004
Chassis/Eng# : MR053ZEC107076063/3ZZ4410167
Accident Date : 22/11/2017
Claim No. :
Reference :
Policy No. :

	Amount S\$
COST OF REPAIR AS AGREED	2,500.00

SingDollars : Two Thousand Six Hundred Seventy-Five Only

Total S\$:	2,500.00
GST S\$:	175.00
Amount Due S\$:	2,675.00

=====

COMPLETE VMS PTE LTD



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
QBE INSURANCE (SINGAPORE) PTE LTD		Ref : CC4/QBE17022534/Kja3n2		
1 RAFFLES QUAY #29-10 SOUTH TOWERS SINGAPORE 048583		Date : 26-04-2018		
		Code : QBE		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	XD 9347K	Veh. Inspected	SLN 6794L	
Policy No.	8-V0008716-MVA-R003	Coverage (\$)	0.00	
Claim No.	VC010932	Excess (\$)	0.00	
Assign From	SYAHEEDA	Assign Date	27/11/2017	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA ALTIS (A)	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2005	
Chassis No.	MR053ZEC107076063	Colour	METALLIC GREY	
Odometer	109637	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/70 R14	CONTINENTAL	7 mm	
L/H Front Tyre	185/70 R14	CONTINENTAL	7 mm	
R/H Rear Tyre	185/70 R14	CONTINENTAL	7 mm	
L/H Rear Tyre	185/70 R14	CONTINENTAL	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	22/11/2017	Inspection Date	27/11/2017	
Survey held at	COMPLETE VMS PTE LTD BLK 176 SIN MING DRIVE #03-14 SIN MING AUTOCARE COMPLEX SINGAPORE 575721			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLN 6794L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BOOT LID	BUCKLED	845.30	610.00
1	BOOT LID LOCK	TO REPAIR SEE LABOUR	129.30	-
1	BOOT WEATHERSTRIP	SERVICEABLE	191.00	-
1	REAR END PANEL	BENT	700.80	700.80
1	REAR END PANEL TOP GARNISH	MTG DISTORTED	178.10	178.10
1	REAR BUMPER	BUCKLED	587.70	458.30
2	REAR BUMPER BRACKET @\$74.40	TO REPAIR SEE LABOUR	148.80	-
6	REAR BUMPER CLIP @\$6.50	NECESSARY	39.00	39.00
2	REAR BUMPER SIDE RETAINER @\$68.90	O/S DISTORTED	137.80	68.90
2	TAIL LAMP @\$359.45	SERVICEABLE	718.90	-
	LESS 25% DISCOUNT		-919.18	-513.78
			2,757.52	1,541.32
1	1.6 E EMBLEM	NECESSARY	63.35	63.35
1	VVTI EMBLEM	NECESSARY	49.80	49.80
1	COROLLA EMBLEM	NECESSARY	55.80	55.80
1	ALTIS EMBLEM	NECESSARY	49.62	49.62
	LESS 25% DISCOUNT		-	-54.64
			218.57	163.93
SPECIAL NETT ITEMS				
1	REVERSE SENSOR (SN)	SHORTED	280.00	200.00
			280.00	200.00
LABOUR				
	RUST PROOFING TREATMENT.		100.00	60.00
	CHANGE TAIL LAMP AND CHECK LIGHTING.		65.00	20.00
	SPRAY PAINT DAMAGED AREA AFFECTED.		950.00	600.00

Report Ref No. CC4/QBE17022534/Kja3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CUT OFF REAR END PANEL, KNOCK AND STRAIGHTEN REAR FLOOR PANEL AND CHASSIS FRAME. INCLUSIVE OF THE REPAIR OF BOOT LID LOCK AND REAR BUMPER BRACKET.		980.00	600.00
			2,095.00	1,280.00
GRAND TOTAL			5,351.09	3,185.25
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,500.00

Report Ref No. CC4/QBE17022534/Kja3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.