

ASS. REC. BY:



ASSIGNMENT (Office)

From (Person): Merimen Elaine Ngu of MSIG Date/Time: 27/11/17 @ 11:38am

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKM 8208S Insured: SLA 8720E

at Workshop m/s Performance Motor Tel: 6319 0174

of 303 Alexandra Road

Policy No: B28946874MCX Claim No: 536671

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 13/11/2017
(Client's Record)

CA / REV / REP. / REV 24 HRS 1wp H.O.D. Endorsement: _____

Date/Time: 11:58am @ 27/11/17 Person Contacted: Caroline Vehicle IN OUT

Date/Time	Action/Instruction (✓) Estimate
	<u>SKM 8208S - X</u>
	<u>SLA 8720E - X</u>
<u>28/11/17</u>	<u>Send preli revised by merimen</u>
<u>13/12/18</u>	<u>Final fig \$ 26,348.64 confirmed by email (Ref 19,990.55, 437)</u>

Surveyor

Taylor

REF:

MS19

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 4203 K

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: _____ days Res: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: WP Vehicle: IN / OUT

Veh No: SKM82085 Yr Regn: 2017, Apr.

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: BMW 520d. cc 1995

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 15268 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WBA X 320706 S84252

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: NI / S/Rim / STD A/Rim or

Tyre Size: F: 245/43 R18

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mm

L/Bal. 6 mm

D.O.A. _____ D.O.I. 23/11/17

Survey held at PML

Des. of Damages: Frt / Rear / O/S (N/S) / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

* Check repair work

RECEIVED 13 APR 2018

Date/Time, File Pass to?

☐ : Prel. Report

1)

☐ : Final Report

Date/Time, File Return to?

2) 13/4 - typist

Days Of Repair: 10

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Weekend (\$

Survey Fee: 450

Transportation:

S + RS \$

Photos

Others

TOTAL

Report Format: merimen

Lump Sum / I.B.I. (\$) 26,348.64

Survey Department Check List (Case Handler)

Reference No.: CS/MSG/17022535/Tivb

Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all information created by the assignment team are **ACCURATE**.

(1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From	✓			
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No	✓			
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded	✓			
---	-------------------------	---	--	--	--

Check By: **VERON** **13/4/18**
Case Handler Date

*C: Critical *N: Non-Critical



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CS/MSG17022535/T1vb	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 27-11-2017	
		Code : MSG	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SLA 8720E	Veh. Inspected	SKM 8208S
Policy No.	B28946874MKC	Coverage (\$)	0.00
Claim No.	536671	Excess (\$)	0.00
Assign From	MERIMEN (ELAINE NGU)	Assign Date	27/11/2017
2. Vehicle Particulars & Condition			
Make & Model	c.c 0		
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	13/11/2017	Inspection Date	27/11/2017
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

MSIG INSURANCE (SINGAPORE) PTE LTD	Ref : CS/MSG17022535/T1vb	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581	Date : 27-11-2017	

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	14 Nov 2017		27 Nov 2017 11:38 Assign				New Assignment Cancel Case

[Main](#)[Reference](#)[Claim Details](#)[Documents](#)[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	PREMIER RENT A CAR PTE LTD, Co. Reg. No.: 200612929E		
Main Claimant:	RIBKAH HANDAJANI ONGKOWIDJAJA, ID: S2649347A		
Vehicle Reg. No.:	SKM8208S	Date of Loss:	13/11/2017 19:00 - :59
Claim Type:	TP / 536671	Policy/Cover Note No.:	B28946874MCX (TP, Fire & Theft) Coverage: 01/05/2017 - 30/04/2018
Vehicle Reg. No. (Insured):	SLA8720E	Policy No. (Claimant):	
		Excess:	S\$750.00
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Elaine Ngu Siau Mei - 6594 2540]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 28/11/2017]		
Driver/Custodian (Insured):	ATKINSON PAUL RAYMOND (), NRIC: G3246161T		
Adj Asg. Remarks:	CAR ALREADY IN. PLS CONTACT CAROLINE FOR SURVEY@63190174		

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607188R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd. 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn: Elaine Ngu Siau Mei	Date: 28 Nov 2017

Preliminary Advice

Insured Vehicle No	: SLA8720E		
TP Vehicle No	: SKM8208S	Accident Date	: 13/11/2017
Make	: BMW 520i	Assignment Date	: 27/11/2017
Date of Inspection	: 27/11/2017	Est. Duration of Repair	: 14.00
Inspection At	PERFORMANCE MOTORS LIMITED (ALEXANDRA) 303 ALEXANDRA ROAD, SIME DARBY PERFORMANCE CENTRE SINGAPORE 159941		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	46,068.25
Revised Amount	:S\$	26,540.55
Check Items (Estimated)	:S\$	16,406.65
Total	:S\$	42,947.20
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type	Singapore NRIC
Owner ID	9347A
Vehicle Details	
Vehicle No.	SKM82085
Vehicle to be Exported	No
Intended De-registration Date	28 Nov 2017
Vehicle Make	B.M.W.
Vehicle Model	520D LED NAV
Primary Colour	Silver
Manufacturing Year	2017
Engine No.	74749883B47D20A
Chassis No.	WBAJC32070G864252
Maximum Power Output	140.0 kW (187 bhp)
Open Market Value	\$44,181.00
Original Registration Date	28 Apr 2017
First Registration Date	28 Apr 2017
Transfer Count	0
Actual ARF Paid	\$48,854.00
Intended PARF Rebate Details	
PARF Eligibility	Yes
PARF Eligibility Expiry Date	27 Apr 2027
PARF Rebate Amount	\$36,640.00
Intended COE Rebate Details	
COE Expiry Date	27 Apr 2027
COE Category	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years)	10
QP Paid	\$54,405.00
COE Rebate Amount	\$51,229.00
Total Rebate Amount	\$87,869.00

The information contained herein is correct as at 28 Nov 2017

OK


Post an Advertisement

 Sell it yourself! Advertise it at just
\$58 until it's SOLD!
[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)
Imported Used. Reg Date On: 25 Nov 2015.

 Important Used Vehicle. Low
 Mileage.
 Direct Owner [StarAd](#)


Browse by Category

Sort by Da

7 vehicles

BMW 520D

Advanced S

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage
------	-------	-------	--------------	----------	---------	---------

Search Selection

BMW 520D

Any

Any

2017

Any

Any


BMW 5 Series 520d
\$200,800
\$17,810 /yr
24-Nov-2017
1,995 cc
-
Fuel Type: Diesel (Euro 5 Engine and Above)

Latest Model. Unregistered. Immediate Registration. Excellent Fuel Efficiency And Dynamic Driving Experience. View Now!

Posted: 25-Nov-2017 Tags: 2017 BMW 520d, 2017 BMW 520d, BMW 520d, BMW 520d, BMW, 520d, 520d, Used BMW


BMW 5 Series 520d
\$204,800
\$19,270 /yr
07-Apr-2017
1,995 cc
5,200
Fuel Type: Diesel (Euro 5 Engine and Above)

Latest Certified Preowned BMW G30/520d In The Market. Metallic Blue Stone With Leather Dakota Canberra Beige. BMW 360 Optical Checks For Your Added Peace Of Mind. View And Test Dr...

Performance Premium Selection Limited

Posted: 24-Nov-2017 Tags: 2017 BMW 520d, 2017 BMW 520d, BMW 520d, BMW 520d, BMW, 520d, 520d, Used BMW


BMW 5 Series 520d
\$204,800
\$19,160 /yr
27-Apr-2017
1,995 cc
4,580
Fuel Type: Diesel (Euro 5 Engine and Above)

Latest Certified Pre-owned BMW G30/520d In The Market. Glacier Silver With Leather Dakota Ivory White/black. BMW 360 Optical Checks For Your Added Peace Of Mind. View And Test-dri...

Performance Premium Selection Limited

Posted: 23-Nov-2017 Tags: 2017 BMW 520d, 2017 BMW 520d, BMW 520d, BMW 520d, BMW, 520d, 520d, Used BMW


BMW 5 Series 520d
\$203,800
\$19,210 /yr
31-Mar-2017
1,995 cc
6,915
Fuel Type: Diesel (Euro 5 Engine and Above)

Promo Interest Rate 1.99% Only! Latest Certified PML Management Unit, 5 Years/200,000Km PML Warranty Till Mar 2022 Fo Mind. Metallic Sapphire Black With Leather Dakota Cognac. Lo...

BW Automobiles

Posted: 22-Nov-2017 Tags: 2017 BMW 520d, 2017 BMW 520d, BMW 520d, BMW 520d, BMW, 520d, 520d, Used BMW

[Car Buying](#)
[Car Selling](#)
[Car Aftermarket](#)
[p](#)
[On The Move](#)
[Lifestyle](#)
[Compare](#)


SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	14/11/2017 11:41
Date Of Accident	13/11/2017 19:40
Exact Location Of Accident	KILLINEY ROAD AT ST THOMAS WALK JUNCTION
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKM8208S
Insured/Policyholder	
Name Of Registered Owner	RIBKAH HANDAJANI ONGKOWIDJAJA
NRIC No	S2649347A
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-91083382
Alternative Phone No	OFFICE-91083382

Vehicle Particulars

Manufacturer	BMW
Model	520D
Exact Purpose for which vehicle was being used at time of accident	NORMAL USAGE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	NOTAVAILABLE
Cover Note Number	

Driver

Name of Driver	RIBKAH HANDAJANI ONGKOWIDJAJA
NRIC No	S2649347A
Date Of Birth	18/08/1967
Occupation	INDOOR
Date Of Driving Pass	03/01/2008
Driving Experience	9 YEARS AND 10 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-91083382
Fax Number	
Contact Number	OFFICE-91083382
Email Address	NOEMAIL

Address
Postcode
Was driver an employee of the Insured's Company NO
If No, Relationship of the Driver with the Insured OWNER
Vehicle Registration Number of Driver's Own Vehicle -
-
-
Insurance Company of Driver's Own Vehicle -
-
-

General Information of the Accident

Type Of Accident COLLISION - MAJOR/MINOR RD
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Was any body injured in the Accident? NO
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
If Yes, Please state which Police Station
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

REFER TO ATTACH

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? YES
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLA8720E
Vehicle Make/Model/Colour
Details Of Properties
Name of Driver PAUL RAYMOND ATKINSON
NRIC/Passport Number G3246161T
Contact Number 91281669
Address
Postcode
Insurance Company Name
Nature Of Damage FRONT
No. Of Passenger (Including Driver) 1

Details of Witness

Name
Phone Number
Email Address

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;

HS

Policyholder's Signature / Date & Time


Sketch Plan 14 NOV 2017

Driver's Signature (If driver is not the policyholder) / Date & Time

MERINA CHIA SAN SAN
Performance Motors Limited
303 Alexandra Road
Sime Darby Performance Centre
Singapore 119551

Witnessed by Reporting Centre Personnel

14 NOV 2017



Sketch Plan Pg. 2

Describe Circumstances of the Accident

- Driving from River valley Road towards Killiney road.
- After traffic turns green for turning right to Killiney road, I drove to Killiney road.
- Almost approaching St. Thomas Walk saw a car waiting for the traffic to clear to driver ~~exit~~ out from St. Thomas Walk.
- I kept driving and suddenly the car ~~crashed~~ drove out and crashed my left side.

Declaration

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date & Time

14 NOV 2017

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

14 NOV 2017

MEYINA CHIA SAN SAN
Performance Motors Limited
303 Alexandra Road
Sime Darby Performance Centre
Singapore 159341

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559M GST Reg. No. M2-0020081-X

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel: 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax: 64747770

280, Raffles Avenue
East Coast Centre
Singapore 438180
Tel: 63188888 (AfterSales)
Fax: 63485773

318, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel: 63190328 (AfterSales)
63190333/330 (Motorrad)
Fax: 64796821 (AfterSales)
64796824 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Car-in

24 NOV 2017

Estimate No. : b1 44841
Date Estimated : 14/11/2017
Prepared By : Merina Chia San San

Page No. : 1 of 4

- ESTIMATE REPAIR FOR -
Ribkah Handajani Ongkowidjaja
25 Hume Avenue
#03-02

Singapore 598730

- ACCOUNT - 238
AXA Insurance Pte Ltd
8 Shenton Way
#24-01 AXA Tower
Singapore 068811

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKM8208S	G864252	28/04/2017	520D	0

DESCRIPTION

To replace front LH door, rear LH door, LH side skirting, rear LH fender including attachment etc and to knock out dented area caused by accident

Painting on front LH door, rear LH door, rear rocker panel, rear LH fender, left side skirting and left roof frame

To transfer lock mechanism from old to new doors including conduct checks on new door power window system for proper functions. (2 doors).

To remove and install rear hat-tray, rear seat, carpet and roof top lining to facilitate repairs.

To remove and install boot compartment carpet and garnish to facilitate repairs.

To remove and install rear seats and carpets to facilitate repairs.

To conduct checks on all doors and bootlid central locking system for proper function.

To remove and install rear suspension, rear axle and control system for inspection and replace of damaged parts.

To replace tyre and wheel rim including balancing. (1x).

Michelin Primacy 3 RFT 245/45/R18

To carry out body cavity preservation.
(For cut panel).

To carry out body cavity preservation.
(Per panel). 2x

VALUE

✓ 7650 . 8,925.00

✓ 4482 . 4,980.00

✓ 902 . 1,062.00

✓ 742 . 873.00

✓ 230 . 271.00

X 742 . 870.00

✓ 150 . 177.00

m X 1128? . 2,655.00

✓ 80 . 94.00

m X 512.50

✓ 451 . 531.00

✓ 200 . 236.00

fender
doors

Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401559M GST Reg. No M2-0020081-X



103, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel: 63180100 (Sales & Admin)
63180111 (AfterSales)
Fax: 64747770

280, Kampong Arkang Road
East Coast Centre
Singapore 416187
Tel: 63180888 (AfterSales)
Fax: 63449773

313, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel: 63180108 (AfterSales)
63180133 (Motorrad)
64796021 (AfterSales)
64796024 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 44841
Date Estimated : 14/11/2017
Prepared By : Merina Chia San San

Page No. : 2 of 4

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKM8208S	G864252	28/04/2017	520D	0

DESCRIPTION

To check steering geometry and conduct wheel alignment in accordance with BMW specifications. (1X).

VALUE

451 531.00

To replace rear windscreen glass including conduct water leak tests.

649.00

To supply and install front or rear windscreen solar film.

531.00

To replace rear door fixed side window including conduct water leak tests.

413.00

To supply and install rear left or right window glass solar film.

425.00

To remove and install fuse box at the rear section to facilitate repairs.

451? 531.00

To reconnect electrical components and wirings at the rear section including conduct checks for proper function.

300 354.00

To remove and install wire harness, control units and battery at the rear section to facilitate panel replacement.

451? 531.00

Sundries

150.00

Total Labour 1: 25,301.50

DESCRIPTION

QTY PRIC

VALUE

PLASTIC NUT FOR COARSE THREADED PIN ?

6 0.80

4.80

SET WHEEL BEARING ?

1 577.50

577.50

REAR LH WHEEL CARRIER ?

1 1,273.15

1,273.15

TRAILING ARM W/RUBBER MOUNT ?

1 205.00

205.00

LH TOE ARM W/RUBBER MOUNT ?

1 250.55

250.55

LH GUIDE ARM ?

1 512.50

512.50

LH WISHBONE W/RUBBER MOUNT ?

1 599.40

599.40

CAMBER LINK

1 553.50

553.50

REAR GUIDE SUPPORT ?

1 131.80

131.80

REAR SPRING STRUT ?

1 511.75

511.75

SPRING PAD UPPER ?

1 16.20

16.20

SPRING PAD LOWER ?

1 16.40

16.40

LIGHT ALLOY RIM 8JX18 W SPK 632 cut

1 938.30

938.30

HUB CAP WITH CHROME EDGE

1 34.90

34.90

FRT LH DOOR ALUMINIUM

1 1,773.45

1,773.45

REAR LH DOOR ALUMINIUM

1 1,773.45

1,773.45

Wheel-house

1 386.70

386.70

Reinforcement entrance LH ?

1 468.50

468.50

C-pillar sup ?

1 136.10

136.10

Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197402339W GST Reg. No. M2-0020081-X



103, Alexandra Road
Sime Darby Performance Centre
Singapore 119941
Tel: 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax: 64747770

180, Kampong Arang Road
East Coast Centre
Singapore 418180
Tel: 63190888 (AfterSales)
Fax: 63449771

115, Alexandra Road
Sime Darby Business Centre
Singapore 119944
Tel: 63190028 (AfterSales)
63190033/330 (Motorrad)
64796001 (AfterSales)
64796024 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 44841
Date Estimated : 14/11/2017
Prepared By : Merina Chia San San

Page No. : 3 of 4

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKM8208S	G864252	28/04/2017	520D	0

DESCRIPTION	QTY	PRIC	VALUE
REAR LH SIDE PANEL <i>bt</i>	1	1,796.10	1,796.10
Reinforcemen, C-pillar LH ?	1	48.00	48.00
Reinforcement sill LH ?	1	48.00	48.00
Side member, ?	1	867.35	867.35
Door hinge, ?	1	55.75	55.75
Door hinge, ?	1	55.75	55.75
PLASTIC NUT	4	0.85	3.40
FRT LH SYSTEM LOCK (SCA/ZS) ?	1	679.70	679.70
Adapter for ?	1	15.50	15.50
STRIKER WITH PAD ?	1	21.20	21.20
STRIKER WITH PAD ?	1	21.20	21.20
Carrier, out ?	1	162.65	162.65
Carrier, out ?	1	162.65	162.65
Door handle, ?	1	571.65	571.65
Door handle, ?	1	571.65	571.65
SYSTEM LOCK REAR LH (SCA/ZS) ?	1	679.70	679.70
REAR DOOR BRAKE ?	2	85.55	171.10
BUMP STOP ?	10	3.25	32.50
REAR WINDOW GREEN (ESG)	1	818.95	818.95 <i>nc</i>
FRT LH DOOR WINDOW FRAME COVER (ALU) ?	1	142.30	142.30
FRT LH DOOR OUTER SHAFT COVER (ALU) ?	1	97.10	97.10
Channel seal <i>nei</i>	1	82.55	82.55
FRT LH DOOR WINDOW GUIDE ?	1	110.80	110.80
Cover, windo	1	71.50	71.50
FRT LH DOOR COLUMN B COVER (GLANZSCH ?	1	135.50	135.50
RR LH DOOR SIDE WINDOW FIXED GREEN ?	1	414.85	414.85
Window well ?	1	61.90	61.90
Seal, end pa ?	1	19.90	19.90
RR LH DOOR WINDOW FRAME TOP FINISHE ?	1	233.30	233.30
RR LH DOOR OUTER CHANNEL COVER (ALU) ?	1	118.35	118.35
REAR LH WINDOW FRAME COVER ?	1	40.95	40.95
REAR LH WINDOW FRAME COVER ?	1	40.95	40.95
RR LH DOOR COLUMN B COVER (GLANZSCH ?	1	49.10	49.10
LH WINDOW GUIDE WEB COVER (GLANZSCH ?	1	98.25	98.25
REAR LH TRIM ENTRANCE ILLUMINATED (?	1	178.55	178.55
Cover moldin ?	1	27.75	27.75
REAR LH WHEEL HOUSING COVER <i>de</i>	1	125.25	125.25
REAR DOOR EDGE PROTECTION ?	1	199.45	199.45
(S/L) DOOR WEATHERSTRIP <i>nei</i>	1	163.15	163.15
(S/L) DOOR WEATHERSTRIP FRT <i>nei</i>	1	163.15	163.15
LH SUPPORTING LEDGE end	1	18.60	18.60
LH SILL TRIM PRIMED <i>de</i>	1	403.00	403.00
CAVITY PROTECTION WAX REMOVER 500ML <i>nei</i>	1	18.45	18.45
BLIND RIVET AVIBVLB <i>nei</i> (30 PCS)	15	0.55	8.25
SCREW (SF PLUS M5X15) <i>nei</i> (10 PCS)	5	0.55	2.75
(DG/SL) BODY ADHESIVE K5B (195ML) <i>nei</i>	1	281.55	281.55
PUNCH RIVET N4 <i>nei</i>	40	0.55	22.00
(DG) BODYWORK ADHESIVE K5A (50ML) <i>nei</i>	1	118.35	118.35
(DG) CLEANER R1 (100ML) <i>nei</i>	1	23.85	23.85



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159841
Tel: 63300000 (Sales & Admin)
63300111 (AfterSales)
Fax: 64747770

387, Tampong Arang Road
East Coast Centre
Singapore 436195
Tel: 63190888 (AfterSales)
Fax: 63449771

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel: 63190028 (AfterSales)
63190033/330 (Motorrad)
Fax: 64796621 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 44841
Date Estimated : 14/11/2017
Prepared By : Merina Chia San San

Page No. : 4 of 4

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKM8208S	G864252	28/04/2017	520D	0

DESCRIPTION

DESCRIPTION	QTY	PRIC	VALUE
(DG) CLEANER R1 (100ML) <i>he</i>	1	23.85	23.85
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR) <i>nee</i>	2	131.55	263.10
(DG/SL) GLASS PRIMER 30ML (VP206) <i>nee</i>	1	27.85	27.85
(S/L) SEAM SEAL 300ML <i>nee</i>	1	33.80	33.80

Total Parts : 20,766.75

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Vehicle ID / VIN: *0* / *U*
 Regn No. *27/11/12 C1745*
 Date & Time *27/11/17 17:45*
 Surveyor's Name *Tan Jiah*
 Surveyor's Tel *97498449*
 Authorized Date *-WP-*
 RESURVEY PARTS PHOTO BY SURVEYOR *0* TO THE Y&S
 Surveyor's E-mail *tanjiah@lkkauto.com*
 No. of Working Days Recommended *14 days*

27/11/17

46,339.19

Labour 1	:	25,301.50
Parts	:	20,766.75
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	3,224.78
Grand Total	:	49,293.03

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **



FINAL REPORT

Estimate No. : b1 44841
 Date Estimated : 14/11/2017
 Prepared By : Merina Chia San San

Page No. :

REPAIR FOR -
 Ribkah Handajani Ongkowidjaja
 25 Hume Avenue
 #03-02

- ACCOUNT - 66
 MSIG Insurance (S) Pte Ltd
 4 Shenton Way
 #21-01 SGX Centre 2
 Singapore 068807

Singapore 598730

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE
SKM8208S	G864252	28/04/2017	520D	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	
To replace front/rear LH doors and attachments, LH side skirting, rear LH fender, rear LH wheel housing cover include making good the LH rocker panel, LH side skirting, LH roof frame and knocking out dents caused by the accident	7650.00		7,650.00	
To spray paint front LH door, rear LH door, LH rocker panel, rear LH fender, LH side skirting and LH roof frame	4482.00		4,482.00	
To transfer lock mechanism from old to new door include conducting checks on new door power window system for proper functions (2x)	902.00		902.00	
To remove and install rear hat-tray, rear seat, carpet and roof top lining to facilitate repairs.	742.00		742.00	
To remove and install boot compartment carpet and garnish to facilitate repairs.	230.00		230.00	
To conduct checks on all doors and boot lid central locking system for proper function	150.00		150.00	
To replace wheel rim include balancing (1x)	80.00		80.00	
To carry out body cavity preservation. (For cut panel).	451.00		451.00	
To carry out body cavity preservation (2x) (Per panel)	200.00		200.00	
To check steering geometry and conduct wheel alignment in accordance with BMW specifications (1x)	451.00		451.00	
To replace rear windscreen glass include conducting water leak tests	649.00		649.00	
To remove and install rear LH door fixed side window glass to facilitate repairs include conducting water leak tests	413.00		413.00	

Performance Motors Limited

A member of the Sims Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



FINAL REPORT

To reconnect electrical components and wirings at the rear section including conduct checks for proper function. (For cut panel)	300.00	300.00
* To remove and install wire harness, control units and battery at the rear section to facilitate panel replacement.	451.00	451.00
Sundries.	150.00	150.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
LIGHT ALLOY RIM 8JX18 W SPK 632	938.30	1.00		938.30
HUB CAP WITH CHROME EDGE	34.90	1.00		34.90
3M S/F PREMIUM REAR WINDSCREEN	252.34	1.00		252.34
FRT LH DOOR ALUMINIUM	1,773.45	1.00		1,773.45
REAR LH DOOR ALUMINIUM	1,773.45	1.00		1,773.45
REAR LH SIDE PANEL	1,796.10	1.00		1,796.10
REAR WINDOW GREEN (ESG)	818.95	1.00		818.95
REAR LH WHEEL HOUSING COVER	125.25	1.00		125.25
(S/L) DOOR WEATHERSTRIP	163.15	2.00		326.30
# LH SUPPORTING LEDGE *	18.60	1.00		18.60
LH SILL TRIM PRIMED	403.00	1.00		403.00
BLIND RIVET AVIBVLB	0.55	20.00		11.00
SCREW (SF PLUS M5X15)	0.55	10.00		5.50
(DG/SL) BODY ADHESIVE K5B (195ML)	281.55	1.00		281.55
PUNCH RIVET N4	0.55	40.00		22.00
(DG) BODYWORK ADHESIVE K5A (50ML)	118.35	1.00		118.35
(DG) CLEANER R1 (100ML)	23.85	1.00		23.85
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	131.55	2.00		263.10
(DG/SL) GLASS PRIMER 30ML (VP206)	27.85	1.00		27.85
(S/L) SEAM SEAL 300ML	33.80	1.00		33.80

ALL ✓

(A) NEW ✓

SUPPLEMENTARY ITEMS

Total Labour :	17,301.00
Total Parts :	9,047.64
Total Labour & Parts :	26,348.64
Deduction for Excess :	0.00
Total Repair Costs less Excess:	26,348.64
GST @7%:	1,844.40
Grand Total :	28,193.04

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



SUPPLEMENTARY

Estimate No. : b1 44841
Date Estimated : 14/11/2017
Prepared By : Merina Chia San San

Page No. :

REPAIR FOR -
Ribkah Handajani Ongkowidjaja
25 Hume Avenue
#03-02

- ACCOUNT - 66
MSIG Insurance (S) Pte Ltd
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

Singapore 598730

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE
SKM8208S	G864252	28/04/2017	520D	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
-------------	----------------	---------	------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# LH SUPPORTING LEDGE *	18.60	1.00		18.60

Total Labour :	0.00
Total Parts :	18.60
Total Labour & Parts :	18.60

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Friday, 13 April 2018 8:27 AM
To: Taufikh (LKKAuto); 'PBSP'
Cc: SUR
Subject: RE: FINAL REPORT / SKM82085

Dear Caroline,

Please ignore the below email.

Confirmed Total Labour & Parts : \$26,348.64 before GST

Repair days: 10 days

Final invoice and all supporting documents sent over to MSIG.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAuto)
Sent: Friday, 13 April 2018 8:26 AM
To: Taufikh (LKKAuto) <Taufikh@lkkauto.com>; 'PBSP' <pml-pbsp@simedarby.com.sg>
Cc: SUR <sur@lkkauto.com>
Subject: RE: FINAL REPORT / SKM82085

Dear Caroline,

Confirmed Total Labour & Parts : \$26,348.64 before GST

Repair days: 10 days

Final invoice and all supporting documents sent over to First Capital Ins Ltd.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Taufikh (LKKAuto)
Sent: Tuesday, 30 January 2018 5:34 PM
To: 'PBSP' <pml-pbsp@simedarby.com.sg>
Cc: Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Subject: RE: FINAL REPORT / SKM8208S

Hi Caroline,

Can forward the before paint photos?

Thank you.

Regards
Taufikh
Lkk Auto

From: PBSP [<mailto:pml-pbsp@simedarby.com.sg>]
Sent: Monday, 29 January 2018 4:07 PM
To: taufikh@lkkauto.com; SUR
Subject: Re: FINAL REPORT / SKM8208S

Gentle reminder

From: PBSP
Sent: Thursday, 18 January 2018 10:22:27 AM
To: taufikh@lkkauto.com; SUR
Subject: FINAL REPORT / SKM8208S

Dear Taufikh

We refer to the above and attached Final Report.

Please confirm COR as follows:

Total Labour : 17,301.00
Total Parts : 9,047.64
Total Labour & Parts : 26,348.64

Repair days: 10

Thank you.

Regards,
Caroline
C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	14 Nov 2017		27 Nov 2017 11:38 Edit Adj Rpt	S\$26,348.64 Edit Estimates	S\$26,348.64 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by Insurer]									
Insured:	PREMIER RENT A CAR PTE LTD , Co. Reg. No.: 200612929E								
Main Claimant:	RIBKAH HANAJANI ONGKOWIDJAJA , ID: S2649347A								
Vehicle Reg. No.:	SKM8208S	Date of Loss:	13/11/2017 19:00 - :59 [6 Months and 16 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 536671	Policy/Cover Note No.:	B28946874MCX (TP, Fire & Theft) Coverage: 01/05/2017 - 30/04/2018						
Vehicle Reg. No. (Insured):	SLA8720E	Policy No. (Claimant):							
		Excess:	S\$750.00						
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Elaine Ngu Siau Mei - 6594 2540]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 27/12/2017]								
Driver/Custodian (Insured):	ATKINSON PAUL RAYMOND (), NRIC: G3246161T								
Adj Asg. Remarks:	CAR ALREADY IN. PLS CONTACT CAROLINE FOR SURVEY@63190174								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SKM8208S (536671)**
[SLA8720E]
TP
RIBKAH HANDAJANI ONGKOWIDJAJA
Nov 13 2017 7:00PM
[PREMIER RENT A CAR PTE LTD]
Performance Motors Limited

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	27/11/17 10:27	Accident Statement From: SC - Reg. No: SLA8720E, Claimant: PREMIER RENT A CAR PTE LTD	 Load HTML	☐
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	28/11/17 12:27	Adjuster Immediate Advice	 Load HTML	☐
Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	28/11/17 12:02	General View	 Load JPG	☒
2	28/11/17 12:02	General View	 Load JPG	☒
3	28/11/17 12:02	General View	 Load JPG	☒
4	28/11/17 12:02	General View	 Load JPG	☒
5	28/11/17 12:02	General View	 Load JPG	☒
6	28/11/17 12:02	General View	 Load JPG	☒
7	28/11/17 12:02	General View	 Load JPG	☒
8	28/11/17 12:02	General View	 Load JPG	☒
9	28/11/17 12:02	General View	 Load JPG	☒
10	28/11/17 12:02	General View	 Load JPG	☒
11	28/11/17 12:02	General View	 Load JPG	☒
12	28/11/17 12:02	General View	 Load JPG	☒
13	28/11/17 12:02	General View	 Load JPG	☒
14	28/11/17 12:02	General View	 Load JPG	☒
15	28/11/17 12:02	General View	 Load JPG	☒
16	28/11/17 12:02	General View	 Load JPG	☒
17	28/11/17 12:02	General View	 Load JPG	☒
18	28/11/17 12:02	General View	 Load JPG	☒
19	28/11/17 12:02	General View	 Load JPG	☒
20	28/11/17 12:02	General View	 Load JPG	☒
21	28/11/17 12:02	General View	 Load JPG	☒
22	28/11/17 12:02	General View	 Load JPG	☒
23	28/11/17 12:02	General View	 Load JPG	☒
24	28/11/17 12:02	General View	 Load JPG	☒
25	28/11/17 12:02	General View	 Load JPG	☒
26	28/11/17 12:02	General View	 Load JPG	☒
27	28/11/17 12:02	General View	 Load JPG	☒
28	28/11/17 12:02	General View	 Load JPG	☒
29	28/11/17 12:02	General View	 Load JPG	☒
30	28/11/17 12:02	General View	 Load JPG	☒
31	28/11/17 12:02	General View	 Load JPG	☒
32	28/11/17 12:02	General View	 Load JPG	☐

Assessment Reports				1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
			1		☒
33	28/11/17 12:02	General View	1	Load JPG	☒
34	28/11/17 12:02	General View	1	Load JPG	☒
35	28/11/17 12:02	General View	1	Load JPG	☒
36	28/11/17 12:02	General View	1	Load JPG	☒
37	28/11/17 12:02	General View	1	Load JPG	☒
38	28/11/17 12:02	General View	1	Load JPG	☒
39	28/11/17 12:02	General View	1	Load JPG	☒
40	28/11/17 12:02	General View	1	Load JPG	☒
41	28/11/17 12:02	General View	1	Load JPG	☒
42	28/11/17 12:02	General View	1	Load JPG	☒
43	28/11/17 12:02	General View	1	Load JPG	☒
44	03/04/18 09:21	Reinspection Photo	1	Load JPG	☒
45	03/04/18 09:21	Reinspection Photo	1	Load JPG	☒
46	03/04/18 09:21	Reinspection Photo	1	Load JPG	☒
47	03/04/18 09:21	Reinspection Photo	1	Load JPG	☒
48	03/04/18 09:21	Reinspection Photo	1	Load JPG	☒
49	03/04/18 09:21	Reinspection Photo	1	Load JPG	☒
50	03/04/18 09:21	Reinspection Photo	1	Load JPG	☒
Documentation				1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	27/11/17 10:26	TPD SKM8208S GIA REPORT.	1	Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	19/04/18 13:35	SUPPLEMENTARY PART	1	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG17022535/T1VBQ2

Date: 19/04/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: B28946874MCX

Claimant Vehicle No: SKM8208S

Insured Vehicle No: SLA8720E

Date of Loss: 13/11/2017

Nature of Claim: TP

Claim No: 536671

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKM8208S

Make & Model: BMW 520i, 2.0 AT D/AB 2WD 4DR LED NAV (A)

Engine No: 74749883B47D20A

Reg. Date: 28/04/2017 (Man. Year: 2017)

Chassis No: WBAJC32070G864252

Colour: Silver

Odometer: 15268 km

Engine Capacity: 1995 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/45 R18

Rear Tyre Size: 245/45 R18

Front Left Side: Michelin 6 mm

Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	21,705.69	9,197.64	12,508.05	57.63
Miscellaneous Items	0.00	0.00	0.00	
Labour	24,639.00	17,151.00	7,488.00	30.39
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	46,344.69	26,348.64	19,996.05	43.15
+ GST 7.00/7.00% (S\$)	3,244.13	1,844.40	1,399.73	43.15
Nett Amount (S\$)	49,588.82	28,193.04	21,395.78	43.15

INSPECTION

Date of Assignment: 27/11/2017

Date Inspected: 27/11/2017 Inspected At:

Performance Motors Limited (Alexandra)
303 Alexandra Road, Sime Darby
Performance Centre
Singapore 159941

Estimated Period of Repair: 10.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 19 Apr 2018)
Parts:	143	BMW 520i 2.0 AT D/AB 2WD 4DR LED NAV (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKM8208S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*MICHELIN PRIMACY 3 RFT 245/45/R18	Not Necessary	512.50 FS	*- FS
2	1		*SUNDRIES	Necessary	150.00 FS	*150.00 FS
3	6		*PLASTIC NUT FOR COARSE THREADED PIN	Not Necessary	4.80 FS	*- FS
4	1		*SET WHEEL BEARING	Not Necessary	577.50 FS	*- FS
5	1		*REAR LH WHEEL CARRIER	Not Necessary	1,273.15 FS	*- FS
6	1		*TRAILING ARM W/RUBBER MOUNT	Not Necessary	205.00 FS	*- FS
7	1		*LH TOE ARM W/RUBBER MOUNT	Not Necessary	250.55 FS	*- FS
8	1		*LH GUIDE ARM	Not Necessary	512.50 FS	*- FS
9	1		*LH WISHBONE W/RUBBER MOUNT	Not Necessary	599.40 FS	*- FS
10	1		*CAMBER LINK	Not Necessary	553.50 FS	*- FS
11	1		*REAR GUIDE SUPPORT	Not Necessary	131.80 FS	*- FS
12	1		*REAR SPRING STRUT	Not Necessary	511.75 FS	*- FS
13	1		*SPRING PAD UPPER	Not Necessary	16.20 FS	*- FS
14	1		*SPRING PAD LOWER	Not Necessary	16.40 FS	*- FS
15	1		*LIGHT ALLOY RIM 8JX18 W SPK 632	Cut	938.30 FS	*938.30 FS
16	1		*HUB CAP WITH CHROME EDGE	Necessary	34.90 FS	*34.90 FS
17	1		*FRT LH DOOR ALUMINIUM	Bent	1,773.45 FS	*1,773.45 FS
18	1		*REAR LH DOOR ALUMINIUM	Bent	1,773.45 FS	*1,773.45 FS
19	1		*WHEEL-HOUSE	Not Necessary	386.70 FS	*- FS
20	1		*REINFORCEMENT ENTRANCE LH	Not Necessary	468.50 FS	*- FS
21	1		*C-PILLAR SUP	Not Necessary	136.10 FS	*- FS
22	1		*REAR LH SIDE PANEL	Bent	1,796.10 FS	*1,796.10 FS
23	1		*REINFORCEMENT,C-PILLAR LH	Not Necessary	48.00 FS	*- FS
24	1		*REINFORCEMENT SILL LH	Not Necessary	48.00 FS	*- FS
25	1		*SIDE MEMBER	Not Necessary	867.35 FS	*- FS
26	1		*DOOR HINGE	Not Necessary	55.75 FS	*- FS
27	1		*DOOR HINGE	Not Necessary	55.75 FS	*- FS
28	4		*PLASTIC NUT	Not Necessary	3.40 FS	*- FS
29	1		*FRT LH SYSTEM LOCK (SCA/ZS)	Not Necessary	679.70 FS	*- FS
30	1		*ADAPTER FOR	Not Necessary	15.50 FS	*- FS
31	1		*STRIKER WITH PAD	Not Necessary	21.20 FS	*- FS
32	1		*STRIKER WITH PAD	Not Necessary	21.20 FS	*- FS
33	1		*CARRIER ,OUT	Not Necessary	162.65 FS	*- FS
34	1		*CARRIER ,OUT	Not Necessary	162.65 FS	*- FS
35	1		*DOOR HANDLE	Not Necessary	571.65 FS	*- FS
36	1		*DOOR HANDLE	Not Necessary	571.65 FS	*- FS
37	1		*SYSTEM LOCK REAR LH (SCA/ZS)	Not Necessary	679.70 FS	*- FS
38	2		*REAR DOOR BRAKE	Not Necessary	171.10 FS	*- FS
39	10		*BUMP STOP	Not Necessary	32.50 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1		*REAR WINDOW GREEN (ESG)	Necessary	818.95 FS	*818.95 FS
41	1		*FRT LH DOOR WINDOW FRAME COVER (ALU)	Not Necessary	142.30 FS	*- FS
42	1		*FRT LH DOOR OUTER SHAFT COVER (ALU)	Not Necessary	97.10 FS	*- FS
43	1		*CHANNEL SEAL	Not Necessary	82.55 FS	*- FS
44	1		*FRT LH DOOR WINDOW GUIDE	Not Necessary	110.80 FS	*- FS
45	1		*COVER ,WINDO	Not Necessary	71.50 FS	*- FS
46	1		*FRT LH DOOR COLUMN B COVER (GLANZSC)	Not Necessary	135.50 FS	*- FS
47	1		*RR LH DOOR SIDE WINDOW FIXED GREEN	Not Necessary	414.85 FS	*- FS
48	1		*WINDOW WELL	Not Necessary	61.90 FS	*- FS
49	1		*SEAL ,END PA	Not Necessary	19.90 FS	*- FS
50	1		*RR LH DOOR WINDOW FRAME TOP FINISHE	Not Necessary	233.30 FS	*- FS
51	1		*RR LH DOOR OUTER CHANNEL COVER (ALU)	Not Necessary	118.35 FS	*- FS
52	1		*REAR LH WINDOW FRAME COVER	Not Necessary	40.95 FS	*- FS
53	1		*REAR LH WINDOW FRAME COVER	Not Necessary	40.95 FS	*- FS
54	1		*RR LH DOOR COLUMN B COVER (GLANZSCH)	Not Necessary	49.10 FS	*- FS
55	1		*LH WINDOW GUIDE WEB COVER (GLANZSCH)	Not Necessary	98.25 FS	*- FS
56	1		*REAR LH TRIM ENTRANCE ILLUMINATED	Not Necessary	178.55 FS	*- FS
57	1		*COVER MOLDIN	Not Necessary	27.75 FS	*- FS
58	1		*REAR LH WHEEL HOUSING COVER	Deformed	125.25 FS	*125.25 FS
59	1		*REAR DOOR EDGE PROTECTION	Not Necessary	199.45 FS	*- FS
60	1		*(S/L) DOOR WEATHERSTRIP	Necessary	163.15 FS	*163.15 FS
61	1		*(S/L) DOOR WEATHERSTRIP FRT	Necessary	163.15 FS	*163.15 FS
62	1		*LH SUPPORTING LEDGE END	Not Necessary	18.60 FS	*- FS
63	1		*LH SILL TRIM PRIMED	Deformed	403.00 FS	*403.00 FS
64	1		*CAVITY PROTECTION WAX REMOVER 500ML	Not Necessary	18.45 FS	*- FS
65	20		*BLIND RIVET AVIBVLB	Necessary	11.00 FS	*11.00 FS
66	10		*SCREW (SF PLUS M5X15)	Necessary	5.50 FS	*5.50 FS
67	1		*(DG/SL) BODY ADHESIVE K5B (195ML)	Necessary	281.55 FS	*281.55 FS
68	1		*PUNCH RIVET N4 (40PCS)	Necessary	22.00 FS	*22.00 FS
69	1		*(DG) BODYWORK ADHESIVE K5A (50ML)	Necessary	118.35 FS	*118.35 FS
70	1		*(DG) CLEANER R1 (100ML)	Necessary	23.85 FS	*23.85 FS
71	1		*(DG) CLEANER R1 (100ML)	Not Necessary	23.85 FS	*- FS
72	2		*(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	Necessary	263.10 FS	*263.10 FS
73	1		*(DG/SL) GLASS PRIMER 30ML (VP206)	Necessary	27.85 FS	*27.85 FS
74	1		*(S/L) SEAM SEAL 300ML	Necessary	33.80 FS	*33.80 FS
75	1		*3M S/F PREMIUM REAR WINDSCREEN	Necessary	252.34 FS	*252.34 FS
76	1		*LH SUPPORTING LEDGE	Necessary	18.60 FS	*18.60 FS

F=Franchise part, S=SpcNet.

Total Parts (\$\$)	21,705.69	9,197.64
--------------------	-----------	----------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE FRONT LH DOOR ,REAR LH DOOR ,LH SIDE SKIRTING ,REAR LH FENDER INCLUDING ATTACHMENT ETC AND TO KNOCK OUT DENTED AREA CAUSED BY ACCIDENT	New	8,925.00	7,650.00
2	PAINTING ON FRONT LH DOOR ,REAR LH DOOR ,REAR ROCKER PANEL,REAR LH FENDER ,LEFT SIDE SKIRTING AND LEFT ROOF FRAME	New	4,980.00	4,482.00
3	TO TRANSFER LOCK MECHANISM FROM OLD TO NEW DOORS INCLUDING CONDUCT CHECKS ON NEW DOOR POWER WINDOW SYSTEM FOR PROPER FUNCTIONS	New	1,062.00	902.00
4	TO REMOVE AND INSTALL REAR HAT-TRAY ,REAR SEAT ,CARPET AND ROOF TOP LINING TO FACILITATE REPAIRS	New	873.00	742.00
5	TO REMOVE AND INSTALL BOOT COMPARTMENT CARPET AND GARNISH TO FACILITATE REPAIRS	New	271.00	230.00
6	TO REMOVE AND INSTALL REAR SEATS AND CARPETS TO FACILITATE REPAIRS	New	870.00	0.00
7	TO CONDUCT CHECKS ON ALL DOORS AND BOOTLID CENTRAL LOCKING SYSTEM FOR PROPER FUNCTION	New	177.00	150.00
8	TO REMOVE AND INSTALL REAR SUSPENSION ,REAR AXLE AND CONTROL SYSTEM FOR INSPECTION AND REPLACE OF DAMAGED PARTS	New	2,655.00	0.00
9	TO REPLACE TYRE AND WHEEL RIM INCLUDING BALANCING	New	94.00	80.00
10	TO CARRY OUT BODY CAVITY PRESERVATION (FOR CUT PANEL)	New	531.00	451.00
11	TO CARRY OUT BODY CAVITY PRESERVATION (PER PANEL)	New	236.00	200.00
12	TO CHECK STEERING GEOMETRY AND CONDUCT WHEEL ALIGNMENT IN ACCORDANCE WITH BMW SPECIFICATIONS	New	531.00	451.00
13	TO REPLACE REAR WINDSCREEN GLASS INCLUDING CONDUCT WATER LEAK TESTS	New	649.00	649.00
14	TO SUPPLY AND INSTALL FRONT OR REAR WINDSCREEN SOLAR FILM	New	531.00	0.00
15	TO REPLACE REAR DOOR FIXED SIDE WINDOW INCLUDING CONDUCT WATER LEAK TESTS	New	413.00	413.00
16	TO SUPPLY AND INSTALL REAR LEFT OR RIGHT WINDOW GLASS SOLAR FILM	New	425.00	0.00
17	TO REMOVE AND INSTALL FUSE BOX AT THE REAR SECTION TO FACILITATE REPAIRS	New	531.00	0.00
18	TO RECONNECT ELECTRICAL COMPONENTS AND WIRINGS AT THE REAR SECTION INCLUDING CONDUCT CHECKS FOR PROPER FUNCTION	New	354.00	300.00
19	TO REMOVE AND INSTALL WIRE HARNESS ,CONTROL UNITS AND BATTERY AT THE REAR SECTION TO FACILITATE PANEL REPLACEMENT	New	531.00	451.00
Gross Labour Cost (\$\$)			24,639.00	17,151.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >