




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
INSIGHT ADJUSTERS AND SURVEYORS PL		Ref : CS/IAS17022538/Avbs2		
c/o INSIGHT ADJUSTERS & SURVEYORS PL 133 CECIL STREET #14-02 KECK SENG TOWER SINGAPORE 069535		Date : 20-04-2018		
		Code : IAS		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	PUBLIC LIABILITY	Veh. Inspected	SJH 68U	
Policy No.		Coverage (\$)	0.00	
Claim No.	IA2017-36578	Excess (\$)	0.00	
Assign From	KENNETH NEO	Assign Date	27/11/2017	
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES BENZ E250	c.c	2143	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	WDD2120032A790128	Colour	BLACK	
Odometer	147352	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	245/40R18	FALKEN	6 mm	
L/H Front Tyre	245/40R18	FALKEN	6 mm	
R/H Rear Tyre	245/40R18	FALKEN	6 mm	
L/H Rear Tyre	245/40R18	FALKEN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	12/11/2017	Inspection Date	27/11/2017	
Survey held at	CRUISE AUTOCARE PL 53 UBI AVE 1 PAYA UBI IND. PARK #03-53 SINGAPORE 408934			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		