

Ke

# AUTOWORX HOUSE

176 SIN MING DRIVE #02-01 SINGAPORE 575721  
TEL: 6452 8211 FAX: 6451 7420

## ESTIMATE

**YONG KIAT MIN**  
c/o 46 Lentor Plain  
Singapore 786548

*Not Authorized*  
*11/12 @ 4200h*  
*Running After Party*  
*6 days* Date: 14/12/2017

QUANTITY	PARTICULARS	AMOUNT (\$)
<b>RE : TOYOTA COROLLA ALTIS / SLD7604Z</b>		
1 pc	rear bumper <i>495.00</i>	<i>Bj</i> 564.10 ✓
1 pc	rear bumper reinforcement <i>336.95</i>	<i>Bj</i> 365.40 ✓
2 pcs	rear bumper reflector @ 173.20	<i>Sm</i> 346.40 X
2 pcs	rear bumper side retainer @ 63.40	<i>Admir</i> 126.80 ✓
2 pcs	rear bumper reinforcement bracket @ 147.10	<i>nd</i> 294.20 ✓
2 pcs	rear bumper corner retainer @ 61.40	<i>Sm</i> 122.80 X
1 pc	rear boot lid	<i>Bj</i> 765.20 ✓
1 pc	rear boot lock	<i>nd</i> 164.40 ✓
1 pc	rear boot lock catch	<i>R</i> 73.20 X
1 pc	rear boot lamp	<i>Sm</i> 357.10 X
1 pc	rear boot weathership <i>168.20</i>	<i>nd/Dis</i> 279.60 ✓
1 pc	rear boot emblem	<i>nd</i> 74.10 ✓
1 pc	rear boot emblem "COROLLA"	<i>nd</i> 64.30 ✓
1 pc	rear boot emblem "ALTIS"	<i>nd</i> 65.70 ✓
1 pc	rear end panel	<i>Bj</i> 571.40 ✓
1 pc	rear end panel garnish <i>240.90</i>	<i>nd/Dis</i> 331.90 ✓
2 pcs	reverse sensor @ 346.40	<i>shot</i> 692.80 <i>2000h</i>
1 pc	rear lock sensor receiver	<i>Sm</i> 275.00 X
2 pcs	rear tail lamp <i>480.45</i>	<i>nd/Dis</i> @ 564.70 1,129.40 ✓
1 pc	rear spare tyre panel top board <i>289.20</i>	<i>nd/Dis</i> 356.10 ✓
1 pc	rear exhaust silencer	<i>R</i> 974.80 X
	sub-total	7,994.70
	less 25%	1,998.68
	sub-total	5,996.03

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

	balance brought forward.	5,996.03	
	To remove and replace the parts mentioned above, above, panel beat and realign the necessary affected areas.	1,000.00	700
	To check wiring system.	50.00	200
	To apply putty and spray painting on affected areas.	750.00	700
	To install reverse sensor & reverse camera.	120.00	500
	To apply rust proofing on affected areas.	200.00	600
	To apply water proof sealant on affected areas.	200.00	300
	To carry out exhaust works.	120.00	600
	<b>Total</b>	<b>8,436.03</b>	