

22/03/2002

ASS. REC. BY:

REF: CS/MSG17022544/T1gb02

Special Instruction:

Survivor: Taufik

ASSIGNMENT (Office)

From (Person): Monica chun of MSIG Date/Time: 27/11/17 @ 8:38am

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLG 8565E Insured: SCY 9108 Y

at Workshop m/s Ding Auto Tel: 92894128

of 249 Jalan Boon Lay, 619523

Policy No: 028808600Q MX Claim No: 538248

Sum Insured: Excess:

Make of Veh: D.O.A. 23/11/2017
(Client's Record)

CA / REV / REP. / REV 24 HRS 'wp'

H.O.D. Endorsement:

Date/Time: 11:24am @ 27/11/17 Person Contacted: Michelle Vehicle: IN OUT

Date/Time	Action/Instruction (✓) Estimate
	SLG 8565E - X
	SCY 9108Y - CS3/MSG17015148/Jbs2-D.O.A.: 09/07/2017

Surveyor: Tan Jiah

REF:

MS16

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD (TP) WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

6

days

Res.: Yes or No

Lum Sum: _____

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

WP

Vehicle: IN / OUT

Date: _____

Person Contacted: _____

Veh No: _____

SLG 8565 E

Yr Regn: _____

2016 Oct.

Type: ☒ Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make: _____

Toyota A115

C.C.

1398

Colour _____

81/10

A/C:

Insured / Std / NI / NA

Sp. Reading _____

72571

T/Radio:

Insured / Std / NI / NA

Eng/No: _____

C/No: _____

MROS3KEH104338828

Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ Burnt

Steering: ☒ Inorder / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Brake: ☒ Inorder / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Modi: ☒ Nil / ☐ S/Rim / ☐ STD A/Rim or

Tyre Size: _____

F:

205/55R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO YOKO or

Front

Rear

R/Bal. _____

6

mm

R/Bal. _____

6

mm

L/Bal. _____

6

mm

L/Bal. _____

6

mm

D.O.A. _____

D.O.I.

27/11/17 0420

Survey held at _____

Ding Auto

Bon Lay.

Des. of Damages: ☐ Frt / ☐ Rear / ☐ O/S ☒ N/S ☐ U/C / ☐ Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

28/11/17

REV preli in merman.

6/12/17

confirmed 4s \$3900 with Jing Peng.

(Red - 7656.64, 66%).

RECEIVED 9 DEC 2017

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 6

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

) \$ + RS \$

) Photos:

) Others:

Report Format: TP

Lump Sum / I.B.I: (\$ 3900)

TOTAL

200

10

210



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MSG INSURANCE (SINGAPORE) PTE LTD		Ref : CS/MSG17022544/T1gb	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 27-11-2017	
		Code : MSG	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SCY 9108Y	Veh. Inspected	SLG 8565E
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	MERIMEN (MONICA CHUNG)	Assign Date	27/11/2017
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	23/11/2017	Inspection Date	27/11/2017
Survey held at	DING AUTO PTE LTD BLK 10 #01-20 SIN MING IND EST SEC C SINGAPORE 575645		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	24 Nov 2017 10:15 Sendback Est	24 Nov 2017 10:33 S\$9,903.40	27 Nov 2017 08:38 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	WONG NGIAP HUA , ID: S0054880D		
Main Claimant:	LCRF PTE LTD , Co. Reg. No.: 201624597K		
Vehicle Reg. No.:	SLG8565E	Date of Loss:	23/11/2017 12:00 - :59
Claim Type:	TP	Policy/Cover Note No.:	Coverage: 02/01/2017 - 30/12/2017
Vehicle Reg. No. (Insured):	SCY9108Y	Policy No. (Claimant):	999995174
		Excess:	
Repairer:	Ding Auto Pte Ltd (HQ) Blk 10, #01-20, Sin Ming Industrial Estate Sector C, 575645 Sin Ming - Tel: 64521208		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]		
Claimant's Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 28/11/2017]		
Adj Asg. Remarks:	ON WP, Car in at 249 Jln Boon Lay S619523		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Monica Chung Pei Zhen

Date: 28 Nov 2017

Preliminary Advice

Insured Vehicle No :	SCY9108Y	Accident Date	: 23/11/2017
TP Vehicle No :	SLG8565E	Assignment Date	: 27/11/2017
Make :	TOYOTA COROLLA ALTIS	Est. Duration of Repair	: 6.00
Date of Inspection :	27/11/2017		
Inspection At :	DING AUTO PTE LTD (HQ) BLK 10, #01-20, SIN MING INDUSTRIAL ESTATE SECTOR C SINGAPORE 575645		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	10,596.64
Revised Amount	:S\$	4,878.70
Check Items (Estimated)	:S\$	1,221.70
Total	:S\$	6,100.40

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available afterwards.

ACCIDENT STATEMENT

Date Of Report 23/11/2017 15:00
Date Of Accident 23/11/2017 12:25
Exact Location Of Accident BLK 90 WHAMPOA DRIVE CARPARK
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLG8565E
Insured/Policyholder
Name Of Registered Owner LCRF PTE LTD
Co Reg No 201624597K
Email Address NOEMAIL
Mobile Phone No
Alternative Phone No OFFICE-31584255
Vehicle Particulars
Manufacturer TOYOTA
Model COROLLA ALTIS CLASSIC 1.6 CVT
Exact Purpose for which vehicle was being used at time of accident PRIVATE HIRER
Are you claiming under your own insurance policy for repair to your vehicle? NO
If No, Please state action to be taken THIRD PARTY
Vehicle Category PRIVATE CAR
Insurance Company
Name of Insurance Company AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage COMPREHENSIVE
Fleet Policy NO
Policy Number 999995174
Cover Note Number
Driver
Name of Driver PAUL CHANDRA SEKARAN S/O ARUMUGAM
NRIC No S1463825C
Date Of Birth 22/10/1961
Occupation OUTDOOR
Date Of Driving Pass 01/10/1991
Driving Experience 26 YEARS AND 1 MONTH
Gender MALE
Mobile Number
Fax Number
Contact Number
Email Address NOEMAIL

Address

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OTHER - PRIVATE HIRER

Vehicle Registration Number of Driver's Own Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

COLLISION - HEAD ON COLLISION

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Was any body injured in the Accident? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

REFER TO STATEMENT

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SCY9108Y

Vehicle Make/Model/Colour

Details Of Properties

Name of Driver WONG NGIAP HUA

NRIC/Passport Number S0054880D

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time: 23/11/17
1425H

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



A = SLK 856SE
B = SC 9108Y
Wong Ngai Hwa
SOCS488CD

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 23 Nov 2017 at about 1225hrs, I was driving along Whampoa Drive (BLK 90) car park. As I turned to the left, suddenly a black Mercedes came out of the parking lot. my car (SLK 856SE) grazed on the Mercedes, thus resulting in damages to my bumper, left side doors (two). 1 DO One was injured

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time: 23/11/17
1428H.

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



11/25/2017

Ding Auto Pte Ltd (Co.Reg.No.201311788Z)

Blk 10, #01-20, Sin Ming Industrial Estate Sector C

Singapore 575645

Tel: 64521208 Fax: 64520614 Email: anna.chua@dingauto.sg; admin@dingauto.sg; ding@dingauto.sg

TP INSURER:

MSIG Insurance (Singapore) Pte. Ltd. (HQ)

WONG NGIAP HUA

N/L

Singapore

Claimant Insurer:

AIG Asia Pacific Insurance Pte. Ltd.

PARTICULARS OF CLAIM

Claim Type: THIRD PARTY

Policy No:

Vehicle Reg. No.: SLG8565E

Party At Fault: THIRD PARTY

Driver (TP): PAUL CHANDRA SEKARAN S/O ARUMUGAM

Ref. No: 85007957

Date of Loss: 23/11/2017

Driveable?

Make/Model:

TOYOTA COROLLA ALTIS, 1.6 CLASSIC
CVT (A)

Vehicle Reg. Date: 17/10/2016

Vehicle Colour:

SILVER

Engine No:

1ZR5593888

Odometer:

72571 KM

Chassis No:

MR053REH104558828

Paint Type:

Total Loss?

NO

Est. Duration of

Repair (day)

8

Description of
Accident/Loss

REFER TO STATEMENT

Present Location:

DING AUTO PTE LTD (JBL)

Tan Jiah 97495749.
- WP 6 days
Resurvey after repair.
surv @ (Lkhanh)

[Signature]
28/11/17

27/11/17 @ 1420

COST OF CLAIMS

Fees

Miscellaneous Items

Labour

Paintwork Labour

Towing

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Amount

5,723.40

0.00

4,180.00

0.00

0.00

Gross Total (\$\$) 9,903.40

+ GST 7.00% (\$\$) 693.24

Nett Amount (\$\$) 10,596.64

+ Car Rental (8.0 x S\$120.00/day) (\$\$) 960.00

Claim Total (\$\$) 11,556.64

This claim is handled by: YOU JING FENG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

25/11/17

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 24 Nov 2017)
 Parts: 143 TOYOTA COROLLA ALTIS 1.6 CLASSIC CVT (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Ding Auto Pte Ltd/SLG8565E/24/11/2017 10:33
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the
 END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BUMPER <i>de</i>	0.00	0.00	*220.00 F
2	1		*FRONT BUMPER SIDE RETAINER LHS <i>nee</i>	0.00	0.00	*28.00 F
3	1		*FOG LAMP COVER LHS <i>x nn</i>	0.00	0.00	*60.00 F
4	1		*FRONT FENDER LHS <i>bt</i>	0.00	0.00	*120.00 F
5	1		*FRONT FENDER INNERSHIELD LHS <i>? x nn</i>	0.00	0.00	*85.00 F
6	1		*FRONT FENDER VVTI EMBLEM LHS <i>nee</i>	0.00	0.00	*30.00 F
7	1		*FRONT FENDER INNER SHIELD CLIP <i>? x nn</i>	0.00	0.00	*35.00 F
8	1		*LHS DOOR FRT <i>Ry</i>	0.00	0.00	*550.00 F
9	1		*LHS DOOR FLAME STICKER <i>x nn</i>	0.00	0.00	*60.00 F
10	1		*LHS DOOR RUBBER BEADING <i>x nn</i>	0.00	0.00	*120.00 F
11	1		*LHS REAR DOOR <i>bt</i>	0.00	0.00	*580.00 F
12	1		*LHS REAR DOOR FALME STICKER <i>nee</i>	0.00	0.00	*60.00 F
13	1		*RREAR BUMPER <i>Ry</i>	0.00	0.00	*220.00 F
14	1		*REAR BUMPER SIDE RETAINER LHS LONG <i>x nn</i>	0.00	0.00	*40.00 F
15	1		*FRONT RIM <i>ant</i>	0.00	0.00	*650.00 F
16	1		*REAR RIM LHS <i>ant</i>	0.00	0.00	*650.00 F
17	1		*FRONT TYRE LHS <i>x nn</i>	0	0.00	*150.00 FS
18	1		*REAR TYRE LHS <i>x nn</i>	0	0.00	*150.00 FS
19	1		*FRONT LOWER ARM LHS <i>? x nn</i>	0.00	0.00	*160.00 F
20	1		*FRONT ABSORBED LHS <i>? x nn</i>	0.00	0.00	*140.00 F
21	1		*FRONT STABILIZER LINK LHS <i>? x nn</i>	0.00	0.00	*58.00 F
22	1		*REAR ABSORBED LHS <i>? x nn</i>	0.00	0.00	*160.00 F
23	1		*REAR DOOR LHS REGULATOR <i>x nn</i>	0.00	0.00	*140.00 F
24	1		*REAR DOOR LHS REGULATOR MOTOR <i>x nn</i>	0.00	0.00	*230.00 F
25	1		*HEAD LAMP LHS <i>* ? x nn</i>	0.00	0.00	*320.00 F

F...omise part, S=SpcNett.

Sub Total (\$\$)

5,016.00

+ Margin on L,N Items 15.00% (\$\$)

707.40

Total Parts (\$\$)

5,723.40

Ding Auto Pte Ltd/SLG8565E/24/11/2017 10:33. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	STRAIGHTEN AND PANEL BEAT ON ACCIDENT AREAS	New 800	1,500.00
2	R&R FRONT AND REAR DOOR COMPONENTS	New 60	200.00
3	R&R FRONT& REAR TYRE AND RIM INCLUDING BALANCING	New 60	200.00
4	R&R FRONT SUSPENSION	New 75 120.7X	150.00
5	R&R REAR SUSPENSION	New X	150.00
6	SPRAY PAINTING FRONT BUMPER ,FRONT FENDER LHS , FRONT DOOR LHS ,REAR DOOR LHS , REAR FENDER LHS ,REAR BUMPER , BONNET	New 1200	1,800.00
7	CHECK WIRING	New 30	80.00
8	RUSH PROOFING	New 40	100.00
Gross Labour Cost (\$\$)			4,180.00

Ding Auto Pte Ltd/SLG8565E/24/11/2017 10:33. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	24 Nov 2017 10:15 Sendback Est	24 Nov 2017 10:33 S\$9,903.40	27 Nov 2017 08:38 Edit Adj Rpt	S\$3,900.00 Edit Estimates	S\$3,900.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured:	WONG NGIAP HUA, ID: S0054880D		
Main Claimant:	LCRF PTE LTD, Co. Reg. No.: 201624597K		
Vehicle Reg. No.:	SLG8565E	Date of Loss:	23/11/2017 00:00 - :59
Claim Type:	TP / 538248	Policy/Cover Note No.:	D28808600QMX (Comprehensive) Coverage: 15/09/2017 - 14/09/2018
Vehicle Reg. No. (Insured):	SCY9108Y	Policy No. (Claimant):	999995174
		Excess:	
Repairer:	Ding Auto Pte Ltd (HQ) Blk 10, #01-20, Sin Ming Industrial Estate Sector C, 575645 Sin Ming - Tel: 64521208		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]		
Claimant's Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH] ... [Final Rpt due 27/12/2017]		
Adj Asg. Remarks:	ON WP. Car in at 249 Jln Boon Lay S619523		

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

[View All](#)
[Compose Case Mail](#)


ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SLG8565E (538248)
[SCY9108Y]
TP
LCRF PTE LTD
Nov 23 2017 12:00AM
[WONG NGIAP HUA]
Ding Auto Pte Ltd

Upload Documents		Upload Photos	Compose New Letter	View Use Viewer ▼	
Assessment Reports				1 per page ▼	☒
No	Finalized On	Ding Auto Pte Ltd (HQ)		Thumbnail	Print
1	23/11/17 15:52	Accident Statement		Load HTM	
2	24/11/17 10:33	Repairer Estimates		Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	28/11/17 16:13	Adjuster Immediate Advice		Load HTM	
Photos/Images				3 per page ▼	☒
No	Finalized On	Ding Auto Pte Ltd (HQ)		Thumbnail	Print
1	23/11/17 15:50	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
2	23/11/17 15:50	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
3	23/11/17 15:50	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
4	23/11/17 15:50	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
5	23/11/17 15:50	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
6	23/11/17 15:50	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
7	23/11/17 15:50	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
8	23/11/17 15:50	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
9	23/11/17 15:50	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
10	23/11/17 15:50	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
11	23/11/17 15:50	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
12	23/11/17 15:50	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
13	23/11/17 15:51	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
14	23/11/17 15:51	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
15	23/11/17 15:51	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
16	23/11/17 15:51	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
17	23/11/17 15:51	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
18	23/11/17 15:51	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
19	23/11/17 15:51	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	28/11/17 16:08	General View		Load JPG	☒
2	28/11/17 16:08	General View		Load JPG	☒
3	28/11/17 16:08	General View		Load JPG	☒
4	28/11/17 16:08	General View		Load JPG	☒
5	28/11/17 16:08	General View		Load JPG	☒
6	28/11/17 16:08	General View		Load JPG	☒
7	28/11/17 16:08	General View		Load JPG	☒
8	28/11/17 16:08	General View		Load JPG	☒

9	28/11/17 16:08	General View		Load JPG	☒
10	28/11/17 16:08	General View		Load JPG	☒
11	28/11/17 16:08	General View		Load JPG	☒
12	28/11/17 16:08	General View		Load JPG	☒
13	28/11/17 16:08	General View		Load JPG	☒
14	28/11/17 16:08	General View		Load JPG	☒
15	28/11/17 16:08	General View		Load JPG	☒
16	28/11/17 16:08	General View		Load JPG	☒
17	28/11/17 16:08	General View		Load JPG	☒
18	28/11/17 16:08	General View		Load JPG	☒
19	28/11/17 16:08	General View		Load JPG	☒
20	28/11/17 16:08	General View		Load JPG	☒
21	28/11/17 16:08	General View		Load JPG	☒
22	28/11/17 16:08	General View		Load JPG	☒
23	28/11/17 16:08	General View		Load JPG	☒
24	28/11/17 16:08	General View		Load JPG	☒
25	28/11/17 16:08	General View		Load JPG	☒
26	28/11/17 16:08	General View		Load JPG	☒
27	28/11/17 16:08	General View		Load JPG	☒
28	28/11/17 16:08	General View		Load JPG	☒
29	28/11/17 16:08	General View		Load JPG	☒
30	28/11/17 16:08	General View		Load JPG	☒
31	28/11/17 16:08	General View		Load JPG	☒
32	28/11/17 16:08	General View		Load JPG	☒
33	28/11/17 16:08	General View		Load JPG	☒
34	28/11/17 16:08	General View		Load JPG	☒
35	28/11/17 16:08	General View		Load JPG	☒
36	28/11/17 16:08	General View		Load JPG	☒
37	28/11/17 16:08	General View		Load JPG	☒
38	28/11/17 16:08	General View		Load JPG	☒
39	28/11/17 16:08	General View		Load JPG	☒
40	28/11/17 16:08	General View		Load JPG	☒
41	28/11/17 16:08	General View		Load JPG	☒
42	28/11/17 16:08	General View		Load JPG	☒
43	28/11/17 16:08	General View		Load JPG	☒
44	28/11/17 16:08	General View		Load JPG	☒
45	28/11/17 16:08	General View		Load JPG	☒
46	28/11/17 16:08	General View		Load JPG	☒
47	28/11/17 16:08	General View		Load JPG	☒
48	28/11/17 16:08	General View		Load JPG	☒
49	28/11/17 16:08	General View		Load JPG	☒
50	28/11/17 16:08	General View		Load JPG	☒
51	28/11/17 16:08	General View		Load JPG	☒
52	28/11/17 16:08	General View		Load JPG	☒
53	06/12/17 14:44	RE-SURVEY PHOTO		Load JPG	☒
54	06/12/17 14:44	RE-SURVEY PHOTO		Load JPG	☒
55	06/12/17 14:44	RE-SURVEY PHOTO		Load JPG	☒
56	06/12/17 14:44	RE-SURVEY PHOTO		Load JPG	☒
57	06/12/17 14:44	RE-SURVEY PHOTO		Load JPG	☒
58	06/12/17 14:44	RE-SURVEY PHOTO		Load JPG	☒
59	06/12/17 14:44	RE-SURVEY PHOTO		Load JPG	☒

Linked Accident Report Documents

			View	Use Viewer	
Assessment Reports			1 per page		☒
No	Finalized On	Ding Auto Pte Ltd (HQ)		Thumbnail	Print
1	23/11/17 15:52	Accident Statement		Load HTM	
Photos/Images			3 per page		☒
No	Finalized On	Ding Auto Pte Ltd (HQ)		Thumbnail	Print
1	23/11/17 15:50	Accident Photo		Load JPG	☒
2	23/11/17 15:50	Accident Photo		Load JPG	☒
3	23/11/17 15:50	Accident Photo		Load JPG	☒
4	23/11/17 15:50	Accident Photo		Load JPG	☒
5	23/11/17 15:50	Accident Photo		Load JPG	☒
6	23/11/17 15:50	Accident Photo		Load JPG	☒
7	23/11/17 15:50	Accident Photo		Load JPG	☒
8	23/11/17 15:50	Accident Photo		Load JPG	☒
9	23/11/17 15:50	Accident Photo		Load JPG	☒
10	23/11/17 15:50	Accident Photo		Load JPG	☒
11	23/11/17 15:50	Accident Photo		Load JPG	☒
12	23/11/17 15:50	Accident Photo		Load JPG	☒
13	23/11/17 15:51	Accident Photo		Load JPG	☒
14	23/11/17 15:51	Accident Photo		Load JPG	☒
15	23/11/17 15:51	Accident Photo		Load JPG	☒
16	23/11/17 15:51	Accident Photo		Load JPG	☒
17	23/11/17 15:51	Accident Photo		Load JPG	☒
18	23/11/17 15:51	Accident Photo		Load JPG	☒
19	23/11/17 15:51	Accident Photo		Load JPG	☒
Documentation			1 per page		☒
No	Finalized On	Ding Auto Pte Ltd (HQ)		Thumbnail	Print
1	23/11/17 15:49	Sketch Plan		Load TIF	
2	23/11/17 15:49	Sketch Plan #2		Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) Show Remarks To: ☐ Repairer ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG17022544/T1GBE2
 Date: 07/12/2017

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	D28808600QMX
Claimant Vehicle No :	SLG8565E	Insured Vehicle No :	SCY9108Y
Date of Loss:	23/11/2017	Nature of Claim:	TP
			Claim No: 538248

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLG8565E		
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 CLASSIC CVT (A)	Engine No:	1ZRX593888
Reg. Date:	17/10/2016 (Man. Year: 2016)	Chassis No:	MR053REH104558828
Colour:	Silver	Odometer:	72571 km
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	5,723.40	2,688.70	3,034.70	53.02
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,180.00	2,190.00	1,990.00	47.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,903.40	4,878.70	5,024.70	50.74
Approved Total (Overridden) (S\$)		3,900.00		
(S\$)	9,903.40	3,900.00	6,003.40	60.62
+ GST 7.00/7.00% (S\$)	693.24	273.00	420.24	60.62
Nett Amount (S\$)	10,596.64	4,173.00	6,423.64	60.62

INSPECTION

Date of Assignment:	27/11/2017	
Date Inspected:	27/11/2017	Inspected At:
		249 Jalan Boon Lay, 619523
Estimated Period of Repair:	6.0 days	Repairer : Ding Auto Pte Ltd (HQ)

Adjuster: MOHD TAUFIKH

Manager: LOW AI PHING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 07 Dec 2017)
Parts:	143	TOYOTA COROLLA ALTIS 1.6 CLASSIC CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLG8565E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	220.00 F	*220.00 F
2	1		*FRONT BUMPER SIDE RETAINER LHS	Necessary	28.00 F	*28.00 F
3	1		*FOG LAMP COVER LHS	Not Necessary	60.00 F	*- F
4	1		*FRONT FENDER LHS	Bent	120.00 F	*120.00 F
5	1		*FRONT FENDER INNERSHIELD LHS	Not Necessary	85.00 F	*- F
6	1		*FRONT FENDER VVTI EMBLEM LHS	Necessary	30.00 F	*30.00 F
7	1		*FRONT FENDER INNER SHIELD CLIP	Not Necessary	35.00 F	*- F
8	1		*LHS DOOR FRT	Repair	550.00 F	*- F
9	1		*LHS DOOR FLAME STICKER	Not Necessary	60.00 F	*- F
10	1		*LHS DOOR RUBBER BEADING	Not Necessary	120.00 F	*- F
11	1		*LHS REAR DOOR	Bent	580.00 F	*580.00 F
12	1		*LHS REAR DOOR FALME STICKER	Necessary	60.00 F	*60.00 F
13	1		*RREAR BUMPER	Repair	220.00 F	*- F
14	1		*REAR BUMPER SIDE RETAINER LHS LONG	Not Necessary	40.00 F	*- F
15	1		*FRONT RIM	Cut	650.00 F	*650.00 F
16	1		*REAR RIM LHS	Cut	650.00 F	*650.00 F
17	1		*FRONT TYRE LHS	Not Necessary	150.00 FS	*- FS
18	1		*REAR TYRE LHS	Not Necessary	150.00 FS	*- FS
19	1		*FRONT LOWER ARM LHS	Not Necessary	160.00 F	*- F
20	1		*FRONT ABOSRBED LHS	Not Necessary	140.00 F	*- F
21	1		*FRONT STABILIZER LINK LHS	Not Necessary	58.00 F	*- F
22	1		*REAR ABSORBED LHS	Not Necessary	160.00 F	*- F
23	1		*REAR DOOR LHS REGULATOR	Not Necessary	140.00 F	*- F
24	1		*REAR DOOR LHS REGULATOR MOTOR	Not Necessary	230.00 F	*- F
25	1		*HEAD LAMP LHS	Not Necessary	320.00 F	*- F

F=Franchise part. S=SpcNett.

Sub Total (\$\$)	5,016.00	2,338.00
+ Margin on L,N Items 15.00/15.00% (\$\$)	707.40	350.70
Total Parts (\$\$)	5,723.40	2,688.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	STRAIGHTEN AND PANEL BEAT ON ACCIDENT AREAS	New	1,500.00	800.00
2	R&R FRONT AND REAR DOOR COMPONENTS	New	200.00	60.00
3	R&R FRONT& REAR TYRE AND RIM INCLUDING BALANCING	New	200.00	60.00
4	R&R FRONT SUSPENSION	New	150.00	0.00
5	R&R REAR SUSPENSION	New	150.00	0.00
6	SPRAY PAINTING FRONT BUMPER ,FRONT FENDER LHS , FRONT DOOR LHS ,REAR DOOR LHS , REAR FENDER LHS ,REAR BUMPER , BONNET	New	1,800.00	1,200.00
7	CHECK WIRING	New	80.00	30.00
8	RUSH PROOFING	New	100.00	40.00
Gross Labour Cost (S\$)			4,180.00	2,190.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >