

INS. CASE OWNER:

Bennie

CC4 / AIG170 22546 1 Keaz

## ASSIGNMENT

Surveyor:

KENNETH

DOI:

27/11/17

Date / Time:

27/11/17

Registered in Merimen:

27/11/17

Pre-assign / CCU / FTE



Insured Vehicle No. : CIV 2886M

Name of Insured : LIM THIAN CHIN

Insured Tel No. : HP:

Excess Sec II : S\$ D.O.A. : 16/11/17

Is driver the owner? (YES / NO) Nature of Accident :

If NO, Driver Name / Age :

Driver Tel No. : 9478 1162

(V/L: YES / NO)

Claim No. : 7383961707SG

Policy No. : 710051067X

Make / Model : MAZDA 6 2.5L

Place of Accident : HILL ST TWO CHINATOWN @ LOH YEW ST JUNCTION

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability : % Final ? Yes / No

SLB 5274R

INSRS:  
WSP: Poon Siang Seow  
Tel:  
Liability:  
RMKS:INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:

Date/ Time

SLB 5274R - NGA/MSG/17021967/Y DOA: 16/11/17  
 CIV 2886M - CC3/MSG/15010732/1A/463 DOA: 28/11/17  
 - NGA/MSG/17021967/Y DOA: 16/11/17

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA :

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

29/11/17 (Acher)

PENDING TP VIDEO, RECD TP VIDEO SAE IN (V: ASHLEY: 201)

12/11/17 12:30 CALLED OI NO RESPONSE

5/12/17 9:59AM CALLED OI (COMPARED ALL DATA OI SOURCE INFO TP LANE AND YH  
 TP VEH. INFORM TP CLAIM AGREED TO SETTLE AND PROVIDE AWARD  
 NED ISSUE

Email wsp liability case

RECEIVED 8 3 Nov 2018

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with: ABERD

Confirm by: KSL

Repair Cost: PIP S\$ 3,856.40 ( 4 days) Reduction: 48 % Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time: 8/3/18

Confirm with: ABERD

Email ☐ Call ☐

Final Liability:

% 80

(Agreed / Assessed) BOLA S/N No. : 15

If NO or B 28, Ass. Lia :

Repair Cost:

S\$ 3,856.40

OI CHANGE LANE (REFER TO TP VIDEO)

Loss of Rental (LOR):

S\$ -

( days)

Loss of Use (LOU):

S\$ 240.00

(\$ 60 x 4 days)

Loss of Income (LOI):

S\$ -

(\$ x days)

LOR only ☐ LOU only ☒LOR + LOU ☐ LOR + LOI ☐ [Tick only one]

GIA/LTA Search

S\$ 5.35

Medical:

S\$ -

Disbursement:

S\$ -

(e.g. Tow/ Independent)

Legal Cost:

S\$ -

Total:

S\$ 4,101.75

Global Sum S\$:

FINAL PAYMENT

Date/Time: 8/3/18

Confirm with: ABERD

Email ☐ Call ☐

Payee 1:

S\$ 4,101.75

Name 1: POON SIANG SEOW

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format: TP

3) Survey fee: \$320 + \$20

COPY SENT

ASS. REC. BY:

REF:

AIG/


Kenneth

## ASSIGNMENT

\* From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s Poon Siang Sean  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
 repair at the time of inspection.



Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: 4 days Res.: Yes or No  
 Lum Sum: 1.31 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: SUB 5274R Yr Regn: 04, 16  
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai <sup>4)</sup> Elastic c.c. 1591  
 Colour: M. Gold A/C: Insured / Std / NI / NA  
 Sp. Reading: 35490 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: KMH0841CM4U131982Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65R15

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or Hankook

Front

Rear

R/Bal. 7 mmR/Bal. 7 mmL/Bal. 7 mmL/Bal. 7 mmD.O.A. 16/11/17D.O.I. 27/11/17Survey held at ✓

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S for body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

28/11 File pass to CatherinePIP: 3.836.40 (RED: 3.664.10 48%)

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

☐ : Prel. Report☐ : Final Report

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Add Fee: ☐ Site Insp (\$☐ Interview (\$☐ Tech. Invs (\$☐ Weekend (\$

Survey Fee:

Transportation

S + RS. \$

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC4/AIG17022546/Kea3	
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 27-11-2017	
		Code : AIG	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	SJV 2886M	Veh. Inspected	SLB 5274R
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	27/11/2017
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
<b>4. Description of Damages</b>			
<b>5. General Information</b>			
Accident Date	16/11/2017	Inspection Date	27/11/2017
Survey held at	POON SIANG SEOW No.160 SIN MING DRIVE #05-13 SIN MING AUTOCITY SINGAPORE 575722		
<b>5a. Remarks</b>			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			



# 方商昭噴漆 POON SIANG SEOW

Sin Ming Autocity, No. 160 Sin Ming Drive, #05-13, Singapore 575722.  
Tel: 6453 7511 Fax: 6453 8046 Email: sitti1@singnet.com.sg Regn. No. 05396600K

HITACHI CAPITAL ASIA PACIFIC PTE LTD  
111 SOMERSET ROAD  
#11-05  
Singapore 238164

*Not Authorized*  
*1. B.1*  
*Permy B4 paint*  
*83856.40*

Dear sir  
Estimate cost of repair to vehicle no. SLB 5274R  
To supply

1. Front bumper	<i>mg cm</i>	580.00	—
2. Front bumper retainersx2	<i>also</i>	100.00	+
3. Head lamp	<i>mg cm</i>	980.00	—
4. Head lamp bracket	<i>in</i>	55.00	X
5. Fog lamp	<i>in</i>	350.00	X
6. Fog lamp cover	<i>in</i>	65.00	✓
7. Front fender	<i>in</i>	380.00	X
8. Front fender inner garish	<i>in</i>	125.00	X
9. Wheel rim	<i>1. x 15</i>	1,015.00	<i>800</i>
10. Chips for garish and bumper x15	<i>in</i>	22.50	—
11. Door mirror	<i>mg cm</i>	750.00	—
12. Lower arm	<i>hit</i>	338.00	—
13. Knuckle arm	<i>hit</i>	350.00	—
14. Shock absorber	<i>2 of hit</i>	300.00	—

*4 days*

Labour charges		
Rust proofing	<i>in</i>	80.00 X
Panel beating		880.00 <i>400</i>
Spray painting		800.00 <i>500</i>
To remove and refit undercarriages		350.00 <i>180</i>
Wheel alignment		

Total *750.50*

Your faithfully

*Albert Poon*

ALBERT POON

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type      Company  
Owner ID            0399N

### Vehicle Details

Vehicle No.            SLB5274R  
Vehicle to be  
Exported              Yes  
Intended De-  
registration Date    25 Nov 2017  
Vehicle Make          HYUNDAI  
Vehicle Model        ELANTRA AD 1.6 GLS  
AT  
Primary Colour        Beige  
Manufacturing Year   2016  
Engine No.            G4FGGU150094  
Chassis No.           KMHD841CMHU131482  
Maximum Power  
Output                93.8 kW (125 bhp)  
Open Market Value    \$12,966.00  
Original Registration  
Date                   13 Apr 2016  
First Registration  
Date                   13 Apr 2016  
Transfer Count        0  
Actual ARF Paid       \$12,966.00

### Intended PARF Rebate Details

PARF Eligibility        Yes  
PARF Eligibility Expiry  
Date                   12 Apr 2026  
PARF Rebate Amount   \$9,724.00

### Intended COE Rebate Details

COE Expiry Date       12 Apr 2026  
COE Category          A - Car up to 1600cc  
& 97kW (130bhp)  
COE Period(Years)    10  
QP Paid                \$46,009.00  
COE Rebate Amount    \$36,807.00  
**Total Rebate Amount    \$46,531.00**

The information contained herein is correct as at 24 Nov 2017

OK



# 方商昭噴漆 POON SIANG SEOW

Sin Ming Autocity, No. 160 Sin Ming Drive, #05-13, Singapore 575722.  
Tel: 6453 7511 Fax: 6453 8046 Email: sitt1@singnet.com.sg Regn. No. 05396600K

HITACHI CAPITAL ASIA PACIFIC PTE LTD  
111 SOMERSET ROAD  
#11-05  
Singapore 238164

*Not Authorized  
I.B.I  
Repair by paint*

Dear sir

Estimate cost of repair to vehicle no. SLB 5274R

To supply

1. Front bumper	<i>mg cm</i>	580.00	—
2. Front bumper retainersx2	<i>also</i>	100.00	+
3. Head lamp		980.00	?
4. Head lamp bracket	<i>sm</i>	55.00	X
5. Fog lamp	<i>sm</i>	350.00	X
6. Fog lamp cover	<i>sm</i>	65.00	X
7. Front fender	<i>sm</i>	380.00	X
8. Front fender inner garish	<i>sm</i>	125.00	X
9. Wheel rim	<i>1. x 300</i>	1,015.00	<i>80sm</i>
10. Chips for garish and bumper x15	<i>sm</i>	22.50	—
11. Door mirror		750.00	?
12. Lower arm		338.00	?
13. Knuckle arm		350.00	?
14. Shock absorber	<i>2 of</i>	300.00	?

Labour charges

Rust proofing	<i>sm</i>	80.00	X
Panel beating		880.00	<i>400</i>
Spray painting		800.00	<i>500</i>
To remove and refit undercarriages		350.00	?
Wheel alignment			

Total

*750.50*

Your faithfully

*Loz*

ALBERT POON

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

## Asher Sng (LKKAUTO)

---

**From:** Asher Sng (LKKAUTO)  
**Sent:** Tuesday, 5 December, 2017 11:17 AM  
**To:** 'Albert Poon'  
**Cc:** Vic (LKKAUTO)  
**Subject:** RE: Emailing: sld5274r

WITHOUT PREJUDICE

Hi Albert,

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear / under BOLA (subject to BOLA guideline settlement) and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident. And the days of LOU/ LOR will base on the number of days of repair as recommended by our surveyor.

Kindly take note that the case handler in-charge is Asher and she can be contacted at her DID 6841 6051

Thank You.

Best Regards,  
Asher Sng | Case Handler  
LKK Auto Consultants Pte Ltd  
phone: 6841-6051 | email: ashersng@lkkauto.com | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933) -----Original Message-----  
From: Albert Poon [mailto:sitti1@singnet.com.sg]  
Sent: Friday, 1 December, 2017 11:04 AM  
To: Asher Sng (LKKAUTO) <AsherSng@lkkauto.com>  
Subject: Emailing: sld5274r


Hope can help u

Thanks

Albert  
M: 96169634, 8458 1169

POON SIANG SEOW  
Sin Ming Autocity  
No.160 Sin Ming Drive, #05-13, S(575722)  
Tel: 6453 7511 Fax:6453 8046  
Email: sitti1@singnet.com.sg

Your message is ready to be sent with the following file or link attachments:

 sld5274r

Note: To protect against computer viruses, e-mail programs may prevent sending or receiving certain types of file attachments. Check your e-mail security settings to determine how attachments are handled.





方商昭噴漆  
**POON SIANG SEOW**

Sin Ming Autocity, No 160 Sin Ming Drive, #05-13, Singapore 575722  
Tel: 6453 7511 Fax: 6453 8046 Email: sitt1@singnet.com.sg Regn. No: 05396600K

Your Ref;

our Ref: SLB 5274R

Date: 26/01/2018  
AIG

Attention; Motor claim dept

Dear Sir

**ACCIDENT ON 16/11/2018 INVOLVING SLB 5274R AND SJV 2886M ALONG**

HITACHI CAPITAL ASIA PACIFIC PTE LTD OF Vehicle No: SLB 5274R

We are instructed by the above named to claim damages against

SJV 2886M connection with a road traffic accident on 16/11/2017  
Particulars of Loss and Expenses

1	Cost of repair ( recommended by your surveyor)	\$3,856.40
2	Loss of use for 4 days	\$ 400.00
3	Loss of use provided under NIMA PROTOCOL 2DAY	\$
4	GIA Search fee	\$ 5.35

**TOTAL \$4,261.75**

Yours Faithfully

  
ALBERT POON

**Asher Sng (LKKAUTO)**

---

**From:** Asher Sng (LKKAUTO)  
**Sent:** Tuesday, 5 December, 2017 3:06 PM  
**To:** 'AURIGAIS@GMAIL.COM'  
**Subject:** ACCIDENT INVOLVING SJV 2886M AND SLB 5274R ON 16/11/2017



Auto  
Consultants  
Pte Ltd

---

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 67414108

**Our Ref: CC4/AIG17022546/Kea3**

05 DEC 2017

**LIM THIAN CHIN**

Dear Sir/Madam,

**ACCIDENT INVOLVING SJV 2886M AND SLB 5274R ON 16/11/2017**

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD)(if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

Asher  
Case Handler  
DID: 6841 6051  
FAX: 6741 4108  
Email: [Ashersng@lkkauto.com](mailto:Ashersng@lkkauto.com)

c.c. AIG Asia Pacific Insurance Pte Ltd  
(Motor Claims Dept)

Name HITACHI CAPITAL ASIA PACIFIC PTE. LTD.

NRIC No.

Address

ROBIN OH (APR)  
Department Manager  
Total Vehicle Solution  
Asia Pacific Business Division

Date

24/11/2017

To

及 噴 漆  
JANIS SEOW  
100, 100, Ming Drive  
# 575722  
# 64530048  
Email: s101@singnet.com.sg

Dear Sirs

#### MY ACCIDENT

I am the owner of motor vehicle SLB 5274R which was involved in the above accident.

I refer to the repairs to my vehicle. I hereby instruct you to proceed with the repairs of my damaged vehicle. Since I would not be able to pay you for the repairs and you have agreed not to exercise your lien on my vehicle for the repairs, I hereby give you authority to claim all costs, expenses and damages caused to my vehicle in particular appointing a surveyor and solicitors on my behalf to protect your interest.

I also authorise the solicitors to be appointed on my behalf to communicate and quantify my claim against the negligent party and/or his insurers.

Yours faithfully

HITACHI CAPITAL ASIA PACIFIC PTE. LTD.

ROBIN OH (APR)  
Department Manager  
Total Vehicle Solution  
Asia Pacific Business Division

**RELEASE VOUCHER**  
**(AIG Asia Pacific - Express Third Party Claim)**

"We/I, POON SIANG SEOW ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for S\$3,856.40 (Repair Cost), S\$240.00 (Loss of Use/Rental), S\$5.35 (Disbursement) for vehicle no. SLB 5274R that was damaged pursuant to the accident which occurred on 16/11/2017 (date) along HILL ST TWD CHINATOWN @ LOKE YEW ST JUNCTION (location) involving vehicle no/s SJV 2886M.

This is pursuant to the inspection conducted on 27/11/2017 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner HITACHI CAPITAL <sup>ASIA PACIFIC PTE LTD</sup> ("the third party claimant") of vehicle no. SLB 5274R make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SLB 5274R (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 8 (day) of 3 (month) 2018 (year)



**KSC**

Signed by appointed surveyor



方商昭噴漆  
**POON SIANG SEOW**  
Sin Ming Autocity  
No. 160 Sin Ming Drive  
#05-13 Singapore 575722  
Tel: 64537511 Fax: 64538046  
Email: s1tt11@singnet.com.sg

Signed by "the workshop" (with chop)



# 方 商 昭 噴 漆 POON SIANG SEOW

Sin Ming Autocity, No. 160 Sin Ming Drive, #05-13, Singapore 575722.  
Tel: 6453 7511 Fax: 6453 8046 Email: sitti1@singnet.com.sg Regn. No. 05396600K

HITACHI CAPITAL ASIA PACIFIC PTE LTD  
111 SOMERSET ROAD  
#11-05  
Singapore 238164

Dear sir

Final cost of repair to vehicle no. SLB 5274R

To supply

1. Front bumper	580.00
2. Front bumper retainer	50.00
3. Head lamp	980.00
4. Chips for garish x15	22.50
5. Door mirror	750.00
6. Lower arm	338.00
7. Knuckle arm	350.00
8. Shock absorber	300.00
Less 20%	3,370.50
	674.10
	2,696.40

Labour charge

Wheel repair	80.00snett
Panel beating	400.00
Spraying	540.00
To remove and refit undercarriages	180.00
Total	3,856.40

Your faithfully

ALBERT POON



Land Transport Authority

10 Sin Ming Drive

Singapore 575701

GST Registration No. : M4-0006529-2

Print Date/Time : 25 Nov 2017 / 09:52:44

Receipt Date/Time : 25 Nov 2017 / 09:52:44

**Tax Invoice/Receipt**

Receipt No. : ITNET-00000-171125-000199

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Result of Insurance Enquiry - SJV2886M				
As at 16 Nov 2017/12:20:00				
Insurance Co: AIG ASIA PACIFIC INSURANCE PTE. LTD.				
1	Insurance Enquiry - SJV2886M			
	Enquiry Fee	5.00	0.35	5.35
	20171125095120634952			
	<b>Sub-Total</b>	5.00	0.35	5.35
	<b>Total Before Rounding</b>	5.00	0.35	5.35
	<b>Rounding Difference</b>			0.00
	<b>Total Amount Payable</b>			5.35
<b>Paid By</b>				
	20171125095137730	Direct Debit: eNETS Debit (Internet Banking)		5.35
	<b>Total</b>			5.35
	<b>Cash Change</b>			0.00
	<b>Tendered Amount</b>			5.35
	<b>Excess Refundable Amount</b>			0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	28 Nov 2017 <a href="#">Edit Reg</a>		27 Nov 2017 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$3,856.40</b> <a href="#">Edit Estimates</a>	<b>S\$3,856.40</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>									
Insured:		Lim Thian Chin (Lin Tianjin), ID: S7521345Z							
Main Claimant:		HITACHI CAPITAL ASIA PACIFIC PTE LTD, Co. Reg. No.: 199400399N							
Vehicle Reg. No.:		SLB5274R	Date of Loss:	16/11/2017 12:00 - :59					
Claim Type:		TP / 7383961707SG	Policy/Cover Note No.:	(Comprehensive)					
Vehicle Reg. No. (Insured):		SJV2886M	Policy No. (Claimant):	MSD/VPCP/17-D00697-00					
		Excess:							
Repairer:		Poon Siang Seow (HQ) 160 Sin Ming Drive, #05-13 Sin Ming AutoCity, 575722 Sin Ming - Tel:							
Handling Insurer:		AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Tan, Bennie-WZ - 6419 1718] Bennie-WZ.Tan@aig.com							
Claimant's Insurer:		MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888							
Adjuster:		LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 06/12/2017]							
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SLB5274R (7383961707SG)

[SJV2886M]

TP

HITACHI CAPITAL ASIA PACIFIC PTE LTD

Nov 16 2017 12:00PM

[Lim Thian Chin (Lin Tianjin)]

Poon Siang Seow

<a href="#">Upload Documents</a> <a href="#">Upload Photos</a> <a href="#">Compose New Letter</a> <a href="#">Upload Video</a> <a href="#">Upload Audio</a>			<b>View</b> <a href="#">View in Browser</a>	
<b>Video</b>			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	03/01/18 17:27	TP Video - Accident	Load MP4	
<b>Letters/Correspondences</b>			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	(Draft)	Third Party Express Settlement - Payment Breakdown	Edit	
<b>Photos/Images</b>			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	08/03/18 11:13	General View	Load JPG	<input checked="" type="checkbox"/>
2	08/03/18 11:13	General View	Load JPG	<input checked="" type="checkbox"/>
3	08/03/18 11:13	General View	Load JPG	<input checked="" type="checkbox"/>
4	08/03/18 11:13	General View	Load JPG	<input checked="" type="checkbox"/>
5	08/03/18 11:13	General View	Load JPG	<input checked="" type="checkbox"/>
6	08/03/18 11:13	General View	Load JPG	<input checked="" type="checkbox"/>
7	08/03/18 11:13	General View	Load JPG	<input checked="" type="checkbox"/>
8	08/03/18 11:13	General View	Load JPG	<input checked="" type="checkbox"/>
9	08/03/18 11:13	General View	Load JPG	<input checked="" type="checkbox"/>
10	08/03/18 11:13	General View	Load JPG	<input checked="" type="checkbox"/>
11	08/03/18 11:13	General View	Load JPG	<input checked="" type="checkbox"/>
12	08/03/18 11:13	Odometer Reading	Load JPG	<input checked="" type="checkbox"/>
13	08/03/18 11:13	Chassis Number	Load JPG	<input checked="" type="checkbox"/>
14	08/03/18 11:13	General View	Load JPG	<input checked="" type="checkbox"/>
15	08/03/18 11:13	General View	Load JPG	<input checked="" type="checkbox"/>
16	08/03/18 11:18	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
17	08/03/18 11:18	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
18	08/03/18 11:18	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
19	08/03/18 11:18	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
20	08/03/18 11:18	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
21	08/03/18 11:18	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
22	08/03/18 11:18	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
23	08/03/18 11:18	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
24	08/03/18 11:18	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
25	08/03/18 11:18	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
26	08/03/18 11:18	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
27	08/03/18 11:18	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
28	08/03/18 11:18	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>



Documentation				1 per page	<input checked="" type="checkbox"/>
No	Relabel/ Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	27/11/17 16:31	ACKNOWLEDGEMENT EMAIL TO AIG DD 27.11.2017		Load PDF	
2	27/11/17 16:31	EMAIL FROM AIG DD 27.11.2017		Load PDF	
3	27/11/17 16:31	NOTIFICATION FROM WORKSHOP + TP GIA REPORT		Load PDF	
4	29/11/17 09:37	TP ESTIMATE- MARKED		Load PDF	
5	05/12/17 15:06	LETTER TO OI		Load PDF	
6	12/03/18 11:45	WORKSHOP INVOICE		Load PDF	
7	12/03/18 11:45	AUTHORISATION TO ACT FORM		Load PDF	
8	12/03/18 11:45	Release Voucher		Load PDF	
9	12/03/18 11:45	LTA SEARCH		Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	28/11/17 09:10	OI GIA report		Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

### Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM \_\_\_\_\_

### THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SJV2886M (Insd veh)	Model:	HYUNDAI ELANTRA 1.6 AD
	SLB5274R (TP veh)		GLS (A)
Date of Accident:	16/11/2017		

Global Sum Settlement	: <input type="checkbox"/> Yes	: <input checked="" type="checkbox"/> No	
Repair Estimate	: \$		7,520.50
Final Repair Cost	: \$		3,856.40
Loss of Use	: \$		240.00
			4.00 days at \$60.00 per day
Rental (if any)	: \$		0.00
			days
LTA / GIA Search Fee	: \$		5.35
Others:	: \$		0.00
	: \$		
Final Settlement Sum	: \$		4,101.75

**Is Third Party Workshop GIA Registered?**    ☐ YES    ☒ NO    (Kindly indicate below)

**A) For Non GIA Registered Workshop:**    Agreed Liability \_\_\_\_ 100 \_\_\_\_ (%)

**B) For GIA Registered Workshop:**    BOLA Applicable: Yes/ No    BOLA Scenario No: \_\_\_\_

BOLA Liability: \_\_\_\_ (%)    Assessed Liability (\*): \_\_\_\_ (%)

*\* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.*

Remarks \_\_\_\_\_

Payment Instruction: Payee's Breakdown			
1)	Poon Siang Seow	: \$	4,101.75
2)		: \$	
3)		: \$	

JOANNE LEE KHANG MIN

12 Mar  
2018

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG17022546/KEA3Q2

Date: 12/03/2018

## REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : SLB5274R

Insured Vehicle No : SJV2886M

Date of Loss: 16/11/2017

Nature of Claim: TP

Claim No: 7383961707SG

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SLB5274R

Make &amp; Model: HYUNDAI ELANTRA, 1.6 AD GLS (A)

Engine No: G4FGGU150094

Reg. Date: 13/04/2016 (Man. Year: 2016)

Chassis No: KMHD841CMHU131482

Colour: Metallic Gold

Odometer: 35490 km

Engine Capacity: 1591 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size: 195/65 R15

Front Left Side: Hankook 7 mm

Rear Left Side: Hankook 7 mm

Front Right Side: Hankook 7 mm

Rear Right Side: Hankook 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,410.50	2,776.40	2,634.10	48.68
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,110.00	1,080.00	1,030.00	48.82
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>7,520.50</b>	<b>3,856.40</b>	<b>3,664.10</b>	<b>48.72</b>
+ Loss of Use (4.0 x S\$60.00/day) (S\$)		240.00		
+ Doc/Search Fee (S\$)		5.35		
<b>Nett Liability (S\$)</b>		<b>4,101.75</b>		

## INSPECTION

Date of Assignment: 27/11/2017

Date Inspected: 27/11/2017 Inspected At:

Poon Siang Seow (HQ)  
160 Sin Ming Drive, #05-13 Sin Ming  
AutoCity  
Singapore 575722

Estimated Period of Repair: 4.0 days

**Adjuster:** KENNETH KONG

**Manager:** Asher Sng Rong Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Mtg Cracked	580.00 F	*580.00 FL
2	1		*FRONT BUMPER RETAINER	O/S Distorted	100.00 F	*50.00 FL
3	1		*HEAD LAMP	Mtg Cracked	980.00 F	*980.00 FL
4	1		*HEAD LAMP BRACKET	Serviceable	55.00 F	*- FL
5	1		*FOG LAMP	Serviceable	350.00 F	*- FL
6	1		*FOG LAMP COVER	Serviceable	65.00 F	*- FL
7	1		*FRONT FENDER	Repair	380.00 F	*- FL
8	1		*FRONT FENDER INNER GARNISH	Serviceable	125.00 F	*- FL
9	1		*WHEEL RIM (LOCAL REPAIR)	Scratched	1,015.00 FS	*80.00 FS
10	15		*CHIPS FOR GARISH AND BUMPER	Necessary	22.50 F	*22.50 FL
11	1		*DOOR MIRROR	Mtg Distorted	750.00 F	*750.00 FL
12	1		*LOWER ARM	Distorted	338.00 F	*338.00 FL
13	1		*KNUCKLE ARM	Bent	350.00 F	*350.00 FL
14	1		*SHOCK ABSORBER	Bent	300.00 F	*300.00 FL

F=Franchise part. S=SpchNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>5,410.50</b>	<b>3,450.50</b>
<b>- List Item Discount on L Items 0.00/20.00% (\$\$)</b>	<b>0.00</b>	<b>674.10</b>
<b>Total Parts (\$\$)</b>	<b>5,410.50</b>	<b>2,776.40</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	RUST PROOFING	New	80.00	0.00
2	PANEL BEATING	New	880.00	400.00
3	SPRAY PAINTING	New	800.00	500.00
4	TO REMOVE AND REFIT UNDERCARRIAGE WHEEL ALIGNMENT	New	350.00	180.00
Gross Labour Cost (S\$)			2,110.00	1,080.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >