

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHB 7549H -**AAD1711-187***Not Authorised*
Q

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHB 7549H - CANDY

KL1LA69RJBB091670

CHEVROLET

EPICA 2.0

16.11.2017

AXA

PART		LIST	
1	1	Rear Bumper	\$ 1,202.00
2	1	Rear Bumper Beam	\$ 239.94
3	1	Rear Bumper Centre Absorber	\$ 260.00
4	1	Rear Bumper Side Retainer RH	\$ 68.76
5	1	Rear Bumper Side Retainer LH	\$ 68.76
6	1	Rear Bumper Reflectors RH	\$ 119.74
7	1	Rear Bumper Reflectors LH	\$ 119.74
8	1	Rear Bumper Tow Hook Cover	\$ 93.00
9	1	Rear End Panel Outer	\$ 623.76
10	1	Rear End Panel Inner Trim	\$ 263.84
11	1	Bootlid	\$ 973.00
12	1	Bootlid inner trim board	\$ 400.00
13	1	Bootlid Weatherstrip	\$ 344.28
14	1	Bootlid Lock - Top	\$ 466.56
15	1	Bootlid 'CHEVROLET' Badge	\$ 120.62
16	1	Bootlid Logo	\$ 138.84
17	1	Bootlid 'EPICA LT' Badge	\$ 119.84
18	1	Bootlid Reflector Centre	\$ 217.97
19	1	Bootlid Reflector LH	\$ 128.40
20	1	Bootlid Hinge LH	\$ 120.00
21	1	Rear Tail Lamp LH	\$ 479.30
22	1	Rear Tail Lamp Panel LH	\$ 359.00
23	1	Rear Fender LH	\$ 1,145.00
24	1	Rear Fender Inner Trim LH	\$ 418.44
TOTAL		\$	8,490.79
10%		\$	849.08
		\$	7,641.71

Special Nett

TRANS-CAB AUTO SERVICES PTE LTD**AAD1711-187**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHB 7549H -

1	1Set	Licence Plate With Holder	\$	60.00	}	X
2	1Set	Bootlid inner trim board Clip	\$	40.00		
3	1Set	Rear Bumper Parking Sensor	\$	300.00		
4	1Set	Rear Bumper Fastener Clip	\$	44.00		
5	1Set	Rear Fender Inner Trim Clip LH	\$	30.00		
6	1Set	Rear Bumper End Dust Cover Clip	\$	30.00		
7	1	Rear Boot Sticker 'Trans-cab'	\$	30.00		
8	1	Rear Boot Sticker '6555-3333'	\$	30.00		
9	1	Rear Exhaust Mounting	\$	10.00		
10	2	Rear Windscreen Sealant	\$	80.00		
11	1	Rear Windscreen Inner Sponge Seal	\$	100.00		
12	1	Spare Tyre	\$	180.00		
13	1	Spare Wheel Rim	\$	126.74		

TOTAL	\$	1,060.74
TOTAL PARTS	\$	8,702.45

Panel Beating, Knocking And Straightening The
Necessary Portion, Remove And Renewal Of
Parts, Adjust And Realign The Same

\$ *nn* 2,700.00 *X*

To Check Electrical Lighting Concerned.

\$ *nn* 170.00 *X*

To Rust-Proofing Of The Affected Areas.

\$ *nn* 170.00 *X*

Putty And Spray Painting Of The Affected
Portion.

\$ 2,800.00 *2ed*

To reinstall rear bumper parking sensor.

\$ *nn* 170.00 *X*

To transfer of end panel fittings and conduct
water seepage test.

\$ *nn* 170.00 *X*

To Remove And Refit Rear W/Screen Glass To
Facilitate Bodywork Repair.

\$ *nn* 170.00 *X*

To transfer of boot fittings and conduct water
seepage test.

\$ *nn* 170.00 *X*

TRANS-CAB AUTO SERVICES PTE LTD**AAD1711-187**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHB 7549H -Towing fees \$ *22* 120.00 *X*To transfer of Fender fittings, attachments and
perform water seepage test. \$ *22* 170.00 *X*To remove and refit interior fittings, trimings,
garnish, fittings and other, to enable repair. \$ *22* 380.00 *X*To check steering geometry and computer
wheel alignment \$ *22* 220.00 *X*

	\$	7,410.00
TOTAL	\$	16,112.45

Repair Days~~10 Days~~*1 day*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: