

CITY CAB PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHA 9469Y

DATE 24/11/2017 10:47

MAKE :

MODEL : HYUNDAI SONATA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper			\$ 578.40
	Rear Bumper Reinforcement ?			\$ 483.30
	Rear Bumper Clip			\$ 22.00
	Rear Bumper Sponge			\$ 137.40
	Rear Bumper Under Cover ?			\$ 185.80
	Rear Bumper Protector (RH)			\$ 38.00
	Tail Lamp (RH)			\$ 344.00
	Rear Fender (RH) x repair			\$ 1,935.90
	Rear Fender Inner Lining (RH) ?			\$ 74.10
	Rear Tray Lugg Side (RH)			\$ 37.40
	Rear Windscreen Moulding x			\$ 60.00
	SUB TOTAL			\$ 3,896.30
	LESS 20%			\$ 779.26
	DISCOUNTED TOTAL			\$ 3,117.04
	Rear Bumper Reverse Sensor			\$ 135.70
	Rear Bumper Advertisement Logo			\$ 50.00
	Rear Bumper Rubber Mat			\$ 50.00
	Rear Fender Advertisement Logo (LH/RH)			\$ 200.00
	Rear Fender Comfort Sticker (RH)			\$ 30.00
	Rear Windscreen Sealant x			\$ 46.00
				\$ 511.70
	Labour Charge			
	Panel Beating			\$ 850.00
	Spray Painting Charge			\$ 400.00
	Wiring Charge			\$ 50.00
	Tuff Kote			\$ 50.00
	Remove/Refix Cushion & Upholstery Rear			\$ 150.00
	Remove/Refix Rear Windscreen Glass			\$ 120.00
	Remove/Refix Reverse Sensor			\$ 120.00
	TOTAL LABOUR			\$ 1,740.00
	ESTIMATE TOTAL			\$ 5,368.74
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

EQ

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged parts for resurvey
- Parts prices are subject to resurvey
- Third party survey is on a "Without prejudice" basis
- No illegal modification of vehicle
- Supplemental survey may be surveyed and is subject to final approval from Insurance Company

Acknowledged by repairer

Signature:

Date:

Kalinia

24/11/17 11:00hr

4 Days

45

After Repair photo

600

360

20

20

50

x

20