



Your Ref: MN.IG.B1.1611246

Date: 27th December 2017

Our Ref: CS1/LAW17022572/Uvbs2

M/s M Nedumaran & Co

No. 11 Sin Ming Road

#B2-09 (Unit 2), Thomson V Two

Singapore 575629

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO:
GR 8969A**

INSURED VEHICLE: SJV 4585T

ACCIDENT DATE: 25/10/2016

We thank you for your instruction on 22/11/2017.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of GR 8969A from M/s Quantum Risk Management (S) Pte Ltd.
- b) Survey report by MC-Coy Appraiser Pte Ltd with colour photographs.
- c) Final Repair Bill of GR 8969A from M/s Bluwel Automotive Service Pte Ltd.
- d) Singapore Accident Statement of Vehicles GR 8969A and SJV 4585T.
- e) Colour damaged vehicle photographs of GR 8969A.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: GR 8969A
Make & Model	: Daihatsu S200RV
Year of Registration	: 2000
Chassis Number	: JDAS200V001000500
Engine Capacity	: 659cc

2. We recommend that the repairs of the entire damage require about 12 (Twelve) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.