

22/03/2002

ASS. REC. BY:

REF:

CS/MSG17022599/Sibez

Special Instruction:

Surveyor:

Sebastian

ASSIGNMENT (Office)

From (Person):

Catherine Thia

of

Meth

Date/Time:

28/11/2017 9:51am

Estimated Cost:

Bill to:

OD / FF / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SL 3657E

Insured:

FBJ 7086E

at Workshop m/s

Eurokar

Tel:

6360 2845

of

12 Sungai Kadut Ave

Policy No:

MSD/VMS/17-366831

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

23-11-2017

CA / REV / REP. / REV 24 HRS 'wp'

4pm owner waiting

H.O.D. Endorsement:

Date/Time:

28/11/2017 9:56am

Person Contacted:

Tobi

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SL 3657E - x
	FBJ 7086E - x
26/1/18@	1.20pm confirmed with Jessica final fig \$9649.22, 6 days.
	Sent preli thru netimen

REF: MS 16 WP


ASSIGNMENT

SL 3657 E

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: _____ Yr Regn: 22/2/2014
 Type: M. Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Mini Cooper S Clubman AT LEI ^{NAV} C.C. 1998
 Colour: Brown A/C: Insured / Std / NI / NA
 Sp. Reading: 7624 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: WMW LN 720 702 1-25470
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In Order / Jammed / Leaked / Burnt or
 Brake: In Order / Jammed / Leaked / Burnt or
 Modi: NH / S/Rim / STD A/Rim or
 Tyre Size: F: 225/40 K18
 R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Pirelli

Front		Rear
R/Bal. <u>6</u> mm		R/Bal. <u>6</u> mm
L/Bal. <u>6</u> mm		L/Bal. <u>6</u> mm
D.O.A. <u>23/11/2014</u>		D.O.I. <u>28/11/2014</u>

Survey held at Trans Ewokars

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Rear o/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time | Action / Instruction

Confirm \$ 9649.22, 6 days
 Paid: \$ 2727.52, 22%.

RECEIVED 28 NOV 2018

Date/Time, File Pass to?



: Preli. Report

1) trip

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 6Resurvey No. of Trip: 1

Survey Fee:

Transportation:

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Weekend (\$

) \$ + RS. \$

) Photos

) Others

Report Format: TVLump Sum / I.B.I. (\$ 9649.22)

TOTAL

300

10

310




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MSG INSURANCE (SINGAPORE) PTE LTD		Ref : CS/MSG17022599/Srb	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 28-11-2017	
Code : MSG			
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	FBJ 7086E	Veh. Inspected	SLL 3657E
Policy No.	MSD/VMS/17-366831	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	MERIMEN (CATHERINE THIA)	Assign Date	28/11/2017
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	23/11/2017	Inspection Date	28/11/2017
Survey held at	EUROKARS HABITAT PTE LTD NO.12 SUNGEI KADUT AVE SINGAPORE 729648		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	23 Nov 2017		28 Nov 2017 09:51 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	NUR KHAIRINA BINTE KHALID, ID: S9542933E		
Main Claimant:	WONG NING, ID: S6843871C		
Vehicle Reg. No.:	SLL3657E	Date of Loss:	23/11/2017 07:00 - :59
Claim Type:	TP	Policy/Cover Note No.:	MSD/VMS/17-366831 (TP, Fire & Theft) Coverage: 23/06/2017 - 15/09/2018
Vehicle Reg. No. (Insured):	FBJ7086E	Policy No. (Claimant):	
	Excess:		
Repairer:	Eurokars Habitat Pte Ltd (HQ) 12 Sungei Kadut Avenue, 729648 Sungei Kadut - Tel: 63602845		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Catherine Thia Shi Yi - 6594 2545]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 29/11/2017]		
Driver/Custodian (Insured):	NUR KHAIRINA BINTE KHALID (/ Female), NRIC: S9542933E		

ASSOCIATED MAIL RECEIVED View All Compose Case Mail

There are no mail for this case.

☐ **ALL ASSOCIATED TASKS** View All Search Tasks Create New Task Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Friday, 26 January 2018 1:20 PM
To: jessicahs@eurokars.com.sg; Mei Kwan (LKKAUTO); jobithomas@eurokars.com.sg; Sebastian Yeang (LKK Auto); Janice Lee (LKKAUTO)
Cc: sarah.candida@eurokars.com.sg; CS A Team; Admin A; SUR; assignments
Subject: RE: SLL3657E finalization *** LKK REF: CS/MSG17022599/Srb

Dear Jess,

Confirm final fig \$9,649.22 before GST and 6 repair days.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: jessicahs@eurokars.com.sg [mailto:jessicahs@eurokars.com.sg]
Sent: Friday, 26 January 2018 11:04 AM
To: Mei Kwan (LKKAUTO) <Meikwan@lkkauto.com>; jobithomas@eurokars.com.sg; Sebastian Yeang (LKK Auto) <SebastianYeang@lkkauto.com>; Janice Lee (LKKAUTO) <JaniceLee@lkkauto.com>
Cc: sarah.candida@eurokars.com.sg; CS A Team <cs-a@lkkauto.com>; Admin A <admin-a@lkkauto.com>; SUR <sur@lkkauto.com>; assignments <assignments@lkkauto.com>
Subject: RE: SLL3657E finalization *** LKK REF: CS/MSG17022599/Srb

Dear Janice,

The below matter refers.

We have been waiting patiently for this confirmation but till today there is no confirmation yet.

If we don't receive your confirmation by today, we will deal with insurance directly.

Thank you very much.

Regards,

Jessica Shastri

Admin Executive – Insurance Claims

Eurokars Group of Companies

(Porsche, Rolls Royce, Saab, Mini, Mazda, Mc.Laren)

Eurokars Centre

12 Sungei Kadut Avenue

Singapore 729648

Tel: +65 63633003

DID: +65 63602863

Fax: +65 63602899

From: Jessica Harry Shastri

Sent: Tuesday, January 16, 2018 11:33 AM

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Catherine Thia Shi Yi

Date: 20 Mar 2018

Preliminary Advice

Insured Vehicle No : FBJ7086E

TP Vehicle No : SLL3657E

Make : MINI COOPER S CLUBMAN

Date of Inspection : 28/11/2017

Inspection At : EUROKARS HABITAT PTE LTD (HQ)
12 SUNGEI KADUT AVENUE
SINGAPORE 729648

Accident Date : 23/11/2017

Assignment Date : 28/11/2017

Est. Duration of Repair : 6.00

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	12,376.74
Revised Amount	:S\$	9,649.22
Check Items (Estimated)	:S\$	0.00
Total	:S\$	9,649.22

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	23/11/2017 10:11
Date Of Accident	23/11/2017 07:30
Exact Location Of Accident	PORTDOWN ROAD NEAR FUSIONOPOLISWAY-BUS STOP 18151
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLL3657E
Insured/Policyholder	
Name Of Registered Owner	WONG NING
NRIC No	S6843871C
Email Address	NJBUCKLEY1968@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-96785955
Alternative Phone No	OTHERS-62545451

Vehicle Particulars

Manufacturer	MINI
Model	MINI CLUBMAN
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100502903-00000
Cover Note Number	

Driver

Name of Driver	WONG NING
NRIC No	S6843871C
Date Of Birth	18/11/1968
Occupation	INDOOR
Date Of Driving Pass	17/06/1987
Driving Experience	30 YEARS AND 5 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-96785955
Fax Number	
Contact Number	OTHERS-62545451
EMail Address	NJBUCKLEY1968@HOTMAIL.COM

Address	96 TREVOSE CRESCENT
Postcode	297746
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN & STATEMENT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	FBJ7086E
Vehicle Make/Model/Colour	
Details Of Properties	
Name of Driver	NUR KHAIRINA BINTE KHALID
NRIC/Passport Number	S9542933E
Contact Number	81615344
Address	
Postcode	
Insurance Company Name	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Nature Of Damage	
No. Of Passenger (Including Driver)	

Details of Witness

Name	
Phone Number	
Email Address	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "**Personal Information**") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "**Insurers**"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "**Purposes**")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time:

23/11/17

9:25am.

Driver's Signature

(If driver is not the policyholder)


Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Accident happened at bus stop 18151. I (driver of SLL3657E) was driving on Portsdown Road, saw that there were cars stationary at traffic light ahead (and there was a bus at the bus stop) ^{and} so stopped just before the yellow box. Then motorcyclist of FBS7086E collided into ~~my~~ right rear of ^{my} car. She fell on the road to the ~~left~~ right ^{rear} of my car. There is a double white line divider on that road. She said that she did not see that there was a big yellow box in front of me and therefore did not anticipate me stopping. She said she was right behind me.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

23/11/17.

9:25am.

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S6843871C

Name

WONG NING

Race

CHINESE

Date of Birth

10-11-1968

Country of Birth

SINGAPORE

Sex

F

S-6843871C



REPUBLIC OF SINGAPORE



1837516



NRIC No. S6843871C



Blood Group Date of Issue

B+ 29-03-1994

REPUBLIC OF SINGAPORE
SINGAPORE

NRIC No: S6843871C

Date: 25/07/2011

No: 6846220

Class 3 Motor Cycle and Motor Transport Specialist of
which collection does not extend to the person

17-Jun-1997

NP 428A





CERTIFICATE OF INSURANCE

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

MLX1

MINI AUTO PROTECTOR

CERTIFICATE NO. 2100502903-00000

OWN DAMAGE EXCESS S\$1000.00 (1)
WINDSCREEN EXCESS S\$100.00

(Windscreen excess is waived if the repair is done at Eurokars Centre)

SUM INSURED Market Value
INSURING WITH COE/PARF Yes

SLL3657E

1) VEHICLE REGISTRATION NO.

Wong Ning

2) NAME OF INSURED

22 Feb 2017

3) EFFECTIVE DATE OF THE COMMENCEMENT
OF INSURANCE FOR THE PURPOSES OF THE ACT

4) DATE OF EXPIRY OF INSURANCE

21 Feb 2018

5) PERSON OR CLASSES OF PERSONS ENTITLED TO DRIVE *

SUBJECT TO AGE CONDITION : All Age Condition

a) The Insured.

b) Any other person who is driving on the Insured's order or with his permission.

This policy will indemnify the insured or any authorised driver only if he/she meets the age conditions.

A Young and/or Inexperienced Driver Excess ("YIDR") of S\$3,000.00, in addition to the Policy Excess, applies to You and any Authorised Driver (named or unnamed) if You are or the said Authorised Driver is below the age of 23 and/or has less than 2 years' driving experience.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6) LIMITATION AS TO USE *

Use only for social, domestic and pleasure purposes and for the Insured's business.

The Policy does not cover use for hire or rewards, tuition, driving test, racing, pace-making, reliability trial speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.

APPROVED REPORTING CENTRES / MINI AUTHORISED REPAIRERS

1. Eurokars Centre - 12 Sungai Kadat Avenue (Tel: 6363 3603)

APPROVED REPORTING CENTRES / AIG AUTHORISED REPAIRERS (FOR CLAIMS-RELATED REPAIRS)

2. ComfortDelgro Engrg - 205 Braddell Rd (Tel: 63837118) 3. DPS Body & Paint Workshop - 209 Pandan Gardens (Tel: 65684501)

4. Ethoz - 30 Bukit Batok Cres (Tel: 66547777) 5. Glass-Fix - 52 Ubi Ave 3 (Tel: 62780887) - For windscreen only

6. Kan Fook Sing Motor - 61 Defu Lane 12 (Tel: 67479560) 7. Lai Huat (Meng Kee) Motor - 21 Sin Ming Ind (Tel: 64538110)

8. Mova Automotive - 1008 Bukit Merah Lane 3 (Tel: 62723892) 9. Progressive Automotive - 3022A Ubi Rd 1 (Tel: 67415336)

10. SME Motor - 1 Kaki Bukit Ave 6 Blk D (Tel: 67476106)

LOSS OF USE Loss of Use 15 Days (1500 - 1600cc) - Refer to policy wordings for details

NAMED DRIVER NA

HIRE PURCHASE COMPANY NA
/ EMPLOYER'S LOAN

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

I / We hereby Certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

Issued At Singapore 28 Feb 2017

AIG Asia Pacific Insurance Pte. Ltd.

503599-140
ARF (AP) PTE LTD - MINI
7 MAXWELL ROAD #01-100 ANNEX B MND
COMPLEX SINGAPORE 069111

AUTHORISED REPRESENTATIVE

ORIGINAL

SSCFKJ

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-17-175418

Date of Request: 23/11/2017

Your Ref No: Online Purchase

Eurokars Habitat Pte Ltd
12 Sungei Kadut Avenue
Singapore 729648

Dear Sir/Madam,

Enquiry Date 23/11/2017

Enquiry By Jessica

TP Vehicle No. FBJ7086E

Accident Date 23/11/2017

SLL 3657 E (mim)

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
FBJ7086E	MSIG Insurance (Singapore) Pte. Ltd.	23/06/2017-15/09/2018	+65 6827 7888

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.



EUROKARS HABITAT PTE LTD
NO:12 SUNGEI KADUT, SINGAPORE 729648
ESTIMATE COST OF REPAIRS



MSIG INSURANCE SINGAPORE P/L		NAME : MS WONG NING		WIP : 14710	
4 SHENTON WAY #21-01		ADDRESS : 96 TREVOSE CRESCENT		EXCESS :	
SGX CENTRE 2		SINGAPORE 297746		DATE : 23-Nov-17	
SINGAPORE 068807		TEL : 96785955			
ATTN. : MOTOR CLAIMS					
FAX :					
VEH NO :	SLL3657E	DATE IN :		CONTACT PERSON :	JOBI THOMAS 6360 2446
CHASSIS NO :	WMWLN720702F25470	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM
MODEL :	MINI CLUBMAN F54	DATE REG.:	22-Feb-17	POLICY NO. :	

NATURE OF WORKS

S/NO	Parts Description	QTY		REVISED	PRICES
1	REAR BUMPER ✓ Deform	1	M51.12.7.422.840	✓	\$ 892.68
2	REAR BUMPER SENSOR HOLDER LH ✓ NEC	1	M51.77.7.381.965	✓	\$ 21.42
3	REAR BUMPER SENSOR HOLDER RH ✓ NEC	1	M51.77.7.381.966	✓	\$ 21.42
4	REAR BUMPER GRILL RH ✓ Deform.	1	M51.12.7.407.934	✓	\$ 49.08
5	REAR BUMPER SPOILER ✓ Cut	1	M51.12.7.381.214	✓	\$ 242.46
6	REAR BUMPER GUIDE RH ✓ NEC	1	M51.12.7.348.902	✓	\$ 102.00
7	REAR BUMPER BREATHER COVER RH ✓ NEC	1	M51.12.7.432.950	✓	\$ 18.30
8	REAR BUMPER CLIP ✓	2	B07.14.7.222.908	✓	\$ 3.84
9	REAR BUMPER GROMMET ✓	2	B51.12.7.020.321	✓	\$ 2.40
10	REAR BUMPER GASKET RING ✓	6	B51.12.7.256.354	✓	\$ 12.96
11	REAR BUMPER EXPANDING RIVET ✓ NEC	4	M51.11.1.908.077	✓	\$ 2.40
12	REAR BUMPER CLIP UPPER ✓	2	B51.49.7.207.958	✓	\$ 9.96
13	REAR BUMPER RIVET ✓	4	B63.12.1.374.075	✓	\$ 2.64
14	REAR WHEEL ARCH RH X AN	1	M51.77.7.348.904		\$ 95.28
15	TAILLAMP GASKET ✓ NEC	2	M63.21.7.447.488	✓	\$ 18.00
16	TAIL LIGHT RH ✓ CRK.	1	M63.21.7.352.156	✓	\$ 480.48
17	REAR BUMPER FOG LAMP RH X AN	1	M63.21.7.352.158		\$ 161.82
18	ULTRASONIC SENSOR GASKET ✓ NEC	4	B66.20.9.283.203	✓	\$ 23.76
19	ULTRASONIC SENSOR ✓ DMG	1	B66.20.9.274.428	✓	\$ 291.18
20	"MAN" EMBLEM ✓ NEC	1	M51.44.7.376.044	✓	\$ 62.28
21	"COOPER S" EMBLEM ✓ NEC	1	M51.14.2.755.618	✓	\$ 62.28
22	SPORT RIM RH ✓ Cut.	1	M36.11.6.856.050	✓	\$ 1,069.68
23	SPORT RIM CAP RH X AN	1	M36.13.6.857.149		\$ 30.42
TOTAL PARTS					\$ 3,676.74
					\$ -
TOTAL PARTS COST					\$ 3,676.74
Labour Description					
					✓ 1680
1	TO REPLACE REAR BUMPER, TO REPAIR REAR FENDER RH AND ALL AREAS AFFECTED BY THE ACCIDENT.	840/day			\$ 2,520.00
					✓ 2400
2	TO RESPRAY REAR BUMPER, REAR SPLIT DOOR RH AND REAR FENDER RH.	800/panel			\$ 2,700.00

3	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING AREAS. X		\$ 350.00
		✓	150
4	TO CARRY-OUT BODY CAVITY PRESERVATION.		\$ 250.00
5	TO REMOVE & REFIT CARPET & TRIMS ON THE REAR SECTION TO GIVE WAY TO THE REPAIR ON THE REAR SECTION. X		\$ 500.00
		✓	420
6	TO TRANSFER THE REVERSE SENSORS.		\$ 500.00
7	TO TRANSFER THE REVERSE CAMERA.	✓	\$ 420 500.00
8	TO MOUNT 1 PC SPORT RIM AND CONDUCT WHEEL BALANCING.	NETT ✓	\$ 120.00 ✓
9	TO CHECK STEERING GEOMETRY & CONDUCT FULL WHEEL ALIGNMENT.	NETT ✓	\$ 560.00 ✓
10	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	✓	180 \$ 250.00
11	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	✓	\$ 350.00 280
12	SUNDRIES.	NETT ✓	\$ 50 100.00
		TOTAL LABOUR	\$ - \$ 8,700.00
		TOTAL PARTS	\$ - \$ 3,676.74
		TOTAL	\$ - \$ 12,376.74
		LESS EXCESS	\$ - \$ -
		TOTAL AFTER EXCESS	\$ -
		GST 7%	\$ - \$ -
		GRAND TOTAL	\$ - \$ -

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT.

TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400.00 WILL BE APPLY AS ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

Sebastian. 28/11/2017.
 - Part by part repair.
 - Photo before paint.
 - Question mark Item Photo.

90036121

Sebastianyang@lkkauto.com.

6 days.

<p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company <p>Acknowledged by Repairer Signature: Date:</p>
--

<p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company <p>Acknowledged by Repairer Signature: Date:</p>
--



EUROKARS HABITAT PTE LTD
NO:12 SUNGEI KADUT, SINGAPORE 729648
FINALIZATION COST OF REPAIRS



MSIG INSURANCE SINGAPORE P/L		NAME : MS WONG NING		WIP : 14710	
4 SHENTON WAY #21-01		ADDRESS : 96 TREVOSE CRESCENT		EXCESS :	
SGX CENTRE 2		SINGAPORE 297746		DATE: 23-Nov-17	
SINGAPORE 068807		TEL : 96785955			
ATTN. : MOTOR CLAIMS		FAX :			
VEH NO :	SLL3657E	DATE IN :		CONTACT PERSON :	JOBI THOMAS 6360 2446
CHASSIS NO :	WMWLN720702F25470	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM
MODEL :	MINI CLUBMAN F54	DATE REG.:	22-Feb-17	POLICY NO. :	
NATURE OF WORKS					
S/NO	Parts Description			REVISED	PRICES
		QTY			
1	REAR BUMPER	1	M51.12.7.422.840	\$ 892.68	\$ 892.68
2	REAR BUMPER SENSOR HOLDER LH	1	M51.77.7.381.965	\$ 21.42	\$ 21.42
3	REAR BUMPER SENSOR HOLDER RH	1	M51.77.7.381.966	\$ 21.42	\$ 21.42
4	REAR BUMPER GRILL RH	1	M51.12.7.407.934	\$ 49.08	\$ 49.08
5	REAR BUMPER SPOILER	1	M51.12.7.381.214	\$ 242.46	\$ 242.46
6	REAR BUMPER GUIDE RH	1	M51.12.7.348.902	\$ 102.00	\$ 102.00
7	REAR BUMPER BREATHER COVER RH	1	M51.12.7.432.950	\$ 18.30	\$ 18.30
8	REAR BUMPER CLIP	2	B07.14.7.222.908	\$ 3.84	\$ 3.84
9	REAR BUMPER GROMMET	2	B51.12.7.020.321	\$ 2.40	\$ 2.40
10	REAR BUMPER GASKET RING	6	B51.12.7.256.354	\$ 12.96	\$ 12.96
11	REAR BUMPER EXPANDING RIVET	4	M51.11.1.908.077	\$ 2.40	\$ 2.40
12	REAR BUMPER CLIP UPPER	2	B51.49.7.207.958	\$ 9.96	\$ 9.96
13	REAR BUMPER RIVET	4	B63.12.1.374.075	\$ 2.64	\$ 2.64
14	REAR WHEEL ARCH RH	1	M51.77.7.348.904	\$ -	\$ 95.28
15	TAILLAMP GASKET	2	M63.21.7.447.488	\$ 18.00	\$ 18.00
16	TAIL LIGHT RH	1	M63.21.7.352.156	\$ 480.48	\$ 480.48
17	REAR BUMPER FOG LAMP RH	1	M63.21.7.352.158	\$ -	\$ 161.82
18	ULTRASONIC SENSOR GASKET	4	B66.20.9.283.203	\$ 23.76	\$ 23.76
19	ULTRASONIC SENSOR	1	B66.20.9.274.428	\$ 291.18	\$ 291.18
20	"MAN" EMBLEM	1	M51.44.7.376.044	\$ 62.28	\$ 62.28
21	"COOPER S" EMBLEM	1	M51.14.2.755.618	\$ 62.28	\$ 62.28
22	SPORT RIM RH	1	M36.11.6.856.050	\$ 1,069.68	\$ 1,069.68
23	SPORT RIM CAP RH	1	M36.13.6.857.149	\$ -	\$ 30.42
TOTAL PARTS				\$ 3,389.22	\$ 3,676.74
				\$ -	
TOTAL PARTS COST				\$ 3,389.22	\$ 3,676.74
Labour Description					
1	TO REPLACE REAR BUMPER. TO REPAIR REAR FENDER RH AND ALL AREAS AFFECTED BY THE ACCIDENT.			\$ 1,680.00	\$ 2,520.00
2	TO RESPRAY REAR BUMPER, REAR SPLIT DOOR RH AND REAR FENDER RH.			\$ 2,400.00	\$ 2,700.00

3	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING AREAS.	\$ -	\$ 350.00
4	TO CARRY-OUT BODY CAVITY PRESERVATION.	\$ 150.00	\$ 250.00
5	TO REMOVE & REFIT CARPET & TRIMS ON THE REAR SECTION TO GIVE WAY TO THE REPAIR ON THE REAR SECTION.	\$ -	\$ 500.00
6	TO TRANSFER THE REVERSE SENSORS.	\$ 420.00	\$ 500.00
7	TO TRANSFER THE REVERSE CAMERA.	\$ 420.00	\$ 500.00
8	TO MOUNT 1 PC SPORT RIM AND CONDUCT WHEEL BALANCING.	\$ 120.00	\$ 120.00
9	TO CHECK STEERING GEOMETRY & CONDUCT FULL WHEEL ALIGNMENT.	\$ 560.00	\$ 560.00
10	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	\$ 180.00	\$ 250.00
11	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	\$ 280.00	\$ 350.00
12	SUNDRIES.	\$ 50.00	\$ 100.00
		TOTAL LABOUR	\$ 6,260.00 \$ 8,700.00
		TOTAL PARTS	\$ 3,389.22 \$ 3,676.74
		TOTAL	\$ 9,649.22 \$ 12,376.74
		LESS EXCESS	\$ - \$ -
		TOTAL AFTER EXCESS	\$ 9,649.22
		GST 7%	\$ 675.45 \$ -
		GRAND TOTAL	\$ 10,324.67 \$ -

NUMBER OF DAYS: 6 WORKING DAYS(EXCLUDE WAITING FOR SURVEY,AUTHORIZATION,PARTS, SAT,SUN,PH)

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	23 Nov 2017		28 Nov 2017 09:51 Edit Adj Rpt	S\$9,649.22 Edit Estimates	S\$9,649.22 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	-----------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	NUR KHAIRINA BINTE KHALID, ID: S9542933E		
Main Claimant:	WONG NING, ID: S6843871C		
Vehicle Reg. No.:	SLL3657E	Date of Loss:	23/11/2017 07:00 - :59
Claim Type:	TP / MSC/V/17-001848	Policy/Cover Note No.:	MSD/VMS/17-366831-C (TP, Fire & Theft) Coverage: 23/06/2017 - 15/09/2018
Vehicle Reg. No. (Insured):	FBJ7086E	Policy No. (Claimant):	
		Excess:	
Repairer:	Eurokars Habitat Pte Ltd (HQ) 12 Sungei Kadut Avenue, 729648 Sungei Kadut - Tel: 63602845		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Catherine Thia Shi Yi - 6594 2545]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Sebastian Yeang Wai Keen] ... [Final Rpt due 28/12/2017]		
Driver/Custodian (Insured):	NUR KHAIRINA BINTE KHALID (/ Female), NRIC: S9542933E		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS ☐
[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLL3657E (MSC/V/17-001848)**
[FBJ7086E]
TP
WONG NING
Nov 23 2017 7:00AM
[NUR KHAIRINA BINTE KHALID]
Eurokars Habitat Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View [View in Browser](#)

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	20/03/18 15:48	Adjuster Immediate Advice	1	Load HTM	

Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	20/03/18 15:48	General View	1	Load JPG	<input checked="" type="checkbox"/>
2	20/03/18 15:48	General View	1	Load JPG	<input checked="" type="checkbox"/>
3	20/03/18 15:48	General View	1	Load JPG	<input checked="" type="checkbox"/>
4	20/03/18 15:48	General View	1	Load JPG	<input checked="" type="checkbox"/>
5	20/03/18 15:48	General View	1	Load JPG	<input checked="" type="checkbox"/>
6	20/03/18 15:48	General View	1	Load JPG	<input checked="" type="checkbox"/>
7	20/03/18 15:48	General View	1	Load JPG	<input checked="" type="checkbox"/>
8	20/03/18 15:48	General View	1	Load JPG	<input checked="" type="checkbox"/>
9	20/03/18 15:48	General View	1	Load JPG	<input checked="" type="checkbox"/>
10	20/03/18 15:48	General View	1	Load JPG	<input checked="" type="checkbox"/>
11	20/03/18 15:48	General View	1	Load JPG	<input checked="" type="checkbox"/>
12	20/03/18 15:48	General View	1	Load JPG	<input checked="" type="checkbox"/>
13	20/03/18 15:48	General View	1	Load JPG	<input checked="" type="checkbox"/>
14	20/03/18 15:48	General View	1	Load JPG	<input checked="" type="checkbox"/>
15	20/03/18 15:48	General View	1	Load JPG	<input checked="" type="checkbox"/>
16	20/03/18 15:48	General View	1	Load JPG	<input checked="" type="checkbox"/>
17	20/03/18 15:48	General View	1	Load JPG	<input checked="" type="checkbox"/>
18	20/03/18 15:48	General View	1	Load JPG	<input checked="" type="checkbox"/>
19	20/03/18 15:48	General View	1	Load JPG	<input checked="" type="checkbox"/>
20	20/03/18 15:48	General View	1	Load JPG	<input checked="" type="checkbox"/>
21	20/03/18 15:48	General View	1	Load JPG	<input checked="" type="checkbox"/>
22	20/03/18 15:48	General View	1	Load JPG	<input checked="" type="checkbox"/>
23	20/03/18 15:48	General View	1	Load JPG	<input checked="" type="checkbox"/>
24	20/03/18 15:48	General View	1	Load JPG	<input checked="" type="checkbox"/>
25	20/03/18 15:48	General View	1	Load JPG	<input checked="" type="checkbox"/>
26	20/03/18 15:48	General View	1	Load JPG	<input checked="" type="checkbox"/>

Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	24/11/17 16:49	Third Party Estimate & TP GIA Report	1	Load PDF	
2	28/11/17 10:04	Request for PRI	1	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div><div></div><div>^</div><div>v</div></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG17022599/SRBE2

Date: 22/03/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	MSD/VMS/17-366831-C
Claimant Vehicle No :	SLL3657E	Insured Vehicle No :	FBJ7086E
Date of Loss:	23/11/2017	Nature of Claim:	TP
		Claim No:	MSC/V/17-001848

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLL3657E		
Make & Model:	MINI COOPER S CLUBMAN, 1.6 A/T ABS AIRBAG (A)	Engine No:	F923H380B48A20A
Reg. Date:	22/02/2017 (Man. Year: 2017)	Chassis No:	WMWLN720702F25470
Colour:	Brown	Odometer:	7624 km
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/40 R18	Rear Tyre Size:	225/40 R18
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,776.74	3,439.22	337.52	8.94
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,600.00	6,210.00	2,390.00	27.79
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	12,376.74	9,649.22	2,727.52	22.04
+ GST 7.00/7.00% (\$\$)	866.37	675.45	190.92	22.04
Nett Amount (\$\$)	13,243.11	10,324.67	2,918.44	22.04

INSPECTION

Date of Assignment:	28/11/2017	
Date Inspected:	28/11/2017	Inspected At: Eurokars Habitat Pte Ltd (HQ) 12 Sungei Kadut Avenue Singapore 729648
Estimated Period of Repair:	6.0 days	

Adjuster: Sebastian Yeang Wai Keen

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG **Version:** 1.0 (Last Synchronised: 22 Mar 2018)

Parts: 144 **MINI COOPER S CLUBMAN 1.6 A/T ABS AIRBAG (A)** (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLL3657E)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	892.68 F	*892.68 F
2	1		*REAR BUMPER SENSOR HOLDER LH	Necessary	21.42 F	*21.42 F
3	1		*REAR BUMPER SENSOR HOLDER RH	Necessary	21.42 F	*21.42 F
4	1		*REAR BUMPER GRILL RH	Deformed	49.08 F	*49.08 F
5	1		*REAR BUMPER SPOILER	Cut	242.46 F	*242.46 F
6	1		*REAR BUMPER GUIDE RH	Necessary	102.00 F	*102.00 F
7	1		*REAR BUMPER BREATHER COVER RH	Necessary	18.30 F	*18.30 F
8	2		*REAR BUMPER CLIP	Necessary	3.84 F	*3.84 F
9	2		*REAR BUMPER GROMMET	Necessary	2.40 F	*2.40 F
10	6		*REAR BUMPER GASKET RING	Necessary	12.96 F	*12.96 F
11	4		*REAR BUMPER EXPANDING RIVET	Necessary	2.40 F	*2.40 F
12	2		*REAR BUMPER CLIP UPPER	Necessary	9.96 F	*9.96 F
13	4		*REAR BUMPER RIVET	Necessary	2.64 F	*2.64 F
14	1		*REAR WHEEL ARCH RH	Not Necessary	95.28 F	*- F
15	2		*TAILLAMP GASKET	Necessary	18.00 F	*18.00 F
16	1		*TAIL LIGHT RH	Cracked	480.48 F	*480.48 F
17	1		*REAR BUMPER FOG LAMP RH	Not Necessary	161.82 F	*- F
18	4		*ULTRASONIC SENSOR GASKET	Necessary	23.76 F	*23.76 F
19	1		*ULTRASONIC SENSOR	Damaged	291.18 F	*291.18 F
20	1		*MAN EMBLEM	Necessary	62.28 F	*62.28 F
21	1		*COOPER S EMBLEM	Necessary	62.28 F	*62.28 F
22	1		*SPORT RIM RH	Cut	1,069.68 F	*1,069.68 F
23	1		*SPORT RIM CAP RH	Not Necessary	30.42 F	*- F
24	1		*SUNDRIES	Necessary	100.00 FS	*50.00 FS
Total Parts (S\$)					3,776.74	3,439.22

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE REAR BUMPER. TO REPAIR REAR FENDER RH AND ALL AREAS AFFECTED BY THE ACCIDENT	New	2,520.00	1,680.00
2	TO RESPRAY REAR BUMPER, REAR SPLIT DOOR RH AND REAR FENDER RH	New	2,700.00	2,400.00
3	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING AREAS	New	350.00	0.00
4	TO CARRY-OUT BODY CAVITY PRESERVATION	New	250.00	150.00
5	TO REMOVE & REFIT CARPET & TRIMS ON THE REAR SECTION TO GIVE WAY TO THE REPAIR ON THE REAR SECTION	New	500.00	0.00
6	TO TRANSFER THE REVERSE SENSORS	New	500.00	420.00
7	TO TRANSFER THE REVERSE CAMERA	New	500.00	420.00
8	TO MOUNT 1PC SPORT RIM AND CONDUCT WHEEL BALANCING	New	120.00	120.00
9	TO CHECK STEERING GEOMETRY & CONDUCT FULL WHEEL ALIGNMENT	New	560.00	560.00
10	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING	New	250.00	180.00
11	TO REPROGRAMME AFTER ACCIDENT REPAIR WORKS	New	350.00	280.00
Gross Labour Cost (\$\$)			8,600.00	6,210.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >