

ASS. REC. BY:

REF: TL /Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

QD / TP / WS / TP RES / QD RES / EVA / INV / MY

To Inspect Vehicle No: _____

at Workshop m/s Trans Cab

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 02 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: S1H05554A Yr Regn: 09, 14Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Perodua L1000 cc 1995Colour: White / Red A/C: Insured / Std / NI / NASp. Reading: 416980 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: VIFIAB215AUX 279244Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 215/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Long Long

Front: _____ Rear: _____

R/Bal. 9 mm R/Bal. 9 mmL/Bal. 9 mm L/Bal. 9 mmD.O.A. 14/11/17 D.O.I. 27/11/17

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

28/11 file pass to Carham" 11 Exp \$1500

(net \$26651.3 / 94.67%)

Date/Time, File Pass to?

☐ : Prel. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee

Transportation

S + RS \$ _____

Photos

Other

TOTAL

Report Format: _____

Lump Sum / I.B.I: (\$ _____)

18x15=270170+27050880578

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	28 Nov 2017 13:33	Cim Veh Model Changed	(205460) RENAULT LATITUDE 2.0 L DCI (A).	[A] Hiew May Fung
2	28 Nov 2017 13:33	Cim Created	Reg No: 200303878K. Acct Date: 2017/11/14. Claim Type: TP. Insurer: India International Insurance Pte Ltd (HQ). TP Insurer: AXA Insurance Pte Ltd (HQ). Workshop: Trans-cab Auto Services Pte Ltd (Ang Mo Kio)	[A] Hiew May Fung
3	28 Nov 2017 13:33	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] Hiew May Fung
4	28 Nov 2017 13:33	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2017/12/07	[A] Hiew May Fung
5	28 Nov 2017 13:33	Adj Mandate Set	Approved:0.00.Reinsp:Adj decides.	[A] Hiew May Fung
6	28 Nov 2017 13:33	Label Added	(30653):Direct Settlement.	[A] Hiew May Fung
7	28 Nov 2017 13:33	Adj Adjuster Assigned	[None] -> KENNETH KONG	[A] Hiew May Fung
8	28 Nov 2017 13:34	Cim Registration Modified	Init.Est.:1,000 - 2,000->25,000 - 30,000.	[A] Hiew May Fung
9	28 Nov 2017 13:35	Adj Rpt Initiated		[A] Hiew May Fung
10	28 Nov 2017 13:35	Cim Dtl Modified	Claimant's Name: -> -. Claimant's ID: -> -.	[A] Hiew May Fung
11	28 Nov 2017 13:35	Cim Details Notified		[A] Hiew May Fung
12	28 Nov 2017 13:36	Cim Registration Modified	Reg No:200303878K->SHC5554A.	[A] Hiew May Fung
13	29 Nov 2017 08:35	Cim Cancelled	Cancelled:SHC7141U is not insured by III. SHC7141U is insured by FCI	[I] Gabriel Wee

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
1651708	28/11/2017 13:35	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	200303878K		10.70

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	28 Nov 2017 13:33	Cim Veh Model Changed	(205460) RENAULT LATITUDE 2.0 L DCI (A).	[A] Hiew May Fung
2	28 Nov 2017 13:33	Cim Created	Reg No: 200303878K. Acct Date: 2017/11/14. Claim Type: TP. Insurer: India International Insurance Pte Ltd (HQ). TP Insurer: AXA Insurance Pte Ltd (HQ). Workshop: Trans-cab Auto Services Pte Ltd (Ang Mo Kio)	[A] Hiew May Fung
3	28 Nov 2017 13:33	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] Hiew May Fung
4	28 Nov 2017 13:33	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2017/12/07	[A] Hiew May Fung
5	28 Nov 2017 13:33	Adj Mandate Set	Approved:0.00.Reinsp:Adj decides.	[A] Hiew May Fung
6	28 Nov 2017 13:33	Label Added	(30653):Direct Settlement.	[A] Hiew May Fung
7	28 Nov 2017 13:33	Adj Adjuster Assigned	[None] -> KENNETH KONG	[A] Hiew May Fung
8	28 Nov 2017 13:34	Cim Registration Modified	Init.Est.:1,000 - 2,000->25,000 - 30,000.	[A] Hiew May Fung
9	28 Nov 2017 13:35	Adj Rpt Initiated		[A] Hiew May Fung
10	28 Nov 2017 13:35	Cim Dtl Modified	Claimant's Name: -> -, Claimant's ID: -> -.	[A] Hiew May Fung
11	28 Nov 2017 13:35	Cim Details Notified		[A] Hiew May Fung
12	28 Nov 2017 13:36	Cim Registration Modified	Reg No:200303878K->SHC5554A.	[A] Hiew May Fung
13	29 Nov 2017 08:35	Cim Cancelled	Cancelled:SHC7141U is not insured by III. SHC7141U is insured by FCI	[I] Gabriel Wee

Date From Date To Audit Type

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
1651708	28/11/2017 13:35	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	200303878K		10.70

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type	Company
Owner ID	3878K

Vehicle Details

Vehicle No.	SHC5554A
Vehicle to be Exported	Yes
Intended De-registration Date	16 Nov 2017
Vehicle Make	RENAULT
Vehicle Model	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour	Red
Manufacturing Year	2014
Engine No.	M9R8839C001979
Chassis No.	VF1ABL15AUC279244
Maximum Power Output	127.0 kW (170 bhp)
Open Market Value	\$19,998.00
Original Registration Date	15 Sep 2014
First Registration Date	15 Sep 2014
Transfer Count	0
Actual ARF Paid	\$12,498.00

Intended PARF Rebate Details

PARF Eligibility	Yes
PARF Eligibility Expiry Date	14 Sep 2022
PARF Rebate Amount	\$9,373.00

Intended COE Rebate Details

COE Expiry Date	14 Sep 2022
COE Category	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years)	8
PQP Paid	\$50,704.00
COE Rebate Amount	\$30,607.00
Total Rebate Amount	\$39,980.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 16 Nov 2017

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC 5554A - III

AAD 711-192

*Not Authored**6/1/2017 8 15 00*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHC 5554A - CANDY

VF1ABL15AUC279244

RENAULT

LATITUDE

14.11.2017

III**PART****LIST**

1	1	BUMPER COVER REAR	\$	<i>Per</i> 1,108.46 ✓
2	1	BUMPER LOWER REAR	\$	<i>Per</i> 768.84 X
3	1	BUMPER BRACKET CTR REAR	\$	<i>Per</i> 113.47 ✓
4	1	BUMEP R BRACKET SIDE RH REAR	\$	<i>Per</i> 135.97 X
5	1	BUMEP R RETAINER RH REAR	\$	<i>Per</i> 44.99 X
6	1	BUMPER REFLECTOR LH	\$	<i>Per</i> 43.61 X
7	1	BUMEP R BRACKET SIDE LH REAR	\$	<i>Per</i> 135.97 X
8	1	BUMEP R RETAINER LH REAR	\$	<i>Per</i> 44.99 ✓
9	1	ROCKER PANEL OUTER LH	\$	<i>Per</i> 987.49
10	1	FENDER PANEL REAR LH	\$	<i>Per</i> 3,299.13
11	1	WHEELARCH REAR LH	\$	<i>Per</i> 543.47
12	1	TAILLAMP LH	\$	<i>Per</i> 552.55
13	1	TAILLAMP PANEL LH	\$	<i>Per</i> 986.70
14	1	DOOR PANEL REAR LH	\$	<i>Per</i> 2,844.66
15	1	DOOR GUIDE REAR LH	\$	<i>Per</i> 176.82
16	1	DOOR HINGE UPPER LH	\$	<i>Per</i> 274.50
17	1	DOOR HINGE LOWER LH	\$	<i>Per</i> 300.55
18	1	DOOR CHECK REAR LH	\$	<i>Per</i> 203.06
19	1	DOOR LOCK REAR LH	\$	<i>Per</i> 908.75
20	1	DOOR GRAB HANDLE REAR LH	\$	<i>Per</i> 210.96
21	1	DOOR HANDLE OUTER REAR LH	\$	<i>Per</i> 126.49
22	1	DOOR HANDLE CAP REAR LH	\$	<i>Per</i> 35.52
23	1	DOOR HANDLE SEAL REAR LH	\$	<i>Per</i> 7.89
24	1	DOOR HANDLE COVER REAR LH	\$	<i>Per</i> 13.22
25	1	DOOR HANDLE MODULE REAR LH	\$	<i>Per</i> 133.60
26	1	DOOR FINISHER REAR LH	\$	<i>Per</i> 423.10
27	1	DOOR WHEATHESTRIIP REAR LH	\$	<i>Per</i> 410.66
28	1	DOOR SEAL REAR LH	\$	<i>Per</i> 162.02
29	1	DOOR WAIST SEAL OUTER REAR LH	\$	<i>Per</i> 334.69
30	1	DOOR MOULDING REAR LH	\$	<i>Per</i> 176.82
31	1	DOOR MIRROR LH	\$	<i>Per</i> 1,483.40
32	1	DOOR MIRROR GLASS LH	\$	<i>Per</i> 148.20
33	1	DOOR MIRROR BACK COVER LH	\$	<i>Per</i> 218.46
34	1	DOOR PANEL FRT LH	\$	<i>Per</i> 2,844.66

TRANS-CAB AUTO SERVICES PTE LTD

NO. 2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC 5554A - III

AAD1711-192

TOTAL	\$	20,203.67
10%	\$	2,020.37
	\$	18,183.30

Specical Nett

1	1SET	REAR BUMPER CLIP	\$	na	66.00	✓
2	1SET	BUMPER BRACKET CTR CLIP	\$	na	33.00	✓
3	1SET	BUMPER BRACKET SIDE CLIP LH RR	\$	na	10.00	✓
4	1SET	BUMPER RETAINER LH CLIP RR	\$	na	20.00	✓
5	1SET	BUMPER LOWER REAR RIVET	\$	na	22.00	✓
6	1SET	BUMPER LOWER REAR CLIP	\$	na	66.00	✓
7	1	TAILLAMP CLIP LH	\$	na	5.00	} X
8	1SET	WHEELARCH CLIP RR LH	\$	na	66.00	
9	2	REAR WINDSCREEN SELANT	\$	na	80.00	
10	1	WINDSCREEN MOULDING	\$	na	100.00	
11	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	na	100.00	
12	1	CAP HUB LH RR	\$	na	35.00	
13	1	RIM LH RR	\$	na	385.00	
14	1	TYRE LH RR	\$	na	330.00	
15	1	CAP HUB LH FRT	\$	na	35.00	
16	1	RIM LH FRT	\$	na	385.00	
17	1	TYRE LH FRT	\$	na	330.00	
18	1	DOOR STICKER "Trans-cab"	\$	na	80.00	

19	1	DOOR STICKER "Classic"	\$	na	30.00	✓
20	1	DOOR STICKER "6555-3333"	\$	na	80.00	✓

TOTAL	\$	2,258.00
TOTAL PARTS	\$	20,441.30

Putty And Spray Painting Of The Affected Portion.	\$	3,000.00	4401
To reinstall rear bumper parking sensor.	\$	170.00	601
To Rust-Proofing Of The Affected Areas.	\$	na 170.00	X
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	2,800.00	3001

TRANS-CAB AUTO SERVICES PTE LTD

AAD1711-192

NO 2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC 5554A - III

To repair and realign rear exhaust pipe.	\$	170.00	✓
Towing Fees	\$	120.00	X
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	380.00	X
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	170.00	X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	170.00	X
To check steering geometry and computer wheel alignment	\$	220.00	X
To transfer of door fittings, attachment and perform water seepage test.	\$	170.00	X
To transfer of tire, rim and on wheel balancing.	\$	170.00	X

TOTAL	\$	7,710.00
Over All Total	\$	28,151.30

(PARTS BY PARTS)

Repair Days

10 Days

2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

...To resurvey before/after spray painting

...To display damaged part(s) during resurvey

...Parts prices are subject to confirmation

...Third party survey is on a "Without Prejudice" basis

...No illegal modification(s) is allowed

...Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

...and

...company



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
TRANS-CAB AUTO SERVICES PTE LTD		Ref : CC3/TP17022608/Kma3q2		
NO.2 ANG MO KIO STREET 63SINGAPORE 569111		Date : 10-04-2018		
		Code : TP378		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	Veh. Inspected		SHC 5554A	
Policy No.	Coverage (\$)		0.00	
Claim No.	Excess (\$)		0.00	
Assign From	Assign Date		27/11/2017	
2. Vehicle Particulars & Condition				
Make & Model	RENAULT LATITUDE (A)	c.c	1995	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	VF1ABL15AUC279244	Colour	METALLIC WHITE/RED	
Odometer	416980	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	LING LONG	9 mm	
L/H Front Tyre	215/60 R16	LING LONG	9 mm	
R/H Rear Tyre	215/60 R16	LING LONG	9 mm	
L/H Rear Tyre	215/60 R16	LING LONG	9 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	14/11/2017	Inspection Date	27/11/2017	
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 5554A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BUMPER COVER REAR	BUCKLED	1,108.46	1,108.46
1	BUMPER LOWER REAR	SERVICEABLE	768.84	-
1	BRACKET BRACKET CTR REAR	SERVICEABLE	113.47	-
1	BUMPER BRACKET SIDE RH REAR	SERVICEABLE	135.97	-
1	BUMPER RETAINER RH REAR	SERVICEABLE	44.99	-
1	BUMPER REFLECTOR LH	SERVICEABLE	43.61	-
1	BUMPER BRACKET SIDE LH REAR	SERVICEABLE	135.97	-
1	BUMPER RETAINER LH REAR	DISTORTED	44.99	44.99
1	ROCKER PANEL OUTER LH	TO REPAIR SEE LABOUR	987.49	-
1	FENDER PANEL REAR LH	TO REPAIR SEE LABOUR	3,299.13	-
1	WHEELARCH REAR LH	SERVICEABLE	543.47	-
1	TAILLAMP LH	SERVICEABLE	552.55	-
1	TAILLAMP PANEL LH	SERVICEABLE	986.70	-
1	DOOR PANEL REAR LH	TO REPAIR SEE LABOUR	2,844.66	-
1	DOOR GUIDE REAR LH	SERVICEABLE	176.82	-
1	DOOR HINGE UPPER LH	TO REPAIR SEE LABOUR	274.50	-
1	DOOR HINGE LOWER LH	TO REPAIR SEE LABOUR	300.55	-
1	DOOR CHECK REAR LH	SERVICEABLE	203.06	-
1	DOOR LOCK REAR LH	TO REPAIR SEE LABOUR	908.75	-
1	DOOR GRAB HANDLE REAR LH	SERVICEABLE	210.96	-
1	DOOR HANDLE OUTER REAR LH	SERVICEABLE	126.49	-
1	DOOR HANDLE CAP REAR LH	SERVICEABLE	35.52	-
1	DOOR HANDLE SEAL REAR LH	SERVICEABLE	7.89	-
1	DOOR HANDLE COVER REAR LH	SERVICEABLE	13.22	-
1	DOOR HANDLE MODULE REAR LH	SERVICEABLE	133.60	-
1	DOOR FINISHER REAR LH	TO REPAIR SEE LABOUR	423.10	-
1	DOOR WEATHERSTRIP REAR LH	SERVICEABLE	410.66	-
1	DOOR SEAL REAR LH	SERVICEABLE	162.02	-
1	DOOR WAIST SEAL OUTER REAR LH	TO REPAIR SEE LABOUR	334.69	-

Report Ref No. CC3/TP17022608/Kma3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	DOOR MOULDING REAR LH	SERVICEABLE	176.82	-
1	DOOR MIRROR LH	SERVICEABLE	1,483.40	-
1	DOOR MIRROR GLASS LH	SERVICEABLE	148.20	-
1	DOOR MIRROR BACK COVER LH	SERVICEABLE	218.46	-
1	DOOR PANEL FRT LH	TO REPAIR SEE LABOUR	2,844.66	-
	LESS 10% DISCOUNT		-2,020.37	-115.35
			18,183.30	1,038.10
	<u>SPECIAL NETT ITEMS</u>			
1	SET REAR BUMPER CLIP (SN)	NECESSARY	66.00	66.00
1	SET BUMPER BRACKET CTR CLIP (SN)	NOT NECESSARY	33.00	-
1	SET BUMPER BRACKET SIDE CLIP LH RR (SN)	NOT NECESSARY	10.00	-
1	SET BUMPER RETAINER LH CLIP RR (SN)	NOT NECESSARY	20.00	-
1	SET BUMPER LOWER REAR RIVET (SN)	NOT NECESSARY	22.00	-
1	SET BUMPER LOWER REAR CLIP (SN)	NOT NECESSARY	66.00	-
1	TAILLAMP CLIP LH (SN)	NOT NECESSARY	5.00	-
1	SET WHEELARCH CLIP RR LH (SN)	NOT NECESSARY	66.00	-
2	REAR WINDSCREEN SELANT (SN)	NOT NECESSARY	80.00	-
1	WINDSCREEN MOULDING (SN)	NOT NECESSARY	100.00	-
1	REAR WINDSCREEN INNER SPONGE SEAL (SN)	NOT NECESSARY	100.00	-
1	CAP HUB LH RR (SN)	SERVICEABLE	35.00	-
1	RIM LH RR (SN)	SERVICEABLE	385.00	-
1	TYRE LH RR (SN)	SERVICEABLE	330.00	-
1	CAP HUB LH FRT (SN)	SERVICEABLE	35.00	-
1	RIM LH FRT (SN)	SERVICEABLE	385.00	-
1	TYRE LH FRT (SN)	SERVICEABLE	330.00	-
1	DOOR STICKER 'TRANS-CAB' (SN)	NOT NECESSARY	80.00	-
1	DOOR STICKER 'CLASSIC' (SN)	NOT NECESSARY	30.00	-
1	DOOR STICKER '6555-3333' (SN)	NOT NECESSARY	80.00	-
			2,258.00	66.00
	<u>LABOUR</u>			
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		3,000.00	440.00
	TO REINSTALL REAR BUMPER PARKING SENSOR.		170.00	60.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.	NOT NECESSARY	170.00	-

Report Ref No. CC3/TP17022608/Kma3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No: 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF ROCKER PANEL OUTER LH,FENDER PANEL REAR LH,DOOR PANEL REAR LH,DOOR HINGE UPPER LH,DOOR HINGE LOWER LH,DOOR LOCK REAR LH,DOOR FINISHER REAR LH,DOOR WAIST SEAL OUTER REAR LH AND DOOR PANEL FRT LH.		2,800.00	300.00
	TO REPAIR AND REALIGN REAR EXHAUST PIPE.	NOT NECESSARY	170.00	-
	TOWING FEES.	NOT NECESSARY	120.00	-
	TO TRANSFER OF REAR FENDER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TO TRANSFER OF FENDER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT .	NOT NECESSARY	220.00	-
	TO TRANSFER OF DOOR FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO TRANSFER OF TIRE ,RIM AND ON WHEEL BALANCING.	NOT NECESSARY	170.00	-
			7,710.00	800.00
GRAND TOTAL			28,151.30	1,904.10
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,500.00

Report Ref No. CC3/TP17022608/Kma3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.