

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC 5554A - III**AAD1711-192***Not Authored
C/Sing & 1500*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHC 5554A - CANDY

VF1ABL15AUC279244

RENAULT

LATITUDE

14.11.2017

III**PART****LIST**

1	1	BUMPER COVER REAR	\$	<i>Rn</i> 1,108.46 ✓
2	1	BUMPER LOWER REAR	\$	<i>Sn</i> 768.84 X
3	1	BUMPER BRACKET CTR REAR	\$	<i>Sn</i> 113.47 ✓
4	1	BUMEPR BRACKET SIDE RH REAR	\$	<i>Sn</i> 135.97 X
5	1	BUMEPR RETAINER RH REAR	\$	<i>Sn</i> 44.99 X
6	1	BUMPER REFLECTOR LH	\$	<i>Sn</i> 43.61 X
7	1	BUMEPR BRACKET SIDE LH REAR	\$	<i>Sn</i> 135.97 X
8	1	BUMEPR RETAINER LH REAR	\$	<i>Rn</i> 44.99 ✓
9	1	ROCKER PANEL OUTER LH	\$	<i>Rn</i> 987.49
10	1	FENDER PANEL REAR LH	\$	<i>Rn</i> 3,299.13
11	1	WHEELARCH REAR LH	\$	<i>Sn</i> 543.47
12	1	TAILLAMP LH	\$	<i>Sn</i> 552.55
13	1	TAILLAMP PANEL LH	\$	<i>Rn</i> 986.70
14	1	DOOR PANEL REAR LH	\$	<i>Rn</i> 2,844.66
15	1	DOOR GUIDE REAR LH	\$	<i>Sn</i> 176.82
16	1	DOOR HINGE UPPER LH	\$	<i>Rn</i> 274.50
17	1	DOOR HINGE LOWER LH	\$	<i>Rn</i> 300.55
18	1	DOOR CHECK REAR LH	\$	<i>Sn</i> 203.06
19	1	DOOR LOCK REAR LH	\$	<i>Rn</i> 908.75
20	1	DOOR GRAB HANDLE REAR LH	\$	<i>Sn</i> 210.96
21	1	DOOR HANDLE OUTER REAR LH	\$	<i>Sn</i> 126.49
22	1	DOOR HANDLE CAP REAR LH	\$	<i>Sn</i> 35.52
23	1	DOOR HANDLE SEAL REAR LH	\$	<i>Sn</i> 7.89
24	1	DOOR HANDLE COVER REAR LH	\$	<i>Sn</i> 13.22
25	1	DOOR HANDLE MODULE REAR LH	\$	<i>Sn</i> 133.60
26	1	DOOR FINISHER REAR LH	\$	<i>Rn</i> 423.10
27	1	DOOR WHEATHESTRIP REAR LH	\$	<i>Sn</i> 410.66
28	1	DOOR SEAL REAR LH	\$	<i>Sn</i> 162.02
29	1	DOOR WAIST SEAL OUTER REAR LH	\$	<i>Rn</i> 334.69
30	1	DOOR MOULDING REAR LH	\$	<i>Sn</i> 176.82
31	1	DOOR MIRROR LH	\$	<i>Sn</i> 1,483.40
32	1	DOOR MIRROR GLASS LH	\$	<i>Sn</i> 148.20
33	1	DOOR MIRROR BACK COVER LH	\$	<i>Sn</i> 218.46
34	1	DOOR PANEL FRT LH	\$	<i>Rn</i> 2,844.66

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC 5554A - III**AAD1711-192**

TOTAL	\$	20,203.67
10%	\$	2,020.37
	\$	18,183.30

Specical Nett

1	1SET	REAR BUMPER CLIP	\$	<i>na</i>	66.00	✓
2	1SET	BUMPER BRACKET CTR CLIP	\$	<i>na</i>	33.00	×
3	1SET	BUMEPR BRACKET SIDE CLIP LH RR	\$	<i>na</i>	10.00	×
4	1SET	BUMEPR RETAINER LH CLIP RR	\$	<i>na</i>	20.00	×
5	1SET	BUMPER LOWER REAR RIVET	\$	<i>na</i>	22.00	×
6	1SET	BUMPER LOWER REAR CLIP	\$	<i>na</i>	66.00	×
7	1	TAILLAMP CLIP LH	\$	<i>na</i>	5.00	} X
8	1SET	WHEELARCH CLIP RR LH	\$	<i>na</i>	66.00	
9	2	REAR WINDSCREEN SELANT	\$	<i>na</i>	80.00	
10	1	WINDSCREEN MOULDING	\$	<i>na</i>	100.00	
11	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	<i>na</i>	100.00	
12	1	CAP HUB LH RR	\$	<i>sn</i>	35.00	
13	1	RIM LH RR	\$	<i>sn</i>	385.00	
14	1	TYRE LH RR	\$	<i>sn</i>	330.00	
15	1	CAP HUB LH FRT	\$	<i>sn</i>	35.00	
16	1	RIM LH FRT	\$	<i>sn</i>	385.00	
17	1	TYRE LH FRT	\$	<i>sn</i>	330.00	
18	1	DOOR STICKER "Trans-cab"	\$	<i>na</i>	80.00	
19	1	DOOR STICKER "Classic"	\$	<i>na</i>	30.00	×
20	1	DOOR STICKER "6555-3333"	\$	<i>na</i>	80.00	×

TOTAL	\$	2,258.00
TOTAL PARTS	\$	20,441.30

Putty And Spray Painting Of The Affected Portion.

\$ 3,000.00 *4401*

To reinstall rear bumper parking sensor.

\$ 170.00 *601*

To Rust-Proofing Of The Affected Areas.

\$ *na* 170.00 XPanel Beating, Knocking And Straightening
The Necessary Portion, Remove And Renewal
Of Parts, Adjust And Realign The Same\$ 2,800.00 *3001*

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC 5554A - III**AAD1711-192**

To repair and realign rear exhaust pipe.	\$	<i>nn</i> 170.00	X
Towing Fees	\$	<i>nn</i> 120.00	X
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	<i>nn</i> 380.00	X
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	<i>nn</i> 170.00	X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	<i>nn</i> 170.00	X
To check steering geometry and computer wheel alignment	\$	<i>nn</i> 220.00	X
To transfer of door fittings, attachment and perform water seepage test.	\$	<i>nn</i> 170.00	X
To transfer of tire, rim and on wheel balancing.	\$	<i>nn</i> 170.00	X

TOTAL \$ 7,710.00**Over All Total \$ 28,151.30****(PARTS BY PARTS)****Repair Days****~~10~~ Days***2 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

\$

Date