

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

27-Nov-17

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHD 1047 T

1 pc	N/s mirror Assy	<i>X repair</i>	\$	590.00
		Less 10%	\$	59.00
			\$	531.00
	Sundry		\$	50.00 <i>X</i>
	To labour charge for dismantle and renew the accident damaged parts.		\$	100.00 <i>50</i>
	To putty and spray painting on mirror		\$	100.00 <i>50</i>
			\$	781.00

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

**THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE
ANY UNFORESEEN DAMAGES.**

K. L. 16/11/17

27/11/17 1355hrs.

1 Days

*PIP
After Repair photo.*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey the car after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: