



Email : darren@completevms.com.sg ()
lily@completevms.com.sg ()
lihui@completevms.com.sg ()

TAN KHENG GEE
30 BRISTOL ROAD #02-01
SINGAPORE 219860

Attention : THE OWNER
Contact : 91172927

Not Authorised
11/11/17
Recovery After Pairs

Estimate : ES006217

Date : 24/11/2017
Vehicle Num. : SLD8054D
Make/Model : HONDA SHUTTLE 1.5G-2015
Chassis/Eng# : GK81002778/L15B3533348
Accident Date : 23/11/2017
Claim No. :
Reference :
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LIST ITEMS :				
1.	1	FRONT BUMPER R/H		
2.	1	FRONT BUMPER SIDE RETAINER R/H		
3.	1	FRONT BUMPER CLIP		
4.	1	FRONT BUMPER LOWER LIP		
5.	1	FRONT SPORT RIM R/H		
6.	1	FRONT WHEEL BEARING R/H		
7.	1	FRONT KNUCKLE ARM		
8.	1	FRONT LOWER ARM		
9.	1	FRONT SHOCK ABSORBER		
10.	1	FRONT FENDER R/H		
11.	1	FRONT FENDER SPLASH SHIELD R/H		
12.	1	HEADLAMP (HID) R/H		
List TotalS\$:				5,979.90
20.00% Discount S\$:				1,195.98
				4,783.92
LABOUR :				
REMOVE & REINSTALL FRONT SUSPENSION R/H			250.00	?
COMPUTER FRONT WHEEL ALIGNMENT			90.00	60
RUST PROOFING TREATMENT			80.00	x
SPRAY PAINT DAMAGED AREA AFFECTED			780.00	50
TO PRESS OUT & IN WHEEL BEARING			60.00	?
CHANGE HEAD LAMP AND CHECK LIGHTING			65.00	?
TO KNOCK OUT AND STRAIGHTEN FRONT CHASSIS FRAME AND				
CHANGE ALL NECESSARY PARTS			980.00	30
Labour Total S\$:				2,305.00

SingDollars : Seven Thousand Eighty-Eight & Cents Ninety-Two Only

Total S\$: 7,088.92

COMPLETE VMS PTE LTD

This is only an estimate bases on our preliminary inspection and does not cover additional parts and labour time which may be required after the work has begun