



Prime Auto Claims Service Pte Ltd

GST Reg. No : 201606560M

5 Benoi Place Singapore 629926

Tel: 6861 0908 Fax: 6515 2948

Date: 28.11.2017

EQ Insurance Company Ltd
5 Maxwell Road #17-00
Tower Block MND Complex
Singapore 069110

Attn: Motor Claims Dept

RE: ESTIMATE COST OF REPAIR TO VEHICLE SHD2694T HYUNDAI AVANTE (2010)

To Supply

1)	1pc	Rear bumper	de	\$	447.00
2)	1pc	Rear bumper clip	ue	\$	30.00
3)	1pc	Rear boot lid "Hyundai" emblem	ue	\$	35.00
4)	1pc	Left tail lamp	X	\$	290.00

Sub total parts	\$	802.00
Less: 20% discount	\$	160.40
	\$	641.60

L/charges

1)	Towing charges	\$	35.00	7
2)	To repair rear boot lid, rear end panel. Remove & replace rear bumper & the above parts	\$	450.00	300
3)	To putty, respray painting rear boot lid outer, rear end panel & rear bumper	\$	650.00	400

Sub total L/charges	\$	1,135.00
Estimated total	\$	1,776.60

hence notify
the following:
after spray painting
used part(s) during resurvey
is subject to confirmation
is on a "Without Prejudice" basis
modification(s) is allowed
complementary item(s) must be resurveyed and
subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Tanjin 97495749
WP' 28/11/17 @ 1530
Resurvey after repair
Sw @ 11/11/17
3 days