

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E**28 NOV 2017**

Estimate No. : b1 44966
Date Estimated : 27/11/2017
Prepared By : Han Kwan Yong

Page No. : 1 of 1

- ESTIMATE REPAIR FOR -
Krishna s/o Supramaniam
410 Bukit Batok West Avenue 4
#02-140

Singapore 650410

- ACCOUNT - 40000
Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKV5985D	0F78687	25/09/2015	X4 xDrive 28i	0

DESCRIPTIONVALUE

To replace rear bumper & attachments including to knock out
dented area caused by the accident

1,275.00

To respray rear bumper

1,038.00

To remove old PDC assembly and
reconnect to new bumper including conduct checks for
proper function.

177.00

To check electrical wiring systems and lightings at the
rear section for proper function.

177.00

Sundries.

80.00

Total Labour 1: 2,747.00

DESCRIPTIONQTY PRICVALUE

RR BUMPER RH MOUNT

1 197.45

197.45

REAR BUMPER PANEL PRIMED (X LINE)

1 1,322.70

1,322.70

CLIP

10 1.30

13.00

Total Parts : 1,533.15

Labour 1 : 2,747.00

Parts : 1,533.15

Labour 2 : 0.00

Excess : 0.00

Total GST @ 7% : 299.61

Grand Total : 4,579.76