

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

GR 7547X

TP/AIG

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
 #07-16 AIG BUILDING
 SINGAPORE 079120

TEL: 64193000

FAX: 64153727

ATTN: Motor Claim Department

WS Ref: TP-AIG

Claim Type: Third Party

Accident Date: 27/11/2017

TP Veh Reg No: GBC6614A

Estimate No: ES1791350

Date: 28 Nov 2017

Policy No: D17MTPCVE000954

Veh Reg No: GQ7547X

Make/Model: TOYOTA LITEACE 5DRS

Chassis No: KR420027980

Engine No: 7K0239151

Reg. Date: 08/04/1999

Estimate Repair Cost to Vehicle No :GQ7547X

PAGE:1/2

Description	U/Price	Quantity	List Price SS	Amount SS
List Price				
1 RH HEAD LAMP RIM	111.86	1 PCS	111.86	✓
2 FRONT BUMPER	382.68	1 PC	382.68	✓
3 FRONT BUMPER RH SIDE RETAINER	18.00	1 PC	18.00	✓
4 FRONT BUMPER CLIPS	3.50	6 PCS	21.00	✓
5 FRONT RH FENDER	361.20	1 PC	361.20	✓
6 FRONT RH FENDER INNER SHIELD	145.30	1 PC	145.30	✓
7 FRONT RH FENDER INNER SHIELD CLIPS	3.00	6 PCS	18.00	✓
8 FRONT RH FENDER LAMP	51.30	1 PC	51.30	✓
9 FRONT WINDSCREEN GLASS	1,070.80	1 PC	1,070.80	✓
10 FRONT WINDSCREEN GLASS MOULDING	80.00	1 PC	80.00	✓
11 FRONT RH MUD FLAP	126.34	1 PCS	126.34	✓
12 FRONT RH MUD FLAP CLIPS	3.50	2 PCS	7.00	✓
13 FRONT RH DOOR	718.50	1 PC	718.50	✓
14 FRONT RH DOOR SIDE MIRROR	207.70	1 PC	207.70	✓
15 FRONT RH DOOR OUTER HANDLE	134.30	1 PC	134.30	✓
16 FRONT RH DOOR GLASS	443.40	1 PC	443.40	✓
17 FRONT RH DOOR GLASS MOULDING	109.00	1 PC	109.00	✓
18 FRONT RH DOOR TOP HINGE	78.00	1 PC	78.00	✓
19 FRONT RH DOOR BOTTOM HINGE	78.00	1 PC	78.00	✓
20 FRONT RH DOOR INNER LOCK	280.00	1 PC	280.00	X
21 FRONT RH DOOR INNER RUBBER	197.30	1 PCS	197.30	?
22 FRONT RH WINDSCREEN PILLAR	505.53	1 PC	505.53	?
23 FUEL DOOR PANEL	448.50	1 PC	448.50	✓
24 RH SLIDING DOOR	1,127.60	1 PC	1,127.60	✓
25 RH SLIDING DOOR OUTER HANDLE	165.06	1 PC	165.06	✓
26 RH SLIDING DOOR INNER BOARD	130.80	1 PCS	130.80	?
27 RH SLIDING DOOR ROLLER TRUCK	272.86	1 PCS	272.86	✓
28 RH SLIDING DOOR ROLLER	119.80	1 PCS	119.80	?
29 RH SLIDING DOOR INNER LOCK	303.00	1 PCS	303.00	?
30 REAR RH SIDE PANEL	1,147.40	1 PC	1,147.40	✓
31 REAR RH TYRE RIM	256.80	1 PCS	256.80	80.80
32 REAR RH WHEEL BEARING	100.30	1 PC	100.30	✓
33 FRONT RH TOP ARM	686.50	1 PC	686.50	?
34 FRONT RH KNUCKLE ARM	296.09	1 PC	296.09	?
35 FRONT RH WHEEL BEARING	98.30	1 PC	98.30	?
			10,298.22	
			Less 25%	2,574.56
				7,723.67

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Cheng Hoe Motor Pte Ltd

Bik 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
 78 SHENTON WAY
 #07-16 AIG BUILDING
 SINGAPORE 079120
 TEL: 64193000 FAX: 64153727
 ATTN: Motor Claim Department
 WS Ref: TP-AIG
 Claim Type: Third Party
 Accident Date: 27/11/2017
 TP Veh Reg No: GBC6614A

Estimate No: ES1791350
Date: 28 Nov 2017
Policy No: D17MTPCVE000954
Veh Reg No: GQ7547X
Make/Model: TOYOTA LITEACE 5DRS
Chassis No: KR420027980
Engine No: 7K0239151
Reg. Date: 08/04/1999

Estimate Repair Cost to Vehicle No :GQ7547X

PAGE:2/2

Description	U/Price	Quantity	List Price S\$	Amount S\$
Special Net				
36 FRONT WINDSCREEN GUM	40.00	1 PC	40.00	✓
37 ERP BRACKET	25.00	1 PC	25.00	✓
38 FRONT RH DOOR COY STICKER	20.00	1 PCS	20.00	✓
39 REAR RH TYRE	160.00	1 PC	160.00	308m
			245.00	245.00
Labour				
40 TOWING	50.00	1 LA	50.00	✓
41 REMOVE AND REFIX FRONT WINDSCREEN GLASS	120.00	1 LA	120.00	✓
42 REMOVE AND REFIX FRONT BUMPER ASSY, FRONT RH FENDER, HEAD LAMP, RH SLIDING DOOR AND ATTACHMENT, FRONT RH DOOR AND ATTACHMENT. TO CUTTING, WELDING AND RENEW FRONT RH W/SCREEN PILLAR, RH DOOR PILLAR OUTER, REAR RH SIDE PANEL. TO KNOCK AND REPAIR FRONT RH WHEEL HOUSING, REAR RH FLOOR BOARD PANEL, RH DOOR PILLAR INNER AND REALIGN THE SAME	2,500.00	1 LA	2,500.00	2100
43 REMOVE AND REFIX DASH BOARD, METER ASSY AND CHECK WIRING	250.00	1 LA	250.00	✓
44 REMOVE AND REFIX AIRCON,CHECK, VACUUM & REFILL GAS	100.00	1 LA	100.00	✓
45 PUTTY AND RESPRAY ON FRONT BUMPER, BONNET, FRONT RH FENDER, WHEEL HOUSING, FRONT RH DOOR, SLIDING DOOR, REAR RH SIDE PANEL, W/SCREEN PILLAR, DOOR PILLAR, ALL AFFECTED AREA	1,800.00	1 LA	1,800.00	1600
46 REMOVE AND REFIX TOP ROOF LINING, SEAT, CARPET ETC	120.00	1 LA	120.00	✓
47 REMOVE AND REFIX FRONT RH DOOR GLASS	60.00	1 LA	60.00	✓
48 REMOVE AND REFIX FRONT AND REAR UNDER CARRIAGE	380.00	1 LA	380.00	✓
49 TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT	60.00	1 PC	60.00	✓
50 RUSTPROOFING	100.00	1 LA	100.00	✓
			5,540.00	5,540.00
Total				S\$ 13,508.67
Add GST @ 7%				945.61
Total Amount Payable				S\$ 14,454.28

For Cheng Hoe Motor Pte Ltd


 AUTHORIZED SIGNATURE