

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559H GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E**28 NOV 2017**

Estimate No. : **b1 44389**
Date Estimated : **09/10/2017**
Prepared By : **Han Kwan Yong**

Page No. : 1 of 1

- ESTIMATE REPAIR FOR -

Vongxaiburana Teerawat
16B Shelford Road
#03-16 Shelford Suites

Singapore 286653

- ACCOUNT - 40000

Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLH8545H	5F02456	22/11/2016	X1 sDrive18i	0

DESCRIPTIONVALUE

To replace front bumper & attachments including to knock out
dented area caused by the accident

1,275.00

To respray front bumper

1,038.00

To remove old PDC assembly and
reconnect to new bumper including conduct checks for
proper function.

177.00

To check electrical wiring systems at the front section
for proper function including adjustments of headlights.

177.00

Sundries.

80.00

Total Labour 1: **2,747.00**

DESCRIPTIONQTYPRICVALUE

IMPACT ABSORBER TOP

1

40.80

40.80

FRT BUMPER PANEL PRIMED (PDC/PMA)

1

685.70

685.70

BMW PLAQUE WITH ADHESIVE FILM

1

67.80

67.80

EXPANDING RIVET

30

1.35

40.50

Total Parts : **834.80**

Labour 1 : **2,747.00**

Parts : **834.80**

Labour 2 : **0.00**

Excess : **0.00**

Total GST @ 7% : **250.73**

Grand Total : **3,832.53**