

SME MOTOR PTE LTD

1 Kaki Bukit Ave 6 #02-15, AutoBay @ Kaki Bukit, Singapore 417883

Tel: 6747 6106 (6 Lines) Fax: 6744 2368

Email: service@smemotor.com.sg Website: www.smemotor.com.sg

Co. & GST Reg. No: 201119451E

INSURER: AXA Insurance Pte Ltd (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	17/AXA/OD-551(11)
Policy No:	GA080020/1	Date of Loss:	20/11/2017
Vehicle Reg. No.:	SGB5369K	Driveable?	
Driver Age/Info:	32 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	SATIMUN BIN TARRU	Contact No:	+6586235207
Driver:	MUHAMMAD KHAIRUL AZHAR BIN SATIMUN		
Make/Model:	MITSUBISHI LANCER, 1.6 (A)	Vehicle Reg. Date:	22/12/2005
Vehicle Colour:	BLUE/BLACK		
Engine No:	4G18GT4536	Chassis No:	JMYSTCS3A6U003515
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	6		
Description of Accident/Loss	VEHICLE B SUDDENLY STOP. I COULDN'T STOP IN TIME AND HIT ONTO VEHICLE B REAR.		
Remarks:	VEHICLE IS IN WORKSHOP		
Present Location:	SME MOTOR PTE LTD (KAKI BUKIT)		

COST OF CLAIMS

	Amount
Parts	2,159.00
Miscellaneous Items	60.00
Labour	1,735.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	3,954.00
+ GST 7.00% (S\$)	276.78
Nett Amount (S\$)	4,230.78

This claim is handled by: KONG WEI SIANG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REF. AIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 28 Nov 2017)

Parts: 143 MITSUBISHI LANCER 1.6 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: SME Motor Pte Ltd/SGB5369K/28/11/2017 14:02

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BONNET X Repair	0.00	0.00	*140.00 F
2	1		*FRONT BONNET LOCK / BT	0.00	0.00	*35.00 F
3	2		*FRONT BONNET HINGE X NN	0.00	0.00	*44.00 F
4	1		*FRONT GRILLE ? ?	0.00	0.00	*140.00 F
5	4		*FRONT GRILLE CLIPS	0.00	0.00	*8.00 F
6	1		*FRONT BUMPER / De	0.00	0.00	*150.00 F
7	2		*FRONT BUMPER SIDE RETAINER / MC	0.00	0.00	*44.00 F
8	10		*FRONT BUMPER CLIPS / MC	0.00	0.00	*20.00 F
9	1		*FRONT BUMPER REINFORCEMENT / BT	0.00	0.00	*60.00 F
10	1		*FRONT BUMPER LOGO / MC	0.00	0.00	*28.00 F
11	1		*FRONT BUMPER LOWER GRILLE / BR	0.00	0.00	*40.00 F
12	1		*FRONT BUMPER CENTER GARNISH ?	0.00	0.00	*95.00 F
13	2		*FRONT HEADLAMP ?	0.00	0.00	*600.00 F
14	1		*HEADLAMP SUPPORT PANEL X Repair	0.00	0.00	*150.00 F
15	1		*AIR CON CONDENSER ?	0.00	0.00	*150.00 F
16	1		*RADIATOR ?	0.00	0.00	*160.00 F
17	1		*AIRCON MOTOR FAN ASSY X	0.00	0.00	*195.00 F
18	1		*RADIATOR FAN COWLING X } NN	0.00	0.00	*55.00 F
19	1		*AIR DUCT X	0.00	0.00	*45.00 F

F=Franchise part.

Total Parts (S\$)

2,159.00

SME Motor Pte Ltd/SGB5369K/28/11/2017 14:02. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No Qty Particulars

Amount

Miscellaneous Items

1	1	COOLANT ?	25.00
2	1	FRONT NUMBER PLATE / BT	35.00

Sub Total (S\$) 60.00

Estimates on Labour

No Particulars

Lab.Type

Amount

Labour Items

1	WIRE CHECKING	New	20.00
2	REMOVE AND REFIX AIRCON AND GAS	New	100.00
3	LTA CHARGE	New	65.00
4	LABOUR	New	400 750.00
5	PAINTING	New	600 800.00

Gross Labour Cost (S\$) 1,735.00

SME Motor Pte Ltd/SGB5369K/28/11/2017 14:02. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

4 Days.

Excess: 0

Authorised

~~Wrapster repair~~ part by not

~~After repair photos~~ before paint photos.

Em. Giam - 82880282

28/11/17

UK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts until resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: