

12/03/2007

ASS: REP BY:

REF: CS/CTI17022641 / WVB

Special Instruction:

From (Person):

Wilson

ASSIGNMENT (Office)

From (Person):

Irene Tay

of

CTI

Date/Time:

28/11/17 @ 3:20pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY / CS

To Inspect Vehicle No:

SLL1445M

Insured:

SK2 8781J

at Workshop m/s

Asia Motorsports

Tel:

6745 3811

of

15 Kedar Bukit Road 4, # 01-53, 417808

Policy No:

5088015806

Claim No:

SNM17006818C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

26/11/2017

CA / REV / REP. / REV 24 HRS

lup

29/11/2017

H.O.D. Endorsement

Date/Time:

3:42pm @ 2/11/17

Person Contacted:

Leo

Vehicle IN/OUT

Date/Time

Action/Instruction (X) Estimate

SLL1445M-X

SKJ8781J-X

18/12/17 Finalised with Wilson @ Lump Sum

Repair of #3450 / 5 Day Repair


(Red 2400, 417)

PRS

REF: ~

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect vehicle No: **SLK 1445M**
 at Workshop No: _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record): _____
 Make of Ver: _____
 (Policy Condition): _____
 Remark: **The veh had commenced its repair at the time of inspection.**
 Bal. or Market Value: _____
 IDAC Accident Report: _____ Consistent? : Yes or No
 G/A PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res: Yes or No
 Lump Sum: _____ % 3 Val: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT



Veh No: **SLK 1445M** Reg: **15/2/2017**
 Type: **M. Car** / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: **Toyota** Year: **1986**
 Colour: **Dark Brown** Insured / Std / NI / NA
 Sp. Reading: **13464** T. Radio: Insured / Std / NI / NA
 Eng. No: _____
 C. No: **ZSU 60-0088883**
 Gen. Cond: **Good** / **Fair** / Poor / Burnt
 Steering: **Inorder** / Jammed / Leaked / Burnt or
 Brake: **Inorder** / Jammed / Leaked / Burnt or
 Modi: **Nil** / S/Rim STD A/Rim or
 Tyre Size F: **235/55 R18**
 R: **235/55 A18**
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or **ECOPIA**
 Front: _____ Rear: _____
 R. Bal: **3** mm R. Bal: **3** mm
 L. Bal: **3** mm L. Bal: **3** mm
 D.O.A: _____ D.O.I: **29/1/2017**
 Survey held at: **As Above**
 Des. of Damages: Frt / Rear / O/S / **N/S** / UIC / Rooftop or
 The UIC / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

Wilson
PLS see me

4/1

RECEIVED 6 JAN 2018

Time/Time File Pass to: ☐ : Preli. Report
☐ : Final Report

Days Of Repair: **5**
 Resurvey No. of Trip: **2**

Survey Fee

Add Fee: ☐ Site Insp. \$
☐ Intern. exp. \$
☐ Tech. ins. \$
☐ Admin. \$

18/1 - typist

Report Format: **Merimen**
 Lump Sum / I.B. : **3450/p**

150
150

Survey Department Check List (Case Handler)

Reference No.: CS/CTI/7022644/Wvb
 Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all information created by the assignment team are ACCURATE.

Office Assign Form		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No	✓			
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)	✓			
C	Report Type				
C	Weekend Charges	✓			
N	Survey held at/Repairer				
C	Excess				

Surveyor (): Case handler to make sure the surveyor completed all required information.

1) Assignment Form		Y-Date	N-Date	Y-Date	N-Date
C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp. Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
N	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des. of Damages	✓			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded	✓			
---	-------------------------	---	--	--	--

Check By: VERON 18/1/18
 Case Handler Date

21/05/2014

*C: Critical *N: Non-Critical



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CS/CTI17022641/Wvb

3 ANSON ROAD #16-00

SPRINGLEAF TOWERS SINGAPORE 079909

Date : 28-11-2017



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKZ 8781J	Veh. Inspected	SLL 1445M
Policy No.	5088015806	Coverage (\$)	0.00
Claim No.	SNM17D06818C02	Excess (\$)	0.00
Assign From	MERIMEN (IRENE TAY)	Assign Date	28/11/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer		Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

5. General Information

Accident Date	26/11/2017	Inspection Date	28/11/2017
Survey held at	15 KAKI BUKIT ROAD 4# 01-53, 417808		
Repairer	ASIA MOTORSPORTS SOLUTION PTE LTD		

5a. Remarks

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Exc Sub Folder	Adj Assigned	Adj Rpt	Adj By	Adj Date	Status
Main	28 Nov 2017		28 Nov 2017 15:36 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	
Main Claimant:	SUN GAN, ID: S83629501
Vehicle Reg. No.:	SLL1445M
Claim Type:	TP / SNM17D06818C02
Vehicle Reg. No. (Insured):	SKZ8781J
Date of Loss:	26/11/2017 21:00 - :59
Policy/Cover Note No.:	DMPCSN3018361701
Policy No. (Claimant):	5088015806 CLASSIC
Excess:	\$0.00
Repairer:	Asia Motorsports Solution Pte Ltd-kaki Bukit (HQ) 15 KAKI BUKIT ROAD 4, #01-05/53 BARTLEY BIZ CENTRE, 417808 Kaki Bukit - Tel: 6745 3811
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 07/12/2017]
Adj Asg. Remarks:	PLEASE ASSIST TO CONDUCT PRS AND REVERT WITH YOUR RECOMMENDATION

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Nivitha (LKK Auto)

From: Irene Tay <irene.tay@sg.cntaiping.com>
Sent: Tuesday, 28 November, 2017 3:20 PM
To: Asia Motorsports Solution Pte Ltd; assignments@lkkauto.com;
assignments@lkkauto.com
Subject: CTP REF NO. SNM17D06818C02 AM REF NO. SLL1445M- ACCIDENT INVOLVING
SKZ8781J AND SLL1445M ON 26 NOVEMBER 2017

WITHOUT PREJUDICE

Dear Sir/Mdm,

We refer to the above matter and the email below.

Please assist to get your surveyor, Adrian Ling to liaise with Asia Motorsports.

Regards

Irene Tay

Claims Department
China Taiping Insurance (Singapore) Pte. Ltd.
3, Anson Road, #16-00
Springleaf Tower,
Singapore 079909
Co. Reg. No. 200208384E
DID: 6389-6192
Fax: 6224 7175
Email: claimsdept@sg.cntaiping.com
Email: irene.tay@sg.cntaiping.com
Website: www.sg.cntaiping.com

From: Asia Motorsports Solution Pte Ltd [mailto:asiamotorsports@hotmail.com]
Sent: Tuesday, 28 November, 2017 3:04 PM
To: Irene Tay <irene.tay@sg.cntaiping.com>; Claims Dept of CTI <claimsdept@sg.cntaiping.com>; Claims Dept of
China Taiping Insurance <e-claims@sg.cntaiping.com>
Cc: Alfred Toh <alfred.toh@sg.cntaiping.com>
Subject: Re: ACCIDENT INVOLVING SLL 1445 M & SKZ 8781 J ON 26 NOVEMBER 2017 - APPOINTMENT OF ADRIAN
LING AS SINGLE JOINT EXPERT (CTP REF NO. SNM17D06818C02)

Your Ref:

Our Ref: SLL 1445 M

28 November 2017

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00

**PROPERTY CLAIM
(WITHOUT PREJUDICE
TO: Any Personal Injury**

Attn: Claims Department

Dear Sir/Mdm,

ACCIDENT INVOLVING SLL 1445 M & SKZ 8781 J ON 26 NOVEMBER 2017 - APPOINTMENT OF ADRIAN LING AS SINGLE JOINT EXPERT

Thank you so much for your reply dated 28 November 2017. We are pleased to inform you that we are agreeable to your selection of **ADRIAN LING** as the Single Joint Expert.

In compliance with the New State Courts Practice Directions, we shall await your kind office to instruct **ADRIAN LING** (as the Single Joint Expert) to attend to the pre-repair survey of our client's damaged vehicle at our premise at 15 Kaki Bukit Road 4 #01-05/53 Bartley Biz Centre Singapore 417808.

We seek your assistance in arranging for the pre-repair survey by **30 November 2017 (Thursday), 3.30pm** so that we can commence repair on our client's damaged vehicle as soon as possible and expedite the return of the vehicle to our client.

Thank you and we hope to hear from you soonest.

Regards,

Asia Motorsports Solution Pte Ltd

6745 3811

6746 5110 (fax)

asiamotorsports@hotmail.com

From: Irene Tay <irene.tay@sg.cntaiping.com>

Sent: Tuesday, November 28, 2017 2:35 PM

To: Asia Motorsports Solution Pte Ltd

Cc: Asia Motorsports Solution Pte Ltd

Subject: CTP REF NO. SNM17D06818C02 AM REF NO. SLL1445M- ACCIDENT INVOLVING SKZ8781J AND SLL1445M ON 26 NOVEMBER 2017

Without Prejudice
Save As To Costs

Dear Sir/Mdm,

We refer to your pre-repair survey request / email.

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop.

Here are the list of surveyors ;

Tay Beng Hee
See Chew Seng
Dereck Oh Siong Wee
Kalvin Ang
Bryan Ang
Steven Foong
Adrian Ling
Marcus Chua
Kenneth Kong
Henry Ng

We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Thank you.

Regards,

Irene Tay

Claims Department
China Taiping Insurance (Singapore) Pte. Ltd.
3, Anson Road, #16-00
Springleaf Tower,
Singapore 079909
Co. Reg. No. 200208384E
DID: 6389-6192
Fax: 6224 7175
Email: claimsdept@sg.cntaiping.com
Email: irene.tay@sg.cntaiping.com
Website: www.sg.cntaiping.com

From: Tee Sunny [<mailto:sunny@wahhong.sg>]

Sent: Friday, 17 November, 2017 2:10 PM

To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>; Irene Tay <irene.tay@sg.cntaiping.com>

Cc: Wah Hong Motors (Nicholas Tee) <nicholas@wahhong.sg>; Wah Hong Motors (Michael Tee) <michael@wahhong.sg>

Subject: Re: Pre-Repairs Assessment Request for SJM9058M - Accident with SCR6656M (China Taiping) on 2017-11-12 -our case no. 171111

Hi Irene

Here are the files.

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the Insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	27/11/2017 11:16
Date Of Accident	26/11/2017 21:30
Exact Location Of Accident	JB SECOND LINK (TO SINGAPORE)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLL1445M
-----------------------------	----------

Insured/Policyholder

Name Of Registered Owner	SUN GAN
NRIC No	S8362950I
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98802861
Alternative Phone No	OFFICE-98802861

Vehicle Particulars

Manufacturer	TOYOTA
Model	HARRIER PREMIUM 2.0 CVT

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
---------------------------	--

Type Of Coverage	COMPREHENSIVE
------------------	---------------

Fleet Policy	NO
--------------	----

Policy Number	5088015806 CLASSIC
---------------	--------------------

Cover Note Number

Driver

Name of Driver	SUN GAN
NRIC No	S8362950I
Date Of Birth	18/07/1983
Occupation	INDOOR
Date Of Driving Pass	14/12/2010
Driving Experience	6 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98802861
Fax Number	
Contact Number	OFFICE-98802861
Email Address	NOEMAIL

Address	BLK 344 #02-2212 ANG MO KIO AVENUE 3
Postcode	560344
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	SLIGHT DRIZZLING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	5

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I WAS DRIVING AT JB SECOND LINK COMING BACK TO SINGAPORE. APPROACHING THE PASSPORT CHECKING, I WAS DRIVING WITHIN MY LANE. A CAR(SKZ8781J) FROM THE LEFT, SUDDENLY CUT INTO MY LANE AND HIT ONTO THE LEFT SIDE OF MY CAR. ATTENDED BY AINI

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKZ8781J
Vehicle Make/Model/Colour	HONDA CIVIC 1.8L A
Details Of Properties	
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Details of Witness

Name	
Phone Number	
Email Address	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The Issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the Insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.


8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

IDAC KAKI BUKIT (VAC)
23 Kaki Bukit Ave 4
Singapore 415933
Tel: 67416697 Fax: 67492305
Email: enquiry@idacsingapore.sg
Name:
NRIC/FIN No.:

Policyholder's Signature



Date & Time: 27 NOV 2017

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Sketch Plan #2 Pg. 1

SKETCH PLAN

SEE
ATTACHED
(SUL 1445M)

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer e-file.

DECLARATION

I/We declare the foregoing particulars are true in every respect.


Policyholder's Signature

Date & Time:

27 NOV 2017

Driver's Signature
(If driver is not the policyholder)
Date & Time:

IDAC KAKI BUKET (VAC)
23 Kaki Bukit Ave 4
Singapore 415933
Tel: 67416697 Fax: 67492305
Email: yackb@singnet.com.sg


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

26/11/2017


9.30 PM

H/P 98802861

SLL1445M



J.B
second link
was



Estimate Repair For Vehicle SLL 1445 M (Toyota Harrier)

Item Description Parts	Qty		Price list	
1 Front bumper cover X R	1	\$	1,842.80	X
2 Front bumper side bracket LH X NN	1	\$	73.60	X
3 Front fender LH ✓ DD / Bu C	1	\$	952.60	✓
4 Front fender under shield LH ✓ DIS	1	\$	232.80	✓
		\$	3,101.80	
	Less 25%	\$	775.45	1185.40
		\$	2,326.35	
S/NETT ITEM				
5 Front fender under shield clips LH ✓ NEC	1 set	\$	40.00	✓
6 Front bumper clips X NN	1 set	\$	64.00	X
7 Front sport rim LH ✓ SCR	1	\$	1,700.00	750
8 Rocker panel side skirt LH ✓ WP / DIS	1	\$	876.70	✓
Parts Total :		\$	5,007.05	1666.70

LABOUR CHARGES & MISC

9 Check lighting, focus headlight & centre locking system X NN	\$	50.00	X
10 Knock out dents front & rear rear door, repair straighten, remove & reinstall necessary fittings to facilitate. Replace LF Fender	\$	950.00	800
11 Putty & Spray painting on all affected portion.	\$	1,100.00	850
12 Anti-rust proofing on affected panel. X NN	\$	100.00	X
13 To conduct front wheel alignment & balancing	\$	120.00	✓
Labour Total :	\$	2,320.00	1770

Sub Total : \$ 7,327.05

Lump sum repair adjustment \$ 5,850.00
Estimated time required for repairs 8 days

Parts (List)	\$ 1185.40
Discount 25%	- \$ 296.35
	\$ 889.05
Part (Special Net)	\$ 1666.70
	\$ 2555.75
Labour	\$ 1770.00
	\$ 4325.75
Discount 20% (Lump Sum)	- \$ 865.15
	\$ 3460.60

* Lump Sum → \$ 3450
Repair Day → 5 Days.

** To Chk with Catherine
For the Estimate.*

Wilson (LKKAuto)

From: Admin-D (LKKAuto)
Sent: Wednesday, 20 December, 2017 1:19 PM
To: 'Asia Motorsports Solution Pte Ltd'; Wilson (LKKAuto)
Cc: SUR; assignments
Subject: RE: (Gentle Reminder) - SLL 1445 M Estimates

Dear Sir / Madam,

Thank you for your email.

Dear Wilson,

Kindly assist.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Asia Motorsports Solution Pte Ltd [<mailto:asiamotorsports@hotmail.com>]

Sent: Wednesday, 20 December, 2017 1:01 PM

To: assignments@lkkauto.com

Subject: Re: (Gentle Reminder) - SLL 1445 M Estimates

Dear Sir/Madam,

here is a reminder that we are awaiting your marked estimates for SLL 1445 M.

Thank you and we hope to hear from you soon.

Regards,

Asia Motorsports Solution Pte Ltd

6745 3811

6746 5110 (fax)

asiamotorsports@hotmail.com

From: Asia Motorsports Solution Pte Ltd <asiamotorsports@hotmail.com>

Sent: Friday, December 8, 2017 10:48 AM

To: assignments@lkkauto.com

Subject: SLL 1445 M Estimates














Dear Sir/Madam,

as requested, attached is the estimates for SLL 1445 M.

We look forward to your marked assessment.

Thank you and we hope to hear from you soon.

Regards,
Asia Motorsports Solution Pte Ltd
6745 3811
6746 5110 (fax)
asiamotorsports@hotmail.com



From: Admin-D (LKKAuto)
To: Asia Motorsports Solution Pte Ltd; Wilson (LKKAuto)
Cc: SLL; assignments
Subject: RE: (Gentle Reminder) - SLL 1445 M Estimates

Sent: Wed 20/12/2017 1:19 PM

Dear Sir / Madam,

Thank you for your email.

Dear Wilson,

Kindly assist.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Asia Motorsports Solution Pte Ltd [<mailto:asia.motorsports@hotmail.com>]
Sent: Wednesday, 20 December, 2017 1:01 PM

To: assignments@lkkauto.com

Subject: Re: (Gentle Reminder) - SLL 1445 M Estimates

Dear Sir/Madam,

here is a reminder that we are awaiting your marked estimates for SLL 1445 M.

Admin-D (LKKAuto)



...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	28 Nov 2017		28 Nov 2017 15:36 Edit Adj Rpt	S\$3,450.00 Edit Estimates	S\$3,450.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	-----------------

CLAIM SUBFOLDER DETAILS				[Created by Insurer]		
Insured:	-, Co. Reg. No.: -					
Main Claimant:	SUN GAN, ID: S8362950I					
Vehicle Reg. No.:	SLL1445M	Date of Loss:	26/11/2017 21:00 - :59			
Claim Type:	TP / SNM17D06818C02	Policy/Cover Note No.:	DMPCSN3018361701			
Vehicle Reg. No. (Insured):	SKZ8781J	Policy No. (Claimant):	5088015806 CLASSIC			
		Excess:	S\$0.00			
Repairer:	Asia Motorsports Solution Pte Ltd-kaki Bukit (HQ) 15 KAKI BUKIT ROAD 4, #01-05/53 BARTLEY BIZ CENTRE, 417808 Kaki Bukit - Tel: 6745 3811					
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]					
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:					
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Teo Cheng Ming Wilson] ... [Final Rpt due 07/12/2017]					
Adj Asg. Remarks:	PLEASE ASSIST TO CONDUCT PRS AND REVERT WITH YOUR RECOMMENDATION					

ASSOCIATED MAIL RECEIVED		View All	Compose Case Mail
There are no mail for this case.			

ALL ASSOCIATED TASKS <input type="checkbox"/>										View All	Search Tasks	Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?				
No results.													

Claim Documents

***SLL1445M (SNM17D06818C02)**

[SKZ8781J]































TP

SUN GAN

Nov 26 2017 9:00PM

[-]

Asia Motorsports Solution Pte Ltd-kaki Bukit

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
1	27/11/17 11:26	Accident Statement	 Load HTM	<input type="checkbox"/>
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
1	27/11/17 11:23	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
2	27/11/17 11:23	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
3	27/11/17 11:23	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
4	27/11/17 11:23	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
5	27/11/17 11:23	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
6	27/11/17 11:23	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	18/01/18 11:46	General View	 Load JPG	<input checked="" type="checkbox"/>
2	18/01/18 11:46	General View	 Load JPG	<input checked="" type="checkbox"/>
3	18/01/18 11:46	General View	 Load JPG	<input checked="" type="checkbox"/>
4	18/01/18 11:46	General View	 Load JPG	<input checked="" type="checkbox"/>
5	18/01/18 11:46	General View	 Load JPG	<input checked="" type="checkbox"/>
6	18/01/18 11:46	General View	 Load JPG	<input checked="" type="checkbox"/>
7	18/01/18 11:46	General View	 Load JPG	<input checked="" type="checkbox"/>
8	18/01/18 11:46	General View	 Load JPG	<input checked="" type="checkbox"/>
9	18/01/18 11:46	General View	 Load JPG	<input checked="" type="checkbox"/>
10	18/01/18 11:46	General View	 Load JPG	<input checked="" type="checkbox"/>
11	18/01/18 11:46	General View	 Load JPG	<input checked="" type="checkbox"/>
12	18/01/18 11:46	General View	 Load JPG	<input checked="" type="checkbox"/>
13	18/01/18 11:46	General View	 Load JPG	<input checked="" type="checkbox"/>
14	18/01/18 11:46	General View	 Load JPG	<input checked="" type="checkbox"/>
15	18/01/18 11:46	General View	 Load JPG	<input checked="" type="checkbox"/>
16	18/01/18 11:46	General View	 Load JPG	<input checked="" type="checkbox"/>
17	18/01/18 11:46	General View	 Load JPG	<input checked="" type="checkbox"/>
18	18/01/18 11:46	General View	 Load JPG	<input checked="" type="checkbox"/>
19	18/01/18 11:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
20	18/01/18 11:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
21	18/01/18 11:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
22	18/01/18 11:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
23	18/01/18 11:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

24	18/01/18 11:50	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
25	18/01/18 11:50	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
26	18/01/18 11:50	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
27	18/01/18 11:50	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
28	18/01/18 11:50	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
29	18/01/18 11:50	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
30	18/01/18 11:50	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
31	18/01/18 11:50	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
32	18/01/18 11:50	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
33	18/01/18 11:50	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
34	18/01/18 11:50	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
35	18/01/18 11:50	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
36	18/01/18 11:50	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
37	18/01/18 11:50	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
38	18/01/18 11:50	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
39	18/01/18 12:01	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
40	18/01/18 12:01	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
41	18/01/18 12:01	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
42	18/01/18 12:01	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
43	18/01/18 12:01	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
44	18/01/18 12:01	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
45	18/01/18 12:01	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	28/11/17 15:37	EMAIL FROM AM	1	Load PDF	
No	Finalized On	VAC (Kaki Bukit)		Thumbnail	Print
1	27/11/17 11:25	Sketch Plan [Linked Accident Report Documents]	1	Load TIF	
2	27/11/17 11:25	Sketch Plan #2 [Linked Accident Report Documents]	1	Load TIF	
3	27/11/17 11:25	Sketch Plan #3 [Linked Accident Report Documents]	1	Load TIF	

Linked Accident Report Documents

				View	View in Browser
Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Kaki Bukit)		Thumbnail	Print
1	27/11/17 11:26	Accident Statement	1	Load HTM	
Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Kaki Bukit)		Thumbnail	Print
1	27/11/17 11:23	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
2	27/11/17 11:23	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
3	27/11/17 11:23	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
4	27/11/17 11:23	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
5	27/11/17 11:23	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
6	27/11/17 11:23	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Kaki Bukit)		Thumbnail	Print
1	27/11/17 11:25	Sketch Plan	1	Load TIF	
2	27/11/17 11:25	Sketch Plan #2	1	Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

^

v

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT117022641/WVBE2

Date: 18/01/2018

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSN3018361701

Claimant Vehicle
No : SLL1445MInsured Vehicle
No : SKZ8781J

Date of Loss: 26/11/2017

Nature of Claim: TP

Claim
No: SNM17D06818C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLL1445M

Make & Model: TOYOTA HARRIER, 2.0 PREMIUM CVT (A)

Engine No: 3ZRB880214

Reg. Date: 15/02/2017 (Man. Year: 2016)

Chassis No: ZSU600088883

Colour: Dark Brown

Odometer: 13464 km

Engine Capacity: 1986 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/55 R18

Rear Tyre Size: 235/55 R18

Front Left Side: Ecopia 3 mm

Rear Left Side: Ecopia 3 mm

Front Right Side: Ecopia 3 mm

Rear Right Side: Ecopia 3 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,007.05	2,555.75	2,451.30	48.96
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,320.00	1,770.00	550.00	23.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	7,327.05	4,325.75	3,001.30	40.96
Approved Total (Overridden) (\$\$)		3,450.00		
Nett Amount (\$\$)	7,327.05	3,450.00	3,877.05	52.91

INSPECTION

Date of Assignment: 28/11/2017

Date Inspected: 29/11/2017 Inspected At:

Asia Motorsports Solution Pte Ltd-kaki
Bukit (HQ)
15 KAKI BUKIT ROAD 4, #01-05/53
BARTLEY BIZ CENTRE
Singapore 417808

Estimated Period of Repair: 5.0 days

Adjuster: Teo Cheng Ming Wilson**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 18 Jan 2018)
Parts: M1-SUV TOYOTA HARRIER 2.0 PREMIUM CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLL1445M)
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER COVER	Repair	1,842.80 FL	*- FL
2	1		*FRONT BUMPER SIDE BRACKET LH	Not Necessary	73.60 FL	*- FL
3	1		*FRONT FENDER LH	Dented / Buckled	952.60 FL	*952.60 FL
4	1		*FRONT FENDER UNDER SHIELD LH	Distorted	232.80 FL	*232.80 FL
5	1		*SET FRONT FENDER UNDER SHIELD CLIPS LH	Necessary	40.00 FS	*40.00 FS
6	1		*SET FRONT BUMPER CLIPS	Not Necessary	64.00 FS	*- FS
7	1		*FRONT SPORT RIM LH	Scratched	1,700.00 FS	*750.00 FS
8	1		*ROCKER PANEL SIDE SKIRT LH	Warped / Distorted	876.70 FS	*876.70 FS
Sub Total (S\$)					5,782.50	2,852.10
- List Item Discount on L Items 25.00/25.00% (S\$)					775.45	296.35
Total Parts (S\$)					5,007.05	2,555.75

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CHECKING LIGHTING, FOCUS HEADLIGHT & CENTRE LOCKING SYSTEM	New	50.00	0.00
2	KNOCK OUT DENTS FRONT & REAR DOOR, REPAIR STRAIGHTEN, REMOVE & REINSTALL NECESSARY FITTINGS TO FACILITATE	New	950.00	800.00
3	PUTTY & SPRAY PAINTING ON ALL AFFECTED PORTION	New	1,100.00	850.00
4	ANTI-RUST PROOFING ON AFFECTED PANEL	New	100.00	0.00
5	TO CONDUCT FRONT WHEEL ALIGNMENT & BALANCING	New	120.00	120.00
Gross Labour Cost (S\$)			2,320.00	1,770.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >