

14148 P 107 ✓

11/11/2017

ASS: REC BY

REF:

CS/CTI17022643 Mgb

Survivor

Mu.

Mehmen

ASSIGNMENT (Office)

From (Person)

Irene Tay

of

CTI

Date/Time

28/11/17 @ 3:15pm

Estimated Cost

Bill to

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.

SLH 9056X

Insured:

SKU 2807K

at Workshop m/s

EM-1 Auto

Tel:

6452 3298

of

Blk 8 Sia Ming Ind. Est. Sec. C # 01-68, 575643

Policy No:

DMPCSN3088501701

Claim No:

SNM17D06813C02

Sum Insured

Excess:

Make of Veh:

(Client's Record)

D.O.A. 27/11/2017

CA / REV / REP. / REV 24 HRS

Imp

29/11/2017

H.O.D. Endorsement

Date/Time

3:40pm @ 28/11/17

Person Contacted

Nicole

Vehicle

IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SLH 9056X -X

SKU 2807K -X

28/6/18 @

12:45pm Confirmed with Nicole vs \$2700, 13 days.

(Ref B1271, 367.)

REF: CTI

ASSIGNMENT

From: Date: 09/11/17

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / M /

To Inspect Vehicle No: SH 9056 X

at Workshop no: EM-1 Auto

of Blk 8, Sin Ming Ind. Est. Sec. C # 01-68, 57564B

Insured:

Policy No:

Claims No:

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bel. or Market Value:

IDAC Accident Report: Consistent? Yes or No

GIA / PR Seen: Consistent? Yes or No

Est. Repairs: days Res: Yes or No

Lump Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle IN / OUT

Date / Time Action / Instruction

Veh No: SH 9056 X Reg: VIC 2016

Type: M/Cat M/Cycle Bus / Van Lorry / Taxi / Prime Mover

Truck / Trailer or

Make: Deugest 3008 cc 1560

Colour: GREY E.C. Insured / Std / NI / NA

Bo Reading: 22098 T.Radio Insured / Std / NI / NA

Eng No:

Ch No: VF36 EBH7TG S14119

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size F: 205/50R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA M/C OHTSU / R/R / SUMI /

TOYO / YOKO or

Front

R.Bal: 8 mm

L.Bal: 8 mm

D.O.A. 27/10/17

Survey held at:

Des. of Damages: Front / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

RECEIVED 29 JUN 2018

DataTime File Pass to: ☐ Prel. Report29/6/2017 ☐ Final Report

DataTime File Return to:

2

Days Of Repair: 13

Resurvey No. of Trip: 1

Survey Fee:

Transporter

Lump Sum

Amount

Date

Total

Remarks

Add Fee: ☐ Site Insp: \$☐ Interview: \$☐ Technician: \$☐ Vehicle: \$

Report Format: MED-TP

Lump Sum: 21700

250



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No: 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD			Ref : CS/CTI17022643/M1qb	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909			Date : 28-11-2017	
			Code : CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKU 2807K	Veh. Inspected	SLH 9056X	
Policy No.	DMPCSN3088501701	Coverage (\$)	0.00	
Claim No.	SNM17D06813C02	Excess (\$)	0.00	
Assign From	MERIMEN (IRENE TAY)	Assign Date	28/11/2017	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	27/11/2017	Inspection Date		
Survey held at	EM-1 AUTO PTE LTD BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C #01-68 SINGAPORE 575643			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ini Auth'd	Status
Main	28 Nov 2017		28 Nov 2017 15:15 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:			
Main Claimant:	POH WAH MACHINERY & TRADING PTE LTD, Co. Reg. No.: -		
Vehicle Reg. No.:	SLH9056X	Date of Loss:	27/11/2017 10:00 - :59
Claim Type:	TP / SNM17D06813C02	Policy/Cover Note No.:	DMPCSN3088501701
Vehicle Reg. No. (Insured):	SKU2807K	Policy No. (Claimant):	8-V0016548
		Excess:	S\$0.00
Repairer:	Em-1 Auto Pte Ltd (HQ) Blk 8 Sin Ming Industrial Estate Sector C, #01-68, 575643 Sin Ming - Tel: 64523298		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]		
Claimant's Insurer:	QBE Insurance (Singapore) Pte Ltd (HQ) - Tel: 62246633		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 07/12/2017]		
Adj Asg. Remarks:	PLEASE ASSIST TO CONDUCT PRS AND REVERT WITH YOUR RECOMMENDATION		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.

Shiau Chan (LKKAUTO)

From: Chia Sin Muk <em1autopteltd@gmail.com>
Sent: Thursday, 28 June 2018 12:14 PM
To: Shiau Chan (LKKAUTO)
Cc: SUR
Subject: Re: FINALISE OF VEHICLE SLH 9056X (DOA: 27/11/2017)

WITHOUT PREJUDICE

Dear All,

Agree 21,700 / 13 days.

Thanks & Best Regards,

Nicole, on behalf of,

Chia Sin Muk (Mr)

m: (65) 9666 6556 | o: (65) 6452 3298 | f: (65) 6457 5776

EM-1 Auto Pte Ltd

Blk 8 #01-68 Sin Ming Rd Industrial Estate Sector C Singapore 575643

Co. / GST Registration Number: 201316380R

Important: This email is confidential and may be privileged. If you are not the intended recipient, please delete it and notify us immediately; you should not copy or use it for any purpose, nor disclose its contents to any other person. Thank you

On 28 June 2018 at 11:44, Shiau Chan (LKKAUTO) <siewsc@lkkauto.com> wrote:

Dear Mr Chia,

Please refer to the attachment.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shiau Chan (LKKAUTO)
Sent: Thursday, 28 June 2018 11:43 AM
To: 'Chia Sin Muk' <em1autopteltd@gmail.com>

Svy

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type

Company

Owner ID

6344N

Vehicle Details

Vehicle No.

SLH9056X

Vehicle to be Exported

Yes

Intended De-registration Date

28 Nov 2017

Vehicle Make

PEUGEOT

Vehicle Model

5008 1.6 BLUEHDI EAT6 S/R

Primary Colour

Grey

Manufacturing Year

2016

Engine No.

10JBHX3002962

Chassis No.

VF30EBHZTGS141119

Maximum Power Output

88.0 kW (118 bhp)

Open Market Value

\$23,685.00

Original Registration Date

23 Nov 2016

First Registration Date

23 Nov 2016

Transfer Count

0

Actual ARF Paid

\$15,159.00

Intended PARF Rebate Details

PARF Eligibility

Yes

PARF Eligibility Expiry Date

22 Nov 2026

PARF Rebate Amount

\$11,369.00

Intended COE Rebate Details

COE Expiry Date

22 Nov 2026

COE Category

A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years)

10

QP Paid

\$52,668.00

COE Rebate Amount

\$42,134.00

Total Rebate Amount

\$53,503.00

The information contained herein is correct as at 27 Nov 2017

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	27/11/2017 15:29
Date Of Accident	27/11/2017 10:20
Exact Location Of Accident	CTE (AYE) BEFORE BRADDELL RD EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLH9056X
Insured/Policyholder	
Name Of Registered Owner	POH WAH MACHINERY & TRADING PTE LTD
Co Reg No	- 6344N
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96367395
Alternative Phone No	OFFICE-96367395

Vehicle Particulars

Manufacturer	PEUGEOT
Model	-
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	QBE INSURANCE (SINGAPORE) PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	8-V0016548
Cover Note Number	

Driver

Name of Driver	TAN YONG YI
NRIC No	S8415612D
Date Of Birth	05/06/1984
Occupation	INDOOR
Date Of Driving Pass	26/10/2005
Driving Experience	12 YEARS AND 1 MONTH
Gender	FEMALE
Mobile Number	
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address
Postcode
Was driver an employee of the Insured's Company YES
If No, Relationship of the Driver with the Insured
Vehicle Registration Number of Driver's Own Vehicle -
Vehicle -
Insurance Company of Driver's Own Vehicle -
-

General Information of the Accident

Type Of Accident CHAIN COLLISION
Weather Conditions AFTER RAIN
Road Surface WET

Other Information

Was any foreign vehicle involved in this accident? NO
Was any body injured in the Accident? NO
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
If Yes, Please state which Police Station
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

refer attached report.

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? NO
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SKU2807K
Vehicle Make/Model/Colour
Details Of Properties
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

Details of Witness

Name
Phone Number
Email Address

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SJE3988K
Vehicle Make/Model/Colour

Details Of Properties

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**


I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time: _____


Driver's Signature
(If driver is not the policyholder)
Date & Time: _____


Reporting Centre Personnel's Signature
Name: _____
NRIC/FIN No.: _____



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was travelling along CTE towards AYE before Braddell Rd exit on lane 1. Due to the heavy traffic, front vehicle slowed down to stopped, then I follow suit (stationary). Suddenly vehicle B hit my vehicle rear portion. And due to the strong impact caused my vehicle to hit front vehicle C. I felt my arm pain caused seat belt cut my right arm. John

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Sign *John*



Policyholder's Signature
Date & Time:

John

Driver's Signature
(If driver is not the policyholder)
Date & Time:

[Signature]

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO. : 201316380R

Vehicle Number : SLH 9056X
Vehicle Model : PEUGEOT 5008
Accident Date : 27.11.2017
Original Reg Date : 23.11.2016

Date : 28.11.2017
Chassis : VF30EBHZTGS141119
TP Ins. CHINA TAIPING

ESTIMATE

1	1 pc	Tailgate	152	1,500.00
4	1 pc	Tailgate Emblem (5008)	114	100.00
5	1 pc	Tailgate Emblem (Blue HDi)	114	100.00
6	1 pc	Tailgate Outer Garnish	dis	420.00
7	1 set	Tailgate Outer Garnish Clip	114	30.00
8	2 pcs	Tailgate Number Plate Lamp	dis 65.00	130.00
9	1 pc	Tailgate Opener Switch	dis	295.00
10	1 pc	Tailgate Inner Trim	dis	620.00
11	2 pcs	Tailgate Inner Side Trim	dis 125.00	250.00
12	1 set	Tailgate Inner Trim Clips	40	40.00
13	1 pc	Tailgate Inner Lock	114	280.00
14	1 pc	Tailgate Lock Catch	114	145.00
15	1 pc	Tailgate Weatherstrip	dis	290.00
16	2 pcs	Tailgate Hinges	120.00	240.00
17	2 pcs	Tailgate Absorber	210.00	420.00
18	1 pc	Tailgate Windscreen Inner Seal		60.00
19	1 pc	Rear Bumper		1,300.00
20	2 pcs	Rear Bumper Side Retainers	85.00	170.00
21	2 pcs	Rear Bumper Attachment Retainers	95.00	190.00
22	1 set	Rear Bumper Clips		50.00
23	1 pc	Rear Bumper Center Retainers		190.00
24	1 pc	Rear Bumper Reinforcement		490.00
25	2 pcs	Rear Bumper Reinforcement Bracket	130.00	260.00
26	1 pc	Rear Bumper Towing Cover		40.00
27	4 pcs	Rear Bumper Reverse Sensor (Original)	295.00	1,180.00
28	4 pcs	Rear Bumper Reverse Sensor Holder	60.00	240.00
29	2 pcs	Rear Bumper Reverse Lamp	135.00	270.00
30	2 pcs	Rear Bumper Stopper	45.00	90.00
31	1 pc	End Panel (Outer)		950.00

C/F

10,340.00

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO. : 201316380R

Vehicle No : SLH 9056X

B/F

10,340.00

1	1 pc	End Panel Top Trim		270.00	CRA
2	1 set	End Panel Top Trim Clips		30.00	NEC
3	2 pcs	Taillamp	480.00	960.00	CRA
4	2 pcs	Taillamps Inner Seal	40.00	80.00	NEC
5	2 set	Taillamps Clips	20.00	40.00	NEC
6	2 pcs	Taillamp Side Garnish	185.00	370.00	CRA
7	2 pcs	Rear Fender Inner Trims	380.00	760.00	CRA
8	2 set	Rear Fender Inner Trims Clips	30.00	60.00	NEC
9	1 pc	Front Bumper		1,350.00	dis
10	2 pcs	Front Bumper Side Retainers	85.00	170.00	dis
11	1 set	Front Bumper Clips		40.00	NEC
12	1 pc	Front Bumper Badge		120.00	NEC
13	1 pc	Front Bumper Tow Cover		40.00	CRA
14	1 pc	Front Bumper Top Garnish		290.00	X SUC
15	1 pc	Front Bumper Reinforcement		430.00	DD
16	2 pcs	Front Bumper Reinforcement Bracket	130.00	260.00	SUC
17	1 pc	Front Bumper Center Pad		580.00	dis
18	1 pc	Front Bumper Lower Grille		320.00	dis
19	2 pcs	Front Bumper Fog Lamps	235.00	470.00	CRA
20	2 pcs	Front Bumper Fog Lamps Cover	120.00	240.00	CRA
21	1 pc	Front Bumper Fog Lamp Cover Chrome Moulding	220.00	440.00	CRA
22	1 pc	Front Grille Assy		520.00	dis
23	1 set	Front Grille Clips		30.00	NEC
24	2 pcs	Headlamps	780.00	1,560.00	CRA
25	2 set	Headlamps Clips	20.00	40.00	CRA
26	1 pc	Support Panel		690.00	CRA
27	1 pc	Support Panel Top Garnish		350.00	dis
28	1 pc	Turbo Intercooler		1,480.00	DD
29	1 pc	Air Con Condenser		1,250.00	DD
30	2 pcs	Condenser Side Garnish	110.00	220.00	CRA
31	1 pc	Condenser Side Garnish Clips		30.00	NEC
32	1 pc	Condenser Fan Motor Assy		730.00	CRA
33	1 pc	Condenser Air Con Pipe		420.00	DD
34	1 pc	Condenser Suction Pipe		400.00	CRA
35	1 pc	Condenser Discharge Pipe		380.00	CRA

C/F

25,760.00

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO. : 201316380R

Vehicle No : SLH 9056X

B/F

25,760.00

1	1 pc	Radiator		1,290.00
2	2 pcs	Front Seat Belt	570.00	1,140.00
3	2 pcs	Front Seat Belt Bucker	290.00	580.00
4	1 pc	SRS Unit Assy		1,620.00
				30,390.00
Less 10%				3,039.00
				27,351.00

Special Nett

1	1 pc	Rear Windscreen Sealant		60.00
2	1 pc	Reverse Camera		450.00
3	1 pc	Body Panel Joint Sealant		120.00
4	1 pc	Rear Number Plate with Cover		70.00
5	1 pc	Front Number Plate with Cover		70.00
6	1 pc	Radiator Coolant		40.00

Labour charge

Panel Beating	No illegal modification is allowed	2,000.00
Spray painting	Supplementary services must be resurveyed and is subject to final approval from Insurance Company	2,000.00
Check Wiring	Acknowledged by Repairer	100.00
Anti rust	Signature:	180.00
Remove and install rear windscreen.		140.00
Remove and install tailgate parts.		80.00
Remove and install reverse sensor.		80.00
Remove and install reverse camera.		150.00
Remove and install carpet and seat.		250.00
Remove and install air con.		450.00
Reprogram and reset SRS Unit		380.00
To reset and check air bag function.		180.00

\$ 33,871.00

Not Action
Lisung Repair
After Paint Photo
HCC Auto (M)
13 wday
29/11/2017

30/11/17

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	28 Nov 2017		28 Nov 2017 15:15 Edit Adj Rpt	S\$21,700.00 Edit Estimates	S\$21,700.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	- ID: -								
Main Claimant:	POH WAH MACHINERY & TRADING PTE LTD , Co. Reg. No.: -								
Vehicle Reg. No.:	SLH9056X	Date of Loss:	27/11/2017 10:00 - :59 [12 Months and 4 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM17D06813C02	Policy/Cover Note No.:	DMPCSN3088501701						
Vehicle Reg. No. (Insured):	SKU2807K	Policy No. (Claimant):	8-V0016548						
		Excess:	S\$0.00						
Repairer:	Em-1 Auto Pte Ltd (HQ) Blk 8 Sin Ming Industrial Estate Sector C, #01-68, 575643 Sin Ming - Tel: 64523298								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]								
Claimant's Insurer:	QBE Insurance (Singapore) Pte Ltd (HQ) - Tel: 62246633								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MA CHIN FOOK] ... [Final Rpt due 07/12/2017]								
Adj Asg. Remarks:	PLEASE ASSIST TO CONDUCT PRS AND REVERT WITH YOUR RECOMMENDATION								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLH9056X (SNM17D06813C02)

[SKU2807K]

TP

POH WAH MACHINERY & TRADING PTE LTD

Nov 27 2017 10:00AM

[-]

Em-1 Auto Pte Ltd

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Assessment Reports							1 per page		☒	
No	Finalized On	S & H Motor Pte Ltd (Sin Ming)					Thumbnail	Print		
1	27/11/17 15:48	Accident Statement					 Load HTM			
Photos/Images							3 per page		☒	
No	Finalized On	S & H Motor Pte Ltd (Sin Ming)					Thumbnail	Print		
1	27/11/17 15:42	Accident Photo [Linked Accident Report Documents]					 Load JPG	☒		
2	27/11/17 15:42	Accident Photo [Linked Accident Report Documents]					 Load JPG	☒		
3	27/11/17 15:42	Accident Photo [Linked Accident Report Documents]					 Load JPG	☒		
4	27/11/17 15:42	Accident Photo [Linked Accident Report Documents]					 Load JPG	☒		
5	27/11/17 15:42	Accident Photo [Linked Accident Report Documents]					 Load JPG	☒		
6	27/11/17 15:42	Accident Photo [Linked Accident Report Documents]					 Load JPG	☒		
7	27/11/17 15:42	Accident Photo [Linked Accident Report Documents]					 Load JPG	☒		
8	27/11/17 15:42	Accident Photo [Linked Accident Report Documents]					 Load JPG	☒		
9	27/11/17 15:42	Accident Photo [Linked Accident Report Documents]					 Load JPG	☒		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)					Thumbnail	Print		
1	28/06/18 17:26	General View					 Load JPG	☒		
2	28/06/18 17:26	General View					 Load JPG	☒		
3	28/06/18 17:26	General View					 Load JPG	☒		
4	28/06/18 17:26	Odometer Reading					 Load JPG	☒		
5	28/06/18 17:26	General View					 Load JPG	☒		
6	28/06/18 17:26	Chassis Number					 Load JPG	☒		
7	28/06/18 17:26	General View					 Load JPG	☒		
8	28/06/18 17:26	General View					 Load JPG	☒		
9	28/06/18 17:26	General View					 Load JPG	☒		
10	28/06/18 17:26	General View					 Load JPG	☒		
11	28/06/18 17:26	General View					 Load JPG	☒		
12	28/06/18 17:26	General View					 Load JPG	☒		
13	28/06/18 17:26	General View					 Load JPG	☒		
14	28/06/18 17:26	General View					 Load JPG	☒		
15	28/06/18 17:26	General View					Load JPG	☒		
16	28/06/18 17:26	General View					Load JPG	☒		
17	28/06/18 17:26	General View					Load JPG	☒		
18	28/06/18 17:26	General View					Load JPG	☒		
19	28/06/18 17:26	General View					Load JPG	☒		
20	28/06/18 17:26	General View					Load JPG	☒		
21	28/06/18 17:26	General View					Load JPG	☒		

Assessment Reports			1 per page	☒
No	Finalized On	S & H Motor Pte Ltd (Sin Ming)	Thumbnail	Print
22	28/06/18 17:26	General View	 Load JPG	☒
23	28/06/18 17:26	General View	 Load JPG	☒
24	28/06/18 17:26	General View	 Load JPG	☒
25	28/06/18 17:26	General View	 Load JPG	☒
26	28/06/18 17:26	General View	 Load JPG	☒
27	28/06/18 17:26	General View	 Load JPG	☒
28	28/06/18 17:26	General View	 Load JPG	☒
29	28/06/18 17:26	General View	 Load JPG	☒
30	28/06/18 17:26	General View	 Load JPG	☒
31	28/06/18 17:26	General View	 Load JPG	☒
32	28/06/18 17:26	General View	 Load JPG	☒
33	28/06/18 17:26	General View	 Load JPG	☒
34	28/06/18 17:26	General View	 Load JPG	☒
35	28/06/18 17:26	General View	 Load JPG	☒
36	28/06/18 17:26	General View	 Load JPG	☒
37	28/06/18 17:26	General View	 Load JPG	☒
38	28/06/18 17:26	General View	 Load JPG	☒
39	28/06/18 17:26	General View	 Load JPG	☒
40	28/06/18 17:26	General View	 Load JPG	☒
41	28/06/18 17:26	General View	 Load JPG	☒
42	28/06/18 17:26	General View	 Load JPG	☒
43	28/06/18 17:26	General View	 Load JPG	☒
44	28/06/18 17:26	General View	 Load JPG	☒
45	28/06/18 17:26	General View	 Load JPG	☒
46	28/06/18 17:26	General View	 Load JPG	☒
47	28/06/18 17:26	General View	 Load JPG	☒
48	28/06/18 17:26	General View	 Load JPG	☒
49	28/06/18 17:26	General View	 Load JPG	☒
50	28/06/18 17:26	General View	 Load JPG	☒
51	28/06/18 17:26	General View	 Load JPG	☒
52	28/06/18 17:26	General View	 Load JPG	☒
53	28/06/18 17:26	General View	 Load JPG	☒
54	28/06/18 17:26	General View	 Load JPG	☒
55	28/06/18 17:26	General View	 Load JPG	☒
56	28/06/18 17:27	Reinspection Photo	 Load JPG	☒
57	28/06/18 17:27	Reinspection Photo	 Load JPG	☒
58	28/06/18 17:27	Reinspection Photo	 Load JPG	☒
59	28/06/18 17:27	Reinspection Photo	 Load JPG	☒
60	28/06/18 17:27	Reinspection Photo	 Load JPG	☒
61	28/06/18 17:27	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	28/11/17 15:16	EMAIL FROM EM-1	 Load PDF	
No	Finalized On	S & H Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	27/11/17 15:44	Sketch Plan [Linked Accident Report Documents]	 Load TIF	
2	27/11/17 15:44	Sketch Plan #2 [Linked Accident Report Documents]	 Load TIF	
3	27/11/17 15:44	Sketch Plan #3 [Linked Accident Report Documents]	 Load TIF	

Linked Accident Report Documents

Assessment Reports				View	View in Browser	
No	Finalized On	S & H Motor Pte Ltd (Sin Ming)		Thumbnail	Print	
1	27/11/17 15:48	Accident Statement	1	Load HTM		
Photos/Images				3 per page		
No	Finalized On	S & H Motor Pte Ltd (Sin Ming)		Thumbnail	Print	
1	27/11/17 15:42	Accident Photo	1	Load JPG		
2	27/11/17 15:42	Accident Photo	1	Load JPG		
3	27/11/17 15:42	Accident Photo	1	Load JPG		
4	27/11/17 15:42	Accident Photo	1	Load JPG		
5	27/11/17 15:42	Accident Photo	1	Load JPG		
6	27/11/17 15:42	Accident Photo	1	Load JPG		
7	27/11/17 15:42	Accident Photo	1	Load JPG		
8	27/11/17 15:42	Accident Photo	1	Load JPG		
9	27/11/17 15:42	Accident Photo	1	Load JPG		
Documentation				1 per page		
No	Finalized On	S & H Motor Pte Ltd (Sin Ming)		Thumbnail	Print	
1	27/11/17 15:44	Sketch Plan	1	Load TIF		
2	27/11/17 15:44	Sketch Plan #2	1	Load TIF		
3	27/11/17 15:44	Sketch Plan #3	1	Load TIF		

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)				
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.				

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT117022643/M1QBQ2

Date: 02/07/2018

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSN3088501701

Claimant Vehicle
No: SLH9056XInsured Vehicle
No: SKU2807K

Date of Loss: 27/11/2017

Nature of Claim: TP

Claim
No: SNM17D06813C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLH9056X

Make & Model: PEUGEOT 408, 1.6 (A)

Reg. Date: 23/11/2016 (Man. Year: 2016)

Colour: Grey

Engine Capacity: 1560 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

Engine No: 10JBHX3002962

Chassis No: VF30EBHZTGS141119

Odometer: 22098 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/50 R17

Rear Tyre Size:

215/50 R17

Front Left Side: Michelin 8 mm

Rear Left Side:

Michelin 8 mm

Front Right Side: Michelin 8 mm

Rear Right Side:

Michelin 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	28,161.00	23,326.00	4,835.00	17.17
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,710.00	3,900.00	1,810.00	31.70
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	33,871.00	27,226.00	6,645.00	19.62
Approved Total (Overridden) (S\$)		21,700.00		
(S\$)	33,871.00	21,700.00	12,171.00	35.93
+ GST 7.00/7.00% (S\$)	2,370.97	1,519.00	851.97	35.93
Nett Amount (S\$)	36,241.97	23,219.00	13,022.97	35.93

INSPECTION

Date of Assignment: 28/11/2017

Date Inspected: 29/11/2017 Inspected At:

Em-1 Auto Pte Ltd (HQ)
Blk 8 Sin Ming Industrial Estate Sector C,
#01-68
Singapore 575643

Estimated Period of Repair: 13.0 days

Adjuster: MA CHIN FOOK**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 02 Jul 2018)
Parts: 143	PEUGEOT 408 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLH9056X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Bent	1,500.00 FL	*1,500.00 FL
2	1		*TAILGATE EMBLEM (5008)	Necessary	100.00 FL	*100.00 FL
3	1		*TAILGATE EMBLEM (BLUE HDI)	Necessary	100.00 FL	*100.00 FL
4	1		*TAILGATE OUTER GARNISH	Distorted	420.00 FL	*420.00 FL
5	1		*SET TAILGATE OUTER GARNISH CLIP	Necessary	30.00 FL	*30.00 FL
6	2		*TAILGATE NUMBER PLATE LAMP	Distorted	130.00 FL	*130.00 FL
7	1		*TAILGATE OPENER SWITCH	Shorted	295.00 FL	*295.00 FL
8	1		*TAILGATE INNER TRIM	Distorted	620.00 FL	*620.00 FL
9	1		*TAILGATE INNER SIDE TRIM	O/S Distorted/ N/S Serviceable	250.00 FL	*125.00 FL
10	1		*SET TAILGATE INNER TRIM CLIPS	Necessary	40.00 FL	*40.00 FL
11	1		*TAILGATE INNER LOCK	Bent	280.00 FL	*280.00 FL
12	1		*TAILGATE LOCK CATCH	Bent	145.00 FL	*145.00 FL
13	1		*TAILGATE WEATHERSTRIP	Distorted	290.00 FL	*290.00 FL
14	2		*TAILGATE HINGES	Repair	240.00 FL	*- FL
15	2		*TAILGATE ABSORBER	Not Necessary	420.00 FL	*- FL
16	1		*TAILGATE WINDSCREEN INNER SEAL	Necessary	60.00 FL	*60.00 FL
17	1		*REAR BUMPER	Deformed	1,300.00 FL	*1,300.00 FL
18	2		*REAR BUMPER SIDE RETAINERS	Distorted	170.00 FL	*170.00 FL
19	2		*REAR BUMPER ATTACHMENT RETAINERS	Distorted	190.00 FL	*190.00 FL
20	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FL	*40.00 FL
21	1		*REAR BUMPER CENTER RETAINERS	Cracked	190.00 FL	*190.00 FL
22	1		*REAR BUMPER REINFORCEMENT	Dented	490.00 FL	*490.00 FL
23	2		*REAR BUMPER REINFORCEMENT BRACKET	Cracked	260.00 FL	*260.00 FL
24	1		*REAR BUMPER TOWING COVER	Distorted	40.00 FL	*40.00 FL
25	4		*REAR BUMPER REVERSE SENSOR (ORIGINAL)	Shorted	1,180.00 FL	*1,180.00 FL
26	4		*REAR BUMPER REVERSE SENSOR HOLDER	Cracked	240.00 FL	*240.00 FL
27	2		*REAR BUMPER REVERSE LAMP	Cracked	270.00 FL	*270.00 FL
28	2		*REAR BUMPER STOPPER	Serviceable	90.00 FL	*- FL
29	1		*END PANEL (OUTER)	Buckled	950.00 FL	*950.00 FL
30	1		*END PANEL TOP TRIM	Cracked	270.00 FL	*270.00 FL
31	1		*SET END PANEL TOP TRIM CLIPS	Necessary	30.00 FL	*30.00 FL
32	2		*TAILLAMP	O/S Cut / N/S Cracked	960.00 FL	*960.00 FL
33	2		*TAILLAMPS INNER SEAL	Necessary	80.00 FL	*80.00 FL
34	2		*SET TAILLAMPS CLIPS	Not Necessary	40.00 FL	*- FL
35	2		*TAILLAMP SIDE GARNISH	Serviceable	370.00 FL	*- FL
36	2		*REAR FENDER INNER TRIMS	Cracked	760.00 FL	*760.00 FL
37	2		*SET REAR FENDER INNER TRIMS CLIPS	Necessary	60.00 FL	*60.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
38	1		*FRONT BUMPER	Deformed	1,350.00 FL	*1,350.00 FL
39	2		*FRONT BUMPER SIDE RETAINERS	Distorted	170.00 FL	*170.00 FL
40	1		*SET FRONT BUMPER CLIPS	Necessary	40.00 FL	*40.00 FL
41	1		*FRONT BUMPER BADGE	Necessary	120.00 FL	*120.00 FL
42	1		*FRONT BUMPER TOW COVER	Serviceable	40.00 FL	*- FL
43	1		*FRONT BUMPER TOP GARNISH	Serviceable	290.00 FL	*- FL
44	1		*FRONT BUMPER REINFORCEMENT	Dented	430.00 FL	*430.00 FL
45	2		*FRONT BUMPER REINFORCEMENT BRACKET	Serviceable	260.00 FL	*- FL
46	1		*FRONT BUMPER CENTER PAD	Distorted	580.00 FL	*580.00 FL
47	1		*FRONT BUMPER LOWER GRILLE	Distorted	320.00 FL	*320.00 FL
48	1		*FRONT BUMPER FOG LAMPS	N/S Serviceable/ O/S Cracked	470.00 FL	*235.00 FL
49	1		*FRONT BUMPER FOG LAMPS COVER	O/S Missing / N/S Serviceable	240.00 FL	*120.00 FL
50	1		*FRONT BUMPER FOG LAMP COVER CHROME MOULDING	O/S Missing / N/S Serviceable	440.00 FL	*220.00 FL
51	1		*FRONT GRILLE ASSY	Distorted	520.00 FL	*520.00 FL
52	1		*SET FRONT GRILLE CLIPS	Necessary	30.00 FL	*30.00 FL
53	2		*HEADLAMPS	Cracked	1,560.00 FL	*1,560.00 FL
54	2		*SET HEADLAMPS CLIPS	Serviceable	40.00 FL	*- FL
55	1		*SUPPORT PANEL	Cracked	690.00 FL	*690.00 FL
56	1		*SUPPORT PANEL TOP GARNISH	Distorted	350.00 FL	*350.00 FL
57	1		*TURBO INTERCOLER	Dented	1,480.00 FL	*1,480.00 FL
58	1		*AIR CON CONDENSER	Dented	1,250.00 FL	*1,250.00 FL
59	2		*CONDENSER SIDE GARNISH	Cracked	220.00 FL	*220.00 FL
60	1		*CONDENSER SIDE GARNISH CLIPS	Necessary	30.00 FL	*30.00 FL
61	1		*CONDENSER FAN MOTOR ASSY	Cracked	730.00 FL	*730.00 FL
62	1		*CONDENSER AIR CON PIPE	Dented	420.00 FL	*420.00 FL
63	1		*CONDENSER SUCTION PIPE	Not Necessary	400.00 FL	*- FL
64	1		*CONDENSER DISCHARGE PIPE	Not Necessary	380.00 FL	*- FL
65	1		*RADIATOR	Not Necessary	1,290.00 FL	*- FL
66	2		*FRONT SEAT BELT	Jammed	1,140.00 FL	*1,140.00 FL
67	2		*FRONT SEAT BELT BUCKER	Not Necessary	580.00 FL	*- FL
68	1		*SRS UNIT ASSY	Activated	1,620.00 FL	*1,620.00 FL
69	1		*REAR WINDSCREEN SEALANT	Necessary	60.00 FS	*60.00 FS
70	1		*REVERSE CAMERA	Shorted	450.00 FS	*350.00 FS
71	1		*BODY PANEL JOINT SEALANT	Necessary	120.00 FS	*80.00 FS
72	1		*REAR NUMBER PLATE WITH COVER	Bent	70.00 FS	*40.00 FS
73	1		*FRONT NUMBER PLATE WITH COVER	Bent	70.00 FS	*40.00 FS
74	1		*RADIATOR COOLANT	Necessary	40.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	31,200.00	25,850.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	3,039.00	2,524.00
Total Parts (\$\$)	28,161.00	23,326.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	2,000.00	1,500.00
2	SPRAY PAINTING	New	2,000.00	1,300.00
3	CHECK WIRING	New	100.00	60.00
4	ANTI RUST	New	180.00	80.00
5	REMOVE AND INSTALL REAR WINDSCREEN	New	140.00	120.00
6	REMOVE AND INSTALL TAILGATE PARTS	New	90.00	60.00
7	REMOVE AND INSTALL REVERSE SENSOR	New	90.00	80.00
8	REMOVE AND INSTALL REVERSE CAMERA	New	150.00	80.00
9	REMOVE AND INSTALL CARPET AND SEAT	New	250.00	150.00
10	REMOVE AND INSTALL AIR CON	New	150.00	120.00
11	REPROGRAM AND RESET SRS UNIT }	New	380.00	350.00
12	TO RESET AND CHECK AIR BAG FUNCTION }	New	180.00	0.00
Gross Labour Cost (\$\$)			5,710.00	3,900.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >