

ASS. REF. NO.

REF CS/FCI/7022645 / A tbn2

Subject

ASSIGNMENT Officer

CWS

Person (Person)

Joanne Yong

FCI

Date/Time 12:58pm @ 28/11/17

Estimated Cost

Bill to

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.

SJW 9521P

Insured

SHB 4067B

at Workshop in

Specialists Motor

Tel

6747 2112

of Blk 3018A Ubi Road 1 # 01-24-26

Policy No.

Claim No.

D17010977MFSH

Sum Insured

Excess

Make of Veh.

(Client's Record)

D.O.A.

24/11/2017

CA / REV / REP. / REV 24 HRS

wpr

HOD Endorsement

Date/Time

3:27pm @ 28/11/17

Person Contacted

Hui Ling

Vehicle IN/OUT

Date/Time

Action/Instruction () Estimate

SJW 9521W - X

SHB 4067B-CC4/AXA 17009569/M1wb3-D.O.A: 12/05/2017

Lump Sum \$20500 (Red: 5264 : 71%)

REF: FCI

ASSIGNMENT

From:

Date:

13/12/17

Estimated Cost:

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SJW 9521P

at Workshop m/s

Specialists Motor

of Blk 3018A Ubi Rd / # 01-24-26, 408711

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

10 am @
owner waiting

N/S	O/S

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

(up)

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SJW 9521P

Yr Regn:

2010 April

Type: ☒ M.Car M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Jaguar XF

c.c. 2967

Colour:

Red

A/C: Insured / Std / NI / NA

Sp. Reading:

107905

T/Radio: Insured / Std / NI / NA

Eng/No:

SAJAC05D6AFR76050

C/No:

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orModi: Nil / ☒ S/Rim / STD A/Rim or

Tyre Size:

F: 245/45 R18

R: 245/45 R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

☒ TOYO / YOKO or

Front

Rear

R/Bal.

06

mm

R/Bal.

06

mm

L/Bal.

06

mm

L/Bal.

06

mm

D.O.A.

D.O.I.

13/12/17

Survey held at

Specialist

Des. of Damages: Frt / Rear / ☒ O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP 1st Cap.

RECEIVED 25 JAN 2018

Date/Time, File Pass to?

☐

Preli. Report

JSL Typist

☒

Final Report

Date/Time, File Return to?

2)

Days Of Repair: 2

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

Add Fee:

☐

Site Insp (\$

) \$ + RS \$ SI

☐

Interview (\$

) Photos

☐

Tech. Invs (\$

) Others

☐

Weekend (\$

)

TOTAL

Report Format :

TP

Lum Sum / I.B.I. (\$) 20501

150
50
50
14
264



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI17022645/Atb		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 28-11-2017		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 4067B	Veh. Inspected	SJW 9521P	
Policy No.		Coverage (\$)	0.00	
Claim No.	D17010977MFSH	Excess (\$)	0.00	
Assign From	CWS (JOANNE YONG)	Assign Date	28/11/2017	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	24/11/2017	Inspection Date		
Survey held at	SPECIALISTS MOTOR PTE LTD BLK 3018A UBI ROAD 1 #01-24-26 SINGAPORE 408711			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

First Capital Insurance Limited

A FAIRFAX Company

Company Reg. No. 195000106C
GST Reg. No. M2-0001676-9

MOTOR SURVEY ASSIGNMENT

Date	27-11-2017	Our Ref No. D17010977MFSH
Accident Date	24-11-2017	Claim Type. Third Party
Insured Vehicle	SHB4067B	Third Party Vehicle. SJW9521P
Survey Location	BLK 3018A UBI ROAD 1 #01-24-26	
Contact Person.	WEI SHUN	
Contact No.	67472112/ 67472112	Fax No. 00
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	SPECIALISTS MOTOR PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	JOANNEY	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/231126)



PRI Documents



Close



PRI Header Details

Claim No	D17010977MFSH	Policy No	D-15072701MFSH	Claimant S.No & Name	1 & SPECIALIS
Workshop Name	SPECIALISTS MOTOR PTE LTD (Contact Person : WEI SHUN)	Survey Location & Contact Details	BLK 3018A UBI ROAD 1 #01-24-26 Mobile: 67472112 , Phone: 67472112 , Fax: 00 EmailId: CARDOC@SINGNET.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM T		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHB4067B	TP Vehicle No	SJW9521P
PRI Recieved Date	27-11-2017 11:46:32 PM	Surveyor Appointed Date	28-11-2017 12:57:13 PM	Surveyor Accept Date	28-11-2017 0

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	28-11-2017	Upload Survey Report *:	Choose File
------------------------------------	--	-----------------------------	------------	--------------------------------	--

Vehicle Particulars

Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select Year ▼
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/SJW9521P/1711293

27th November 2017

The Manager
Motor Claim Dept.
First Capital Insurance Limited
6 Raffles Quay #21-00,
Singapore 048580.

Denise

Date of Accident : 24th November 2017
Location : Keppel Tower Entrance
Third Party Claim Vehicle No : SHB 4067 B
Repair Cost For Vehicle No : SJW 9521 P (Jaguar XF 3.0 V6 Luxury AT ABS)

Estimate Supply of Parts & Labours

No.	Particulars	Qty	Price	Amounts
1	Front fender RH <i>Devited</i>	1	1,600.00	\$ 1,600.00 ✓
2	Front fender cowling RH <i>Deland</i>	1	500.00	\$ 500.00 ✓
3	Front fender cowling clips RH <i>new</i>	1 set	40.00	\$ 40.00 ✓
4	Headlamp assy RH <i>new</i>	1	1,980.00	\$ 1,980.00 +
5	Front shock absorber RH <i>new</i>	1	595.00	\$ 595.00 +
6	Front fender emblem (Jaguar) RH <i>new</i>	1	84.00	\$ 84.00 +
7	Front fender garnish RH <i>new</i>	1	280.00	\$ 280.00 +
				\$ 5,079.00

Ans: 2033

Labour Charges :-

	Amounts
Cut out, renew, knocking & welding front fender RH, remove & install all damage parts & re-align body	\$ 880.00 <i>250</i>
Remove & install front undercarriage to facilitate repairs	\$ 320.00 <i>x</i>
Computerise wheel alignment	\$ 180.00 <i>x</i>
Tuff-kote on damage parts	\$ 40.00 <i>20</i>
Spray painting on damage parts	\$ 780.00 <i>250</i>
Check lighting after repairs	\$ 35.00 ✓

Check lighting after repairs

LKK Auto Consultants hence notify the Repairer of the following:

• To resurvey vehicle after spray painting

• Labour Charge

• Total Amount

• The repair is on a "Without Prejudice" basis

• No illegal modification(s) is allowed

• GST will be reflected in the final bills.

• The repair is subject to final approval from Insurance Company

Notes : -Please inform us within 14 days, from the date of this letter, in the event that the owner/driver is in breach of its policy with your company, failing which we shall hold your company liable for all costs of repairs, loss of use and storage.

Signature: _____

Date: _____

Adrian Ly

L/S 13/12/17

02 Days

\$ 2,235.00

\$ 7,314.00

total: 2588

r/s: 2050



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI17022645/Atbn2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 26-01-2018		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 4067B	Veh. Inspected	SJW 9521P	
Policy No.	D-15072701MFSH	Coverage (\$)	0.00	
Claim No.	D17010977MFSH	Excess (\$)	0.00	
Assign From	JOANNE YONG	Assign Date	28/11/2017	
2. Vehicle Particulars & Condition				
Make & Model	JAGUAR XF	c.c	2967	
Engine No.	HIDDEN	Year of Reg.	2010	
Chassis No.	SAJAC05D6AFR76050	Colour	RED	
Odometer	107905	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	245/45 R18	TOYO	6 mm	
L/H Front Tyre	245/45 R18	TOYO	6 mm	
R/H Rear Tyre	245/45 R18	TOYO	6 mm	
L/H Rear Tyre	245/45 R18	TOYO	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	24/11/2017	Inspection Date	13/12/2017	
Survey held at	SPECIALISTS MOTOR PTE LTD BLK 3018A UBI ROAD 1 #01-24-26 SINGAPORE 408711			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJW 9521P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT FENDER RH	DENTED	1,600.00	1,600.00
1	FRONT FENDER COWLING RH	DEFORMED	500.00	500.00
1	SET FRONT FENDER COWLING CLIPS RH	NECESSARY	40.00	40.00
1	HEADLAMP ASSY RH	NOT NECESSARY	1,980.00	-
1	FRONT SHOCK ABSORBER RH	NOT NECESSARY	595.00	-
1	FRONT FENDER EMBLEM (JAGUAR) RH	NOT NECESSARY	84.00	-
1	FRONT FENDER GARNISH RH	NOT NECESSARY	280.00	-
	LESS 5% DISCOUNT		-	-107.00
			5,079.00	2,033.00
	<u>LABOUR</u>			
	CUT OUT,RENEW,KNOCKING & WELDING FRONT FENDER RH,REMOVE & INSTALL ALL DAMAGE PARTS & RE-ALIGN BODY.		880.00	250.00
	REMOVE & INSTALL FRONT UNDERCARRIAGE TO FACILITATE REPAIRS.	NOT NECESSARY	320.00	-
	COMPUTERISE WHEEL ALIGNMENT.	NOT NECESSARY	180.00	-
	TUFF-KOTE ON DAMAGE PARTS.		40.00	20.00
	SPRAY PAINTING ON DAMAGE PARTS.		780.00	250.00
	CHECK LIGHTING AFTER REPAIRS.		35.00	35.00
			2,235.00	555.00
	GRAND TOTAL		7,314.00	2,588.00
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,050.00

Report Ref No. CS/FCI17022645/Atbn2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.