

CS/FCI 17022650 / 1111V602

ASSIGNMENT (Office)

Ma.  
CWS  
Eileen Lee

FCI

4:10pm @ 28/11/17

Estimated Cost: Bill to:

OD / ☒ WS / IF RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SHD 4818R Insured SHD 3088L

at Workshop no: Chummi Motor Tel: 65127162

of AMK Autopoint, 800n Heck Motor, # 01-05/06

Policy No: Claim No: D17010989 MFSH

Sum Insured: Excess:

Make of Veh: (Client's Record) DOA 27/11/2017

CA / REV / REP. / REV 24 HRS 'DS' 29/11/17

Date/Time: 4:19pm @ 28/11/17 Person Contacted: Dorene R.O.D. Endorsement:

Vehicle: ☒ IN ☐ OUT

Date/Time	Action/Instructions (✓) Estimate
	SHD 4818R - X
	SHD 3088L - CS/FCI 17018964 / Arb - DOA: 29/09/2017

30/11/17 Email preli revised to FCI

>7/18 Ma confirmed LS \$14,200 (Reel 18,548.16, 5616)

FCI

## ASSIGNMENT

Date: 29/11/17  
 SHD 4818R  
 MAR 2014  
 Type: Motor Cycle, Bus, Van, Lorry, ☒ Prime Mover  
 Truck, Trailer or  
 Make: HYN SONATA 1688  
 Colour: BLUE  
 So Reading: 612496  
 Eng No:  
 O No: KMHLB41UM64691  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: In order / Jammed / Leaked / Burnt or  
 Brake: In order / Jammed / Leaked / Burnt or  
 Mod: Nil / S/Rim / STD A/Rim or  
 Tyre Size: F: 205/60 R16  
 R:  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or Westlake  
 Front: R Bal. 8 mm  
 L Bal. 8 mm  
 D.O.A. 27/11/2012  
 Survey held at: 2  
 Des. of Damages: Front / Rear / O/S / N/S / U/O / Rooftop or  
 The U/C / Chassis frame / Body Structure affected due to collision  
 (Policy Condition)  
 Remark: The veh had commenced its repair at the time of inspection.  
 Ball or Market Value:  
 IDAO Accident Report: Consistent? : Yes or No  
 GIA / PP Seen: Consistent? : Yes or No  
 Est. Repairs: days Res: Yes or No  
 Lim. Surp. % 3 Val: Yes or No  
 CA / REV / REP. / 24 HRS 'DS'  
 Date: Person Contacted: Vehicle IN / OUT

Date Time Action Instruction

Date Time File Pass No:

☐

Preli. Report

☐

Final Report

Date Time File Return No:

2/2- typist

Receipt Format:

CWS

Lump Sum: 14,200/-

Days Of Repair: 10

Resurvey No. of Trip: 1

Add Fee:

☐

Site Insp: S

☐

Inspection: S

☐

Tech Insp: S

☐

Accident: S

Survey Fee

Transport

Lump Sum

Total

Net

Gross

22 X19

1704 330

50

50

63

63

663

 RECEIVED 06 FEB 2019  
 14 200/-  
 10 w/days  
 OK

## Survey Department Check List (Case Handler)

Reference No. : CS/F317022650/M/vb  
 Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

**Admin (** ): Case handler to make sure all Information created by the assignment team are ACCURATE.

**(1) Office Assign Form**

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From	✓			
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No				
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

**Surveyor (** ): Case handler to make sure the surveyor completed all required information.

**(1) Assignment Form**

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

**(2) System - (Views/Merimen)**

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

**(3) Workshop Estimate/Assignment Form**

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

**(4) System - (Views/Merimen)**

C	Resurvey photo Uploaded	✓			
---	-------------------------	---	--	--	--

Check By: VERON 22/18  
 Case Handler Date

\*C: Critical \*N: Non-Critical

21/05/2014




# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI17022650/M1vb		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 28-11-2017		
		Code : FCI2		
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SHD 3088L	Veh. Inspected	SHD 4818R	
Policy No.		Coverage (\$)	0.00	
Claim No.	D17010989MFSH	Excess (\$)	0.00	
Assign From	CWS (EILEEN LEE)	Assign Date	28/11/2017	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer		Steering		
Brakes		Modification		
General				
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
<b>4. Description of Damages</b>				
<b>5. General Information</b>				
Accident Date	27/11/2017	Inspection Date		
Survey held at	CHUNNI MOTOR WORK PTE LTD BLK 10 ANG MO KIO IND. PARK 2A, #03-19 AMK AUTOPOINT SINGAPORE 568047.			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

# First Capital Insurance Limited

A FAIRFAX Company

Company Reg. No. 195000106C  
GST Reg. No. M2-0001676-9

## MOTOR SURVEY ASSIGNMENT

<b>Date</b>	27-11-2017	<b>Our Ref No.</b> D17010989MFSH
<b>Accident Date</b>	27-11-2017	<b>Claim Type.</b> Third Party
<b>Insured Vehicle</b>	SHD3088L	<b>Third Party Vehicle.</b> SHD4818R
<b>Survey Location</b>	AMK AUTOPOINT, SOON HOCK MOTOR, #01-05/06	
<b>Contact Person.</b>	LYNN OR IRENE	
<b>Contact No.</b>	65427162/ 64836016	<b>Fax No.</b> 65426039
<b>Survey Type</b>	DIRECT SETTLEMENT:	
<b>Appointed Surveyor</b>	LKK AUTO CONSULTANTS PTE LTD	
<b>Contact Person</b>	NA	<b>Fax No.</b> 68416315
<b>Contact Number.</b>	NA	

## FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

## THIRD PARTY SURVEY REQUEST

<b>Cc : Workshop</b>	CHUNNI MOTOR WORK PTE LTD	<b>Attention.</b> NIL
<b>Cc : TP Solicitor</b>	NA	<b>TP Solicitor Fax No.</b> NA
<b>Officer Incharge</b>	EILEEN LEE	

## IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.  
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/231140)



PRI Documents



Close



## PRI Header Details

<b>Claim No</b>	D17010989MFSH	<b>Policy No</b>	D-15072701MFSH	<b>Claimant S.No &amp; Name</b>	1 & CHUNNI M
<b>Workshop Name</b>	CHUNNI MOTOR WORK PTE LTD (Contact Person : LYNN OR IRENE)	<b>Survey Location &amp; Contact Details</b>	AMK AUTOPOINT, SOON HOCK MOTOR, #01-05/06 <b>Mobile:</b> 64836016 , <b>Phone:</b> 65427162 , <b>Fax:</b> 65426039 <b>EmailId:</b> CHUNNIMOTOR@GMAIL.COM		
<b>Our Surveyor</b>	LKK AUTO CONSULTANTS PTE LTD	<b>Instructions To Surveyor</b>	DIRECT SETTLEMENT:		
<b>Insured Name</b>	COMFORT TRANSPORTATION PTE LTD	<b>Insured Vehicle No</b>	SHD3088L	<b>TP Vehicle No</b>	SHD4818R
<b>PRI Recieved Date</b>	28-11-2017 03:28:29 PM	<b>Surveyor Appointed Date</b>	28-11-2017 04:09:15 PM	<b>Surveyor Accept Date</b>	28-11-2017 0

## Survey Report Upload

<b>Surveyor Inspection Date *:</b>		<b>Surveyor Report Date</b>	28-11-2017	<b>Upload Survey Report *:</b>	<input type="button" value="Choose File"/>
------------------------------------	--	-----------------------------	------------	--------------------------------	--

## Vehicle Particulars

<b>Make</b>	Please Select Make ▼	<b>Model</b>	Please Select Model ▼	<b>Year</b>	Select Year ▼
<b>Chasis No</b>	<input type="text"/>	<b>Engine No</b>	<input type="text"/>	<b>Mileage</b>	<input type="text"/>
<b>Color</b>	<input type="text"/>	<b>Cubic Capacity</b>	<input type="text"/>		

## Multiple Documents Upload

[Upload Multiple Documents](#)

File Name	Action
-----------	--------

## Surveyor Job Remarks

<b>Remarks</b>	<input type="text"/>	<input type="button" value="Save"/>
----------------	----------------------	-------------------------------------

Veron Chen (LKKAUTO)

---

**From:** Veron Chen (LKKAUTO)  
**Sent:** Thursday, 30 November, 2017 8:37 AM  
**To:** 'Claim Workflow System'  
**Cc:** EILEENLEE@FIRST-INSURANCE.COM.SG; SUR  
**Subject:** RE: SURVEY ASSESSMENT - D17010989MFSH/1, SHD 4818R  
**Attachments:** SHD 4818R PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SHD 4818R  
Date of survey: 29/11/2017  
Number of days: 12 days

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** Admin-D (LKKAUTO)  
**Sent:** Tuesday, 28 November, 2017 4:21 PM  
**To:** 'Claim Workflow System' <cwsmotorclaims@first-insurance.com.sg>; assignments <assignments@lkkauto.com>  
**Cc:** EILEENLEE@FIRST-INSURANCE.COM.SG; SUR <sur@lkkauto.com>  
**Subject:** RE: SURVEY ASSESSMENT - D17010989MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards,

**G.Nivitha** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** Claim Workflow System [<mailto:cwsmotorclaims@first-insurance.com.sg>]  
**Sent:** Tuesday, 28 November, 2017 4:09 PM  
**To:** [ASSIGNMENTS@LKKAUTO.COM](mailto:ASSIGNMENTS@LKKAUTO.COM)  
**Cc:** [CWSMOTORCLAIMS@FIRST-INSURANCE.COM.SG](mailto:CWSMOTORCLAIMS@FIRST-INSURANCE.COM.SG); [EILEENLEE@FIRST-INSURANCE.COM.SG](mailto:EILEENLEE@FIRST-INSURANCE.COM.SG)  
**Subject:** PRI: SURVEY ASSESSMENT - D17010989MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

**PS: This is a system generated mail. Please do not reply to this mail.**





Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D17010989MFSH

Our ref: CS/FCI17022650/M1vb

Date : 30/11/2017

The Motor Claims Department  
M/s First Capital Insurance Ltd

*Without Prejudice*

Dear Sir/Madam,

**INITIAL INSPECTION REPORT OF VEHICLE NO. SHD 4818R**


We thank you for your instruction on 28/11/2017

Please be informed that we had conducted the inspection of the above mentioned vehicle on 29/11/2017 at the premises of M/s CHUNNI NOTOR WORK PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$32,748.16
Revised Estimate Amount	: S\$13,814.72
"Check" Items Amount	: S\$4,278.24
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

**Description of Damage:**

The vehicle sustained damages at the front and rear portion.



**Comments/Present Status:**  
Damages Consistent

Yours faithfully,

**MA CHIN FOOK**  
Automotive Assessor

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type	Company
Owner ID	3821R

### Vehicle Details

Vehicle No.	SHD4818R
Vehicle to be Exported	No
Intended De-registration Date	30 Nov 2017
Vehicle Make	HYUNDAI
Vehicle Model	I40 1.7L CRDI AT ABS AIRBAG 4DR
Primary Colour	Blue
Manufacturing Year	2014
Engine No.	D4FDEU410894
Chassis No.	KMHLB41UMEU047691
Maximum Power Output	100.0 kW (134 bhp)
Open Market Value	\$18,824.00
Original Registration Date	04 Mar 2014
First Registration Date	04 Mar 2014
Transfer Count	0
Actual ARF Paid	\$11,324.00

### Intended PARF Rebate Details

PARF Eligibility	Yes
PARF Eligibility Expiry Date	03 Mar 2022
PARF Rebate Amount	\$8,493.00

### Intended COE Rebate Details

COE Expiry Date	03 Mar 2022
COE Category	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years)	8
PQP Paid	\$58,745.00
COE Rebate Amount	\$31,267.00
<b>Total Rebate Amount</b>	<b>\$39,760.00</b>

### Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 30 Nov 2017

OK



Please read through the [Privacy Statement](#), [Terms of Use](#), and [Disclaimer](#).

Please do not use the Back or Forward buttons on your browser as this may alter the results of the transactions.

Best viewed with IE 10 and above, Chrome, Firefox, and Safari.

Copyright 2017 LTA [Privacy Statement](#) [Terms of Use](#) [Disclaimer](#) [Rate the Website](#) [Rate this e-Service](#)

Last updated on 19 Nov 2017 at 12:12 AM

MCD617156528 / ComfortDelGro Engineering Pte Ltd - Layan  
ENTRY DATE & TIME: 27/11/2017 15:16

**SINGAPORE ACCIDENT STATEMENT****IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

**ACCIDENT STATEMENT**

Date Of Report 27/11/2017 15:16  
Date Of Accident 27/11/2017 09:10  
Exact Location Of Accident PIE > CHANGI AIRPORT B4 THOMSON EXIT  
Country/State of Loss SINGAPORE

**DETAILS OF OWN VEHICLE**

Vehicle Registration Number SHD4818R  
Insured/Policyholder  
Name Of Registered Owner COMFORT TRANSPORTATION PTE LTD  
Co Reg No 199303821R  
Email Address FLEETSAFETY@CDGTAXI.COM.SG  
Mobile Phone No  
Alternative Phone No OFFICE-65508768

**Vehicle Particulars**

Manufacturer HYUNDAI  
Model I40

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category TAXI

**Insurance Company**

Name of Insurance Company FIRST CAPITAL INSURANCE LTD  
Type Of Coverage THIRD PARTY FIRE AND/OR THEFT  
Fleet Policy YES  
Policy Number D-1572701MFSH

**Cover Note Number****Driver**

Name of Driver LEE SONG YANG  
NRIC No S1316589J  
Date Of Birth 01/02/1958  
Occupation OUTDOOR  
Date Of Driving Pass 17/03/1978  
Driving Experience 39 YEARS AND 8 MONTHS  
Gender MALE  
Mobile Number  
Fax Number  
Contact Number  
EMail Address CANDYLEE-@LIVE.COM

Address 649 HOUGANG AVENUE 8 #03-341  
 Postcode S530649  
 Was driver an employee of the Insured's Company NO  
 If No, Relationship of the Driver with the Insured OTHER - TAXI DRIVER  
 Vehicle Registration Number of Driver's Own Vehicle -  
 -  
 Insurance Company of Driver's Own Vehicle -  
 -  
 -

**General Information of the Accident**

Type Of Accident CHAIN COLLISION  
 Weather Conditions RAINING  
 Road Surface WET

**Other Information**

Was any foreign vehicle involved in this accident? NO  
 Was any body injured in the Accident? NO  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (Including Driver) 2

**Details of Police Action**

Was the accident reported to the police? NO  
 If Yes, Please state which Police Station  
 Was notice of intended Prosecution given? NO  
 If Yes, against whom?

**Circumstances of Accident**

PLS SEE ATTACHED

**Attachment(s)**

Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? YES  
 Remarks/ Reasons: -  
 Was there any audio recorded? NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number SHD3088L  
 Vehicle Make/Model/Colour  
 Details Of Properties  
 Name of Driver MR HOO YEOW GEE  
 NRIC/Passport Number S1741904H  
 Contact Number 96188429  
 Address  
 Postcode  
 Insurance Company Name  
 Nature Of Damage FRT  
 No. Of Passenger (Including Driver)

**Details of Witness**

Name  
 Phone Number  
 Email Address

**DETAILS OF OTHER VEHICLE PROPERTY 2**

Vehicle Registration Number SJJ5564K

Vehicle Make/Model/Colour

Details Of Properties

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage REAR

No. Of Passenger (Including Driver)

**Details of Witness**

Name

Phone Number

Email Address

**DETAILS OF INJURED PERSON 1**

Name PAX

Approximate Age

Injuries Sustain FEELING GIDDY

Injured person in which vehicle? SHD4818R

Were seat belts worn?

Was Injured conveyed to hospital by ambulance? YES

Address

Postcode

**SKETCH PLAN****IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**


I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) Investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

COMFORT TRANSPORTATION PTE LTD  
CO. REG. NO. 199303821R

Policyholder's Signature  
Date & Time:

  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time: 27.11.2017 @ 12:00 Hrs

  
Reporting Centre Personnel's Signature  
Name: *Rubini*  
NRIC/FIN No.:

**SKETCH PLAN**

A - SHD 4818R.

B - SHD 3088L. (CTPL)

C - SJJ 5564K.

Along PIE (Changi) Before Thomson Exit.

**Describe Circumstances of the Accident**

On 27/11/2017 @ about 09:10hrs, my taxi (A) (SHD 4818R) was travelling
along PIE (Changi) before Thomson exit with one female passenger on board.
I saw in front of my vehicles slowing down and stopped, So I follow
too. Out of sudden, there was a loud impact coming from the rear portion and
caused my taxi (A), to lose control and surge forward, and colliding onto veh (C)
(SJJ 5564K) rear portion. My taxi (A) front and rear portion were damaged.
I assessed the damages to my taxi (A) and come to know that there were 3
vehicles involved in the chain accident.
No one was conveyed by the ambulance.
The parties involved in the accident are:
A - SHD 4818R.
B - SHD 3088L (CTPL). Mr. Hoo Yeow Gee. NRIC : S 1741904H. Hp : 9618 8429.
C - SJJ 5564K. Male driver.
No injury in this accident.

**Declaration**

I/We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION PTE LTD  
CO. REG. NO. 199303821Rpolicyholder's Signature  
Date & TimeDriver's Signature (If driver is not the policyholder)  
Date & Time 27-11-2017 @ 12:00 HrsReporting Centre Personnel's Signature  
Name: Rubini  
NRIC/FIN No: -



**CHUNNI MOTOR WORK PTE LTD**

## REPAIR ESTIMATE\*

VEHICLE NO : SHD 4818R

**DATE : 27.11.2017**

**MAKE :**

**TEL : 6542 5119**

**MODEL : HYUNDAI i40**

**FAX : 8542 6039 FCI**

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Radiator Grille			\$ 294.35
	Radiator Grille H Emblem			\$ 113.65
	Front Bumper Cover			\$ 562.30
	Front Bumper Sponge			\$ 142.20
	Front Bumper Reinforcement			\$ 526.10
	Front Bumper Bracket Top (LH/RH)		\$ 22.40	\$ 44.80
	Front Bumper Bracket (LH/RH)		\$ 24.60	\$ 49.20
	Front Bumper Retainer Mounting		\$ 9.20	\$ 18.40
	Headlamp Support Panel Assy			\$ 1,067.50
	Headlamp (LH/RH)		\$ 1,388.00	\$ 2,776.00
	Radiator			\$ 850.20
	Radiator Fan Blade,Cowling,Motor Assy			\$ 792.95
	Radiator Bracket (RH/LH)		\$ 6.50	\$ 13.00
	Radiator Guard		\$ 35.00	\$ 70.00
	Horn Unit (LH/RH)		\$ 86.75	\$ 173.50
	Horn Wire			\$ 156.50
	Aircon Condenser			\$ 1,137.35
	Inter Cooler			\$ 921.90
	Inter Cooler Mounting (2 PCS)			\$ 25.90
	SUB TOTAL			\$ 9,735.80
	LESS 20%			\$ 1,947.16
	DISCOUNTED TOTAL			\$ 7,788.64
	Labour Charge			
	Panel Beating			\$ 1,000.00
	Spray Painting Charge			\$ 200.00
	Wiring Charge			\$ 50.00
	Towing Charge			\$ 50.00
	Remove/Refix Aircon & Refill Gas			\$ 150.00
	TOTAL LABOUR			\$ 1,450.00

**DISCOUNTED TOTAL**

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Boot Lid			\$ 1,681.40
	Boot Lid Rubber			\$ 115.80
	Boot Lid Lock Upper			\$ 137.90
	Boot Lid Lock Lower			\$ 131.70
	Boot Lid 'H' Emblem			\$ 27.20
	Boot Lid CRDI Plate			\$ 41.00
	Boot Lid Lamp (LH/RH)		\$ 556.80	\$ 1,113.60
	Boot Lid Trimboard			\$ 172.70
	Boot Lid Trimboard Clips (10pcs)			\$ 11.00
	Bootlid Moulding			\$ 85.00
	Bootlid i40 Emblem			\$ 41.00
	Bootlid Lower Garnish			\$ 398.00
	Rear Bumper			\$ 603.60
	Rear Bumper Reinforcement			\$ 504.35
	Rear Bumper Reinforcement Bracket (LH/RH) NS	KT OSC MC	(180.00)	\$ 360.00
	Rear Bumper Clip 10 pcs			\$ 22.00
	Rear Bumper Bracket		\$ 49.00	\$ 98.00
	Rear Bumper Sponge			\$ 143.40
	Rear Bumper Under Cover			\$ 225.00
	Rear Bumper Reflector Lamp (LH)			\$ 32.00
	Tail Lamp (LH/RH)		\$ 565.60	\$ 1,131.20
	Tail Lamp Quarter Panel (LH)			\$ 97.90
	Rear Panel			\$ 592.30
	Rear Panel Garnish			\$ 57.70
	Rear Panel Lower Panel			\$ 495.50
	Spare Tyre Holder			\$ 28.80
	Spare Tyre Panel			\$ 900.50
	Spare Tyre Panel Cushion			\$ 209.05
	Rear Towing Hook			\$ 94.60
	Member Assy- Rear Floor Centre			\$ 170.75
	Panel Assy-Rear Floor Side (LH)			\$ 92.40
	Rear Floor Chassis Member (LH)			\$ 74,232.50
	Exhaust Pipe Insulator		\$ 58.55	\$ 117.10
	Exhaust Silencer NS RT OC EV		\$ 954.00	\$ 1,908.00
	Exhaust Pipe Hanger NS RT >		\$ 58.55	\$ 117.10
	Exhaust Pipe Centre			\$ 1,150.30
	Rear Fender With Housing (LH)			\$ 4,736.80
	Rear Fender Inner Lining (LH)			\$ 164.40
	Rear Fender Air-Duct			\$ 51.60
	Rear Fender Trim Board (LH)			\$ 188.75
	Rear Windscreen Moulding			\$ X 60.00
<b>SUB TOTAL</b>				<b>\$ 22,441.90</b>
<b>LESS 20%</b>				<b>\$ 4,488.38</b>
<b>DISCOUNTED TOTAL</b>				<b>\$ 17,953.52</b>

SHD 4818R

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Boot Lid Comfort Logo & Tel No. Sticker			\$ 30.00
	Boot Lid Advertisement Logo			\$ 100.00
	Rear Bumper Rubber Mat			\$ 50.00
	Rear Fender Advertisement Logo (LH/RH)		\$ 100.00	\$ 200.00
	Rear Windscreen Sealant			\$ 46.00
				\$ 426.00
	<b>Labour Charge</b>			
	Panel Beating			\$ 2,400.00
	Spray Painting Charge			\$ 1,400.00
	Wiring Charge			\$ 50.00
	Tuff Kote			\$ 100.00
	Rear Chassis Alignment Charge			\$ 400.00
	Remove/Refix Cushion & Upholstery Rear			\$ 150.00
	Remove/Refix Rear Windscreen Glass			\$ 120.00
	Remove/Refix Fuel Tank			\$ 150.00
	Remove/Refix Exhaust Pipe			\$ 360.00
	<b>TOTAL LABOUR</b>			\$ 5,130.00
	<b>ESTIMATE TOTAL</b>			\$ 32,748.16

Nett he  
Nett he  
Nett he  
Nett he  
Nett NIN

1200.  
900  
30  
60  
x  
60  
x  
180

Not Authorized  
HS Repair.  
A Goe polua Photo.  
HCC Auto (MA).  
29/11/2017.

12w days

30/11/17

- LKH Auto Consultants hence notify the Repairer of the following:
- To survey before after spray painting
  - To display damaged parts during resurvey
  - All prices are subject to confirmation
  - Temporary survey is on a "Without Prejudice" basis
  - Legal modification is allowed
  - Supplementary items must be surveyed and is subject to final approval from insurance company

Acknowledged by Repairer  
Signature:  
Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI17022650/M1vbe2

36 ROBINSON ROAD  
#16-01 CITY HOUSESINGAPORE 068877

Date : 05-02-2018



Code : FCI2

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHD 3088L	Veh. Inspected	SHD 4818R
Policy No.	D-15072701MFSH	Coverage (\$)	0.00
Claim No.	D17010989MFSH	Excess (\$)	0.00
Assign From	EILEEN LEE	Assign Date	28/11/2017

## 2. Vehicle Particulars & Condition

Make & Model	HYUNDAI SONATA	c.c	1685
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	KMHLB41UMEU047691	Colour	BLUE
Odometer	612496	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/60 R16	WEST LAKE	8 mm
L/H Front Tyre	205/60 R16	WEST LAKE	8 mm
R/H Rear Tyre	205/60 R16	WEST LAKE	8 mm
L/H Rear Tyre	205/60 R16	WEST LAKE	8 mm

## 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.
--

## 5. General Information

Accident Date	27/11/2017	Inspection Date	29/11/2017
Survey held at	AMK AUTOPOINT, SOON HOCK MOTOR, #01-05/06		
Repairer	CHUNNI MOTOR WORK PTE LTD		

## 5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

## 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	10 Working Days
-------------------------------------	-----------------



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 4818R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	RADIATOR GRILLE	DISTORTED	294.35	294.35
1	RADIATOR GRILLE H EMBLEM	DISTORTED	113.65	113.65
1	FRONT BUMPER COVER	DEFORMED	562.30	562.30
1	FRONT BUMPER SPONGE	TORN	142.20	142.20
1	FRONT BUMPER REINFORCEMENT	BENT	526.10	526.10
2	FRONT BUMPER BRACKET TOP (LH/RH) @\$22.40	DISTORTED	44.80	44.80
2	FRONT BUMPER BRACKET (LH/RH) @\$24.60	DISTORTED	49.20	49.20
2	FRONT BUMPER RETAINER MOUNTING @\$9.20	DISTORTED	18.40	18.40
1	HEADLAMP SUPPORT PANEL ASSY	DISTORTED	1,067.50	1,067.50
2	HEADLAMP (LH/RH) @\$1388.00	CRACKED	2,776.00	2,776.00
1	RADIATOR	BENT	850.20	850.20
1	RADIATOR FAN BLADE, COWLING, MOTOR ASSY	SERVICEABLE	792.95	-
2	RADIATOR BRACKET (LH/RH) @\$6.50	SERVICEABLE	13.00	-
2	RADIATOR GUARD @\$35.00	NO SUCH PARTS	70.00	-
2	HORN UNIT (LH/RH) @\$86.75	DISTORTED	173.50	173.50
1	HORN WIRE	SERVICEABLE	156.50	-
1	AIRCON CONDENSER	BENT	1,137.35	1,137.35
1	INTER COOLER	DENTED	921.90	921.90
2	INTER COOLER MOUNTING	SERVICEABLE	25.90	-
1	BOOT LID	BENT	1,681.40	1,681.40
1	BOOT LID RUBBER	DISTORTED	115.80	115.80
1	BOOT LID LOCK UPPER	BENT	137.90	137.90
1	BOOT LID LOCK LOWER	TO REPAIR SEE LABOUR	31.70	-
1	BOOT LID 'H' EMBLEM	NECESSARY	27.20	27.20
1	BOOT LID CRDI PLATE	NECESSARY	41.00	41.00
2	BOOT LID LAMP (LH/RH) @\$556.80	CRACKED	1,113.60	1,113.60
1	BOOT LID TRIMBOARD	TORN	172.70	172.70
10	BOOT LID TRIMBOARD CLIPS	NECESSARY	11.00	11.00
1	BOOTLID MOULDING	DISTORTED	85.00	85.00
1	BOOTLID 140 EMBLEM	NECESSARY	41.00	41.00

Report Ref No. CS/FCI17022650/M1vbe2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BOOTLID LOWER GARNISH	DISTORTED	398.00	398.00
1	REAR BUMPER	DEFORMED	603.60	603.60
1	REAR BUMPER REINFORCEMENT	BENT	504.35	504.35
2	REAR BUMPER REINFORCEMENT BRACKET (LH/RH) @\$180.00	N/S BENT / O/S SERVICEABLE	360.00	180.00
10	REAR BUMPER CLIP	NECESSARY	22.00	22.00
2	REAR BUMPER BRACKET @\$49.00	DISTORTED	98.00	98.00
1	REAR BUMPER SPONGE	TORN	143.40	143.40
1	REAR BUMPER UNDER COVER	DISTORTED	225.00	225.00
1	REAR BUMPER REFLECTOR LAMP (LH)	DISTORTED	32.00	32.00
2	TAIL LAMP (LH/RH) @\$565.60	CRACKED	1,131.20	1,131.20
1	TAIL LAMP QUARTER PANEL (LH)	TO REPAIR SEE LABOUR	97.90	-
1	REAR PANEL	BENT	592.30	592.30
1	REAR PANEL GARNISH	DISTORTED	57.70	57.70
1	REAR PANEL LOWER PANEL	BENT	495.50	495.50
1	SPARE TYRE HOLDER	NOT NECESSARY	28.80	-
1	SPARE TYRE PANEL	BUCKLED	900.50	900.50
1	SPARE TYRE PANEL CUSHION	SERVICEABLE	209.05	-
1	REAR TOWING HOOK	SERVICEABLE	94.60	-
1	MEMBER ASSY - REAR FLOOR CENTRE	TO REPAIR SEE LABOUR	170.75	-
1	PANEL ASSY-REAR FLOOR SIDE (LH)	TO REPAIR SEE LABOUR	92.40	-
1	REAR FLOOR CHASSIS MEMBER (LH)	TO REPAIR SEE LABOUR	4,232.50	-
2	EXHAUST PIPE INSULATOR @\$58.55	NOT NECESSARY	117.10	-
2	EXHAUST SILENCER @\$954.00	N/S BENT / O/S SERVICEABLE	1,908.00	954.00
2	EXHAUST PIPE HANGER @\$58.55	N/S DISTORTED	117.10	58.55
1	EXHAUST PIPE CENTRE	BENT	1,150.30	1,150.30
1	REAR FENDER WITH HOUSING (LH)	TO REPAIR SEE LABOUR	4,736.80	-
1	REAR FENDER INNER LINING (LH)	SERVICEABLE	164.40	-
1	REAR FENDER AIR-DUCT	SERVICEABLE	51.60	-

Report Ref No. CS/FCI17022650/M1vbe2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR FENDER TRIM BOARD (LH)	SERVICEABLE	188.75	-
1	REAR WINDSCREEN MOULDING	SERVICEABLE	60.00	-
	LESS 20% DISCOUNT		-6,435.54	-3,930.09
			25,742.16	15,720.36
	<b>SPECIAL NETT ITEMS</b>			
1	BOOT LID COMFORT LOGO & TEL NO. STICKER (SN)	NECESSARY	30.00	30.00
1	BOOT LID ADVERTISEMENT LOGO (SN)	NECESSARY	100.00	100.00
1	REAR BUMPER RUBBER MAT (SN)	NECESSARY	50.00	50.00
2	REAR FENDER ADVERTISEMENT LOGO (LH/RH) @\$100.00 (SN)	NECESSARY	200.00	200.00
1	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	46.00	-
			426.00	380.00
	<b>LABOUR</b>			
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF BOOT LID LOCK LOWER, TAIL LAMP QUARTER PANEL (LH), MEMBER ASSY - REAR FLOOR CENTRE, PANEL ASSY- REAR FLOOR SIDE (LH), REAR FLOOR CHASSIS MEMBER (LH) AND REAR FENDER WITH HOUSING (LH).		3,400.00	1,800.00
	SPRAY PAINTING CHARGE.		1,600.00	1,080.00
	WIRING CHARGE.		100.00	60.00
	TOWING CHARGE.		50.00	50.00
	REMOVE / REFILL AIRCON & REFILL GAS.		150.00	120.00
	TUFF KOTE.		100.00	60.00
	REAR CHASSIS ALIGNMENT CHARGE.	NOT NECESSARY	400.00	-
	REMOVE/ REFILL CUSHION & UPHOLSTERY REAR.		150.00	60.00
	REMOVE/ REFILL REAR WINDSCREEN GLASS.	NOT NECESSARY	120.00	-
	REMOVE/ REFILL FUEL TANK.	NOT NECESSARY	150.00	-
	REMOVE/ REFILL EXHAUST PIPE.		360.00	100.00
			-	-
			-	-
			-	-
			6,580.00	3,330.00
	<b>GRAND TOTAL</b>		<b>32,748.16</b>	<b>19,430.36</b>

Report Ref No. CS/FCI17022650/M1vbe2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			14,200.00
---	--	--	-----------

Report Ref No. CS/FCI17022650/M1vbe2

MA CHIN FOOK

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.