

M/S AXA INS (S'PORE) PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811

ESTIMATE

DATE : 28/11/2017
ACC DATE : 27/11/2017
REF NO. : VFIX-TP20170375
POLICY NO :

Attention: Motor Claim Department

RE : VEHICLE NO XD7299D IVECO TRAKKER

DESCRIPTION	AMOUNT S\$
1 1 FRONT BUMPER LH <i>Rx</i>	1,456.00
2 1 FRONT BUMPER END GARNISH LH <i>de</i>	230.00
3 1 STEP BOARD PLATE CENTER LH <i>cut</i>	1,127.00
4 1 STEP BOARD PLATE LOWER LH <i>dis</i>	725.00
5 1 STEP BOARD PLATE HOLDER LOWER LH <i>bt</i>	285.00
	<u>\$ 3,823.00</u>

LABOUR & MISCELLANEOUS:	AMOUNT S\$
1 To remove damaged parts with all necessary components/attachments apply hot-works where necessary straighten, repair member replace new parts refit align into position with all necessary components attachmets	<i>\$500</i> 800.00
2 To spray paint replaced/repaired body panels inclusive of preparatory works and painting materials	<i>400</i> 600.00
	<u>\$ 1,400.00</u>

GRAND TOTAL : \$ 5,223.00

SINGAPORE DOLLARS : FIVE THOUSAND TWO HUNDRED & TWENTY THREE ONLY

Vfix Auto Service Pte Ltd



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Tanfer 97495747
- WP'
30/11/17 @ 1020
B days
humpson
Resurvey after repair
sur@lkkauto.com