

Summary

Kalvin

REF:

CC3/TML7022655/K14bnz

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: SGM 7E

Policy No. MHO 01440

Claims No. M1706046

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHD 71317 Yr Regn: Nov 2016
 Type: M.Car / M.Cycle / Bus / Van / Lorry / T@ / Prime Mover /
 Truck / Trailer or
 Make: Hyundai Ix0 C.C. 1600
 Colour: Blue A/C: Insured / Std / NI / NA
 Sp. Reading: 168083 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: 1CMHCB414444096277
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD / Rim or
 Tyre Size: F: 205/60R16
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Hankook
 Front Rear
 R/Bal. 7 mm R/Bal. 7 mm
 L/Bal. 7 mm L/Bal. 7 mm
 D.O.A. 28/11/17 D.O.I. 28/11/17
 Survey held at (OAE (loging))
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Rear
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	SHD 71317 - CC3 / TML7022655 / K2b3
	SGM 7E - NA / MSC10010206 / W1
30/11/17	Continue PIP \$1526.18 / 2 P.Y.S. (Red: 1698.36 / 52%)

RECEIVED 01 DEC 2017

Date/Time, File Pass to?

1) 11/12 Typist

Date/Time, File Return to?

2)

☐ : Preli. Report

☒ : Final Report

Days Of Repair: 2

Resurvey No. of Trip: 1

Survey Fee:

Transportation

Add Fee:

☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

) \$ + RS \$

) Photos

) Others

TOTAL

250
10

260

Report Format: TP

Lump Sum / (B): (\$ 1526.18)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

TOKIO MARINE INSURANCE SINGAPORE LTD Ref : CC3/TMI17022655/K1tb

20 MCCALLUM STREET #09-01
TOKIO MARINE CENTRESINGAPORE 069046

Date : 28-11-2017

Code : TMI



1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SGM 7E	Veh. Inspected	SHD 7131T
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	28/11/2017

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

5. General Information

Accident Date	28/11/2017	Inspection Date	28/11/2017
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		

5a. Remarks

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	28/11/2017 11:25
Date Of Accident	28/11/2017 08:05
Exact Location Of Accident	PIE TOWARDS JURONG BEFORE JALAN EUNOS EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHD7131T
Insured/Policyholder	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768

Vehicle Particulars

Manufacturer	HYUNDAI
Model	I40
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	INDIA INTERNATIONAL INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	MCOM0016
Cover Note Number	

Driver

Name of Driver	GOH CHEE KIAT
NRIC No	S1182578H
Date Of Birth	17/12/1956
Occupation	OUTDOOR
Date Of Driving Pass	25/09/1979
Driving Experience	38 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	
Fax Number	
Contact Number	
EMail Address	GOHCHEEKIAT@YAHOO.COM

Address	BLK 556 PASIR RIS STREET 51 #03-153
Postcode	510556
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLS REFER TO ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	-
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGM7E
Vehicle Make/Model/Colour	
Details Of Properties	
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	TOKIO MARINE INSURANCE SINGAPORE LTD
Nature Of Damage	FRT
No. Of Passenger (Including Driver)	

Details of Witness

Name	
Phone Number	
Email Address	

DETAILS OF INJURED PERSON 1

Name	GOH CHEE KIAT
------	---------------

Approximate Age	61
Injuries Sustain	PAINS BEHIND THE BACK AND NECK.
Injured person in which vehicle?	SHD7131T
Were seat belts worn?	YES
Was injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

COMFORT TRANSPORTATION PTE. LTD.
CO. REG. NO. 192203321R


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Signature of the Reporting Centre Personnel

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

This morning (28/11/17), when I saw a private car in front stopped on PIE before Jalan Eunos exit, I braked and slowed down the speed and all of a sudden, car B (SG M 7E), a Mercedes behind, banged into the rear of my taxi.

One female passenger in my taxi.
I felt body pains following the accident.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION PTE LTD
CO. REG NO. 192702341R

Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

28/11/17

Im Ee Soon
CSO

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE*

Tokio Marine - CP/P)

TS

VEHICLE NO : SHD 7131T

DATE 28/11/2017

MAKE :

Tyre: Hankook

LKK - Kalvin

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Boot Lid 'H' Emblem X ^{an}			\$ 27.20
	Boot Lid CRDI Plate X ^{an}			\$ 41.00
	Bootlid Moulding X ^{an}			\$ 85.00
	Bootlid i40 Emblem X ^{an}			\$ 41.00
	Bootlid Lower Garnish X sm			\$ 398.00
	Rear Bumper / <i>Rehab</i>			\$ 603.60
	Rear Bumper Reinforcement X sm			\$ 504.35
	Rear Bumper Reinforcement Bracket (LH/RH) X sm	\$	180.00	\$ 360.00
	Rear Bumper Side Bracket X sm	\$	49.00	\$ 98.00
	Rear Bumper Clips / <i>rec</i>			\$ 22.00
	Rear Bumper Sponge X sm			\$ 143.40
	Rear Bumper Under Cover / <i>cut</i>			\$ 225.00
	SUB TOTAL			\$ 2,548.55
	LESS 20%			\$ 509.71
	DISCOUNTED TOTAL			\$ 2,038.84
	Boot Lid Comfort Logo & Tel No. Sticker X ^{an}			\$ 30.00
	Rear Bumper Reverse Sensor / <i>shorted</i>			\$ 135.70
	Rear Bumper Rubber Mat / <i>rec</i>			\$ 50.00
	Rear Bumper Advertisement Logo / <i>rec</i>			\$ 50.00
	Rear Fender Advertisement Logo (LH/RH) / <i>rec</i>	\$	100.00	\$ 200.00
				\$ 465.70
	Labour Charge			
	Panel Beating			\$ 350.00
	Spray Painting Charge			\$ 200.00
	Wiring Charge			\$ 50.00
	Remove/Refix Reverse Sensor			\$ 120.00
	<i>Meriam Fee \$10</i>			
	TOTAL LABOUR			\$ 720.00
	ESTIMATE TOTAL			\$ 3,224.54

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary term(s) must be resurveyed and approved by insurance company

Acknowledged by Repairer

Date:

Kalvin LKK/14

28/11/17 1345hrs.

2 Days.

P/P

Before Paint photo

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

ComfortDelGro Engineering Pte Ltd (Co. Reg No: 199506048W)

59 Loyang Drive
Singapore 508969
Tel: 6214 8300

TP INSURER: Tokio Marine Insurance Singapore Ltd (HQ)
CTPL

Singapore

PARTICULARS OF CLAIM

Claim Type: THIRD PARTY

Ref. No:

Policy No:

Date of Loss:

28/11/2017

Vehicle Reg. SHD7131T

Driveable?

NO

No.:

Party At UNKNOWN

Fault:

Make/Model: HYUNDAI I40, 1.7 D CRDI (A)

Vehicle Reg. Date:

10/11/2016

Vehicle BLUE

Gen Condition:

GOOD

Colour:

Engine No: D4FDGU689104

Chassis No:

KMHLB41UMHU096277

Odometer: 0 KM

Paint Type:

List Item 20.00 %

Discount:

Total Loss? NO

Est. 3

Duration of
Repair (day)

Present COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)

Location:

COST OF CLAIMS

Amount

Parts

2,504.54

Miscellaneous Items

10.00

Labour

720.00

Paintwork Labour

0.00

Towing

0.00

Gross Total (S\$)

3,234.54

+ GST 7.00% (S\$)

226.42

Nett Amount (S\$)

3,460.96

This claim is handled by: LIM TIEN SIONG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference****Part Source:** MRM-SG **Version:** 1.0 (Last Synchronised: 28 Nov 2017)**Parts:** 143 HYUNDAI I40 1.7 D CRDi (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** ComfortDelGro Engineering Pte Ltd/SHD7131T/28/11/2017 18:02**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*BOOTLID EMBLEM H	20.00	0.00	*27.20 FL	nn
2	1		*BOOTLID EMBLEM CRDI	20.00	0.00	*41.00 FL	nn
3	1		*BOOTLID MOULDING	20.00	0.00	*85.00 FL	nn
4	1		*BOOTLID EMBLEM I40	20.00	0.00	*41.00 FL	nn
5	1		*BOOTLID LOWER GARNISH	20.00	0.00	*398.00 FL	s/c
6	1		*REAR BUMPER	20.00	0.00	*603.60 FL	pe
7	1		*REAR BUMPER REINFORCEMENT	20.00	0.00	*504.35 FL	s/c
8	2		*REAR BUMPER REINFORCEMENT BRKT RH/LH	20.00	0.00	*360.00 FL	s/c
9	2		*REAR BUMPER SIDE BRKT RH/LH	20.00	0.00	*98.00 FL	s/c
10	10		*REAR BUMPER CLIPS	20.00	0.00	*22.00 FL	nec
11	1		*REAR BUMPER SPONGE	20.00	0.00	*143.40 FL	s/c
12	1		*REAR BUMPER UNDER COVER	20.00	0.00	*225.00 FL	cut
13	1		*BOOTLID COMFORTDELGRO	0.00	0.00	*20.00 F	nn
14	1		*BOOTLID 65521111	0.00	0.00	*10.00 F	nn
15	1		*REVERSE SENSOR	0.00	0.00	*135.70 F	short
16	1		*REAR BUMPER MAT	0.00	0.00	*50.00 F	nec
17	1		*REAR BUMPER ADVERTISEMENT STICKER	0.00	0.00	*50.00 F	nec
18	2		*REAR FENDER ADVERTISEMENT STICKER RH/LH	0.00	0.00	*200.00 F	nec

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	3,014.25
- List Item Discount on L Items (S\$)	509.71
Total Parts (S\$)	2,504.54

ComfortDelGro Engineering Pte Ltd/SHD7131T/28/11/2017 18:02. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	OD/TP Case (Insurer)	10.00
Sub Total (S\$)			10.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	PANEL BEATING	New	350.00 200
2	SPRAY PAINTING	New	200.00 180
3	WIRING CHECK	New	50.00 111
4	R/I REVERSE SENSOR	New	120.00 70
Gross Labour Cost (S\$)			720.00

ComfortDelGro Engineering Pte Ltd/SHD7131T/28/11/2017 18:02. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305092971
 REGN NO : SHD7131T
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : I-40
 DATE OF REGN : 10.11.2016
 DATE/TIME IN : 28.11.2017 09:45
 ACCIDENT DATE : 28.11.2017

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0103-0579-G	BUMPER REAR	1	603.60	20.00	482.88
0002	04-01-0101-0111-G	BUMPER CLIPS	10 L	22.00	20.00	17.60
0003	04-01-0103-0738-G	BUMPER LOWER REAR	1	225.00	20.00	180.00
0004	09-01-9999-0068-A	REVERSE SENSOR	1	135.70		135.70
0005	04-01-0103-1150-A	BUMPER PROTECTOR MAT	1	50.00		50.00

SUB-TOTAL : 866.18

JOB NATURE

0000 L	PANEL BEATING	200.00
0001 23-502	SPRAYPAINT ON AFFECTED AREA	180.00
0002 L	R/I REVERSE SENSOR	20.00
0003 20-05	TP MERIMEN	10.00
0004 20-05	Rear Bumper Adv.Sticker	50.00
0005 20-05	Rear Fender Adv.Sticker RH/H	200.00

REPAIR ESTIMATE

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305092971
REGN NO : SHD7131T
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 10.11.2016
DATE/TIME IN : 28.11.2017 09:45
ACCIDENT DATE : 28.11.2017

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

SUB-TOTAL : 660.00

TOTAL : 1,526.18


MVA NAME & SIGNATURE
DATE :

SURVEYOR NAME & SIGNATURE
DATE : _____

AUTHORISED : YES / NO

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508959
Fax: 6546 8156

Our Job Ref No : 305092971
Date : 29/11/17

FINALIZATION FORM


To : LKK Fax :
Attn : KALVIN ANG
Vehicle Reg No. : SHD7131T Date of Accident : 28-Nov-17


The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: TOKIO MARINE --- SGM 7E
2. The finalized amount shall be:

(a) Spare Parts after List discount	\$866.18
(b) Labour Charges	\$660.00
Total for Part-By-Part Repair Cost	\$1,526.18
(c.) Lumpsum Repair (if applicable)	
Total for Lumpsum repair cost after Less: 20%	
Final Lumpsum Repair cost	
3. Estimated normal period for repairs: 2 working days.
4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days
5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 
Name : LIM T S
Tel : 62148398
Fax : 65468156

Signature : 
Name : KALVIN
Date : 30/11/17

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid				
3. Survey Fees	-----			
4. LTA Search Fee				
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/TMI17022655/K1TBN2

Date: 06/12/2017

REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MH001440
Claimant Vehicle No :	SHD7131T	Insured Vehicle No :	SGM7E
Date of Loss:	28/11/2017	Nature of Claim:	TP
		Claim No:	M1706046

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD7131T	Engine No:	D4FDGU689104
Make & Model:	HYUNDAI I40, 1.7 D CRDi (A)	Chassis No:	KMHLB41UMHU096277
Reg. Date:	10/11/2016 (Man. Year: 2016)	Odometer:	168083 km
Colour:	Blue		
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

CONDITION OF TYRES

Front Tyre Size:	205/60R16	Rear Tyre Size:	205/60R16
Front Left Side:	Hankook 7 mm	Rear Left Side:	Hankook 7 mm
Front Right Side:	Hankook 7 mm	Rear Right Side:	Hankook 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,504.54	1,116.18	1,388.36	55.43
Miscellaneous Items	10.00	10.00	0.00	0.00
Labour	720.00	400.00	320.00	44.44
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	3,234.54	1,526.18	1,708.36	52.82
+ GST 7.00/7.00% (\$\$)	226.42	106.83	119.59	52.82
Nett Amount (\$\$)	3,460.96	1,633.01	1,827.95	52.82

INSPECTION

Date of Assignment:	29/11/2017	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	28/11/2017	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	2.0 days		

Adjuster: KALVIN ANG WEI KUN

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 06 Dec 2017)
Parts: 143	HYUNDAI I40 1.7 D CRDi (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SHD7131T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*BOOTLID EMBLEM H	Not Necessary	27.20 FL	*- FL
2	1	*BOOTLID EMBLEM CRDI	Not Necessary	41.00 FL	*- FL
3	1	*BOOTLID MOULDING	Not Necessary	85.00 FL	*- FL
4	1	*BOOTLID EMBLEM I40	Not Necessary	41.00 FL	*- FL
5	1	*BOOTLID LOWER GARNISH	Serviceable	398.00 FL	*- FL
6	1	*REAR BUMPER	Deformed	603.60 FL	*603.60 FL
7	1	*REAR BUMPER REINFORCEMENT	Serviceable	504.35 FL	*- FL
8	2	*REAR BUMPER REINFORCEMENT BRKT RH/LH	Serviceable	360.00 FL	*- FL
9	2	*REAR BUMPER SIDE BRKT RH/LH	Serviceable	98.00 FL	*- FL
10	10	*REAR BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
11	1	*REAR BUMPER SPONGE	Serviceable	143.40 FL	*- FL
12	1	*REAR BUMPER UNDER COVER	Cut	225.00 FL	*225.00 FL
13	1	*BOOTLID COMFORTDELGRO	Not Necessary	20.00 F	*- FS
14	1	*BOOTLID 65521111	Not Necessary	10.00 F	*- FS
15	1	*REVERSE SENSOR	Shorted	135.70 F	*135.70 FS
16	1	*REAR BUMPER MAT	Necessary	50.00 F	*50.00 FS
17	1	*REAR BUMPER ADVERTISEMENT STICKER	Necessary	50.00 F	*50.00 FS
18	2	*REAR FENDER ADVERTISEMENT STICKER RH/LH	Necessary	200.00 F	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3,014.25	1,286.30
- List Item Discount on L Items 20.00/20.00% (\$\$)	509.71	170.12
Total Parts (\$\$)	2,504.54	1,116.18

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	10.00	10.00
Sub Total (S\$)			10.00	10.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	350.00	200.00
2	SPRAY PAINTING	New	200.00	180.00
3	WIRING CHECK	New	50.00	-
4	R/I REVERSE SENSOR	New	120.00	20.00
Gross Labour Cost (S\$)			720.00	400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >