

View Received Message

This mail is associated with :

*SHD438E (C0460765) [SLD8160E]

TP
TRANS-CAB SERVICES PTE LTD
Nov 24 2017 9:00AM
[SEAN NG]
Trans-cab Auto Services Pte Ltd

Reply	Reply All	Mark as Unread	Print Message	Delete Message	Forward		
rom		surance Pte Ltd	(HQ) (AXA_SG)	, sent on 29/07/	2018 22:29 PM.		
o iubject	Alert -	Adj Mandate App	roved (S\$3616	.73) - SHD438E	- Claim Handler: I	rnest Tay	
DOCUM	ENTS SUM	IMARY					



51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL.: (065) 62563561 FAX: (065) 62564315

11 JANUARY 2018

SEAN NG BLK 55 TELOK BLANGAH DRIVE, #12-46 SINGAPORE 100055

Dear Sir/Madam,

OUR REF

: CC3/AXA17022657/Kwb3

YOUR REF

: SLD 8160E

ACCIDENT INVOLVING SLD 8160E AND SHD 438E ALONG HENDERSON ROAD ON 24,11,2017

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AXA Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from TRANS-CAB AUTO SERVICES PTE LTD, acting on behalf of the owner of SHD 438E against your motor insurance policy.

Based on the accident report, accident scenario, it was reported that your vehicle had collided to the Third Party vehicle SHD 438E while changing lane. As such, liability is down against us.

Please be informed that your No Claim Discount (NCD) may be affected as a result of the claim against your policy.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 7 days from the date of this letter.

Your full co-operation in the handling of the claim is required and kindly submit the following to vicalpeh@lkkauto.com within 7 days from the date of this letter if not provided at AXA's reporting centre. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- · Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- · Coloured photographs of damage to all vehicles involved (If any)
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)



51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

 If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AXA's prior knowledge and consent.

This letter should not be regarded as a waiver by AXA of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AXA shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6256 3561 or email us at vicalpeh@lkkauto.com.

Please quote the claim reference when you contact us that we can assist you more effectively.

Yours sincerely,

Siti

Case Handler DID: 6256 3561 FAX: 6741 4108

Email: vicalpeh@lkkauto.com

AXA Insurance Pte Ltd (AXA) C.C.

(Motor Claims Dept)

Trans-Cab Services Pte Ltd

No. 2 Ang Mo Kio Street 63

Tel No.: 6287 6666 Fax No. 6281 1400

Co./GST Reg. No. 200303878K

Authorization To Act

We, Trans-cab Services Pte Ltd of Company Registration No. 200303878K hereby authorize Trans-cab Auto Services Pte Ltd to act on behalf to claim for all losses incurred for the accident involving SHD0438E and SLD8160E along HENDERSON RD TOWARDS TELOK BLANGAH WAY on 24/11/17 09:30 AM.

In addition, we also hereby authorize the above payment to be made in favour of Trans-cab Auto Services Pte Ltd upon settlement.

Dated this 9 (day) of February 2018

Yours Faithfully

Trans-Cab Services Pte Ltd

Jasmine Tan

General Manager

TRANS-CAB AUTO SERVICES PTE LTD

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel: 6287 6565

Fax: 6281 1400

GST Reg No. : 201019626G Co. Reg No. : 201019626G

Autho	rization	to Act
MULIIO	12000	LU ALI

1	An Ying	Seng.	(Hire	7),	69 243].	_ (NRIC
		- 4	. 11		If to claim for n	
along	Hendy	Vison Vo	d towards	Telok	Blangah	nay
on W(u	i}_at_	09:40 hrs				
In addition, I Auto Services	-35		above payment	t to be made	in favour of T	rans-Cab
Dated this	•9	day of	Feb.	201g.		
(Hirer	's signature)					
Name:T	an Yong	Serg.		-		
NRIC Number:				_		



CLAIM REF INSURED

: (0460765 : SEMM NG.

		DISCHAR	RGE VOUCHER
autito	rans-Cab Auto Servi ised to and do hereby g Ton Yong Seng		at by letter of authorisation dated 9/2/18, we are irselves and on behalf of Trans-Cab Services Pte Ltd and the of vehicle no. 340 438 E
Now			elves and the said Hirer and the driver jointly and severally:-
a)	only (S\$ 3616-75 including damages for AXA INSURANCE F) in the aggregate i personal injuries and/or	in full and final settlement of all claims of whatever kind damage to property that all and any of us may have against insured and/or the driver of vehicle no (SLD 8160E) on 24 [11] 7.
b)	shall not be liable for a have against AXA IN	any further claim(s) wha	nd/or their Insured and/or the driver of the Insured vehicle atsoever or howsoever present or future that any of us may D and/or their Insured and/or the driver of vehicle no. a consequence of the accident and hereby give our full and
c)	We hereby declare that indertake to indemnify of this settlement.	AXA INSURANCE P	on(s) entitled to receive the above settlement and hereby TTE LTD against any claim made or to be made in respect
withou	derstood and agreed the tany admission of liab the driver of vehicle no	ility whatsoever on the p	ade in favour of Trans-Cab Auto Services Pte Ltd is made part of AXA INSURANCE PTE LTD and/or their Insured
Dated	his31 d d 628	7 6666 CC	2018
Signed		SED SIGNATORY)	
Comp	ny Stamp		
Witne		E TAN SIEW KINA 74056361	
Name I/C No	: TRANS-CAB A	UTO SERVICES PTE L'	ID

AXA Insurance Pte Ltd (Company Reg. No. 199903512M) 8 Shenton Way, #24-01 AXA Tower, Singapore 068811 Customer Centre #B1-01

Tel: +65 6880 4888 Fax: +65 6338 2522 Website: www.axa.com.sg

No. 2 Ang Mo Kio Street 63 Singapore 569111 Tel: 6287 6666 Fax: 6287 7764

Trans-Cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel: 6287 6666 Fax: 6287 7764

Co. Reg. No.: 201019626G GST Reg. No.: 201019626G

Tax Invoice / Debit Note

TO:

AXA INSURANCE PTE LTD 8 SHENTON WAY,#27-01

AXA TOWER

ATTENTION:

068811 SINGAPORE

: INV1712-244

: 29. December 2017 REFERENCE NO : AAD1711-271

TERMS

DUE DATE

INVOICE NO.

DATE

: 29. December 2017

PAGE : 1

AMOUNT QTY **UNIT PRICE** NO. CODE DESCRIPTION 2,979.88 2.979.88 REPAIR-SHD0438E;DOA 24.11.17(PART-BY-PART-17) 1 6050101

> 2,784.93 Total SGD Excl. GST:

7% GST: 194.95

**** TWO THOUSAND NINE HUNDRED SEVENTY NINE AND EIGHTY EIGHT SGD

ONLY ****

Total SGD Incl. GST: 2,979.88

¹⁾ All cheques should be crossed and made payable to "Trans-Cab Auto Services Pte Ltd"

²⁾ Please quote our Invoice Number during payment.

³⁾ We reserve the right to charge interest @ 1.5% per month on overdue invoice.

⁴⁾ Any dispute as to the accuracy, charges etc of this invoice must be communicated within 10 days from the date hereof falling which it shall be deemed to have been unconditionally accepted.

Trans-Cab Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Tel No.: 6287 6666 Fax No. 6281 1400 Co./GST Reg. No. 200303878K

09 February, 2018

To Whom It May Concern

Dear Sir / Madam,

Accident on 24/11/17 09:30 AM at HENDERSON RD TOWARDS TELOK BLANGAH WAY

- We refer to the above-mentioned accident and wish to inform that Trans-Cab Services Pte Ltd is the
 registered owner of the taxi bearing vehicle registration no. SHD0438E. The taxi was hired to TAN YONG
 SENG a registered hirer-operator of Trans-Cab Services Pte Ltd at the time of occurrence of the
 aforementioned accident at a rental rate \$107.88 per day (inclusive of GST).
- Please be advised that the Taxi is insured with AXA INSURANCE PTE LTD on a third party basis at the material time of the accident.
- 3. Please liaise with us directly for any settlement of claims in respect of the said accident.

Yours faithfully,

Jasmine Tan General Manager

Trans-Cab Services Pte Ltd

No. 2 Ang Mo Kio Street 63

Tel No.: 6287 6666 Fax No. 6281 1400

Co./GST Reg. No. 200303878K

24-11-2017

Dear Sir/Madam,

Please be informed that the taxi was undergo accident repair in the workshop as follow:

Date In	Date Out	Vehicle No.	
Accident No.	AAD1711-271		24-11-2017
24/11/2017	28/11/2017	SHD0438E	

Yours Faithfully,

Trans-Cab Services Pte Ltd

Jasmine Tan

General Manager



Vehicle Insurance Particulars Result

Vehicle No.	Incident Date/Time	Insurance Company Name
SLD8160E	24 Nov 2017 / 09:30:00	AXA INSURANCE PTE LTD
FBD8850R	23 Nov 2017 / 08:20:00	SOMPO INSURANCE SINGAPORE PTE. LTD.
PC507A	24 Nov 2017 / 15:30:00	NTUC INCOME INS CO-OP LTD

...CLAIM SUBFOLDER...(Pending for Survey Report) Direct Settlement

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj S	ubmitted	Ins Auth'ed	Status			
Main	30 Nov 2017	01 Dec 2017		S\$2,784.92 S\$2,78		784.92 w Rpt		Pending for Survey Report Cancel Case			
	Main	R	eference	Claim De	tails	\Box	Documents		Show All		
CLAIM SU	BFOLDER DE	TAILS				[Created	by insurer]				
Insured:	SEAN NG	EAN NG, ID: S8874912Z, Tel: +6592214267									
Main Claimant:	TRANS-CA	AB SERVICES PT	ELTD, Co. Reg. M	io.: 200303878K							
Vehicle Reg No.:	SHD438	E		Date of	Loss:		7 09:00 - :59 and 28 Days From	LTA Reg Date	e (Man Yr)]		
Claim Type:	TP / C04	60765		Policy/0 Note N		GA219304	(Comprehensive)				
Vehicle Reg No. (Insured):	The Contract of the Contract o	SLD8160E			lo. nt):	VPX/P1680520					
		Excess: 5\$0.00									
Repairer:	Trans-cat	Auto Services	Pte Ltd (Ang Mo Ki	a) 2, Ang Mo Kio S	reet 63	, 569111 A	ng Mo Kio - Tel: 6	2876666			
Handling Insurer:	AXA Insu	rance Pte Ltd (H	(Q) - Tel: 6338 7288	[Handled by Ki	or Saw	Theng - 6	880 4754]				
Claimant's Insurer:	AXA Insu	rance Pte Ltd (H	(Q) - Tel: 6338 7288	1							
Adjuster:	LKK Auto	Consultants Pte	Ltd (HQ) - Tel: 62	56-3561 [Handle	d by KE	NNETH KO	NG] [Final R	tpt due 12/	12/2017]		
Driver/Custo dian (Insured):), NRIC: S8874	912Z, Tel: +6592	214267			\$1 VA				
ASSOCIAT	ED MAIL RE	CEIVED					Vies	w All Com	pose Case Ma		
			ndate Approved (S ment - C0460765		38E - (Claim Hand	iler: Ernest Tay				
ALL ASSO	CIATED TAS	ks⊟			V	ew All S	Search Tasks C	reate New Task	Complet		
Due Date	Priority	Type Task	Group Subjec	t Handler	Assigne	d By	Completed On	Created	On Don		

Claim Documents

*SHD438E (C0460765)
[SLD8160E]
TP
TRANS-CAB SERVICES PTE LTD
Nov 24 2017 9:00AM
[SEAN NG]
Trans-cab Auto Services Pte Ltd

_	oload Documents U	pload Photos Compose New Letter Upload Video Upload Audio	Paramonian	Type 1	proje
Let	ters/Corresponder	nces	1 per	NAME OF TAXABLE PARTY.	V
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	_	Thumbnail	Print
1	(Draft)	Third Party Express Settlement - Payment Breakdown	0	Edit	-
Ass	essment Reports		1 per	page 🔻	V
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	01/12/17 08:56	Adjuster Immediate Advice	0	Load HTM	
Pho	otos/Images		3 per	page V	V
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	[3.55]	Thumbnail	-
1	06/03/18 14:58	General View	0	Load JPG	V
2	06/03/18 14:58	General View	0	Load JPG	V
3	06/03/18 14:58	General View	0	Load JPG	V
4	06/03/18 14:58	General View	0	Load JPG	V
5	06/03/18 14:58	General View	0	Load JPG	V
6	06/03/18 14:58	General View	0	Load JPG	V
7	06/03/18 14:58	General View	0	Load JPG	V
8	06/03/18 14:58	General View	0	Load JPG	V
9	06/03/18 14:58	General View	0	Load JPG	Ø
Doc	cumentation		1 per s	page V	V
No	Finalized On	AXA Insurance Pte Ltd (HQ)	11 per i	Thumbnail	1
1	30/11/17 15:07	EMAIL ABS	0	Load PDF	Print
2	30/11/17 15:07	SLD8160E GIA REPORT_ABS	0	Load PDF	
3	30/11/17 15:07	TP ESTIMATE- MARKED_ABS	ő	Load PDF	
4	30/11/17 15:07	TP GIA REPORT_ABS	ő	Load PDF	
5	30/11/17 17:11	Certificate of Insurance -GA219304	ő	Load PDF	
6	30/11/17 17:11	Certificate Schedule -GA219304	Ö	Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	12/01/18 14:50	LETTER TO OI	0	Load PDF	2.00
2	26/02/18 15:09	RENTAL RECEIPT	0	Load PDF	
3	26/02/18 15:09	LTA SEARCH	0	Load PDF	
4	02/08/18 08:53	WORKSHOP INVOICE	0	Load PDF	
5	02/08/18 08:53	AUTHORISATION TO ACT FORM	0	Load PDF	
6	02/08/18 08:53	DISCHARGE VOUCHER	0	Load PDF	
7	02/08/18 08:53	LOD	0	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
3 7 7 8 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7			

Merimen e-Claims Page 2 of 2

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	
•	
Show Remarks To: Handling Insurer Note: Remarks are private unless you show it to other parties.	

Page 1 of 1

NOTE: TO BE COMPLETED BY SURVEYOR

	_		-
т	E	A	N
а.		m	uΨ

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vel	nicle No:	SLD8160E (Insd vel	h)	Mod	lel:			RENAU	LT LATITUDE 2.0 CVT	
		SHD438E (TP veh)						ABS (A)		
Dat	te of Accident:									
Glo	bal Sum Settlem	nent : [] Yes	_	[X]	No					
-	pair Estimate	ient . 1 1 163	: \$		6,527.	11				
-	al Repair Cost		:\$	-	2,979	_				
	s of Token Sum	K	: \$		COSTA	0.00	- 5	4.00 da	ys at \$50.00 per day	
	ntal (if any)		: \$		11000	.52			ys at coolee per coy	
	A / GIA Search F	ee	: \$.35		100	, u	
_	ers:		: \$			0.00				
-			: \$							
Fin	al Settlement Su	ım	: \$		3,616	.75				
Is 1	20	kshop GIA Registered	4? [1	YES	_	x]	NO	(Kindly indicate	
_		egistered Workshop:	8	Agre	ed Liab	oility	<u></u>	100	(%)	
B)	BOLA Liability: * Assessed Lia	tered Workshop:(%) bility to be filled only fo		collision	s and f	or c	ases v	vhere B	A 1947 (A 1940) - A 1947 (A 1947) - A 1947 (A 19	
		3 MO KIO ST 63 SING	SAPORE	56911	1.					
Pav	ment Instruction	on: Payee's Breakdow	/n							
1)		o Services Pte Ltd			: \$				3,616.75	
2)		AND SOUTH OF THE PROPERTY OF			: \$				2-5-8-0-19-0	
3)					: \$					
4)					: \$					
5)					: \$					
	JOANNE I	LEE KHANG MIN			Aug 18					

Please attach all the supporting documents to the form. (Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any)

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CC3/AXA17022657/KWB3Q2

Date:

02/08/2018

REFERENCE

Handling Insurer: AXA Insurance Pte Ltd

Policy No:

GA219304

Claimant Vehicle No :

SHD438E

Insured Vehicle No :

SLD8160E

Date of Loss:

24/11/2017

Nature of Claim:

TP

Claim No:

C0460765

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SHD438E

Make & Model:

RENAULT LATITUDE, 2.0 CVT ABS (A) 27/04/2017 (Man. Year: 2016) Engine No: Chassis No: M9R8839C003338

Reg. Date: Colour:

Metallic White/Red

Odometer:

VF1ABL15AUC283409 59209 km

Engine Capacity:

1995 cc

Market Value/New Car Price: N/A Sum Insured (S\$): Mar

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes Engine Modification:

No Pre-accident Condition:

165

CONDITION OF TYRES

Front Tyre Size:

215/60 R16

Rear Tyre Size:

215/60 R16

Front Left Side: Front Right Side: Falken 8 mm

Rear Left Side: Rear Right Side: Goodyear 8 mm Goodyear 8 mm

Front Right Side: Falken 8 mm
The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	26,597.49	1,904.92	24,692.57	92.84
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,540.00	880.00	6,660.00	88.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	34,137.49	2,784.92	31,352.57	91.84
+ GST 7.00/7.00% (S\$)	2,389.62	194.94	2,194.68	91.84
Nett Amount (S\$)	36,527.11	2,979.86	33,547.25	91.84
+ Loss of Use (4.0 x 5	S\$50.00/day) (S\$)	200.00		
+ Car Rental (4.0 x S	\$107.88/day) (S\$)	431.52		

+ Doc/Search Fee (S\$)

Nett Liability (S\$)

INSPECTION

Date of Assignment:

01/12/2017

Date Inspected:

27/11/2017 Inspected At:

Trans-cab Auto Services Pte Ltd (Ang Mo

Kio)

5.35

3,616.73

2, Ang Mo Kio Street 63 Singapore 569111

Estimated Period of Repair:

2.0 days

Adjuster Report Page 2 of 5

Adjuster: KENNETH KONG Manager: VIVIAN LAU PEI FENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Page 3 of 5

REPAIR DETAILS

Referen	ce		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 26 Feb 2018)	
Parts:	143	RENAULT LATITUDE 2.0 CVT ABS (A) (Catalogue:Merimen Singapore 1.0)	
Labour:	Repairer's	(Price-denominated Standard List)	
Print Code:	(Unsubmitted, no print-code for SHD438E)		
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page		
Further Info:	Items/values	not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER FRT (CONSISTENT)	Buckled	1,259.42 FL	*1,259.42 FL
2	1		*BUMPER ABSORBER FRT (CONSISTENT)	Serviceable	394.68 FL	*-FL
3	1		*BUMPER BRAM FRT (CONSISTENT)	Repair	914.08 FL	*-FL
4	1		*BUMPER SPOILER FRT (CONSISTENT)	Serviceable	181.75FL	*-FL
5	1		*BUMPER GRILLE LOWER FRT (CONSISTENT)	Serviceable	266.80 FL	*-FL
6	1		*BUMPER FOG LAMP GRILLE LH (CONSISTENT)	Serviceable	207.22 FL	*-FL
7	1		*BUMPER RETAINER FRT RH (CONSISTENT)	Serviceable	151.41 FL	*- FL
8	1		*BUMPER BRACKET FRT RH (CONSISTENT)	Serviceable	181.75 FL	*-FL
9	1		*HEADLAMP RH (CONSISTENT)	Serviceable	1,184.43 FL	*-FL
10	1		*HEADLAMP PANEL FRT RH (CONSISTENT)	Repair	152.15 FL	*-FL
11	1		*FENDER PANEL FRT RH (CONSISTENT)	Bent	783.83 FL	*783.83 FL
12	1		*FENDER INSULATOR RH (CONSISTENT)	Serviceable	130.84 FL	*-FL
13	1		*FENDER BRACKET FRT RH (CONSISTENT)	Serviceable	34.14 FL	*-FL
14	1		*WHEELARCH FRT RH (CONSISTENT)	Serviceable	278.84 FL	*-FL
15	1		*RADIATOR GRILLE (CONSISTENT)	Serviceable	1,707.78 FL	*-FL
16	1		*RADIATOR GRILLE BADGE RENAULT (CONSISTENT)	Serviceable	173.36 FL	*-FL
17	1		*RADIATOR GRILLE FRAME (CONSISTENT)	Serviceable	1,353.75 FL	*-FL
18	1		*FRAME FULL SUPPORT PANEL (CONSISTENT)	Repair	615.90 FL	*-FL
19	1		*FRAME FULL SUPPORT BRACKET (CONSISTENT)	Repair	89.79 FL	*-FL
20	1		*BONNET (CONSISTENT)	Repair	1,941.63 FL	*-FL
21	1		*LOWER ARM RH (CONSISTENT)	Serviceable	685.76 FL	*-FL
22	1		*KNUCKLE ARM RH (CONSISTENT)	Serviceable	846.98 FL	*-FL
23	1		*ABSORBER FRT RH (CONSISTENT)	Serviceable	360.54 FL	*-FL
24	1		*WHEEL HOUSE PANEL FRT RH (CONSISTENT)	Repair	4,682.09 FL	*-FL
25	1		*DOOR PANEL FRT RH (CONSISTENT)	Repair	2,844.66 FL	*-FL
26	1		*DOOR HINGE UPPER RH (CONSISTENT)	Repair	274.50 FL	*-FL
27	1		*DOOR HINGE LOWER RH (CONSISTENT)	Repair	300.55 FL	*-FL
28	1		*DOOR MOULDING FRT RH (CONSISTENT)	Serviceable	176.82 FL	*-FL
29	1		*DOOR MIRROR RH (CONSISTENT)	Serviceable	1,483.40 FL	*-FL
30	1		*DOOR MIRROR GLASS RH (CONSISTENT)	Serviceable	148.20 FL	*-FL
31	1		*DOOR MIRROR BACK COVER RH (CONSISTENT)	Serviceable	218.46 FL	*-FL
32	1		*DOOR WEATHERSTRIP FRT RH (CONSISTENT)	Serviceable	474.21 FL	*-FL
33	1		*DOOR SEAL FRT RH (CONSISTENT)	Serviceable	68.67 FL	*-FL
34	1		*ROCKER PANEL OUTER RH (CONSISTENT)	Repair	987.49 FL	*-FL
35	1		*DOOR PANEL REAR RH (CONSISTENT)	Repair	2,844.66 FL	*-FL
36	1		*SET WHEELARCH CLIP FRT RH (CONSISTENT)	Not Necessary	66.00 FS	*-FS
37	1		*SET FRONT BUMPER CLIP (CONSISTENT)	Necessary	66.00 FS	*66.00 FS
38	1		*RIM RH FRT (CONSISTENT)	Serviceable	385.00 FS	*-FS
39	1		*TYRE RH FRT (CONSISTENT)	Serviceable	330.00 FS	*-FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1		*DOOR STICKER TRANS-CAB (CONSISTENT)	Not Necessary	80.00 FS	*-FS
41	1		*DOOR STICKER CLASSIC (CONSISTENT)	Not Necessary	30.00 FS	*-FS
42	1		- 1. Thi A. (1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1	Not Necessary	80.00 FS	*-FS
5736	F=Franchise part. S=SpcNett. L=ListIttemDisc. Sub Total (S\$) - List Item Discount on L Items 10.00/10.00% (S\$)					2,109.25 204.33
			1	otal Parts (S\$)	26,597.49	1,904.92
			Report was unsubmitted during this print-	out.		

Adjuster Report Page 5 of 5

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	10.00
2	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	2,800.00	400.00
3	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	3,000.00	440.00
4	TO TRANSFER OF FENDER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
5	TO TRANSFER OF TIRE ,RIM AND ON WHEEL BALANCING	New	170.00	0.00
6	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
7	TO REMOVE AND REFIT FRONT W/SCREEN GLASS TO FACILITATE BODYWORK REPAIR	New	170.00	0.00
В	TO TRANSFER OF DOOR FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
9	TOWING FEES	New	120.00	0.00
10	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	30.00
11	TO DISMANTLE AND REFIT FRONT END SUSPENSION, UNDERCARRIAGE PARTS, FINAL CHECKING AND TESTING	New	380.00	0.00
	Gross Labou	r Cost (S\$)	7,540.00	880.00

< END OF ESTIMATES >