

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD438E - AXA**AAD1711-271**

Not Notified
Runny B4 pain 82784.93

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHD438E - JHOW

VF1ABL15AUC283409

RENAULT

LATITUDE

24.11.2017

AXA**PART****LIST**

1	1	BUMPER COVER FRT	\$	<i>Bu</i> 1,259.42 ✓
2	1	BUMPER ABSORBER FRT	\$	<i>Sn</i> 394.68 X
3	1	BUMPER BEAM FRT	\$	<i>R</i> 914.08 X
4	1	BUMPER SPOILER FRT	\$	<i>Sn</i> 181.75 X
5	1	BUMPER GRILLE LOWER FRT	\$	<i>Sn</i> 266.80 X
6	1	BUMPER FOG LAMP GRILLE RH	\$	<i>Sn</i> 207.22 X
7	1	BUMPER RETAINER FRT RH	\$	<i>Dis</i> 151.41 X
8	1	BUMPER BRACKET FRT RH	\$	<i>Sn</i> 181.75 X
9	1	HEADLAMP RH	\$	<i>Sn</i> 1,184.43 X
10	1	HEADLAMP PANEL FRT RH	\$	<i>R</i> 152.15 X
11	1	FENDER PANEL FRT RH	\$	<i>Bu</i> 783.83 ✓
12	1	FENDER INSULATOR RH	\$	<i>Sn</i> 130.84
13	1	FENDER BRACKET FRT RH	\$	<i>Sn</i> 34.14
14	1	WHEELARCH FRT RH	\$	<i>Sn</i> 278.84
15	1	RADAITOR GRILLE	\$	<i>Sn</i> 1,707.78
16	1	RADAITOR GRILLE BADGE 'RENAULT'	\$	<i>Sn</i> 173.36
17	1	RADAITOR GRILLE FRAME	\$	<i>Sn</i> 1,353.75
18	1	FRAME FULL SUPPORT PANEL	\$	<i>R</i> 615.90
19	1	FRAME FULL SUPPORT BRACKET	\$	<i>R</i> 89.79
20	1	BONNET	\$	<i>R</i> 1,941.63 } X
21	1	LOWER ARM RH	\$	<i>Sn</i> 685.76
22	1	KUNCKLE ARM RH	\$	<i>Sn</i> 846.98
23	1	ABSORBER FRT RH	\$	<i>Sn</i> 360.54
24	1	WHEEL HOUSING PANEL FRT RH	\$	<i>R</i> 4,682.09
25	1	DOOR PANEL FRT RH	\$	<i>R</i> 2,844.66
26	1	DOOR HINGE UPPER RH	\$	<i>R</i> 274.50
27	1	DOOR HINGE LOWER RH	\$	<i>R</i> 300.55
28	1	DOOR MOULDING FRT RH	\$	<i>Sn</i> 176.82
29	1	DOOR MIRROR RH	\$	<i>Sn</i> 1,483.40
30	1	DOOR MIRROR GLASS RH	\$	<i>Sn</i> 148.20
31	1	DOOR MIRROR BACK COVER RH	\$	<i>Sn</i> 218.46
32	1	DOOR WHETHERSTRIP FRT RH	\$	<i>Sn</i> 474.21
33	1	DOOR SEAL FRT RH	\$	<i>Sn</i> 68.67
34	1	ROCKER PANEL OUTER RH	\$	<i>R</i> 987.49

TRANS-CAB AUTO SERVICES PTE LTD

AAD1711-271

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD438E - AXA

35	1	DOOR PANEL REAR RH	\$	<i>nn</i> 2,844.66 <i>X</i>
----	---	--------------------	----	-----------------------------

TOTAL	\$	<u>28,400.54</u>
10%	\$	<u>2,840.05</u>
	\$	<u>25,560.49</u>

Specical Nett

1	1SET	WHEELARCH CLIP FRT RH	\$	<i>nn</i> 66.00 <i>X</i>
2	1SET	FRONT BUMPER CLIP	\$	<i>nn</i> 66.00 <i>✓</i>
3	1	RIM RH FRT	\$	<i>nn</i> 385.00 <i>X</i>
4	1	TYRE RH FRT	\$	<i>nn</i> 330.00 <i>X</i>
5	1	DOOR STICKER "Trans-cab"	\$	<i>nn</i> 80.00 <i>X</i>
6	1	DOOR STICKER "Classic"	\$	<i>nn</i> 30.00 <i>X</i>
7	1	DOOR STICKER "6555-3333"	\$	<i>nn</i> 80.00 <i>X</i>

TOTAL	\$	<u>1,037.00</u>
TOTAL PARTS	\$	<u>26,597.49</u>

To Check Electrical Lighting Concerned.	\$	170.00 <i>100</i>
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	2,800.00 <i>400</i>
Putty and spray painting of the affected portion.	\$	3,000.00 <i>440</i>
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	<i>nn</i> 170.00 <i>X</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>nn</i> 170.00 <i>X</i>
To check steering geometry and computer wheel alignment	\$	<i>nn</i> 220.00 <i>X</i>
To Remove And Refit Front W/Screen Glass To Facilitate Bodywork Repair.	\$	<i>nn</i> 170.00 <i>X</i>
To transfer of door fittings, attachment and perform water seepage test.	\$	<i>nn</i> 170.00 <i>X</i>
Towing fees	\$	<i>nn</i> 120.00 <i>X</i>

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD438E - AXA**AAD1711-271**

To rust-proofing of the affected areas. \$ 170.00 *30/*

To dismantle and refit front end suspension,
undercarriage parts, final checking and testing. \$ *~ 380.00 X*

TOTAL	\$	7,540.00
Over All Total	\$	34,137.49

(PARTS BY PARTS) Repair Days**10 Days***2 days*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: