




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC3/AIG17022659/K1ka3		
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 28-11-2017		
		Code : AIG		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJN 1479D	Veh. Inspected	SHC 2772G	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	28/11/2017	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	24/11/2017	Inspection Date	27/11/2017	
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Team: ARC Repair TP(CLSO)1		JOB CARD Sales Order:		JC NO.305092148
CUSTOMER		REGN NO:	MILEAGE	
COMFORT TRANSPORTATION PTE LTD		SHC2772G		
MS 7010045		MAKE:	FUEL	
CUSTOMER NO 383 SIN MING DRIVE		HYUNDAI	E 1/2 F	
ADDRESS Singapore SINGAPORE 575717		MODEL	DATE/TIME IN	
(R) 65508755 (O)		SONATA	24.11.2017 20:00	
(P)		YR OF MANU	TARGET DATE	
		31.07.2012		
COUNT CARD NO.		CHASSIS CODE	COMPLETION DATE/TIME	
		FMHET41VMCA827789		

Accident Date: 24.11.2017
NATURE: 3P 24.11.2017

JOB DESCRIPTION

S / NO	LABOR CODE	DESCRIPTION
		ACC - taxi Rear damage
		LKK/KALVIN -

CHECKED & PASSED OUT BY:			
SERVICE ADVISOR		CUSTOMER'S SIGNATURE	
Acknowledgement Slip		Exit Pass	
Vehicle No.: SHC2772G		Vehicle No.: SHC2772G	
Name of Service Advisor		Name of Service Advisor	
Signature/Date		Date	
returned to Service Reception upon collection		To be kept by Security Guard	

COMFORTDELGRO ENGINEERING

Our Job Ref No. : 305092148

Date : 27.11.2017

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK

Fax :

Attn : KALVIN

Vehicle Reg No. : SHC2772G

Date of Accident: 24.11.2017

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: AIG SJN1479D

2. The finalized amount shall be:

(a) Spare Parts after List discount

(b) Labour Charges

Total for Part-By-Part Repair Cost

(c) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less:

Final Lumpsum Repair cost

\$2,950.00

3. Estimated normal period for repairs: 4 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount.

Signature : 

Name : Larry Ng

Tel : 6214 8316

Fax : 8546 8156

Signature : 

Name : K. Goh

Date : 28/11/17

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid				
3. Survey Fees				
4. LTA Search Fee	\$5.35			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

REPAIR ESTIMATE*

VEHICLE NO : SHC 2772G

DATE 25/11/2017 10:28

MAKE :

DOA: 24.11.2017

MODEL : HYUNDAI SONATA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Boot Lid <i>Defect</i>			\$ 1,349.50
	Boot Lid Rubber <i>X sue</i>			\$ 110.90
	Boot Lid Lock Upper <i>X sue</i>			\$ 132.10
	Boot Lid Lock Lower <i>X sue</i>			\$ 30.30
	Boot Lid Sonata Plate <i>nee</i>			\$ 43.60
	Boot Lid Hyundai Plate <i>nee</i>			\$ 24.20
	Boot Lid 'H' Emblem <i>nee</i>			\$ 26.10
	Boot Lid CRDI Plate <i>nee</i>			\$ 22.70
	Rear Bumper <i>Defect</i>			\$ 578.40
	Rear Bumper Reinforcement <i>cra</i>			\$ 483.30
	Rear Bumper Clip <i>nee</i>			\$ 22.00
	Rear Bumper Bracket <i>X sue</i>		\$ 49.00	\$ 98.00
	Rear Bumper Sponge <i>tee</i>			\$ 137.40
	Rear Bumper Under Cover <i>nee</i>			\$ 185.80
	Rear Bumper Protector (LH/RH) <i>X sue</i>		\$ 38.00	\$ 76.00
	Rear Panel <i>X sue</i>			\$ 391.80
	Rear Panel Garnish <i>X sue</i>			\$ 95.80
	Spare Tyre Holder <i>X sue</i>			\$ 27.60
	Spare Tyre Panel <i>X sue</i>			\$ 863.00
	Spare Tyre Panel Cushion <i>X sue</i>			\$ 200.30
	Rear Towing Hook <i>X sue</i>			\$ 135.30
	Member Assy- Rear Floor Centre <i>X sue</i>			\$ 163.60
SUB TOTAL				\$ 5,197.70
LESS 20%				\$ 1,039.54
DISCOUNTED TOTAL				\$ 4,158.16
	Boot Lid Comfort Logo & Tel No. Sticker <i>nee</i>			\$ 30.00
	Rear No. Plate <i>X sue</i>			\$ 25.00
	Rear Bumper Reverse Sensor <i>should</i>			\$ 135.70
				\$ 190.70
Labour Charge				
	Panel Beating			\$ 1,500.00
	Spray Painting Charge			\$ 800.00
	Wiring Charge			\$ 50.00
	Tuff Kote			\$ 50.00
	Remove/Refix Reverse Sensor			\$ 120.00
	Towing (Kilometrage)			\$ 150.00
TOTAL LABOUR				\$ 2,520.00
ESTIMATE TOTAL				\$ 6,868.86

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHC 2772G

DATE 25/11/2017 10:28

MAKE :

MODEL : HYUNDAI SONATA

AIG

DOA: 24.11.2017

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Boot Lid ✓			\$ 1,349.50	
	Boot Lid Rubber ✕			\$ 110.90	
	Boot Lid Lock Upper ✕			\$ 132.10	
	Boot Lid Lock Lower ✕			\$ 30.30	
	Boot Lid Sonata Plate ✓			\$ 43.60	
	Boot Lid Hyundai Plate ✓			\$ 24.20	
	Boot Lid 'H' Emblem ✓			\$ 26.10	
	Boot Lid CRDI Plate ✓			\$ 22.70	
	Rear Bumper ✓			\$ 578.40	
	Rear Bumper Reinforcement ✓			\$ 483.30	
	Rear Bumper Clip ✓			\$ 22.00	
	Rear Bumper Bracket ?		\$ 49.00	\$ 98.00	
	Rear Bumper Sponge ?			\$ 137.40	
	Rear Bumper Under Cover ✓			\$ 185.80	
	Rear Bumper Protector (LH/RH) ✕		\$ 38.00	\$ 76.00	
	Rear Panel ✕			\$ 391.80	
	Rear Panel Garnish ?			\$ 95.80	
	Spare Tyre Holder ?			\$ 27.60	
	Spare Tyre Panel ?			\$ 863.00	
	Spare Tyre Panel Cushion ?			\$ 200.30	
	Rear Towing Hook ?			\$ 135.30	
	Member Assy- Rear Floor Centre ?			\$ 163.60	
	SUB TOTAL			\$ 5,197.70	
	LESS 20%			\$ 1,039.54	
	DISCOUNTED TOTAL			\$ 4,158.16	
	Boot Lid Comfort Logo & Tel No, Sticker ✓			\$ 30.00	Nett
	Rear No. Plate ✕			\$ 25.00	Nett
	Rear Bumper Reverse Sensor ✓			\$ 135.70	Nett
				\$ 190.70	
	Labour Charge				
	Panel Beating			\$ 1,500.00	
	Spray Painting Charge			\$ 800.00	5%
	Wiring Charge			\$ 50.00	✕
	Tuff Kote			\$ 50.00	2%
	Remove/Refix Reverse Sensor			\$ 120.00	2%
	TOWING (KING DOLBY)			\$ 150.00	50
	TOTAL LABOUR			\$ 2,520.00	
	ESTIMATE TOTAL			\$ 6,868.86	
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					

Larry Ng

Our Ref : T 1117 / SHC2772G /CL(st)
Your Ref: _____
Date : 8-Dec-17

AIG ASIA PACIFIC INSURANCE PTE LTD
CHARTIS Building
78 Shenton Way
#07-16
Singapore 079120

Attn : Motor Claims Department WITHOUT PREJUDICE

Dear Sir

ACCIDENT INVOLVING OUR TAXI SHC2772G YOUR INSURED SJN1479D
AND OTHER SJW6297G ON 24.11.17

We are the authorised repair workshop for Comfort Transportation Pte Ltd, the owner of motor Vehicle No : SHC2772G which was involved in the captioned accident with your insured vehicle. The vehicle owner and the taxi driver concerned have requested and authorized us to assist them in presenting their claims against the party responsible for all applicable matters arising from the damage to the vehicle.

As the accident was caused by the negligent act of your insured driving SJN1479D we are submitting these claim for your consideration on behalf of the claimants.

TAXI OWNER'S CLAIM

1	Cost of Repair	\$	3,156.50
2	<u>4.5</u> days Loss of Rental @ \$ <u>98.25</u> per day	\$	442.13
3	Survey Report Fees <i>(Surveyed by M/s LKK)</i>	\$	-
4	GIA / LTA Search Fees	\$	5.35
5	GIA / Police Report Fees	\$	-
6	Towing / Medical / Transportation	\$	-
Sub Total :		\$	3,603.98

HIRER'S CLAIM

7	<u>4.5</u> days Loss of Income @ \$ <u>80.00</u> per days	\$	360.00
Total Claims :		\$	3,963.98

We enclosed herewith the following documents to support the claims: -

- a) Original repair bill and photocopies of photographs : 4 pcs.
b) LTA search slip/s of : SJN1479D
c) GIA / Police report/s of : SHC2772G
d) Letter of authority from owner / hirer / operator
(X) Photograph/s of Accident Scene () Certificate of Insurance
() Witness statement/s (x) Downtime/Mileage record

Kindly look into the matter and let us hear from you on the settlement of the said claims as soon as possible.

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the taxi driver.

Yours faithfully
Cecilia Lee

Executive
CDGE Claims Department
Tel : 6214 8354 Fax: 6214 1843 Email : cecilialee@sparkcarcare.com

This is a computer generated letter. No signature is required.

ComfortDelGro Engineering Pte Ltd
205 Braddell Road Singapore 579701

CDGE Taxi Claims Dept
59 Loyang Drive 4th Flr
Singapore 508969

Mainline +65 6383 6280
Facsimile +65 6280 9755

www.cdge.com.sg

Company Registration No. 196486489

Workshops

Braddell
205 Braddell Road
Singapore 579701

Loyang
59 Loyang Drive
Singapore 508969

Sin Ming
383 Sin Ming Drive
Singapore 575717

Pandan
45 Pandan Road
Singapore 609286

Ubi
320 Ubi Road 3
Singapore 408649

Senoko
24 Senoko Loop
Singapore 758155

Sungei Kadut
7 Sungei Kadut Way
Singapore 728791

Yishun
501 Yishun Industrial Park A
Singapore 768732

DATE	HOURS OPERATED (TIME)		DATE	NAME OF DRIVER	MILEAGE READING		MILEAGE TRAVELLED (KM)	HOURS OPERATED (TIME)	
	FROM	TO						FROM	TO
6	0825	2220	24.11.17	ACCIDENT			14	0800	-
	0830	0130	28.11.17	PAPERWORK			0017	-	1115
	1140	2135							
	1105	2020							
	0825	2225							
	0800	2305							
	0830	2210							
	0830	2255							
	0830	1811							

Zaini (LKK Auto)

From: Zaini (LKK Auto)
Sent: Thursday, 30 November, 2017 4:33 PM
To: 'PSYC71@GMAIL.COM'
Cc: Hsiao Tong (LKKAuto)
Subject: Your Ref: SJN 1479D_ACCIDENT INVOLVING SJN 1479D / SHC 2772G / OTHERS ON 24.11.2017

Our Ref: CC3/AIG17022659/K1ka3
Your Ref: SJN 1479D

30 NOVEMBER 2017

SHEN YU CHUAN (SHEN YUJUAN)

Dear Sir/Madam,

ACCIDENT INVOLVING SJN 1479D / SHC 2772G / OTHERS ON 24.11.2017

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Pursuant to the above said accident wherein you and/or your authorized driver had amongst other information given us your version of how the accident had occurred, we as the appointed agent of your insurers shall proceed to negotiate for an amicable settlement with third party claimant.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

You are aware that your No-Claim Discount (NCD – if applicable) will be with held for the time being. Pending for final allocation of liability in settlement by our principal AIG Asia Pacific Insurance Pte Ltd.

Please call us if you have further queries.

Best Regards,

Zaini Kusaini | Case Handler

LKK Auto Consultants Pte Ltd

DID: 6841-2132 | email: Zaini@lkkauto.com | fax: 6741-4108

Blk 51, PayaUbi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

LETTER OF AUTHORISATION

(NAF / PAF)

ACCIDENT INVOLVING **SONATA SHC2772G , SJN1479D , SJW62...** **ON 24-Nov-17 18:10**
ALONG **INSIDE KPE TUNNEL TWDS CITY B4 PIE/TUAS EXIT**

I / We **NG CHOON HEE** (Hirer) NRIC No.: **S1502405D**

and/or (Relief) NRIC No.:

Taxi Number **SHC2772G**

hereby authorise ComfortDelGro Engineering Pte Ltd(CDGE):

1. To submit my/our claims for damages, costs and expense, including loss of income, loss of rental, medical fee and legal costs.
2. To have absolute discretion to agree to any settlement or compensation amount in respect of my/our claim against third party (except personal injuries and medical claims).
3. To sign Discharge Voucher on my/our behalf.
4. To accept any payment (claim proceeds) in respect of the claim against third party and payment by cheque shall be forward directly to CDGE in accordance with CDGE's instruction and made in favour of **"ComfortDelGro Engineering Pte Ltd"**.

Date **25-Nov-2017**

Name of Hirer **NG CHOON HEE**
Hirer NRIC **S1502405D**

Signature :



Address **534 BEDOK NORTH STREET 3 #07-8...**
460534

Contact No. **87006441**

RELEASE VOUCHER
(AIG Asia Pacific - Express Third Party Claim)

"We/I, COMFORTDELGRO ENGINEERING PTE LTD ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for S\$3826.00 (Global Sum) for vehicle no. SHC 2772G that was damaged pursuant to the accident which occurred on 24/11/2017 (date) along KPE NEAR PIE TUAS EXIT (location) involving vehicle no/s SJN 1479D.

This is pursuant to the inspection conducted on 27/11/2017 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner COMFORT TRANSPORTATION PTE LTD ("the third party claimant") of vehicle no. SHC 2772G make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SHC 2772G (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 16 (day) of 01 (month) 20 18 (year)



AUK

Signed by appointed surveyor

CLAIMS DEPARTMENT
COMFORTDELGRO ENGINEERING PTE LTD
205 BRANDELL ROAD
SINGAPORE 67001

Signed by "the workshop" (with chop)

Please forward your cheque made payable to:
COMFORTDELGRO ENGINEERING PTE LTD

"The contents of this document apply to vehicle damages only.
All personal injuries and damages arising therefrom are excluded
from the ambit and application of this document"

GST REG. NO. M2-8921817-3

TAX INVOICE

8010004

AIG ASIA PACIFIC INSURANCE PTE LTD

#08-16 78 SHENTON WAY, CHARTIS BUILD
SINGAPORE 079120

CONTACT NO: 64193000 3225094

VEHICLE NO
SHC2772G

MAKE
HYUNDAI

MODEL
SONATA

DATE OF REG
31.07.2012

CHASSIS CODE
KMHET41VMCA827789

INV. NO/DATE
91343240 28.11.2017

JOB NO.
305092148

ODOMETER READING

JOB TYPE

Description : 3P 24.11.2017

Invoice for Lump Sum Repair

Total Lump Sum Repair Amt	2,950.00
Add GST @ 7.000 %	206.50
Total Invoice amount	3,156.50

Issued by : CHEWBEELENG 28.11.2017 15:56:26
Repair Type : CLSO/57/57
Payment Type/Term : /Credit 30 days

ComfortDelGro Engineering Pte Ltd
A member of COMFORTDELGRO

Head Office:
205 Braddell Road
Singapore 579701

Kindly note that no receipt shall be issued unless requested.

CUSTOMER'S COPY

ACCOUNT No.	INVOICE No.	AMOUNT	BANK/CHQ No.

Our Ref: CT17110853

Date: 28 November 2017



TO WHOM IT MAY CONCERN

Dear Sir/Madam

ACCIDENT ON	24/11/2017 @ 18:10 hrs
ALONG	INSIDE KPE TUNNEL TWDS CITY B4 PIE/TUAS EXIT
INVOLVING	SJN1479D, SJW6297G

We refer to the above-mentioned accident and wish to inform that **Comfort Transportation Pte Ltd** is the registered owner of the taxi bearing vehicle registration number **SHC2772G** (the "Taxi"). The Taxi was hired to **NG CHOON HEE IC NO S1502405D** a registered hirer-operator of **Comfort Transportation Pte Ltd** at the time of occurrence of the aforementioned accident at a rental rate **\$98.25** per day (inclusive of GST).

Please be advised that the Taxi was insured with **India International Insurance Pte Ltd** on a third party basis at the material time of the accident.

We wish to confirm that the aforesaid hirer-operator had obtained our permission to undertake repairs for damage on the Taxi arising from the said accident with a motor workshop of his choice.

Please liaise with the said hirer-operator or his authorized workshop directly for settlement of claims with third party's insurance company in respect of the said accident.

Yours faithfully

Christine Tay
Executive, Fleet Safety

This is a computer generated letter. No signature is required.

Enquire Vehicle Insurer

Vehicle No.	Incident Date/Time	Search Status	Insurance Company Code	Insurance Company Name
SJN1479D	24 Nov 2017 / ✓ 18:10:00	Successful	A04	AIG ASIA PACIFIC INSURANCE PTE. LTD.

Previous

OK

SUC 2772 G

...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	28 Nov 2017 Edit Reg		27 Nov 2017 00:00 Edit Adj Rpt	S\$2,950.00 Edit Estimates	S\$2,950.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by adjuster]

Insured:	Shen Yu Chuan (Shen Yajuan), ID: S2205398A		
Main Claimant:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R		
Vehicle Reg. No.:	SHC2772G	Date of Loss:	24/11/2017 18:00 - :59
Claim Type:	TP / 6206880595SG	Policy/Cover Note No.:	2100118584 (Comprehensive)
Vehicle Reg. No. (Insured):	SJN1479D	Policy No. (Claimant):	MCDM0016
		Excess:	
Repairer:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive, 508969 Loyang - Tel: 6214 8300		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Syed-Yusoff, Saliha] Saliha.Syed-Yusoff@aig.com		
Claimant's Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KALVIN ANG WEI KUN] ... [Final Rpt due 07/12/2017]		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

- AIG_SG (29/11/2017): Request To Upload TP GIA Report

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SHC2772G (6206880595SG)
[SJN1479D]

TP

COMFORT TRANSPORTATION PTE LTD
Nov 24 2017 6:00PM
[Shen Yu Chuan (Shen Yujuan)]
ComfortDelGro Engineering Pte Ltd

Upload Documents		Upload Photos	Compose New Letter	Upload Video	Upload Audio	View View in Browser
----------------------------------	--	-------------------------------	------------------------------------	------------------------------	------------------------------	---

Letters/Correspondences				1 per page	<input checked="" type="checkbox"/>
No	Finalized On			Thumbnail	Print
1	(Draft)	LKK Auto Consultants Pte Ltd (HQ)			
		Third Party Express Settlement – Payment Breakdown	1	Edit	

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On			Thumbnail	Print
		AIG Asia Pacific Insurance Pte. Ltd. (SG)			
1	29/11/17 11:05	Accident Statement	1	Load HTM	
<small>From: DD - Reg. No: SJN1479D, Claimant: SHEN YU CHUAN (SHEN YUJUAN)</small>					

Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder			Thumbnail	Print
		LKK Auto Consultants Pte Ltd (HQ)			
1	28/11/17 19:11	General View	1	Load JPG	<input checked="" type="checkbox"/>
2	28/11/17 19:11	General View	1	Load JPG	<input checked="" type="checkbox"/>
3	28/11/17 19:11	General View	1	Load JPG	<input checked="" type="checkbox"/>
4	28/11/17 19:11	General View	1	Load JPG	<input checked="" type="checkbox"/>
5	28/11/17 19:11	General View	1	Load JPG	<input checked="" type="checkbox"/>
6	28/11/17 19:11	General View	1	Load JPG	<input checked="" type="checkbox"/>
7	28/11/17 19:11	General View	1	Load JPG	<input checked="" type="checkbox"/>
8	28/11/17 19:11	General View	1	Load JPG	<input checked="" type="checkbox"/>
9	28/11/17 19:11	General View	1	Load JPG	<input checked="" type="checkbox"/>
10	28/11/17 19:11	General View	1	Load JPG	<input checked="" type="checkbox"/>
11	28/11/17 19:11	General View	1	Load JPG	<input checked="" type="checkbox"/>
12	28/11/17 19:11	General View	1	Load JPG	<input checked="" type="checkbox"/>
13	28/11/17 19:11	General View	1	Load JPG	<input checked="" type="checkbox"/>
14	28/11/17 19:11	General View	1	Load JPG	<input checked="" type="checkbox"/>
15	28/11/17 19:11	General View	1	Load JPG	<input checked="" type="checkbox"/>
16	28/11/17 19:11	General View	1	Load JPG	<input checked="" type="checkbox"/>
17	28/11/17 19:11	General View	1	Load JPG	<input checked="" type="checkbox"/>
18	29/11/17 19:22	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
19	29/11/17 19:22	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
20	29/11/17 19:22	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
21	29/11/17 19:23	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
22	29/11/17 19:23	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
23	29/11/17 19:23	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
24	29/11/17 19:23	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>

Documentation				1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder			Thumbnail	Print
		LKK Auto Consultants Pte Ltd (HQ)			
1	29/11/17 13:18	TP ESTIMATE + TOWING	1	Load PDF	
2	29/11/17 13:18	TP GIA REPORT	1	Load PDF	

3	23/01/18 09:33	WORKSHOP INVOICE	1	Load PDF	
4	23/01/18 09:33	AUTHORISATION TO ACT FORM	1	Load PDF	
5	23/01/18 09:33	Release Voucher	1	Load PDF	
6	23/01/18 09:33	RENTAL RECEIPT	1	Load PDF	
7	23/01/18 09:33	LTA SEARCH	1	Load PDF	
8	23/01/18 09:33	LETTER TO OI	1	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div><div></div><div>^</div><div>v</div></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer
<small>Note: Remarks are private unless you show it to other parties.</small>

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SJN1479D (Insd veh)	Model:	HYUNDAI SONATA NF 2.0 2.0
	SHC2772G (TP veh)		CRDI AT ABS 2WD 4DR
Date of Accident:	24/11/2017		TURBO (A)

Global Sum Settlement	:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
Repair Estimate	:	\$	7,510.18
Final Repair Cost	:	\$	3,820.00
Loss of Use	:	\$	4.50 days at \$50.00 per day
Rental (if any)	:	\$	4.50 days
LTA / GIA Search Fee	:	\$	
Others:	:	\$	
	:	\$	
Final Settlement Sum (Global Sum)	:	\$	3,820.00
Is Third Party Workshop GIA Registered? <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO (Kindly indicate below)			
A) For <u>Non GIA Registered Workshop</u> : Agreed Liability _____ (%)			
B) For <u>GIA Registered Workshop</u> : BOLA Applicable: Yes/ No BOLA Scenario No: _____			
BOLA Liability: _____ 100 (%) Assessed Liability (*): _____ 0 (%)			
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	ComfortDelGro Engineering Pte Ltd	:	\$ 3,820.00
2)		:	\$
3)		:	\$
4)		:	\$
5)		:	\$

JOANNE LEE KHANG MIN

23 Jan
2018

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG17022659/K1KA3Q2

Date: 23/01/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100118584
Claimant Vehicle No : SHC2772G **Insured Vehicle No :** SJN1479D
 Date of Loss: 24/11/2017 Nature of Claim: TP Claim No: 6206880595SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHC2772G**
 Make & Model: HYUNDAI SONATA NF, 2.0 2.0 CRDI AT ABS 2WD 4DR TURBO (A) Engine No: D4EAC121066
 Reg. Date: 31/07/2012 (Man. Year: 2012) Chassis No: KMHET41VMCA827789
 Colour: Blue Odometer: 96350 km
 Engine Capacity: 1991 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16
 Front Left Side: West Lake 7 mm Rear Left Side: West Lake 7 mm
 Front Right Side: West Lake 7 mm Rear Right Side: West Lake 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,348.86	2,464.10	1,884.76	43.34
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,670.00	1,230.00	1,440.00	53.93
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,018.86	3,694.10	3,324.76	47.37
Approved Total (Overridden) (S\$)		2,950.00		
(S\$)	7,018.86	2,950.00	4,068.86	57.97
+ GST 7.00/7.00% (S\$)	491.32	206.50	284.82	57.97
Nett Amount (S\$)	7,510.18	3,156.50	4,353.68	57.97
+ Loss of Use (4.5 x S\$50.00/day) (S\$)		225.00		
+ Car Rental (4.5 x S\$98.25/day) (S\$)		442.13		
+ Doc/Search Fee (S\$)		5.35		
Nett Liability (S\$)		3,828.98		
Global Sum Settlement (S\$)		3,820.00		

INSPECTION

Date of Assignment: 27/11/2017

Date Inspected: 27/11/2017 Inspected At:

ComfortDelGro Engineering Pte Ltd
(Loyang)
59 Loyang Drive
Singapore 508969

Estimated Period of Repair: 4.0 days

Adjuster: KALVIN ANG WEI KUN**Manager:** Zaini Bin Kusaini

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID	Dented	1,349.50 FL	*1,349.50 FL
2	1		*BOOT LID RUBBER	Serviceable	110.90 FL	*- FL
3	1		*BOOT LID LOCK UPPER	Serviceable	132.10 FL	*- FL
4	1		*BOOT LID LOCK LOWER	Serviceable	30.30 FL	*- FL
5	1		*BOOT LID SONATA PLATE	Necessary	43.60 FL	*43.60 FL
6	1		*BOOT LID HYUNDAI PLATE	Necessary	24.20 FL	*24.20 FL
7	1		*BOOT LID H EMBLEM	Necessary	26.10 FL	*26.10 FL
8	1		*BOOT LID CRDI PLATE	Necessary	22.70 FL	*22.70 FL
9	1		*REAR BUMPER	Deformed	578.40 FL	*578.40 FL
10	1		*REAR BUMPER REINFORCEMENT	Cracked	483.30 FL	*483.30 FL
11	1		*REAR BUMPER CLIP	Necessary	22.00 FL	*22.00 FL
12	2		*REAR BUMPER BRACKET	Serviceable	98.00 FL	*- FL
13	1		*REAR BUMPER SPONGE	Torn	137.40 FL	*137.40 FL
14	1		*REAR BUMPER UNDER COVER	Cracked	185.80 FL	*185.80 FL
15	2		*REAR BUMPER PROTECTOR (LH/RH)	Repair	76.00 FL	*- FL
16	1		*REAR PANEL	Repair	391.80 FL	*- FL
17	1		*REAR PANEL GARNISH	Serviceable	95.80 FL	*- FL
18	1		*SPARE TYRE HOLDER	Serviceable	27.60 FL	*- FL
19	1		*SPARE TYRE PANEL	Serviceable	863.00 FL	*- FL
20	1		*SPARE TYRE PANEL CUSHION	Serviceable	200.30 FL	*- FL
21	1		*REAR TOWING HOOK	Serviceable	135.30 FL	*- FL
22	1		*MEMBER ASSY -REAR FLOOR CENTRE	Serviceable	163.60 FL	*- FL
23	1		*BOOT LID COMFORT LOGO & TEL NO.STICKER	Necessary	30.00 FS	*30.00 FS
24	1		*REAR NO.PLATE	Serviceable	25.00 FS	*- FS
25	1		*REAR BUMPER REVERSE SENSOR	Shorted	135.70 FS	*135.70 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,388.40	3,038.70
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,039.54	574.60
Total Parts (\$\$)	4,348.86	2,464.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	1,500.00	600.00
2	SPRAY PAINTING CHARGE	New	800.00	540.00
3	WIRING CHARGE	New	50.00	0.00
4	TUFF KOTE	New	50.00	20.00
5	REMOVE/REFIX REVERSE SENSOR	New	120.00	20.00
6	TOWING	New	150.00	50.00
Gross Labour Cost (S\$)			2,670.00	1,230.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >