Kalvin REF: CS/DE	CC3/TM217022660/Klvbn2
2.50	Veh No: SH (1328M Yr Regn: 23 Am 257
timated Cost:	Type: M.Car / M.Cycle / Bus / Van / Lorry / Tag / Prime Mover /
/TP/WS/TP RES/OD RES/EVA/INV/MV	Truck / Trailer or
Inspect Vehicle No:	Make: Toylo Prins c.c. Heb Colour Blue A/C: Insufed/Std/NI/NA
Workshop m/s	
	Sp.Reading 3 9 0 8 2 T/Radio: Inserted / Std / NI / NA
ured: PZ 802T	Eng/No:
licy No. mbolou47	C/No: JTDKB3F460356366x
aims No. M1706010	Gen. Cond: Good / Fag/ Poor / Burnt
m Insured: Excess:	Steering: Inordigr / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inorder Jammed / Leaked / Burnt or
ake of Veh:	Modi: Nil / S/Rim / STD B/Rim or
	Tyre Size: F: 195/65 No.5
(Policy Condition)	R:
emark: The veh had commenced its N/S O	
repair at the time of inspection.	TOYO / YONO or
al. or Market Value:	Front Rear 7 mm R/Bel. 2 mm
DAC Accident Rport: Consistent? : Yes or No	R/Bal. 7 mm R/Bal. 7 mm
BIA / PR Seen: Consistent? : Yes or No	D.O.A. 25/11/2 D.O.I. 28/1-7
st. Repairs: days Res.: Yes or No	106501
um Sum: % 3 Val.: Yes or No	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
CA / REV / REP. / 24 HRS Vehicle: IN/	Frank w/s
Date: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision
Date / Time Action / Instruction	Kuhali DUA: 15(1)4 7.Ki>
SHC 1328M - 08/FCLIHUNSONA/	1110011 010
36/4/2 Color 1/1 \$ 3546.03 /2Pm	1(4)(2)(2)
30/11/12 (what P/F\$ 3546.03 /2/2	
1/12/17 @ HUlpm Re-confirmed \$	3 3556.03 with Larry (Red 1965.17, 3590) different 14 in merimon system
RECEIVED 0 4 DEC 2	Luin.
Date/Time, File Pass to? : Preli. Report	Days Of Repair: 2
Einal Paport	Resurvey No. of Trip: \ Survey Fee:
Data/Time, File Return to?	Transportation 250
a ilis-typist Add	d Fee: Site Insp (\$)s+Rssi(0
	: Interview (\$) Photos
	grant to the state of the state
Report Format: merimen	Tech Invs (\$) Others Weekend (\$)

Reference No.: (C3) TMI (70 >> 660 KIVD
Policy Type: OD / TP / TP RES / TL / EVA

Typist

dmin (): Case handler to make sure all Inform	Y-Date	N-Date	Y-Date	N-Date
	Assign Form Reference No.	~			
C	Customer Code				
C	Assign From				
N	Assign Date	~			
C	Veh No (Inspected)	_			
С	Veh No (Insured)	1			
С	D.O.A	-			
C	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	~			
С	Policy No	~			
C	Claim No Insurance Authorisation (CA /REV/REP)				
С		~			
С	Report Type				
С	Weekend Charges	/			
N	Survey held at/Repairer				
С	Excess		loted	all required	informa
urvey	or (): Case handler to make sure t	he surveryor c	ompleted	an required	IIIIOIIIIa
L) Assig	nment Form				T
c	Vehicle No	~		-	-
С	Regn Month/Year	~			-
N	Vehicle Type	~			-
N	Make & Model	~			
C	Engine Capacity. (C.C)	_			
N	Colour	~			
c	Odometer. (Sp.Reading)	-			-
c	Chassis No	~			
N	General Condition	_			
N	Steering	-			
N	Brake	~			
N	Modification (Modi)	_			
C	Tyre Size	~			
N	Tyre Make	~			
C	Tyre Balance	-			
C	Date of Inspection	~			
00.71	Survey held	-	1 12 1 15 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		
N	Des. of Damages	_			
N					
(2) Syst	tem - (Views/Merimen)	~			
С	Damaged Vehicle Photographs Uploaded		in a second		
(3) Wo	rkshop Estimate/Assignment Form				-1
N	ALL Parts condition	/			_
С	Market Value for OD cases			1	
c	Estimate Repair Cost for PRI (RSI, TMI, MSIG)			-	
C	Days of repair	~			_
C	Finalised Amount	~		-	
C	Re-inspection Cases to Finalize within 5 Days				
	tem - (Views/Merimen)	10 Table 10		_	
(4) Suc					

Date

Case Handler

...CLAIM SUBFOLDER...(Pending for Survey Report)

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Pending for
Main	28 Nov 2017 10:56 Sendback Est	28 Nov 2017 11:04 S\$5,446.95	28 Nov 2017 17:44 Edit Adj Rpt				Survey Report
					Docur		Show All

Main	Reference	Claim Details Docu	uments Show All
CLAIM SUBFOLDER D	ETAILS		1002028218
Insured:	COMFORT TRANSPORTA	TION PTE LTD, Co. Reg. No.:	199303621K
Main Claimant:	COMFORT TRANSPORTA		25/11/2017 10:00 - :59
Vehicle Reg. No.:	SHC1328M	Date of Loss:	
Claim Type:	TP / M1706010	Policy/Cover Note No.:	MB010047 (Comprehensive) Coverage: 26/06/2017 - 25/06/2018
Vehicle Reg. No. (Insured):	PZ822T	Policy No. (Claimant):	
(Insureu).		Excess:	S\$3,000.00
Repairer:	6214 8300	ring Pte Ltd (Loyang) 59 Loya	
Handling Insurer:	Tay - 650264131	Singapore Ltd (HQ) - Tel: 62	
Adjuster:	LKK Auto Consultants F WEI KUN] [Final R	Pte Ltd (HQ) - Tel: 6256-3561 . pt due 07/12/2017]	[Handled by KALVIN ANG
ASSOCIATED MAIL R	ECEIVED	View	All Compose Case Mail
There are no mail for th	is case.		
8		ew ΔII Search Tasks C	Create New Task Complete
ALL ASSOCIATED TA	5.70 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	en an en	
Due Date Priority T	ype Task Group Subject H	landler Assigned By Comp	leted On Created On Done



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Affiliated to Federation Internat	tionale Des Experts En Autom	obile
OKIO MARINE INS	SURANCE SINGAPORE LTD	Ref : CC3/TMI17022	660/K1vb
0 MCCALLUM ST OKIO MARINE CE	REET #09-01 NTRESINGAPORE 069046	Date: 28-11-2017 Code: TMI	
ALL STATE OF THE PARTY OF THE P	Policy Particular	s :- THIRD PARTY CLAI	M
Insured Veh.	PZ 822T	Veh. Inspected	SHC 1328M
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	28/11/2017
2.	Vehicle Par	rticulars & Condition	
Make & Mod	el	c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	Ē.	Steering	
Brakes		Modification	
General			
3.	Conc	ditions of Tyres	
	Size	Make	Balance
R/H Front Ty	re		mm
L/H Front Ty	re		mm
R/H Rear Ty	re		mm
L/H Rear Tyr	re		mm
4.	Descri	ption of Damages	
5.	Gene	eral Information	
Accident Da	A SECTION OF THE PARTY OF THE P	Inspection Date	28/11/2017
Survey held		The state of the s	2000/000 (2.5) (2500/000 Cafood
Carroy mora	59 LOYANG DRIVE SINGAPORE 508969		
5a.		Remarks	
A)THE INSPE B)IN ACCORE	CTION WAS CONDUCTED ON A"O	WITHOUT PREJUDICE" BA , WE HAVE NOT AUTHORI	SIS. ISED REPAIRS.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

- 6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

oforesaid.	The second secon
	ACCIDENT STATEMENT
Date Of Report	26/11/2017 07:25
Date Of Accident	25/11/2017 10:00
Exact Location Of Accident	INSIDE FURAMA RIVERFRONT HOTEL COMPOUND
Country/State of Loss	SINGAPORE
	DETAILS OF OWN VEHICLE
Vehicle Registration Number	SHC1328M
Insured/Policyholder	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768
Vehicle Particulars	
Manufacturer	TOYOTA
Model	PRIUS
Exact Purpose for which vehicle was being used a time of accident	t
Are you claiming under your own insurance policy for repair to your vehicle?	
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI
Insurance Company	
Name of Insurance Company	FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
574	

YES

D-15072701MFSH

Policy	Number
Cover	Note Number

Driver

Fleet Policy

HO THIAN CHOON Name of Driver

S0447543G NRIC No 22/10/1948 Date Of Birth OUTDOOR Occupation 28/04/1973 Date Of Driving Pass

44 YEARS AND 6 MONTHS Driving Experience

MALE Gender

Mobile Number Fax Number Contact Number

EMail Address

RICKYHO235@GMAIL.COM

Address

332 07-1891 ANG MO KIO AVENUE 1

(Hend to side)

Postcode

560332

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

OTHER - TAXI DRIVER

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

SIDE SWIPE

CLEAR

Weather Conditions Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

Was any body injured in the Accident?

NO NO

Was any other material or property damaged?

YES

I have been approached by unknown person(s)

NO

soliciting/offering accident claims assistance.

Number of Passengers (Including Driver)

1

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

SEE ATTACH.

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

YES

Remarks/ Reasons:

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

PZ822T

Vehicle Make/Model/Colour

Details Of Properties Name of Driver

BOON

NRIC/Passport Number

Contact Number

93881608

Address

Postcode

Insurance Company Name

Nature Of Damage

RHT REAR

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

Sketch Plan Pg. 1

U 000 102 200 1	T	7 1	4	
TCH PLAN	11-1-1-1	THAT		\Box
A SHC /328 M				
B: PZ 822T		4	FURKIM LOBB	4 RIVE
	10			
	14	THE		
1851 Chin				
SCRIBE CIRCUMSTANCES OF THE ACCI	DENT			
AQ A	ves, attach	erl.		
No II		<u> </u>		
				-
		-		9144

Policyholder's Signature Date & Time:

Driver's Signature (if driver is not the policyholder)

Hother Cher

Date & Time:

Reporting Centre Personnel's Signature

Name: NRIC/FIN No :

Sketch Plan Pg. 2

escrib	e Circumstances of the Accident
On 25 N	ov 2017 at about 10:00 hrs I stopped my taxi along the waiting area just after the
entranc	e leading towards Furama Hotel Riverfront waiting for the hotel usher to signal me to
move f	orward towards the hotel lobby to pick-up the passenger.
Shortly	after the usher gave me the green light to move forward. Hence I slowly moved
forwar	d towards the Hotel lobby.
Sudder	ly a parked bus PZ822T on my left drive out from the parking lot. As a result of this.
the rigi	nt hand side rear of the bus hit and grazed the front left portion towards the front
right o	f my taxi thus damaging them in the process.
No inju	ry at the point of the accident.

Declaration

I/We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION PTE L.. CO. REG. NO. 199303821R 116Than Chr

Policyholder's Signature/Date &


Time

Driver's Signature(If driver is not the policyholder)/Date

& Time


Witnessed b Reporting

Centre Personnel





















COMFORTDELGRO ENGINEERING

A member of COMFORTDELGRO

Date/Time: 27.11.2017 09:34

Page : 1

eam: ARC Repair TP(C	(SO)1 JOB CAR	D Sales Order:	JC NO.305092292
eam: ARC Repair IF(C		REGN NO int 220M	MILEAGE
MS COMFORT TRANSPO	RTATION PTE LTD VAR	MAKE: TOYOTA	FUELF
STOMER NO. 83 SIN MING DR PRESS Singapore SINGA	IVE PORE 575717	MODELPRIUS HYBRID(G4)25.19 ^{AT} 2017 11:35
65508755	(O)	YR OF MANUS. 2017	TARGET DATE
(P)		CHASSIS FORE 3FU6035636	64 COMPLETION DATE/TIME:
COLINE CARD NO.			

JOB DESCRIPTION

Accident Date: 25.11.2017

NATURE: 3P 25.11.2017

C/NO

LABOR CODE

DESCRIPTION

TOKIO - taxi Frut dansay

HECKED &	PASSED OUT BY:				
-	SERVICE ADVIS	SOR		CUSTOMER'S SIGNATURE	
rowledgen	nent Slip		Exit Pass		
e: lo.; ble No.:	SHC1328M	LARRY	Vehicle No.: SHC1328M		
on of Seni	Larry Ng	Signature/Date	Name of Service Advisor	Date	
	d to Service Reception up		To be kept by Security Guard		

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

VEHIC: SHC 1328M

MAKE:

28/11/2017 9:52

Larry

DESCRIPTION	QTY	UNIT PRICE	AN	IOUNT
LAMP ASSY, FOG, LH / hard			\$	910.20
FRONT BUMPER COVER / Pu	land		s	490.50
FRONT BUMPER COVER	ENT XSK		s	691.50
FRONT BUMPER REINFORCEMNI FRONT BUMPER REINFORCEMNI	ENT ARSORRER XJA		s	115.70
BRACKET SUB-ASSY, FRONT SIDE	MEMBER LH V		\$	250.40
FRONT BUMPER SPONGE	MEMBER, EN		s	78.80
FRONT BUMPER SPONGE FRONT BUMPER CENTRE GRILLI	· Xsic		s	301.90
FRONT BUMPER CENTRE GRIEDI FRONT BUMPER TOWING COVER	-ut		s	82.70
SUPPORT FR BUMPER, LH	-1		s	81.70
SUPPORT FR BUMPER, LH V	NTING You		s	29.6
BRACKET, FRONT BUMPER MOU	1 24		s	2,530.6
UNIT ASSY, HEADLAMP, LH (LED	1) - 1/21		s	213.5
HEAD LAMP PANEL (LH)	V.cv		s	25.5
BRACKET, HEADLAMP MOUNTIN	NG, LH X		1 3	1.00
	SUB TOTAL		s	5,802.6
	SUB TOTAL		S	1,450.6
200	LESS 25%		s	4,351.9
Front Number Plate Frame	SCOUNTED TOTAL			1,00210
		11 6.63		
Labour Charge	LKK Auto Consultants h	ence notify		
Labour Charge Panel Beating	the Repairer of the follow	ence notify wing:	5	
Panel Beating	To resurvey before after 500 To display damagest partisp	ence notify wing: ey painting during resirvey	\$ \$	560. 490.
Panel Beating Spray Painting Charge	the Repairer of the folio To resurvey before after sor To display damaged partis; Parts prices are subject to re Third party slave us one	ence notify wing: ey painting during resurvey continue on	0.55	568.0 490.1
Panel Beating Spray Painting Charge Wiring Charge	the Repairer of the folio To resurvey before after sor To display damaged partis; Parts prices are subject to a Third party survey is on a No illegal or discassion(s) as	ence notify wing: ay paining during reservey confirms on the interestical basis as were	s	200 568.0 499.1 594
Panel Beating Spray Painting Charge	the Repairer of the folio To resurvey before after sor To display damaged partis; Parts prices are subject to a Third party survey is on a No illegal or discassion(s) as	ence notify wing: ay paining during reservey confirms on the interestical basis as were	s s	560.0 490.7 59.4 59.4
Panel Beating Spray Painting Charge Wiring Charge	the Repairer of the folio To resurvey before after sor To display damaged partis; Parts prices are subject to o Third party survey is on a No illegal mindficution(s) is Supplementary length must be subject to final approval	ence notify wing: ay paining during reservey confirms on the interestical basis as were	s s	560.0 490.1
Panel Beating Spray Painting Charge Wiring Charge	the Repairer of the folio To resurvey before after sor To display damagest pairis; Parts prices are subject to o Third party survey is on a No illegal middle shorts; mulis subject to final approval TOFAL LABOUR Acknowledged by Repairer Signature;	ence notify wing: ay paining during reservey confirms on the interestical basis as were	s s	560.0 490.1 59.4 59.1
Panel Beating Spray Painting Charge Wiring Charge Tuff Kote	the Repairer of the folio To resurvey before after sor To display damaged partis; Parts prices are subject to o Third party survey is on a No illegal of dictation(s) is Supplementary demissions and is subject to final approval TOTAL LABOUR Acknowledged by Repairer Signature; ESTIMATE: TOTAL	ence notify wing: ay paining during reservey confirms on the interestical basis as were	s s s	560.0 490.1 59.4 59.1 1,060.
Panel Beating Spray Painting Charge Wiring Charge Tuff Kote	the Repairer of the folio To resurvey before after sor To display damaged partis; Parts prices are subject to o Third party survey is on a No illegal of dictation(s) is Supplementary demissions and is subject to final approval TOTAL LABOUR Acknowledged by Repairer Signature; ESTIMATE: TOTAL	ence notify wing: ay paining during reservey confirms on the interestical basis as were	s s s	560.0 490.1 59.4 59.1 1,060.
Panel Beating Spray Painting Charge Wiring Charge Tuff Kote	the Repairer of the folio To resurvey before after sor To display damaged partis; Parts prices are subject to o Third party survey is on a No illegal of dictation(s) is Supplementary demissions and is subject to final approval TOTAL LABOUR Acknowledged by Repairer Signature; ESTIMATE: TOTAL	ence notify wing: ay paining during reservey confirms on the interestical basis as were	s s s	560.0 490.7 59.4 59.4
Panel Beating Spray Painting Charge Wiring Charge Tuff Kote	the Repairer of the folio To resurvey before after sor To display damaged partis; Parts prices are subject to o Third party survey is on a No illegal of dictation(s) is Supplementary demissions and is subject to final approval TOTAL LABOUR Acknowledged by Repairer Signature; ESTIMATE: TOTAL	ence notify wing: ay paining during reservey confirms on the interestical basis as were	s s s	560.0 490.1 59.4 59.1 1,060.
Panel Beating Spray Painting Charge Wiring Charge Tuff Kote	the Repairer of the folio To resurvey before after sor To display damaged partis; Parts prices are subject to o Third party survey is on a No illegal of dictation(s) is Supplementary demissions and is subject to final approval TOTAL LABOUR Acknowledged by Repairer Signature; ESTIMATE: TOTAL	ence notify wing: ay paining during reservey confirms on the interestical basis as were	s s s	560.0 490.1 59.4 59.1 1,060.
Panel Beating Spray Painting Charge Wiring Charge Tuff Kote	the Repairer of the folio To resurvey before after sor To display damaged partis; Parts prices are subject to o Third party survey is on a No illegal of dictation(s) is Supplementary demissions and is subject to final approval TOTAL LABOUR Acknowledged by Repairer Signature; ESTIMATE: TOTAL	ence notify wing: ay paining during reservey confirms on the interestical basis as were	s s s	560.0 490.1 59.4 59.1
Panel Beating Spray Painting Charge Wiring Charge Tuff Kote	the Repairer of the folio To resurvey before after sor To display damaged partis; Parts prices are subject to o Third party survey is on a No illegal of dictation(s) is Supplementary demissions and is subject to final approval TOTAL LABOUR Acknowledged by Repairer Signature; ESTIMATE: TOTAL	ence notify wing: ay paining during reservey confirms on the interestical basis as were	s s s	560.0 490.1 59.4 59.1 1,060.
Panel Beating Spray Painting Charge Wiring Charge Tuff Kote	the Repairer of the folio To resurvey before after sor To display damaged partis; Parts prices are subject to o Third party survey is on a No illegal of dictation(s) is Supplementary demissions and is subject to final approval TOTAL LABOUR Acknowledged by Repairer Signature; ESTIMATE: TOTAL	ence notify wing: ay paining during reservey confirms on the interestical basis as were	s s s	560.0 490.1 59.4 59.1 1,060.

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

59 Loyang Drive Singapore 508969 Tel: 6214 8300

TP INSURER:

Tokio Marine Insurance Singapore Ltd (HQ)

COMFORT TRANSPORTATION PTE LTD

Singapore

PARTICULARS OF CLAIM

Claim Type:

Third Party

Ref. No: Date of Loss:

25/11/2017

Policy No:

Driveable?

Party At Fault:

Vehicle Reg. No.: SHC1328M UNKNOWN

YES

Make/Model:

TOYOTA PRIUS C, 1.5 (A)

Vehicle Reg.

23/08/2017

Vehicle Colour:

Date:

Gen Condition: Excellent

Engine No:

2ZRS062234

Chassis No:

JTDKB3FU603563664

Odometer:

39082 KM

Paint Type:

List Item Discount: 25.00 %

Total Loss?

NO

Blue

Est. Duration of

3

Repair (day)

Present Location: COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)

COST OF CLAIMS		Amount
A POR CLOSE VENEZUE VENEZUE CON CONTROL CONTRO		4,376.95
Parts		10.00
		1,060.00
Labour		0.00
Paintwork Labour		
Towing		0.00
	Gross Total (S\$)	5,446.95
	+ GST 7.00% (S\$)	381.29
	Nett Amount (S\$)	5,828.24

This claim is handled by: NG NYUK PHIN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG

Version: 1.0 (Last Synchronised: 28 Nov 2017)

Parts:

TOYOTA PRIUS C 1.5 (A) (Catalogue:Merimen Singapore 1.0)

Labour:

Repairer's

(Price-denominated Standard List)

Print Code: ComfortDelGro Engineering Pte Ltd/SHC1328M/28/11/2017 11:04

Validity:

These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Est	imate	es on F	Parts	0/ Dies	%Depr	Amount
No.	Qty I	Part No.	Particulars	%Disc	лосрі	
-	4		*FOG LAMP - LH Grazed	25.00	0.00	*910.20 FL
1	1		*FRONT BUMPER COVER DEF	25.00	0.00	*490.50 FL
2	1		*FRONT BUMPER REINFORCEMENT SVC	25.00	0.00	*691.50 FL
3	1		*FRONT BUMPER REINFORCEMENT ABSORBER SYC	25.00	0.00	*115.70 FL
4	1		*BRACKET SUB-ASSY, FRONT SIDE MEMBER - LH SYC	25.00	0.00	*250.40 FL
5	1		BRACKET SUB-ASST, FRONT SIDE INCIDEN	25.00	0.00	*78.80 FL
6	1		*FRONT BUMPER SPONGE SYC	25.00	0.00	*301.90 FL
7	1		*FRONT BUMPER CENTRE GRILLE SVC	25.00	0.00	*82.70 FL
8	1		*FRONT BUMPER TOWING COVER (4)	25.00	0.00	*81.70 FL
9	1		*SUPPORT FR BUMPER - LH CYN *BRACKET ERT BUMPER MOUNTING SYC	25.00	0.00	*29.60 FL
10	1		BRACKETT KT BOM ENTING	25.00	0.00	*2,530.60 FL
11	1		*UNIT ASSY, HEADLAMP - LH Grazed	25.00	0.00	*213.50 FL
12	1		*HEADLAMP PANEL - LH SVC		0.00	*25.50 FL
13	1		*BRACKET HEADLAMP MOUNTING - LH SVC	25.00	0.00	*25.00 FS
14	1		*FRONT NUMBER PLATE SVC	0	0.00	20.0010
F=Fr	anchise pa	art. S=SpcNe	ett, L=ListItemDisc.			5,827.60
			Sub Total (S\$)			1,450.65
			- List Item Discount on L Items (S\$)			1,400.00
			Total Parts (S\$)			4,376.95

ComfortDelGro Engineering Pte Ltd/SHC1328M/28/11/2017 11:04. Not valid without Reference section. Generated using Merimen e-Claims IEAS

Est	Estimates on Miscellaneous Items			Amount
No	Qty	Particulars		
Misc	ellan	eous Items		10.00
1	1	OD/TP Case (Insurer)		
			Sub Total (S\$)	10.00

Es No	timates on Labour Particulars	Lab.Type	Amount	
Lab 1 2 3	OUR Items PANEL BEATING SPRAY PAINTING WIRING CHARGE TUFF KOTE	New New New New	560.00 400.00 50.00 50.00	189
7	IST ROLL	Gross Labour Cost (S\$)	1,060.00	

ComfortDelGro Engineering Pte Ltd/SHC1328M/28/11/2017 11:04. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

59 Loyang Drive Singapore 508969 Tel: 6214 8300

(SUPPLEMENTARY)

TP INSURER:

Tokio Marine Insurance Singapore Ltd (HQ)

COMFORT TRANSPORTATION PTE LTD

Singapore

PARTICULARS OF CLAIM

Claim Type: Policy No:

Third Party

MB010047

Vehicle Reg. No.: SHC1328M

Party At Fault: Make/Model:

UNKNOWN

TOYOTA PRIUS C, 1.5 (A)

Vehicle Reg.

Date of Loss:

Driveable?

23/08/2017

25/11/2017

YES

Date:

Ref. No:

Vehicle Colour:

Blue

2ZRS062234

Engine No: Odometer:

39082 KM

Gen Condition: Excellent Chassis No:

JTDKB3FU603563664

Paint Type:

List Item Discount: 25.00 %

Total Loss?

NO 3

Est. Duration of

Repair (day)

Present Location: COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)

COST OF CLAIMS		Amount
Parts		/4.25
Miscellaneous Items		0.00
Labour		0.00
Paintwork Labour		0.00
Towing		0.00
SOURCE STATE OF THE STATE OF TH	Gross Total (S\$)	74.25
	+ GST 7.00% (S\$)	5.20
	Nett Amount (S\$)	79.45
	+ Previous Estimates (S\$)	5,828.24
	Claim Total (S\$)	5,907.69
	200000000 AN EXP	

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG

Version: 1.0 (Last Synchronised: 01 Dec 2017)

Parts:

144

TOYOTA PRIUS C 1.5 (A) (Catalogue:Merimen Singapore 1.0)

Labour:

Repairer's

(Price-denominated Standard List)

Print Code: ComfortDelGro Engineering Pte Ltd/SHC1328M/01/12/2017 14:50

Validity:

These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qtv	Part No.	Particulars		%Disc	%Depr	Amount
1	1		*Front number plate garnish frame	Gigzeel	25.00	0.00	*99,00 FL
F=Fra	inchise	part, L=ListItemDis		Sub Total (S\$) Discount on L Items (S\$)			99.00 24.75
				Total Parts (S\$)			74.25

ComfortDelGro Engineering Pte Ltd/SHC1328M/01/12/2017 14:50. Not valid without Reference section. Generated using Merimen e-Claims IEAS

COMFORTDELGRO ENGINEERING

305092292 Our Job Ref No . ComfortDelGro Engineering Pte Ltd 59 Loyang Drive Singapore 508969 Fax: 6546 8156 30.11.2017 Date **FINALIZATION FORM** Fax: LKK KALVIN Attn : 25.11.2017 Date of Accident: Vehicle Reg No. : SHC1328M The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-PZ822T TOKIO The repair job shall bill to: 1. The finalized amount shall be: 2. \$3,146.03 Spare Parts after List discount (a) \$400.00 (b) Labour Charges \$3,546.03 Total for Part-By-Part Repair Cost (c.) Lumpsum Repair (if applicable) Total for Lumpsum repair cost after Less: Final Lumpsum Repair cost Estimated normal period for repairs: 2 working days. 3. We shall treat the above amount as Correct and Confirmed if there is no reply from you 4. within 7 working days We confirm the estimates and Thank you for your assistance. 5. finalized amount Signature: Signature: Name Name : 30/11/17 Date 6214 8316 Tel 6546 8156 Fax For Official Use Only Document Confirm By Remarks Attached Amount (Signature) Item Yes or No YES Rental Rate P/Day Loss of Income Paid Survey Fees \$5.35 4. LTA Search Fee Medical Fees (on behalf of driver, if applicable)

Overrun

Remarks:

COMFORTDELGRO ENGINEERING PTE LTD

Date: 30.11.2017 Time: 11:44:35

Page: 1

: 305092292

REPAIR ESTIMATE

COMPANY: THIRD PARTY'S CLAIMS (CAS)

CUSTOMER: 7010045

ADDRESS: COMFORT TRANSPORTATION PTE LTD

383 SIN MING DRIVE

SINGAPORE SINGAPORE 575717

65508755

JOB NO REGN NO MILEAGE

: SHC1328M : 0000000000

MAKE

MODEL

: TOYOTA : PRIUS HYBRID(G4)

DATE OF REGN : 23.08.2017

DATE/TIME IN

: 25.11.2017 11:35

ACCIDENT DATE : 25.11.2017

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0302-2292-G PRIG4 COVER FRONT BUMPER 1 490.50 25.00 367.87

0002 04-01-0302-0632-G PRIG4 COVER FRONT BUMPER 1 82.70 25.00 62.02

0003 04-01-0302-2871-G PRIG4 SUPPORT FRONT BUMPE 1 81.70 25.00 61.27

1 2,530.60 25.00 1,897.95 0004 04-01-0302-2815-G PRIG4 UNIT ASSY HEADLAMP

0005 04-01-0302-4891-G PRIG4 LAMP ASSY FOG LH 1 910.20 25.00 682.65

0006 04-01-0302-2170-G PRIG4 FRAME FRT BUMPER PL 1 99.00 25.00 74.25

SUB-TOTAL : 3,146.01

JOB NATURE

200.00 PANEL BEATING 0000 L

180.00 SPRAYPAINT ON AFFECTED AREA 0001 23-502

20.00 WIRING CHARGE 0002 17-01

SUB-TOTAL: 400.00

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 30.11.2017 Time: 11:44:35

Page: 2

COMPANY: THIRD PARTY'S CLAIMS (CAS)

CUSTOMER: 7010045

ADDRESS: COMFORT TRANSPORTATION PTE LTD

383 SIN MING DRIVE

SINGAPORE SINGAPORE 575717

65508755

; 305092292 JOB NO : SHC1328M REGN NO : 0000000000 MILEAGE : TOYOTA

MAKE

: PRIUS HYBRID(C MODEL

DATE OF REGN : 23.08.2017 DATE/TIME IN : 25.11.2017 11:35

ACCIDENT DATE : 25.11.2017

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

TOTAL : 3,546.01

AUTHORISED: YES / NO

SURVEYOR NAME & SIGNATURE MVA NAME & SIGNATURE DATE:

DATE:

LKK Auto Consultants Pte Ltd (Co Reg. No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CC3/TMI17022660/K1VBN2

Date:

06/12/2017

REFERENCE

Handling Insurer:

Tokio Marine Insurance Singapore Ltd

Policy No:

MB010047

Claimant

SHC1328M

Insured Vehicle No:

PZ822T

Vehicle No: Date of Loss:

Make & Model:

25/11/2017

Nature of Claim:

TP

Claim No: M1706010

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SHC1328M

TOYOTA PRIUS C, 1.5 (A)

23/08/2017 (Man. Year: 2017)

Engine No: Chassis No: Odometer:

2ZRS062234 JTDKB3FU603563664

39082 km

Reg. Date: Colour:

Blue

Engine Capacity: Market Value/New Car Price:

1798 cc N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Excellent Yes

Steering (Serviceable): Engine Modification:

Yes Footbrake (Serviceable): No Pre-accident Condition:

Yes Good

Handbrake (Serviceable):

CONDITION OF TYRES Front Tyre Size:

195/65R15

Rear Tyre Size:

195/65R15

Front Left Side:

Yokohama 7 mm

Rear Left Side:

Yokohama 7 mm

Front Right Side:

Yokohama 7 mm

Rear Right Side:

Yokohama 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS Parts	Repairer's 4,451.20 10.00	Adjuster's 3,146.02 10.00	1,305.18 0.00	Diff % 29.32 0.00
Miscellaneous Items Labour Paintwork Labour	1,060.00 0.00 0.00	400.00 0.00 0.00	660.00 0.00 0.00	62.26
Towing Gross Total (S\$) + GST 7.00/7.00% (S\$)	5,521.20 386.49	3,556.02 248.92	1,965.18 137.57	35.59 35.59
Nett Amount (S\$)	5,907.69	3,804.94	2,102.75	35.59

INSPECTION

Date of Assignment:

28/11/2017 Present Location:

ComfortDelGro Engineering Pte Ltd

(Loyang)

Date Inspected:

28/11/2017 Inspected At:

ComfortDelGro Engineering Pte Ltd

(Loyang)

59 Loyang Drive Singapore 508969

Estimated Period of Repair:

2.0 days

Adjuster: KALVIN ANG WEI KUN

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 06 Dec 2017)

Parts: 144 TOYOTA PRIUS C 1.5 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SHC1328M)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

		mended Parts Part No. Particulars	Condition	Repairer's	Amount
4	1	*FOG LAMP - LH	Grazed	910.20 FL	*910.20 FL
2	1		Deformed	490.50 FL	*490.50 FL
3	1	*FRONT BUMPER REINFORCEMENT	Serviceable	691.50 FL	*-FL
4	4	*FRONT BUMPER REINFORCEMENT ABSORBER	Serviceable	115.70 FL	*-FL
	4	*BRACKET SUB-ASSY, FRONT SIDE MEMBER - LH	Serviceable	250.40 FL	*-FL
5 6	1	*FRONT BUMPER SPONGE	Serviceable	78.80 FL	*-FL
	1	*FRONT BUMPER CENTRE GRILLE	Serviceable	301.90 FL	*- FL
7 8	1		Cut	82.70 FL	*82.70 FL
	1	*SUPPORT FR BUMPER - LH	Cracked	81.70 FL	*81.70 FL
9	1	*BRACKET FRT BUMPER MOUNTING	Serviceable	29.60 FL	*- FL
10	1	BRACKET I'M BOIM EN MOONTHIE	Grazed	2,530.60 FL	*2,530.60 FL
11	1	*HEADLAMP PANEL - LH	Serviceable	213.50 FL	*- FL
12	1		Serviceable	25.50 FL	*- FL
13 14	1	*FRONT NUMBER PLATE	Serviceable	25.00 FS	*- FS
	pleme	entary #1		00 00 EI	*99.00 FL
15	1	*Front number plate garnish frame	Grazed	99.00 FL	99.0011
F=Fr	anchise	part. S=SpcNett. L=ListItemDisc.			
			ub Total (S\$)		4,194.70
		- List Item Discount on L Items 25.00	/25.00% (S\$)	1,475.40	1,048.68
		Tot	al Parts (S\$)	4,451.20	3,146.02

Report was unsubmitted during this print-out.

No No	commended Miscellaneou Oty Particulars	35 1101110	Repairer's	Amount
Misc	ellaneous Items		10.00	10.00
1	1 OD/TP Case (Insurer)		10.00	10.00
		Sub Total (S\$)	10.00	10.00
Re	commended Labour Particulars	Lab.Type	Repairer's	Amount
Lab	our Items	94617.0		200.00
1	PANEL BEATING	New	560.00	200.00
2	SPRAY PAINTING	New	400.00	180.00
3	WIRING CHARGE	New	50.00	20.00
4	TUFF KOTE	New	50.00	
		Gross Labour Cost (S\$)	1,060.00	400.00
	Repo	t was unsubmitted during this print-out.		

< END OF ESTIMATES >